to beam	C Evingst	1 1		TI MADO LIKK	
INS. CASE OWN	ER:	CC 4/AXA1702			1
Surveyor:	Taufith	DOI: ASSIGN	2/17	Date / Time:	NIME -
Pre-assign / CC	U/FTE SUV 857	X.		Registered in Merimen:	
Insured Vehicle	No. :		Claim No. Policy No.	CN 85607	>
Insured Tel No.	9	HP: 93799370	Make / Model		
Excess Sec II :S		DOA: WINA	Place of Accid	ient: CF	
Is driver the own If NO, Driver N		Nature of Accident	OI GIA REPO	ORT YES NO ; TP GIA REPOR	TYBS/NO
Driver To	THEOREM	(V/L-YES/NO)	Insured Liabili	ity: % Final? Ye	s/No
50 6 187	<u> </u>		-		
INSRS. WSP: Tel: Liability: RMKS:	WN tov INSR. WSP: Tel: Liabil RMK	ity:	INSRS: WSP: Tel: Liability: RMKS:	INSR WSP: Tel: Liabil RMK	ity:
Date/Time	Str trans-4	312 v 24c2	4-4	STAGE	DATE / PIC
MAN				Non-Reporting ltr (1st): Non-Reporting ltr (2nd):	
LPF				Non-Reporting ltr (Final): Notification ltr (if non-pickup):	
19/14/14/0 3.540	m (alled Ol, Mr - Ol rear ender	Chew. Not pickup)	Call Ot: 24 Star Cy	19/4/4
	- Sont latter	N 61		Documentation Check List: Ha	ndler Typist
7				Notification ltr (if non-pickup) After call ltr to OI:	
1 9/2/18 -	File pass to t	ype mandale.		Authorisation To Act: Release Voucher:	
%:	At Tork Imor	udthern I and i	dueto	Final Repair Bill: Car Rental Invoice:	
Mille		21		Towing Invoice	
2/11/10	PECEN	shules to close.		Medical Bill:	
	Kro	2010		PIR: Manuate/Reject Instruction:	
	RECEIVI	ED 0 5 NOV 2018		LOD	
ILIMINARY ADVICE		Sent By:		Payment Breakdown Form: Post-Repair Photos:	
i i i i i i i i i i i i i i i i i i i	E Date Time.	ON BY		Others:	
PINALIZATION	Date/Time:	Confirm with: days) Reduction:	9	Confirm by:	Call
Repair Cost: Y12/AL SETTLEMENT	Date/Time: 4 1018	Confirm with WMW	.76	Email Call	
Recair Cost: W/65T		I / Assessed) BOLA S/N No.: 7	7.	If NO or B 28, Ass. Liu:	
Loss of Rental (LOR)	4755 674.10 (days) X Mr.W		DOWN REMS	2
Low of Income (LOU):	SS - (S)			CHIEF !	
LOU on	lor + Lou	LOR + LOI Tick only one	r)		
GIA/LPA Search Molical:	55 -			1) Claim status: Napal/Reject	Private Settle
Didestrement:	SS =	(e.g. Tow/ Independe	nt)	2) Report Format: 33 Survey fee: 53 50 -	w
Legal Cost Total:	ss \$520-90	Global Sum S\$:			
LUAL PAYMENT	Date/Time:	Confirm with:	C. Cal.	Emaji Call	
Physic 1:	ss 8520-90	Name 1: Kah Mote Name 2:	er (o soln	. Bhol	
Physe 2: (Strike if N.A.) Puree 3: (Strike if N.A.)	SS SS	Name 3:			
The state of the s					

Interview: (\$

Tech Invs (\$

Weekend (\$

Report Format:

Lump Sym / I.B.I: (S

J. Phones



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

		Anniated to Constitution	nternationale Des Experts En Autor	
XA IN	SURANCE PTE	LTD	Ref : CC4/AXA1702	3766/pb3
	ITON WAY #24- WERSINGAPO		Date: 14-12-2017 Code: AXA2	
		Policy Part	iculars :- THIRD PARTY CLA	IM
	sured Veh.	SGV 857X	Veh. Inspected	SDG 1839G
P	olicy No.		Coverage (\$)	0.00
_	laim No.		Excess (\$)	0.00
A	ssign From		Assign Date	14/12/2017
2.		Vehic	le Particulars & Condition	
22	lake & Model		c,c	0
E	ngine No.	HIDDEN	Year of Reg.	
C	hassis No.		Colour	
C	dometer	2 1	Steering	
E	irakes		Modification	
G	General			
3.			Conditions of Tyres	
		Size	Make	Balance
F	VH Front Tyre			mm
L	JH Front Tyre			mm
F	VH Rear Tyre			mm
L	JH Rear Tyre		7	mm
4.		D	escription of Damages	
5.			General Information	
	Accident Date	11/12/2017	Inspection Date	
_	Survey held at	KAH MOTOR CO SDN		
1	ourvey neid at	NO. 255 ALEXANDRA SINGAPORE 159937		
5a.	En		Remarks	



QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

: SQT17005045 : AXA INSURANCE S'PORE PTE LTD Document No. Page 1 Customer 8 SHENTON WAY Date : 11. Dec 2017 #27-01 AXA TOWER Customer No. : WZA006 SINGAPORE 068811 Svc Advisor : NG SIN HAI Registration No : SDG1839G : K24Z21801867 Engine No Chassis No : JHMRB3850DC201592 : 11. Dec 2017 7:21:38 PM Date | Time Model : ODYSSEY 2.4 EXV AUTO 13YM Surveyor Name Owner's Name : MCNEICE ANTHONY TERENCE Survey Date

ns Policy No.		Survey Date : Authorisation Date :					
Date of Accident	: 11/12/2017						
Water Control			Hall Date: Dis-	- 84		GST	Amount incld GST
Item	Description TP DIRECT SETTLEMENT (J/NO:)	Qty	Unit Price Dis	c %	Amount	2.011	mora ou i
	OWNER MCNEICE ANTHONY TERENCE						
	OWNER INSURER: AXA INSURANCE S'PORE PTE LTD						
	ACC DATE:11/12/2017						
	SURVEYED BY:						
	DATE:						
	REF NO						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH:SGV857X						
					1		
BOSUN	SUNDRIES	1	50.00	30	50.00	3.50	53.50
BOJSE	SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	100.00		100.00 🖟	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER	1	100.00		/ 100.00 🖇	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN (N)	1	280.00	-	280.00	19.60	299.60
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00	15	✓ 80.00 N	5.60	85.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		√450.00°	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00 //	31.50	481.50
BKRP02M	CUT OFF & RENEW RR PANEL STRAIGHTEN 453	1	3000.00	2250	3000.00	210.00	3210.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	1	2800.00	2100	2800.00	196.00	2996.00
BOMISC	REMOVE TRANSFER REVERSE CAMERA, CALIBRATE SETTING.	1	380.00	٧	380.00	26.60	406.60
			Sum L	abor	7850.00	549.50	8,399.50
				49	7		4
RS-4P	BUMPER SENSOR 4PCS	1	180.00	NA.	7- 180.00	12.60	192.60
33501-SLE-003	LAMP UNITR.	1		15 un	X 127.20	8.90	136,10
34150-SLE-003	LIGHT ASSYR LID	1	Hearman G		X 127.20	8.90	136.10
68100-SLE-305ZZ	TAILGATE COMP	1	1010.30 / 3	15 h	656.69	45.97	702.66



QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

Page

2

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sq

For 24-hours Roadside Assistance, Call 98203838

: AXA INSURANCE S'PORE PTE LTD Customer

> 8 SHENTON WAY #27-01 AXA TOWER

SINGAPORE 068811

Registration No

Chassis No

- JHMRB3850DC201592

Model Owner's Name

Ins Policy No. Date of Accident

: SDG1839G

: ODYSSEY 2.4 EXV AUTO 13YM

MCNEICE ANTHONY TERENCE

: 11/12/2017

Document No.

: SQT17005045

: 11. Dec 2017

: WZA006

Customer No. Svc Advisor

Date

: NG SIN HAI : K24Z21801867

Date | Time

Engine No

: 11. Dec 2017 7:21:38 PM

Surveyor Name Survey Date

Authorisation Date

74890-SLE-013ZC GARNISHTAILGATE LOWER 1 #14 7 89210 35	Item	Description	Qty	Unit Price	Disc % Amount	GST Amt	Amount incld GST
75701-SLE-003 EMBLEM(H) 1 27.30 35 ML 17.74 3 1.24 18 75722-SLE-003 EMBLEM(ODYSSEY) 1 30.90 35 ML 20.08 11.41 21 73225-SLE-000 RUBBERWINDSHIELD DAM 1 21.30 35 ML 13.84 3 0.97 14 73226-SLE-000 RUBBERWINDSHIELD DAM 1 19.00 35 ML 12.35 1 0.86 13 73228-SLE-000 MOLDINGR.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73227-SLE-000 MOULDINGR.RR.WINDSHIELD 2 17.80 35 ML 23.14 16.62 24 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 10.77 10.70 10.70 10.70 10.70 10.70 10.70 10.70 10.70 10.70 10.70 10.70 10.7	74800-TF0-J01	LOCKTAILGATE			35 7 × 118.10	8.27	126.37
75722-SLE-003 EMBLEM(ODYSSEY) 1 30.90 35 ML 20.08 1.1.41 21 73225-SLE-000 RUBBERWINDSHIELD DAM 1 21.30 35 ML 13.84 30.97 14 73226-SLE-000 RUBBERWINDSHIELD DAM 1 19.00 35 ML 12.35 1 0.86 13 73228-SLE-000 MOLDINGR.R.WINDSHIELD 1 16.60 35 ML 10.79 1 0.76 11 73227-SLE-000 MOULDINGL.R.R.WINDSHIELD 2 17.80 35 ML 23.14 1.62 24 73278-SLE-000 MOULDINGL.R.R.WINDSHIELD 1 16.60 35 ML 10.79 1 0.76 11 73278-SLE-000 MOULDINGL.R.R.WINDSHIELD 1 16.60 35 ML 10.79 1 0.76 11 73278-SLE-000 MOULDINGL.R.R.WINDSHIELD 1 16.60 35 ML 10.79 1 0.76 11 76707-STK-000 SEALA 1 6.40 35 ML 4.16 0.29 4 04731-SAA-000 RUBBER, W/SHIELD 1 24.20 35 ML 15.73 1.10 16 BO-WS-SEALANT WINDSCREEN SEALANT (N) 2 60.00 ML 120.00 8.40 128 04715-SLE-900ZZ FACERR.BUMPER 1 714.90 35 ML 464.68 32.53 497 33505-SLE-003 REFLECTOR.R.R. 1 42.80 35 ML 27.82 1.95 26 71530-SFE-000ZZ BEAM R.B.UMPER 1 98.70 35 ML 64.15 ML 4.49 66 71593-SLE-003 SPACERR.R.B.UMPER 1 20.20 35 ML 13.13 0.92 14 71598-SLE-003 SPACERR.R.B.UMPER 1 20.20 35 ML 13.13 0.92 14 91505-S9A-003 CLIP.ABUMPER 2 3.90 35 ML 3.01.13 10.92 14 91505-S9A-003 CLIP.ABUMPER 2 3.90 35 ML 3.01.01 21.07 322 84615-SLE-J01ZC LINING COMPR.R.S.IDE 1 463.10 35 ML 301.01 21.07 322	74890-SLE-013ZC	GARNISHTAILGATE LOWER	1 4/4	9382.10	35 de 313.36	21.94	335.30
73225-SLE-000 RUBBERWINDSHIELD DAM 1 21.30 35 ML 13.84 3 0.97 14 73226-SLE-000 RUBBERWINDSHIELD DAM 1 19.00 35 ML 12.35 1 0.86 13 73228-SLE-000 MOLDINGR.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73227-SLE-000 MOLDINGR.R.WINDSHIELD 2 17.80 35 ML 23.14 1.62 24 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278	75701-SLE-003	EMBLEM(H)	1	27.30	35 Mer 17.74 18	331.24	18.98
73226-SLE-000 RUBBERWINDSHIELD DAM 1 19.00 35 12.35 10.86 13 13.228-SLE-000 MOLDINGR.R.WINDSHIELD 1 16.60 35 10.79 10.76 11 11.79 10.76 11.79 10.76 11.79 10.76 11.79 10.76 11.79 10.76 11.79 10.76 11.79 10.76 11.79 10.76 11.79 10.76 11.79 10.79 10.76 11.79 10.76 11.79 10.79 10.76 11.79 10.79 10.76 11.79 10.76 11.79 10.79 10.79 10.79 10.79 10.79 10.79 10.76 11.79 10.79 1	75722-SLE-003	EMBLEM(ODYSSEY)	1	30.90	35 Mer 20.08 3	V-1.41	21.49
73228-SLE-000 MOLDINGR RR WINDSHIELD 1 16.60 35 ML 10.79 1 0.76 11 73227-SLE-000 MOLDINGR RR WINDSHIELD 2 17.80 35 ML 23.14 16.62 24 73278-SLE-000 MOULDINGL RR WINDSHIELD 1 16.60 35 ML 10.79 1 0.76 11 73278-SLE-000 MOULDINGL RR WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL RR WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 76707-STK-000 SEALA 1 6.40 35 ML 4.16 0.29 ML 16.70 0.76 11 76707-STK-000 RUBBER, W/SHIELD 1 24.20 35 ML 15.73 1.10 16 80-WS-SEALANT WINDSCREEN SEALANT (N) 2 60.00 ML 120.00 8.40 128 04715-SLE-900ZZ FACERR BUMPER 1 714.90 35 ML 464.68 32.53 497 33505-SLE-003 REFLECTORR RR 1 42.80 35 727.82 1.95 25 77.82 1.95 25	73225-SLE-000	RUBBERWINDSHIELD DAM	1	21.30	35 MI 13.84 11	30 0.97	14.81
73227-SLE-000 MOLDINGRR.WINDSHIELD 2 17.80 35 23.14 21.62 24.73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 24.710.79 10.76 11.73278-SLE-000 MOULDINGL.RR.WINDSHIELD 1 16.60 35 24.710.79 0.76 11.76707-STK-000 SEALA 1 6.40 35 24.710.79 0.76 11.76707-STK-000 SEALA 1 6.40 35 24.710.79 0.76 11.76707-STK-000 RUBBER, W/SHIELD 1 24.20 35 24.710.73 1.10 16.710	73226-SLE-000	RUBBERWINDSHIELD DAM	1	19.00	35 Mel 12.35 12	₹0.86	13.21
73278-SLE-000 MOULDINGL RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 73278-SLE-000 MOULDINGL RR.WINDSHIELD 1 16.60 35 ML 10.79 0.76 11 76707-STK-000 SEALA 1 6.40 35 ML 4.16 0.29 4 16 16 16 16 16 16 16 16 16 16 16 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18	73228-SLE-000	MOLDINGR.RR.WINDSHIELD	1	16.60	35 ML/ 10.79	0.76	11.55
73278-SLE-000 MOULDINGLRR.WINDSHIELD 1 16.60 35 W 10.79 0.76 11 76707-STK-000 SEALA 1 6.40 35 W 4.16 0.29 4 04731-SAA-000 RUBBER, W/SHIELD 1 24.20 35 W 15.73 1.10 16 BO-WS-SEALANT WINDSCREEN SEALANT (N) 2 60.00 W 120.00 8.40 128 04715-SLE-900ZZ FACERR.BUMPER 1 714.90 35 de 464.68 32.53 497 33505-SLE-003 REFLECTORR.RR 1 42.80 35 72.82 1.95 28 71530-SFE-000ZZ BEAM RR BUMPER 1 98.70 35 W 64.15 4.49 68 71593-SLE-003 SPACERR.RR.BUMPER 1 20.20 35 W 13.13 0.92 14 71598-SLE-003 SPACERL.RR.BUMPER 1 20.20 35 W 13.13 0.92 14 71598-SLE-003 CLIP ABUMPER 2 3.90 35 W 5.07 0.35 5 66100-SLE-300ZZ PANEL COMP.RR - PW 1 470.30 35 W 305.69 21.40 327 84615-SLE-JOIZC LINING COMP.RR.SIDE 1 463.10 35 W 301.01 21.07 322	73227-SLE-000	MOLDINGRR.WINDSHIELD	2	17.80	35 WLL 23.14 7	1.62	24.76
76707-STK-000 SEALA 1 6.40 35 ML 4.16 0.29 4 04731-SAA-000 RUBBER, W/SHIELD 1 24.20 35 ML 15.73 1.10 16 BO-WS-SEALANT WINDSCREEN SEALANT (N) 2 60.00 ML 120.00 8.40 128 04715-SLE-900ZZ FACERR BUMPER 1 714.90 35 ML 464.68 32.53 497 33505-SLE-003 REFLECTORR.RR 1 42.80 35 727.82 1.95 26 71530-SFE-000ZZ BEAM RR BUMPER 1 98.70 35 M 64.15 M 4.49 68 71593-SLE-003 SPACERR RR BUMPER 1 20.20 35 ML 13.13 0.92 14 71598-SLE-003 SPACERL RR BUMPER 1 20.20 35 ML 13.13 0.92 14 91505-S9A-003 CLIP ABUMPER 2 3.90 35 ML 5.07 0.35 5 66100-SLE-300ZZ PANEL COMP RR - ρ M 60 84615-SLE-J01ZC LINING COMPR.RR SIDE 1 463.10 35 M 305.69 21.40 327	73278-SLE-000	MOULDINGL RR.WINDSHIELD	1	16.60		0.76	11.55
04731-SAA-000 RUBBER, W/SHIELD 1 24.20 35 M/m 15.73 × 1.10 16 BO-WS-SEALANT WINDSCREEN SEALANT (N) 2 60.00 MI 120.00 8.40 128 04715-SLE-900ZZ FACERR BUMPER 1 714.90 35 M/m 64.68 32.53 497 33505-SLE-003 REFLECTORR.RR 1 42.80 35 M/m 64.15 4.49 68 71530-SFE-000ZZ BEAM RR BUMPER 1 98.70 35 M/m 64.15 4.49 68 71593-SLE-003 SPACERR RR BUMPER 1 20.20 35 M/m 13.13 0.92 14 71598-SLE-003 SPACERL RR BUMPER 1 20.20 35 M/m 13.13 0.92 14 91505-S9A-003 CLIP ABUMPER 2 3.90 35 M/m 50.69 21.40 327 86100-SLE-300ZZ PANEL COMP RR - ρ I/ω 1 470.30 35 M/m 50.69 21.40 327 84615-SLE-J01ZC LINING COMPR RR SIDE 1 463.10 35 M/m 50.01 21.07 322	73278-SLE-000	MOULDINGL RR WINDSHIELD	1	16.60	35 WET + 10.79	0.76	11.55
BO-WS-SEALANT WINDSCREEN SEALANT (N) 2 60.00 120.00 8.40 128 04715-SLE-900ZZ FACERR BUMPER 1 714.90 35 64.68 32.53 497 33505-SLE-003 REFLECTORR RR 1 42.80 35 727.82 1.95 28 71530-SFE-000ZZ BEAM RR BUMPER 1 98.70 35 64.15 4.49 68 71593-SLE-003 SPACERR RR BUMPER 1 20.20 35 64.15 4.49 68 71598-SLE-003 SPACERL RR BUMPER 1 20.20 35 64.15 4.49 1470.30 35 69 21.40 327 84615-SLE-300ZZ PANEL COMP RR - PLOFO 1 470.30 35 69 21.40 327 328 328 329 330 35 69 21.40 327 328	76707-STK-000	SEALA	1	6.40	35 Mel 4.16	0.29	4.45
04715-SLE-900ZZ FACERR BUMPER 1 714.90 35 35 464.68 32.53 497 33505-SLE-003 REFLECTORR RR 1 42.80 35 727.82 1.95 28 71530-SFE-000ZZ BEAM RR BUMPER 1 98.70 35 764.15 4.49 68 71593-SLE-003 SPACERR RR BUMPER 1 20.20 35 713.13 0.92 14 71598-SLE-003 SPACERL RR BUMPER 1 20.20 35 713.13 0.92 14 91505-S9A-003 CLIP ABUMPER 2 3.90 35 75 5.07 0.35 5 66100-SLE-300ZZ PANEL COMP RR - plus fo 1 470.30 35 75 305.69 21.40 327 84615-SLE-J01ZC LINING COMPR RR SIDE 1 463.10 35 75 301.01 21.07 322	04731-SAA-000	RUBBER, W/SHIELD	1	24.20		1.10	16.83
33505-SLE-003 REFLECTORR.RR 1 42.80 35 727.82 1.95 25 71530-SFE-000ZZ BEAM RR BUMPER 1 98.70 35 764.15 4.49 68 71593-SLE-003 SPACERR.R.BUMPER 1 20.20 35 71 13.13 0.92 14 71598-SLE-003 SPACERL.R.BUMPER 1 20.20 35 71 13.13 0.92 14 91505-S9A-003 CLIP ABUMPER 2 3.90 35 71 5.07 0.35 5 66100-SLE-300ZZ PANEL COMP.RR - plus 6 1 470.30 35 71 305.69 21.40 327 84615-SLE-J01ZC LINING COMP.R.R.SIDE 1 463.10 35 71 301.01 21.07 322	BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00	ALL 120.00	8.40	128.40
71530-SFE-000ZZ BEAM RR BUMPER 1 98.70 35 764.15 4.49 68 71593-SLE-003 SPACER RR.BUMPER 1 20.20 35 71 13.13 0.92 14 71598-SLE-003 SPACER RR.BUMPER 1 20.20 35 71 13.13 0.92 14 91505-S9A-003 CLIP ABUMPER 2 3.90 35 71 5.07 0.35 5 66100-SLE-300ZZ PANEL COMP RR - plus 6 1 470.30 35 71 305.69 21.40 327 84615-SLE-J01ZC LINING COMPR.RR.SIDE 1 463.10 35 71 301.01 21.07 322	04715-SLE-900ZZ	FACERR BUMPER	1	714.90		32.53	497.21
71530-SFE-000ZZ BEAM RR BUMPER 1 98.70 35 764.15 4.49 68 71593-SLE-003 SPACER RR.BUMPER 1 20.20 35 71 13.13 0.92 14 71598-SLE-003 SPACER RR.BUMPER 1 20.20 35 71 13.13 0.92 14 91505-S9A-003 CLIP ABUMPER 2 3.90 35 71 5.07 0.35 5 66100-SLE-300ZZ PANEL COMP RR - plus 6 1 470.30 35 71 305.69 21.40 327 84615-SLE-J01ZC LINING COMPR.RR.SIDE 1 463.10 35 71 301.01 21.07 322	33505-SLE-003	REFLECTORR.RR.	1	42.80	35 27.82	1.95	29.77
71598-SLE-003 SPACERL.RR.BUMPER 1 20.20 35 WL 13.13 0.92 14 91505-S9A-003 CLIP ABUMPER 2 3.90 35 WL 5.07 0.35 5 66100-SLE-300ZZ PANEL COMP.RR - plub 6 1 470.30 35 WL 305.69 21.40 327 84615-SLE-J01ZC LINING COMPR.RR.SIDE. 1 463.10 35 WL 301.01 21.07 322	71530-SFE-000ZZ	BEAM RR BUMPER	1	98.70	35 \$1 64.15	4.49	68.64
91505-S9A-003 CLIP ABUMPER 2 3.90 35 M 5.07 0.35 5 66100-SLE-300ZZ PANEL COMP RR — PLOFO 1 470.30 35 M 305.69 21.40 327 84615-SLE-J01ZC LINING COMPR.RR.SIDE. 1 463.10 35 M 301.01 21.07 322	71593-SLE-003	SPACERR RR BUMPER	1	20.20	35 ~ 13.131	53 0.92	14.05
66100-SLE-300ZZ PANEL COMPRR - plus 5 1 470.30 35 5 305.69 21.40 327 84615-SLE-J01ZC LINING COMPR.RR.SIDE. 1 463.10 35 4 301.01 21.07 322	71598-SLE-003	SPACERL RR. BUMPER	1	20.20	35 WLI - 13.1317	0.92	14.05
84615-SLE-J01ZC LINING COMPR.RR.SIDE. 1 463.10 35 4 301.01 21.07 322	91505-S9A-003	CLIP ABUMPER	2	3.90		0.35	5.42
	66100-SLE-300ZZ	PANEL COMP RR - plus fo	1	470.30		21.40	327.09
84640-SLE-U01ZC LINING ASSYRR PANEL 1 186.30 35 de 121.09 1 121.09 1 121.09	84615-SLE-J01ZC	LINING COMPR.RR.SIDE.	1	463.10	35 4 × 301.01 ×	21.07	322.08
	84640-SLE-U01ZC	LINING ASSYRR PANEL	1	186.30		8.48	129.57
84431-SLE-J01ZA LININGTAILGATE LOWER 1 218.50 35 X 142.02 9.94 151	84431-SLE-J01ZA	LININGTAILGATE LOWER	1	218.50	35 X 142.02 X	9.94	151.96
Sum Item 3239.75 226.80 3.466					Sum Item 3239.75	226.80	3,466,55

Survey By	lentur 4+	42+44			
Date & Time	27/12/17/0	1820.			
Excess	DS'		-1		1
Status			8day	5.	
Signature	hym	Rosery	befre	periut	
Printed on 11/12/2017		يو	no luk	auto win	V.
Part prices are subjected	ted invoice. No signature is required to change without notice.	tay	him Olle	kanfocar	1.

434653416

14.7

Total Amount 11,089.75 776.30 11,866.05 LKK Auto Consultants hence notify Total find usive of GSD following: • To resurvey before lafter spray painting 1,866.05

- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed
- . Supplementary item(x) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part prices are subjected to change without notice The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	; SQT18000062 Page	7
	8 SHENTON WAY	Date	: 5. Jan 2018	
	#27-01 AXA TOWER	Customer No.	: WZA006	
	SINGAPORE 068811	Svc Advisor	1	
Registration No	; SDG1839G	Engine No	: K24Z21801867	
Chassis No	: JHMRB3850DC201592	Date Time	5. Jan 2018 10:23:33 AM	
Model	: ODYSSEY 2.4 EXV AUTO 13YM	Surveyor Name		
Owner's Name	: MCNEICE ANTHONY TERENCE	Survey Date		
Ins Policy No.	•	Authorisation Date		
Date of Accident	1		-	

Item	Description		Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:							
	OWNER INSURER:							
	ACC DATE:							
	SURVEYED BY:							
	DATE:							
	REF NO:							
	TP INSURER:							
	TP VEH:							
	SUPPLEMENTARY							
						de/		
71504-SLE-900ZF	COVERRR TOWING HOOK	UM.	1	15.90	35	10.33	0.72	11.05
		Alte			Sum Item	10.33	0.72	11.05
Survey By								
Date & Time				Tota	Amount	10.33	0.72	11.05
Excess				Total (Inclusive	e of GST)			11.05
Status								
Signature								



SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S50FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:

WZA006 / AXA INSURANCE

Chassis No:

JHMRB3850DC201592

License No:

SDG1839G

Mileage: Engine No: 55271

K24Z21801867

Document No:

SVO17080702

Printed By:

SHNG

Order Date:

27. December 2017

Order Time: Service Advisor: 7:06:49 PM

NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	mount incld GST
	TP DIRECT SETTLEMENT (J/NO:)					
	OWNER: MCNEICE ANTHONY TERENCH	E					
	OWNER INSURER: AXA INSURANCE ST	ORE PTE	LTD				
	ACC DATE:11/12/2017						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE	PTE LTD					
	TP VEH:SGV857X						
	ADDITIONAL PART						
68100-SLE-010ZZ	TAIL GATE COMP	1	1,010.30	35	656.69	45.97	702.66
74896-SLE-J51ZG	GARNISH SETTAILGATE LOWER	1	414.90	35	269.68	18.88	288.56
75701-SLE-003	EMBLEM(H)	1	28.20	35	18.33		19.61
75722-SLE-003	EMBLEM(ODYSSEY)	1	31.80	35	20.67	1.45	22.12
73225-SLE-000	RUBBERWINDSHIELD DAM	1	22.00	35	14.30	1.00	15.30
73226-SLE-000	RUBBERWINDSHIELD DAM	1	19.60	35	12.74	0.89	13.63
73228-SLE-000	MOLDINGR.RR.WINDSHIELD	1	17.10	35	11.11	1000000	11.89
73227-SLE-000	MOLDINGRR, WINDSHIELD	2	18.40	35	23,92	100000000000000000000000000000000000000	25.59
73278-SLE-000	MOULDINGL RR. WINDSHIELD	1	17.10	35	11.11		11.89
76707-STK-000	SEALA	1	6.40	35	4,16		4.45
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00	1.50	120.00	200	128.40
04715-SLE-900ZZ	FACERR.BUMPER	1	714.90	35	464.68	32.53	497.21
71530-SFE-000ZZ	BEAM RR BUMPER	1	101.70	35	66.10	1	70.73
71593-SLE-003	SPACERR.RR.BUMPER	1	20.80	35	13.52	0.95	14.47
71598-SLE-003	SPACERL.RR.BUMPER	1	20.80	35	13.52		14,47
91505-S9A-003	CLIP ABUMPER	2	3.90	35	5.07		5.42
66100-SLE-300ZZ	PANEL COMP RR	1	484.40	35	314.86	22.04	336.90
84640-SLE-U01ZC	LINING ASSYRR.PANEL	1	191.80	35	124.67	8.73	133.40
71504-SLE-900ZF	COVERRR.TOWING HOOK &	1	15.90	35	10.33	0.72	11.05
			1.500	PARTS:	2,175.46	152.29	2,327.75
BOSUN		3	30.00		30,00	2.10	32.10
	SUNDRIES					A. 10	02.10
BOJSE		1	80.00		80.00	5.60	85.60
	SEALANT FOR REAR END PANEL				00.00	5.00	00.00
BOJSE	Control of the transfer of the control of the contr	1	80.00		80.00	5.60	85.60
	SEALANT FOR TAILGATE				00.00	0.00	05.00
BA02R	ALE PROPERTY OF THE PERSON OF	1	100.00	20	80:00	5.60	85.60
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)		100.00	-	00.00	5.00	00.00
BML021	25.470	1	100.00	20	80.00	5.60	85.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)					077.50	553/150
3G02R		1	280.00	20	224.00	15.68	239.68
	REPLACE RR. WINDSCREEN (N)		200.00	20	224.00	10.00	239.00
BODAMKIT	The second secon	1	80.00		80.00	5.60	95.00
The second second	WINDSCREEN DAM KIT.		00.00		00.00	5.00	85.50



SERVICE PRE-INVOICE

GST Reg No.: M200050223 Company Ref. No.: \$60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022.

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:

WZA006 / AXA INSURANCE

Document No:

SVO17080702

Chassis No:

JHMRB3850DC201592

Printed By:

SHNG

License No:

SDG1839G

20

Order Date:

27. December 2017

Mileage:

55271

Order Time:

7:06:49 PM

Engine No:

K24Z21801867

Service Advisor:

BKTG02R

REMOVE & TRANSFER ITEMS TO NEW

450.00

NG SIN HAI

TAILGATE, ADJUST & ALIGN TAILGATE.(N)

25.20

385.20

BMI03D

REMOVE & INSTALL REAR COMPARTMENT LININGS

450.00 360.00 385.20 20 25.20

360.00

GARNISHES (N)

BKRP02M

CUT OFF & RENEW RR PANEL.

2.250.00 1,800.00 1.926.00 20 126 00

STRAIGHTEN ALIGN RR FLOOR PAN & RENEW

DAMAGE PARTS.

7,333.46

BP06R

SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)

2,100.00

20 1,680.00 117.60 1,797.60

380.00 20 304.00 21.28 325.28

BOMISC

REMOVE TRANSFER REVERSE CAMERA, CALIBRATE SETTING.

SUM LABOUR:

5,158.00 361.06 5,519.06

513.35

TOTAL SGD Total Payable (SGD)

7,846.81

7,846.81

GST Amount is calculated from individual line(s)



QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

. AXA INSURANCE S'PORE PTE LTD Customer

> 8 SHENTON WAY #27-01 AXA TOWER

SINGAPORE 068811

Registration No

: SDG1839G

Chassis No

Item

: JHMRB3850DC201592

Model

: ODYSSEY 2.4 EXV AUTO 13YM

Owner's Name

Ins Policy No. Date of Accident

: MCNEICE ANTHONY TERENCE

: 11/12/2017

Description

Document No.

Date

Qty

: SQT17005045

: 11. Dec 2017

: WZA006

Customer No. Svc Advisor

: NG SIN HAI

Engine No Date | Time : K24Z21801867 : 11. Dec 2017 7:21:38 PM

Surveyor Name

Survey Date

Authorisation Date :

GST Amt Amount

Unit Price Disc %

Amount

incld GST

Page

3

Printed on 11/12/2017 7:48:25 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)

Sent: Tuesday, 19 December, 2017 3:57 PM

To: 'Ng Sin Hai'

Cc: assignments; Admin A

Subject: Your Ref: SDG 1839G *Our Ref: CC4/AXA17023766/pb3 [ACCIDENT INVOLVING

SGV 857X(AXA) & SDG 1839G ON 11/12/2017]

Your Ref: SDG 1839G

Without Prejudice

Our Ref: CC4/AXA17023766/pb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SGV 857X(AXA) & SDG 1839G ON 11/12/2017

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SG AXA Insurance SM AXA SGP - Motor Survey

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Sent: Monday, December 11, 2017 7:56 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey

Subject: RE: 3rd party direct settlement for SDG1839G/ & your insured SGV857X

/DOA:11/12/2017/Est \$

Attachments: 1105_001.pdf

Categories: Mateen

Dear MotorClaims,

Please refer to the attached pdf, we are assisting our insured vehicle SDG1839G to file a 3rd party claim against your insured vehicle SGV857X.

Kindly assist and expedite to check the claim liability soonest and to request for direct settlement.

Thank you and have a nice day,

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad) Body Repair & Paint Centre 255 Alexandra Road Singapore 159937

DID: 6471 5419 HP: 9072 1769

Hsiao Tong (LKKAuto)

From:

Winson Chow <winsonchow@honda.com.sg>

Sent:

Monday, 30 April 2018 7:19 PM Hsiao Tong (LKKAuto); Admin A

To:

Jerome Tan; Desmond Toh

Subject:

LOD Submission of TPDS - Accident Involving SDG 1839 G and SGV 857 X on

11-12-2017

Attachments:

LOD of TPDS - Accident Involving SDG 1839 G and SGV 857 X on 11-12-2017 pdf

30 April 2018

Your ref

: CC4/AXA17023766/pb3

Our ref

: SDG 1839 G

AXA Insurance Singapore Pte Ltd C/o LKK Auto Consultant Pte Ltd 8 Shenton Way #27-01 Singapore 068811

Singapore 068811

Attn: Motor Claims Department / Chew Hsiao Tong

Dear Sir/Madam.

We herewith email you a copy of Third Party Direct Settlement documents for Accident Involving SDG 1839 G and SGV 857 X on 11-12-2017

Please kindly acknowledge and fax or email back with the name of OIC to me, I will send you the original documents by mail as well.

Your prompt replied would be much appreciated.

Thank you,

Please note that under the MCF code of practice for insurer in handling Third Party Claims, "Insurers to pay claims within 1 month from submission of full documents from repairers".

We would appreciate if you could process payment for this claim soonest possible.

Kindly contact us if you need any clarifications.

Best Regards.

Winson Chow (Mandai Bodyshop Claims Co-ordinator) Tel: +65 6514 5266 winsonchow a honda.com.sg

KAH MOTOR CO. SDN. BHD. (A member of Oriental Holdings Berhad) Body Repair & Paint Centre
 8 Mandai Estate Singapore 729905
 Tel: +65 6514 5266 Fax: +65 6365 1949



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



KAH MOTOR CO. SDN. BHD.


(A Member of Oriental Holdings Berhad)

Tel: +65 6841 3838 www.honda.com.sg

15 Ubi Road 4 Singapore 408610 Fax: +65 6748 0770 6A Mandai Estate Singapore 729903 Fax: +65 6362 5015

SATISFACTION NOTE

I / We		MC	NEICE ANT	HONY TEREN	CE	
Hereby	certified that repairs to Car	SDG1839G		have been	carried out to my/our e	entire satisfaction
and I / v	we agree that the discharge of	of the repair acco	ount from	KAH MOTO	OR CO. SDN. BHD.	
for S\$	7,846.81	by	AXA	INSURANCE :	S'PORE PTE LTD	shall be in full
dischar	ge of all claims under Policy	No.	_	in r	espect of damage to th	nis car resulting
from an	accident which occurred on	or about the	11	day of	December on	017
Date:	5/1/18			Signature:	as hin	ui





AXA INSURANCE PTE LTD

8 Shenton Way, #24-01 ,
AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel:(65)63387288 Fax:(65)63382522
Website:www.axa.com.sg
GST Registration Number: 199903512M
customer.service@axa.com.sg



1. 150

Private Cars COMP POLICY SCHEDULE RENEWAL Duplicate

POLICY INFORMATION	Policy No. : VPA/P1443265
Source	: (01) 03365 WINNER INSURANCE AGENCIES PL
Insured	: MCNEICE ANTHONY TERENCE
Address	: 12 JALAN SAMPURNA SINGAPORE 268280
Business/Profession	: PRIVATE INVESTOR
	Carrying on or engaged in the business or profession last declared and no other for the purpose of this insurance.
Period of Insurance	: From 22/11/2017 To 21/11/2018 (Both Dates Inclusive)

Period of Insurance : From 22/11/2017 To 21/11/2018 (Both Dates Inclusive)

Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.

PREMIUM

Premium After 40.00%: BGD 1,380.52

NCD

Discount (5.00%) : SGD 69.03 GST 7.00% : SGD 91.80

Annual Premium : SGD 1,403.28 Total Payable : SGD 1,403.28

RISK DETAILS THE MOTOR VEHICLE

Type Of Cover : Comprehensive

Regn No. : SDG1839G

Type Of Use : Private Car

Make/Model : HONDA ODYSSEY 2.4 EXV AUTO 13YM

Year of Manufacture : 2013 Seating Capacity (excl. Driver) : 06

Body Type : MULTI - PURPOSE VEHICLE Engine C.C. : 2354
Engine No. : K24Z21801867 Chassis No. : JHMRB3850DC201592

Insured's Estimated : Market Value At The Time Of Loss

Market Value (including Accessories and Spare Parts)

Limitations as to Use: As specified in Certificate of Insurance
Basic Own Damage Excess : SGD 600.00

Named Drivers

1 MCNEICE ANTHONY TERENCE

2 SAID BIN SORIK

JG

MEMORANDA, CLAUSES, WARRANTIES & ENDORSEMENTS

Subject to the Memoranda, Clauses, Warranties & Endorsements attached hereto:

HODA

HODA - These supplementary clauses forms part of the Schedule:

Print Sent Message

This mail is associated with:

*SDG1839G (C0462507) [SGV857X]

MCNEICE ANTHONY TERENCE Dec 11 2017 10:00AM [CHEW, YONG ALEX]

From

LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 19/06/2018 09:28 AM.

To

emest.tay@axa.com.sg

CC

AXA_SG; chewht@lkkauto.com <Seek Mandate> C0462507

Subject

Hi Ernest,

We refer to our mandate request dated 19/05/2018.

Kindly let us have your instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Claim Audit

Nai.	011	Audit	Busharius	By
1	12 Dec 2017 09:58	Clm Veh Model Changed	(204672) HONDA ODYSSEY 2.4 (A).	[1] Mateen Kadri
2	12 Dec 2017 09:58	Clm Created	Reg No: SDG1839G, Policy No: P2026133, Acct Date: 2017/12/11, Claim Type: TP. Insurer: AXA Insurance Pte Ltd (HQ). Ins.Status => Incoming Claim	[I] Mateen Kadri
3	13 Dec 2017 13:24	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[1] Flossie Ang
4	13 Dec 2017 13:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date: 2017/12/22	[I] Flossie Ang
5	13 Dec 2017 13:24	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[1] Flossie Ang
6	13 Dec 2017 13:48	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
7	13 Dec 2017 14:08	Label Added	(469):VNI_	[A] Nivitha Govindasamy
B	14 Dec 2017 16:14	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH	[A] Lau Shu Pel
9	28 Dec 2017 16:19	Label Removed	(469):VNI.	[A] Lau Shu Pei
10	28 Dec 2017 16:24	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/22	[A] Lau Shu Pei
11	08 May 2018 11:27	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
12	08 May 2018 11:27	Clm Dtl Modified	3PJ Reg. Date: -> 2013/11/22.	[A] JOANNE LEE KHANG MIN
13	08 May 2018 11:27	Clm Details Notified		[A] JOANNE LEE KHANG MIN
14	19 May 2018 09:10	Adj Mandate Request	Cur.Req:8520.90:Liability: Insured rear-ended TP. Spoken to insured, agreed to set tle and aware NCD(if any) will be affected. Quantum:(a)COR(w/GST):\$7,846.80 + (b)LOR(w/GST):\$674.10(9days x \$70.00) = Total: \$8,520.90 For your approval	[A] CHEW HSIAO TONG

ACTIVITY

[13/12/2017 14:08] Nivitha Govindasamy: Vehicle not in workshop, repairer will arrange.

Merimen Billin	erimen Billing for this case - Transaction History								
1680477	28/12/2017 16:24	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SDG1839G		10.70		



33 CHEAVE J. 002-25 PAVA URLENDENTRIAL PARK, SUNGADORE 400933, TEL: 1000/142503503, BAN: 1000/142504515

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 19.05.2018

Survey Details:

Date of loss	11.12.2017
Date of appointment	13.12.2017
Date of survey	27.12.2017
Location of survey	Kah Motor Co Sdn Bhd

Vehicle Details:

Claim Type:	Third party
Vehicle number	SDG 1839G
Make and Model	Honda Odyssey
Date of registration	22.11.2013
Excess	
Market Value	
Parf Rebate	
Nett Loss	

Repair details:

Initial Estimate	\$ 11,089.75

Proposed/Revised repair cost:

Lump Sum(if applicable)	
Total	\$ 7,333.46
Labour	\$ 5,158.00
Check items (estimate)	
Parts	\$ 2,175.46

Number of days for repair	<u>8</u>
---------------------------	----------



51 URLANE L 1912-25 PAVA URLINDUSTRIAL PARK, SINGAPORE 4000 UTEL 1003 (\$20630), PAX 1003 (\$20640).

Date: 19.05.2018

Remarks:

Mandate:

Liability(TP)	0	100%	
Proposed repair cost (w/GST)	\$	7,846.80	
Loss of use		-	
Loss of rental (w/GST)	\$	674.10	(9days x \$70.00)
Loss of income			
LTA search fees			
Others			
Proposed Total	\$	8,520.90	

Print Received Message

This mail is associated with:

*SDG1839G (C0462507) [SGV857X] MCNEICE ANTHONY TERENCE Dec 11 2017 10:00AM [CHEW, YONG ALEX]

AXA Insurance Pte Ltd (HQ) (AXA_SG); sent on 02/10/2018 11:50 AM. From

To

Alert - Adj Mandate Approved (S\$8520.90) - SDG1839G - Claim Handler: Chan Kian Chuan Subject

Approved:8520.90.



KAH MOTOR CO. SDN. BHD.

(A Member of Oriental Holdings Berhad)

Tel: +65 6841 3838 www.honda.com.sg

15 Ubi Road 4 Singapore 408610 Fax: +65 6748 0770 6A Mandai Estate Singapore 729903 Fax: +65 6362 5015

SATISFACTION NOTE

I / We	MCNEICE ANTHONY TERENCE							
Hereby o	y certified that repairs to Car SDG1839G			have been carried out to my/our entire satisfa				
and I / w	e agree that the discharge of	of the repair acco	ount from	KAH MOT	OR CO. SDN. BHD.			
for S\$	7,846.81	by	AXA	INSURANCE	S'PORE PTE LTD	shall be in full		
discharg	e of all claims under Policy	No.	_	in r	espect of damage to the	nis car resulting		
from an	accident which occurred on	or about the	11	day of	December 2	017		
	1.5				7			
Date:	5 1 18			Signature:	a.7 h.2	and .		





AXA INSURANCE PTE LTD

8 Shenton Way, #24-01

AXA Tower, Singapore 068811

Customer Service Centre #B1-01

Tel:(65)63387288 Fax:(65)63382522

Website:www.axa.com.sg

GST Registration Number: 199903512M

customer.service@axa.com.sg



Private Cars COMP POLICY SCHEDULE RENEWAL Duplicate

POLICY INFORMATION Policy No.: VPA/P1443265

Source : (01) 03365 WINNER INSURANCE AGENCIES PL

Insured : MCNEICE ANTHONY TERENCE

Address : 12 JALAN SAMPURNA

SINGAPORE 268280

Business/Profession : PRIVATE INVESTOR

Carrying on or engaged in the business or profession last declared and no other for the purpose of this

insurance.

Period of Insurance : From 22/11/2017 To 21/11/2018 (Both Dates Inclusive)

Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.

PREMIUM

Premium After 40.00%: SGD 1,380.52

NCD

Discount (5.00%)

: SGD 69.03

GST

7.00%

: SGD 91.80

Annual Premium

: SGD 1,403.28

Total Payable

: SGD 1,403.28

RISK DETAILS THE MOTOR VEHICLE

Type Of Cover

: Comprehensive

Regn No.

: SDG1839G

Type Of Use

: Private Car

Make/Model

: HONDA ODYSSEY 2.4 EXV AUTO 13YM

Year of Manufacture

: 2013

Seating Capacity (excl. Driver) : 06

Body Type

: MULTI - PURPOSE VEHICLE

Engine C.C. : 2354

Engine No.

: K24Z21801867

Chassis No. : JHMRB3850DC201592

Insured's Estimated

insured a Estim

: Market Value At The Time Of Loss

Market Value

(including Accessories and Spare Parts)

Limitations as to Use : As specified in Certificate of Insurance

Basic Own Damage Excess

: SGD 600.00

Named Drivers

- 1 MCNEICE ANTHONY TERENCE
- 2 SAID BIN SORIK

JG

MEMORANDA, CLAUSES, WARRANTIES & ENDORSEMENTS

Subject to the Memoranda, Clauses, Warranties & Endorsements attached hereto:

HODA

HODA - These supplementary clauses forms part of the Schedule:

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Thursday, 4 October 2018 11:08 AM

To:

'Winson Chow'

Cc:

Jerome Tan: Desmond Toh; Admin A

Subject:

RE: LOD Submission of TPDS - Accident Involving SDG 1839 G and SGV 857 X on

/OK.

11-12-2017

Attachments:

DV_SDG 1839G.pdf

Without Prejudice

Hi Winson,

We apologise for late response.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)

\$7,846.80

2. Loss of Rental (9days x \$70.00) (w/GST)

\$ 674.10

TOTAL \$ 8,520.90

If our offer is agreeable by your client, please duly sign the DV enclosed and return to us(LKK) for our necessary action.

Thank you.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Winson Chow <winsonchow@honda.com.sg>

Sent: Monday, 30 April 2018 7:19 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com> Cc: Jerome Tan <jerometan@honda.com.sg>; Desmond Toh <desmondtoh@honda.com.sg> Subject: LOD Submission of TPDS - Accident Involving SDG 1839 G and SGV 857 X on 11-12-2017

30 April 2018

Your ref

: CC4/AXA17023766/pb3

Our ref

: SDG 1839 G

AXA Insurance Singapore Pte Ltd C/o LKK Auto Consultant Pte Ltd 8 Shenton Way #27-01



Kah Motor Co. Sdn. Bhd.

A Member of Oriental Heidings (forthers)

Mandal Body Repair & Paint Centre

B Mandal Estate

Singapore 729905

Tat: +65 6841 3838

Fax: +65 6365 1949

www.honda.com.sg 26 October 2018

LKK Auto Consultants Pte Ltd

Blk 51, Ubi Avenue 1 #02-25, Paya Ubi Industrial Park Singapore 408933

Attn: Motor Claims Dept

Dear Sir / Madam.

ACCIDENT INVOLVING SDG 1839 G and SGV 857 X on 17-12-2017

We herewith enclosed the original discharge voucher duly signed by our client for your necessary action.

Kindly let us have your cheque payment of S\$ 7,846.80 (nett) in favour of KAH MOTOR CO. SDN. BHD. and S\$ 674.10 (nett) in favour MCNEICE ANTHONY TERENCE within one month.

Your prompt settlement would be much appreciated.

Thank you.

Best Regards, Winson Chow (Mandai Bodyshop Claims Co-ordinator) Tel: +65 6514 5266 winsonchow@honda.com.sg

KAH MOTOR CO. SDN. BHD. (A member of Oriental Holdings Berhad) Body Repair & Paint Centre 8 Mandai Estate Singapore 729905 Tel: +65 6514 5266 Fax: +65 6365 1949 11



Kah Motor Co. Sdn. Bhd.

14 Member of Oriental Holdings Berhald.

Body Repair & Paint Centre

6A Mandal Estate

Singapore 729903

Tel: +65 8841 3838

Fax: +65 6362 5015

www.honds.com.sg

NG SIN HAI

M/s: AXA Insurance Singapore Pte Ltd 26/4/2018 Date C/o LKK Auto Consultants Pte Ltd 8 Shenton Way #27-01 AXA Tower Singapore 068811 Attn: Motor Claims Department Your ref : SGV857X Our ref : SDG1839G Dear Sir / Madam. THIRD PARTY DIRECT SETTLEMENT ACCIDENT INVOLVING SDG1839G AND SGV857X ON 11.12.2017 We refer to the item(s) marked (✓) below: (✓) We refer to your email dated 19.12.2017) Kindly forward the discharge voucher for our client's signature within 2 weeks via email to jerometan@honda.com.sg (✓) We return your discharge voucher duly completed. Kindly expedite settlement the following :-(4) Repair Cost SS 7,846.81 payable to Kah Motor Co. Sdn. Bhd. Loss of Use SS 674.10 payable to Mcneice Anthony Terence Third Party Insurer Search NIL LTA Search NIL Kindly let us have your cheque made in favour of the above mentioned name(s) for our (4) transmission as soon as possible. (✓) Letter of Authority, Tax Invoice, Rental Bill Thank you. Yours faithfully,



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

20 DECEMBER 2017

CHEW YONG ALEX BLK 299C COMPASSVALE ST #04-124 SINGAPORE 543299

Dear Sir/ Mdm

OUR REF : CC4/AXA17023766/pb3 YOUR REF : P2026133 (SGV 857X)

ACCIDENT INVOLVING SGV 857X & SDG 1839G ALONG/AT CTE ON 11/12/2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Kah Motor Co Sdn Bhd, acting on behalf of the owner of SDG 1839G against your motor insurance policy.

Based on the accident report and accident scenario, we are of the opinion that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 10 days from the date of this letter if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- · Driver's driving license or foreign driving license (if any)
- · Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- · Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you
 are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

Chew Hsiao Tong

Case Handler DID: 6742 3197

FAX: 6741 4108

EMAIL: chewht@lkkauto.com

Cc AXA Insurance Pte Ltd (Motor Claims Dept)

LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

ACCIDENT INVOLVING (OW	NER'S VEHICLE NO	SDG	18	30	7 G	86
(THIRD PARTY'S VEHICLE NO.)	SGV 857X	on	11	12	IT	
ALONG CTE Towards	City.					

I hereby authorize Kah Motor Co. Sdn Bhd (Kah Motor) and its agents or any person authorized by Kah Motor to do all or any of the following:

- To submit, resolve and make any claim(s) which I may have against the 3rd party insurers.
- To execute, sign discharge voucher/indemnity forms and all necessary documents in connection with and arising out of the above claim.
- Any payment should be made in favour of my name / Kah Motor Co. Sdn. Bhd.

Co sta				l signat	ure if	is Co	register	ed vehicle
Name	: M	cnei	ce	Anth	ory	Tere	nce	
NRIC	No:	S11	92	190 F				
Vehicle	e No	. 9	De	7183	99			
Date	:	5/1	11	t	20			





CLAIM REF

: C0462507

INSURED

: CHEW YONG ALEX

DISCHARGE VOUCHER

We/I, MCNEICE ANTHONY TERENCE, NRIC NO. S1192190F hereby agree to accept the sum of dollars EIGHT THOUSAND FIVE HUNDRED TWENTY AND CENTS NINETY ONLY (\$\$8,520.90) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SGV 857X as a result of an accident along CTE TOWARDS CITY on 11/12/2017 which we/I were/was the driver/ owner/ hirer/passenger/rider/pillion/ insurer of motor vehicle no. SDG 1839G.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. <u>SGV 857X</u> in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. **SGV 857X.**

Dated this	26	day of October	20/8
Claimant's Signature		a. I. In nei	
NRIC no./ Company Stamp	:_51	192190 F	
Occupation/ Business	:		
Address			
Telephone No.	-		
Witness's Name	:_W	linson Chow	
Witness's Signature	:	V:V	2
Witness's NRIC No.	:	(A STREET	

AXA Insurance Pte Ltd (Company Reg. No. 199903512M) 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 Customer Centre #B1-01

Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg



Mandai Parts Centre

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Kah Motor Co. Sdn. Bhd.

Phone No.: +65 6841 3838 Fax No.:

AXA INSURANCE S'PORE PTE LTD

(A Member of Oriental Holdings Berhad) 6A Mundai Estate, 729903 SINGAPORE

Service Tax Invoice

GST Reg No. M200050223

SHNG

Company Ref. No. S60FC1380G

SINV-BM18000242

Invoice Date 15/03/18 Order No. SVO17080702

Reference

Invoice No.

Job Card No. 08931

Date/Time Received 11/12/17 / 7:21:38 PM Licence No. SDG1839G **ODYSSEY 2.4 EXV AUTO** Model JHMRB3850DC201592 Car Chassis No.

: Car Engine No. K24Z21801867 Mileage 55271 Service Advisor NG SIN HAI 1596

Served By

Customer No. : WZA006

		Р	age	:			1.
N-	Departmen	Ot		II Disable N		7% GST Amo	
No.	TP DIRECT SETTLEMENT (J/NO:	Qty.	LloM	U. PriceDisc %	Amount	Amount	GST
	OWNER: MCNEICE ANTHONY TERENC	E					
	OWNER INSURER: AXA INSURANCE ST		TD				
	ACC DATE:11/12/2017	NATIONAL PARTY					
	SURVEYED BY:						
	DATE:						

		OWNER:MCNEICE ANTHONY TERENCE OWNER INSURER:AXA INSURANCE S'PORE P ACC DATE:11/12/2017 SURVEYED BY: DATE:	TEL	.TD					
		REF NO: TP INSURER:AXA INSURANCE S'PORE PTE LT	D						
		TP VEH:SGV857X							
BOSUN	0701	SUNDRIES	1	Hours	30.00		30.00	2.10	32.10
BOJSE	0701	SEALANT FOR REAR END PANEL	1	Hours	80.00		80.00	5.60	85.60
BOJSE	0701	SEALANT FOR TAILGATE	1	Hours	80.00		80.00	5.60	85.60
BA02R	0701	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	Hours	100.00	20	80.00	5.60	85.60
BML02I	0701	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	Hours	100.00	20	80.00	5.60	85.60
BG02R	0701	REPLACE RR. WINDSCREEN (N)	1	Hours	280.00	20	224.00	15.68	239.68
BODAMKIT	0701	WINDSCREEN DAM KIT.	1	Hours	80.00		80.00	5.60	85.60
BKTG02R	0701	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST & ALIGN TAILGATE.(N)	1	Hours	450.00	20	360.00	25.20	385.20
BMI03D	0701	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	Hours	450.00	20	360,00	25.20	385.20
BKRP02M	0701	CUT OFF & RENEW RR PANEL, STRAIGHTEN	1	Hours	2,250.00	20	1,800.00	126.00	1,926.00
		ALIGN RR FLOOR PAN & RENEW DAMAGE PAI	RTS	20					
BP06R	0701	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	Hours	2,100.00	20	1,680.00	117.60	1,797.60
BOMISC	0701	REMOVE TRANSFER REVERSE CAMERA, CALIBRATE SETTING.	1	Hours	380.00	20	304.00	21.28	325.28
68100-SLE-010ZZ		TAIL GATE COMP	1	Each	1,010.30	35	656.69	45.97	702.66
74896-SLE-J51ZG		GARNISH SETTAILGATE LOWER	1	Each	414.90	35	269.68	18.88	288.56
75701-SLE-003		EMBLEM(H)	1	Each	28.20	35	18.33	1.28	19.61
75722-SLE-003		EMBLEM(ODYSSEY)	1	Each	31.80	35	20.67	1.45	22.12
73225-SLE-000		RUBBERWINDSHIELD DAM	1	Each	22.00	35	14.30	1.00	15.30
73226-SLE-000		RUBBERWINDSHIELD DAM	1	Each	19.60	35	12.74	0.89	13.63
73228-SLE-000		MOLDINGR.RR.WINDSHIELD	1	Each	17.10	35	11.11	0.78	11.89
73227-SLE-000		MOLDINGRR.WINDSHIELD	2	Each	18.40	35	23.92	1.67	25.59
73278-SLE-000		MOULDINGL.RR.WINDSHIELD	1	Each	17.10	35	11.11	0.78	11.89
76707-STK-000		SEALA	1	Each	6.40	35	4.16	0.29	4.45

Printed by SHNG on 15 Mar 2018 at 53634 PM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge smitted GST Amount is calculated from individual line(x)

Please give us your feedback by scanning the GR Code using mobile device





Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

6A Mandai Estate, 729903 SINGAPORE Mandai Parts Centre

Phone No.: +65 6841 3838 Fax No.:

AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY #27-01 AXA TOWER

SINGAPORE, 068811

Customer No. :

WZA006

Service Tax Invoice

GST Rep No. M200050223

7% GST Amount incld

Company Ref. No. S60FC1380G

SINV-BM18000242 Invoice No. : Invoice Date 15/03/18 :

SVO17080702 Order No.

Reference

Served By

08931 Job Card No. 11/12/17 / 7:21:38 PM

Date/Time Received Licence No. SDG1839G ODYSSEY 2.4 EXV AUTO Model

JHMRB3850DC201592 Car Chassis No. : K24Z21801867 Car Engine No. :

55271 Mileage Service Advisor NG SIN HAI 1596 SHNG

2 Page :

U. PriceDisc % Qty. **UoM** Amount Amount GST Description No. WINDSCREEN SEALANT (N) 60.00 120.00 8.40 128.40 BO-WS-SEALANT Each 497.21 714.90 35 464.68 32.53 FACERR BUMPER Each 04715-SLE-900ZZ 4.63 70.73 101.70 35 66.10 BEAM RR BUMPER Each 71530-SFE-000ZZ 35 13.52 0.95 14.47 SPACERR RR BUMPER Each 20.80 71593-SLE-003 13.52 0.95 14.47 SPACERL RR. BUMPER Each 20.80 35 71598-SLE-003 5.07 0.35 5.42 2 Each 3.90 35 91505-S9A-003 CLIP ABUMPER 470.30 33 314.86 22.04 336.90 Each 66100-SLE-300ZZ PANEL COMP RR 1 133.40 191.80 124.67 8.73 35 84640-SLE-U01ZC LINING ASSYRR PANEL 1 Each ADDITIONAL PART 10.33 0.72 11.05 35 71504-SLE-900ZF COVERRR.TOWING HOOK 1 Each 15.90

> 361.06 5,158.00 5,519.06 Sum Labor 152.29 2,327.75 Sum Item 2,175.46

> > Total SGD

Total Payable (SGD) 7,846.81

7,333.46

513.35

7,846.81





229236

SINGAPORE

Rental & Leasing Department

370 Ubi Road 3 Singapore 408651 Tel: +65 6513 0645 | Fax: +65 6841 2611 | www.honda.com.sg GST Reg. No.: M200050223 Company Reg. No.: 560FC1880G

Tax Invoice

Invoice No. Invoice Date : CRINV/18/00010 : 08 Jan 2018

Customer No.

: *****190F

Ref

Currency Terms

: SGD

: COD RA No. : 03845

Customer Information

20 HANDY ROAD #11-01

MCNEICE ANTHONY TERENCE

Customer Name : MCNEICE ANTHONY TERENCE

Customer Ref No. : SDG1839G (SH)

Car Information

Registration No. : SJZ2634C Car Model

: CRV 2.0L 5AT

Car Color : GREY

Rental Information

Date/Time Out

: 27/12/2017 12:00 Date/Time Return : 05/01/2018 13:00

Starting Mileage : 76766 Ending Mileage : 77198 Mileage Travelled: 432

Billing Detail

#	Description	Amt
1	9 DAYS @ 70.00	630.00

Remarks:

LK/BS - SA: NG SIN HAI

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms. Interest will be charged at 2% per month on overdue amounts.

Printed by Ng Sin Hai at 21/04/2018 13:34

Subtotal: 5\$ 630.00 GST 7.0%: 5\$ 44.10 Total: 5\$ 674.10

Paid: 5\$ 674.10 5\$ 0.00 Outstanding:



Rental & Leasing Department 370 Ubi Road 3 Singapore 408651 Tel: +65 6513 0645 | Fax: +65 6841 2611 | www.honda.com.ag GST Reg. No.: M200050223 Company Reg. No.: 560FC1380G

RENTAL AGREEMENT

No. 03845

Date: 27 Dec 2017

			Dec 2017
VEHICLE PARTICULA	R	PAYMENT	AMOUNT
Vehicle No.	: SJZ2634C	Day: 1 days x 70.00	70.00
Make	: HONDA	Week	0.00
Model	: CRV 2.0L 5AT	Month \$74.90 X 9 days	0.00
Out (Date & Time)	: 27 Dec 2017 1200	Add HRS	0.00
In (Date & Time)	: 5 1 18 1300 ms.	SUB TOTAL 1 171 16	70.00
HIRER PARTICULAR		GST = \$ 674.10	4.90
Name	: MCNEICE ANTHONY TERENCE	NETT AMOUNT	74.90
Address (Res)	: 20 HANDY ROAD #11-01	SECURITY DEPOSIT	0.00
Commisses Williams	229236 SINGAPORE	REMARKS	
Tel	: 65198927	SDG1839G CLAIM THIRD PARTY AXA	
Name on Credit Card	:	SDUIDSO CEAN THIND TART TARA	
Credit Card No.	Ĭ	TERMS & CONDITIONS	
Payment Mode	: Cash	Malaysia Drive Surcharge Annual description 200 CCT	
MAIN DRIVER PARTIC	CULAR	 Normal days \$20/day + 7% GST Blackout dates, Eve of PH & PH \$40/day + 7% GST 	
Name	: SAID BIN SORIK	 Insurance Excess 5'pore Drive Excess - \$1500 + 7% GST 	
Address (Res)	:	0 Malaysia Drive Excess - \$2500 + 7% GST (Excluding	ng towing &
Driving License No.	: S0126374I	 vehicle is rented to hirer upon terms and conditions on the fi 	ront and back of
Passing Date	: 07/10/1997	this agreement.	Between whenever
Date of Birth	: 12/10/1954	 Vehicle is to be driven only by hirer and any additional hirer Hirer is responsible for all parking, fines and ERP charges. 	isted soove.
NRIC/FIN/Passport No	: S0126374I	Hirer must report all accidents to Kah Motor within 24 hours.	
ADDITIONAL DRIVER	PARTICULAR	 Violation of the terms of this agreement makes the hirer respond to the vehicle whether insurance is accepted. 	
Name	:	 Vehicle is strictly for Singapore use, unless covered by insurause. 	ance for Malaysia
Address (Res)	:	Return of rental car beyond the stated duration will incur the	following
Driving License No.	:	1. Less than or equal to 5 hours, a 0.5 day charge will ap	niv
Passing Date	1	2. More than 5 hours, a FULL DAY charge will apply	P I I
Date of Birth		 Unpaid rental bookings will not be confirmed, and will subset released after 10 mins. 	quently be
NRIC/FIN/Passport Ne	ELE	Rental Deposit	
Je	0 5 JAN 2018, POSB Chique 475 294	 A rental deposit will be collected upon confirmation of re Rental deposit & rental fees will be forfeited if cancellatioooking is made less than 7 working days from intended rental. 	on of rental
F	3Y: 10xD O.	Rental deposit will be refunded after the end of the rent.	
	475294	 Refund process will take approx 2-3 weeks via respective used at point of initial payment. 	e payment mode

I have read and agree to the terms and conditions on both sides of this agreement.

I authorize Kah Motor Co. Sdn. Bhd. to process a credit card voucher if any for charges under this agreement including any miscellaneous charges.

All information i have given Kah Motor Co. Sdn. Bhd. in connection with this agreement is true.

Hirer's Signature

Main Driver's Signature (if not hirer) Credit Card Holder's Signature (if not hirer)

**Kindly top up the petrol before you return us the rental car.

Otherwise, there will be charges added to your final hill. **

Rented out by

Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report) Direct Settlement

Case	Notified	Est Submitted	(Ad) Assigned	Adj Rpt		Adj Submitted	Ins Auth'ed	Status	
Main	12 Dec 2017		13 Dec 2017 13:24 Edit Adj Rpt	S\$7,333. Edit Estir		\$\$7,333.46 View Rpt		Pending Report Cancel C	for Survey
	Main	R	eference	CI	im Deta	ils	Docume	nts	Show All
CLAIM SU	BFOLDER DE	TAILS				[Created	by insurer]		
Insured:	CHEW, YO	ONG ALEX, ID: 9	7813099G, Tel:	+6593259320	, Email	ALEXNCAROU	NE@HOTMAIL.C	OM	
Main Claimant:		ANTHONY TERE	NCE, ID: S11921	90F					
Vehicle Reg No.:	SDG183	SDG1839G					17 10:00 - :59 hs and 19 Days	From LTA Reg Da	te (Man Yr)]
Claim Type:	TP / C04	TP / C0462507			Policy/Co Note No.		(Comprehensiv	e)	
Vehicle Reg No. (Insured):	SGV857X				Policy No Claiman		VPA/P1443265		
				The second second	Excess:	5\$0.00			
Repairer	Kah Moto	r Co Sdn Bhd (H	Q) 64 MANDAI EST	ATE, SINGAP	ORE 7299	903, 729903 Ma	indai - Tel:		
Handling Insurer:	AXA Insu	rance Pte Ltd (H	Q) - Tel: 6338 728	8 [Handled	by Char	n Kian Chuan -	6880 4269]		
Claimant's Insurer:	AXA Insu	rance Pte Ltd (H	Q) - Tel: 6338 728	8					
Adjuster:	22/12/20		Ltd (HQ) - Tel: 62	56-3561 [Handled	by MOHD TAU	FIKH BIN HAM	ID] [Final R	pt due
Driver/Custo dian (Insured):		NG ALEX (39 / Ma	le), NRIC: S7813	099G, Tel:	+659325	9320			
ASSOCIAT	ED MAIL RE	CEIVED						View All Comp	ose Case Mail
			date Approved (S ment - C0462507		SDG18	39G - Claim Ha	andler: Chan K	ian C	
ALL ASSO	CIATED TAS	ks⊟				View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type Task	Group Subject	t Handle	r As	signed By	Completed O	n Created	On Done

Merimen e-Claims Page 1 of 1

Claim Documents

*SDG1839G (C0462507)
[SGV857X]
TP
MCNEICE ANTHONY TERENCE
Dec 11 2017 10:00AM
[CHEW, YONG ALEX]
Kah Motor Co Sdn Bhd

nt	oload Documents U	pload Photos Compose New Letter Upload Video Upload Audio	Alew	View in Brown	ser v
Let	ters/Corresponder	nces	1 per	page 💟	V
Νo	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	
Ass	essment Reports		1 per	page V	7
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/12/17 16:24	Adjuster Immediate Advice	0	Load HTM	
Doc	umentation		1 per	page 🔍	V
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 10:03	EMAIL_ABS	0	Load POF	
2	12/12/17 10:03	ESTIMATE & GIA REPORT_ABS	0	Load PDF	
3	12/12/17 10:03	GIA REPORT OF SDG1839G (TP)_ABS	0	Load POF	
4	12/12/17 10:03	GIA REPORT OF SGV857X (INSD)_ABS	0	Load POF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/12/17 16:59	TP ESTIMATE- MARKED	0	Load PDF	
2	08/05/18 11:37	RENTAL RECEIPT	0	Load PDF	
3	08/05/18 11:37	LETTER TO OI	0	Load PDF	
4	19/05/18 09:00	LKK Survey Photos	0	Load PDF	
5	19/05/18 09:00	LKK Resurvey Photos	Ð	Load PDF	
6	19/05/18 09:08	Immediate Advice(with mandate) dd 190518	0	Load PDF	
7	05/11/18 14:00	WORKSHOP INVOICE	0	Load PDF	
8	05/11/18 14:00	AUTHORISATION TO ACT FORM	0	Load PDF	
9	05/11/18 14:00	DISCHARGE VOUCHER	0	Load PDF	
10	05/11/18 14:00	LOD	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEABL		
LEAN		

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGV857X (Insd veh)	SGV857X (Insd veh)		HONDA ODYSSEY 2.4 (A	()
	SDG1839G (TP veh)				
Date of Accident	11/12/2017				
					_
Global Sum Settle	ment : [] Yes		[X] No]	
Repair Estimate		: 5	11,897.34]	
Final Repair Cost		: \$	7,846.80		
Loss of Use		: \$		days at \$0.00 per day	y
Rental (if any)		: 5	674.10	9 days	
LTA / GIA Search	Fee	: \$	0.00		
Others:		: \$	0.00		
		: \$			
Final Settlement S	Sum	: \$	8,520.90		
below)	orkshop GIA Registered		•070. •1 05791 1	[] NO (Kindly indicate	E
A) For Non GIA	Registered Workshop:			(%)	
B) For GIA Regi	stered Workshop:		27	le: Yes/ No- BOLA Scenario No	12
BOLA Liability	/:100(%)		Assessed Liabil	lity (*):(%)	
* Assessed Li	iability to be filled only for	r chain	collisions and for c	ases where BOLA does not app	ly.
Remarks					
Payment Instruct	tion: Payee's Breakdow	'n			
1) Kah Motor C	o.Sdn.Bhd.		: \$	8,52	20.90
2)			: \$		
JOANNE	LEE KHANG MIN		05 Nov 2018		
LKK Auto	Consultants Pte Ltd		Date		

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607 198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AXA17023766/T1PB3Q2

Date:

05/11/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P2026133

Claimant Vehicle

SDG1839G

Insured Vehicle No:

SGV857X

No: Date of Loss:

11/12/2017

Nature of Claim:

TP

Claim No:

C0462507

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SDG1839G

Make & Model:

HONDA ODYSSEY, 2.4 (A)

Engine No:

K24Z21801867

Reg. Date: Colour

22/11/2013 (Man. Year: 2013)

Chassis No: Odometer:

JHMRB3850DC201592 56053 km

Engine Capacity:

2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

215/55 R17

Rear Tyre Size:

215/55 R17

Front Tyre Size: Front Left Side:

Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side:

Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,319.01	2,205.46	1,113.55	33.55
Miscellaneous Items		0.00	0.00	0.00	
Labour		7,800.00	5,128.00	2,672.00	34.26
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	11,119.01	7,333.46	3,785.55	34.05
	+ GST 7.00/7.00% (S\$)	778.33	513.34	264.99	34.05
	Nett Amount (S\$)	11,897.34	7,846.80	4,050.54	34.05
	+ Car Rental (9.0 x S\$70.00/day	+ 7.00% GST) (S\$)	674.10		
			A A		

INSPECTION

Date of Assignment:

13/12/2017

Date Inspected:

27/12/2017

Inspected At:

8,520.90

Estimated Period of Repair:

8.0 days

MOHD TAUFIKH BIN HAMID Adjuster:

Nett Liability (S\$)

Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4 NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded. https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 5/11/2018

Adjuster Report Page 3 of 4

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 May 2018)

Parts: M1-MPV HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDG1839G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES (CONSISTENT)	Necessary	50.00 FS	*30.00 FS
2	4		*BUMPER SENSOR (CONSISTENT)	Not Necessary	180.00 FS	*-FS
3	1		*LAMP UNITR (CONSISTENT)	Not Necessary	127.20 FS	*-FS
4	1		*LIGHT ASSYRLID (CONSISTENT)	Not Necessary	127.20 FS	*-FS
5	1		*TAILGATE COMP (CONSISTENT)	Bent	656.69 FS	*656.69 FS
6	1		*LOCKTAILGATE (CONSISTENT)	Not Necessary	118.10FS	*-FS
7	1		'GARNISHTAILGATE LOWER (CONSISTENT)	Deformed	313.36 FS	*269.68 FS
8	1		*EMBLEM (H)(CONSISTENT)	Necessary	18.33 FS	*18.33 FS
9	1		*EMBLEM (ODYSSEY) (CONSISTENT)	Necessary	20.67 FS	*20.67 FS
10	1		*RUBBERWINDSHIELD DAM (CONSISTENT)	Necessary	14.30 FS	*14.30 FS
11	1		*RUBBERWINDSHIELD DAM (CONSISTENT)	Necessary	12.74 FS	*12.74 FS
12	1		*MOLDING.RR.WINDSHIELD (CONSISTENT)	Necessary	11.11 FS	*11.11 FS
13	2		*MOLDINGRR.WINDSHIELD (CONSISTENT)	Necessary	23.92 FS	*23.92 FS
14	1		*MOULDINGL.RR.WINDSHIELD (CONSISTENT)	Necessary	11.11 FS	*11.11 FS
15	1		*MOULDINGL.RR.WINDSHIELD (CONSISTENT)	Not Necessary	10.79 FS	*-FS
16	1		*SEALA (CONSISTENT)	Necessary	4.16 FS	*4.16FS
17	1		*RUBBER ,W/SHIELD (CONSISTENT)	Not Necessary	15.73 FS	*-FS
18	2		*WINDSCREEN SEALANT (CONSISTENT)	Necessary	120.00 FS	*120.00 FS
19	1		*FACERR.BUMPER (CONSISTENT)	Deformed	464.68 FS	*464.68 FS
20	1		*REFLECTORR .RR (CONSISTENT)	Not Necessary	27.82 FS	*-FS
21	1		*BEAM RR BUMPER (CONSISTENT)	Bent	66.10 FS	*66.10FS
22	1		*SPACERR.RR.BUMPER (CONSISTENT)	Necessary	13.52 FS	*13.52FS
23	1		*SPACERL.RR.BUMPER (CONSISTENT)	Necessary	13.52 FS	*13.52 FS
24	1		*CLIP ABUMPER (CONSISTENT) (2 PCS)	Necessary	5.07 FS	*5.07FS
25	1		*PANEL COMP RR (CONSISTENT)	Bent	314.86 FS	*314.86FS
26	1		*LINING COMPR.RR.SIDE (CONSISTENT)	Not Necessary	301.01 FS	*-FS
27	1		*LINING ASSYRR.PANEL (CONSISTENT)	Deformed	124.67 FS	*124.67 FS
28	1		*LININGTAILGATE LOWER (CONSISTENT)	Not Necessary	142.02 FS	*-FS
29	1		*COVERRR.TOWING HOOK (CONSISTENT)	Deformed	10.33 FS	*10.33FS
F=Fra	nchise	part. S=Spcf	Nett	Total Parts (S\$)	3,319,01	2,205,46
				Total Parts (53)	3,313.01	2,200,40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	SEALANT FOR REAR END PANEL	New	80.00	80.00
2	SEALANT FOR TAILGATE	New	80.00	80.00
3	REMOVE & RENEW REVERSE SENSORS	New	100.00	80.00
4	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER	New	100.00	80.00
5	REPLACE RR.WINDSCREEN	New	280.00	224.00
6	WINDSCREEN DAM KIT	New	80.00	80.00
7	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	450.00	360.00
3	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	360.00
9	CUT OFF & RENEW RR PANEL .STRAIGHTEN	New	3,000.00	1,800.00
10	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,800.00	1,680.00
11	REMOVE TRANSFER REVERSE CAMERA ,CALIBRATE SETTING	New	380.00	304.00
	Gross Labou	r Cost (S\$)	7,800.00	5,128.00

< END OF ESTIMATES >