

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	: SQT17005045	Page	1
	8 SHENTON WAY	Date	: 11. Dec 2017		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: NG SIN HAI		
Registration No	: SDG1839G	Engine No	: K24Z21801867		
Chassis No	: JHMRB3850DC201592	Date Time	: 11. Dec 2017 7:21:38 PM		
Model	: ODYSSEY 2.4 EXV AUTO 13YM	Surveyor Name	:		
Owner's Name	: MCNEICE ANTHONY TERENCE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 11/12/2017				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:MCNEICE ANTHONY TERENCE						
	OWNER INSURER:AXA INSURANCE S'PORE PTE LTD						
	ACC DATE:11/12/2017						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:AXA INSURANCE S'PORE PTE LTD						
	TP VEH:SGV857X						
BOSUN	SUNDRIES	1	50.00		30. 50.00	3.50	53.50
BOJSE	SEALANT FOR REAR END PANEL	1	80.00		✓ 80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00		✓ 80.00	5.60	85.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	100.00		✓ 100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		✓ 100.00	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	280.00		✓ 280.00	19.60	299.60
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00		✓ 80.00	5.60	85.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		✓ 450.00	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		✓ 450.00	31.50	481.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN 450.	1	3000.00		2250. 3000.00	210.00	3210.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2800.00		2100. 2800.00	196.00	2996.00
BOMISC	REMOVE TRANSFER REVERSE CAMERA, CALIBRATE SETTING.	1	380.00		✓ 380.00	26.60	406.60
					Sum Labor	7850.00	549.50
							8,399.50
RS-4P	BUMPER SENSOR 4PCS	1	180.00		? 180.00	12.60	192.60
33501-SLE-003	LAMP UNITR.	1	195.70	35	? 127.20	8.90	136.10
34150-SLE-003	LIGHT ASSYR.LID	1	195.70	35	? 127.20	8.90	136.10
68100-SLE-305ZZ	TAILGATE COMP	1	1010.30	35	bt ✓ 656.69	45.97	702.66

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SDG1839G

Chassis No : JHMRB3850DC201592

Model : ODYSSEY 2.4 EXV AUTO 13YM

Owner's Name : MCNEICE ANTHONY TERENCE

Ins Policy No. :

Date of Accident : 11/12/2017

Document No. : SQT17005045

Date : 11. Dec 2017

Customer No. : WZA006

Svc Advisor : NG SIN HAI

Engine No : K24Z21801867

Date | Time : 11. Dec 2017 7:21:38 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
74800-TF0-J01	LOCKTAILGATE	1	181.70	35	118.10	8.27	126.37
74890-SLE-013ZC	GARNISHTAILGATE LOWER	1	482.10	35	313.36	21.94	335.30
75701-SLE-003	EMBLEM(H)	1	27.30	35	17.74	1.24	18.98
75722-SLE-003	EMBLEM(ODYSSEY)	1	30.90	35	20.08	1.41	21.49
73225-SLE-000	RUBBERWINDSHIELD DAM	1	21.30	35	13.84	0.97	14.81
73226-SLE-000	RUBBERWINDSHIELD DAM	1	19.00	35	12.35	0.86	13.21
73228-SLE-000	MOLDINGR.RR.WINDSHIELD	1	16.60	35	10.79	0.76	11.55
73227-SLE-000	MOLDINGRR.WINDSHIELD	2	17.80	35	23.14	1.62	24.76
73278-SLE-000	MOULDINGL.RR.WINDSHIELD	1	16.60	35	10.79	0.76	11.55
73278-SLE-000	MOULDINGL.RR.WINDSHIELD	1	16.60	35	10.79	0.76	11.55
76707-STK-000	SEALA	1	6.40	35	4.16	0.29	4.45
04731-SAA-000	RUBBER, W/SHIELD	1	24.20	35	15.73	1.10	16.83
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
04715-SLE-900ZZ	FACERR.BUMPER	1	714.90	35	464.68	32.53	497.21
33505-SLE-003	REFLECTORR.RR.	1	42.80	35	27.82	1.95	29.77
71530-SFE-000ZZ	BEAM RR BUMPER	1	98.70	35	64.15	4.49	68.64
71593-SLE-003	SPACERR.RR.BUMPER	1	20.20	35	13.13	0.92	14.05
71598-SLE-003	SPACERL.RR.BUMPER	1	20.20	35	13.13	0.92	14.05
91505-S9A-003	CLIP ABUMPER	2	3.90	35	5.07	0.35	5.42
66100-SLE-300ZZ	PANEL COMP RR - photo	1	470.30	35	305.69	21.40	327.09
84615-SLE-J01ZC	LINING COMPR.RR.SIDE.	1	463.10	35	301.01	21.07	322.08
84640-SLE-U01ZC	LINING ASSYRR.PANEL	1	186.30	35	121.09	8.48	129.57
84431-SLE-J01ZA	LININGTAILGATE LOWER	1	218.50	35	142.02	9.94	151.96
Sum Item					3239.75	226.80	3,466.55

Survey By

Date & Time

Excess

Status

Signature

Printed on 11/12/2017 7:48:25 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Total Amount 11,089.75 776.30 11,866.05

Total (Inclusive of GST) 11,866.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97493449

27/12/17 @ 1820

DS

8 days

Resurvey before paint

sur@lkkauto.com
taufik@lkkauto.com



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer	: AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT17005045	Page	3
Registration No	: SDG1839G	Date	: 11. Dec 2017	Customer No.	: WZA006
Chassis No	: JHMRB3850DC201592	Svc Advisor	: NG SIN HAI	Engine No	: K24Z21801867
Model	: ODYSSEY 2.4 EXV AUTO 13YM	Date Time	: 11. Dec 2017 7:21:38 PM	Surveyor Name	:
Owner's Name	: MCNEICE ANTHONY TERENCE	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 11/12/2017				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incl GST
------	-------------	-----	------------	--------	--------	------------	--------------------

Printed on 11/12/2017 7:48:25 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)