



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Arvind Verma ADDRESS : Blk 260b Sengkang East Way #08-442 Singapore 542260 TEL : 98525824		WIP : 50389 EXCESS : DATE: 12-Dec-17	
VEH NO :	SLH438L	DATE IN :		CONTACT PERSON :	RONALD 6395 7875
CHASSIS NO :	JM6GJ1072G0242283	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6 2.0L	DATE REG.:	21-Oct-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MGJR9-50-221ABB	dl ✓	\$ 1,172.80
2	RETAINER(LHS), REAR BUMPER	1	MGJR9-50-2J1	nei ✓	\$ 39.00
3	RETAINER(RHS), REAR BUMPER	1	MGJR9-50-2H1	X	\$ 39.00
4	BRACKET CENTER, REAR BUMPER	1	MKD53-50-251	?	\$ 5.10
5	REFLECTOR LHS	1	MD350-51-5L0E	?	\$ 50.40
6	REFLECTOR RHS	1	MD350-51-5M0E	X	\$ 50.40
7	COVER(LHS), TOWING	1	MG4YL-50-EL1 E4	mis ✓	\$ 23.70
8	COVER(RHS), TOWING	1	MG4YL-50-EK1 E4	X	\$ 22.00
9	REAR REINFORCEMENT	1	MGHK1-50-260	?	\$ 512.60
10	FASTENER, REAR BUMPER	6	MB45A-56-146A	nei ✓	\$ 16.80
11	GROMMET, REAR BUMPER	6	MH260-50-841	nei ✓	\$ 16.80
12	GROMMET, REAR BUMPER	1	M9991-00-501	nei ✓	\$ 2.80
13	CLIP, REAR BUMPER	4	MC274-50-133	nei ✓	\$ 14.00
14	PANEL, REAR END	1	MGHY1-70-75Z	?	\$ 666.70
15	BOOT LID	1	MGJY0-52-61X	bt ✓	\$ 1,061.90
16	HINGE(LHS), BOOT LID	1	MGMD9-52-720	Ry	\$ 208.80
17	HINGE(RHS), BOOT LID	1	MGMD9-52-710	Ry	\$ 208.80
18	WEATHERSTRIP, BOOT LID	1	MGHK1-56-951A	X	\$ 129.10
19	GASKET(LHS), TAILLAMP	1	MGJA1-51-163	nei ✓	\$ 26.30
20	GASKET(RHS), TAILLAMP	1	MGJA1-51-153	nei ✓	\$ 26.30
21	LHS TAILLAMP	1	MGJA1-51-160B	?	\$ 1,516.40
22	RHS TAILLAMP	1	MGJA1-51-150B	X	\$ 1,516.40
23	FASTENER, TAILLAMP	2	MKD53-51-146B	?	\$ 7.80
24	FASTENER, TAILLAMP	2	MGHP9-51-146	?	\$ 6.60
25	GROMMET, TAILLAMP	2	MGJ6A-51-14Y	?	\$ 29.80
26	GASKET(LHS), BOOT LID LAMP	1	MG45F-51-3J8	nei ✓	\$ 50.00
27	GASKET(RHS), BOOT LID LAMP	1	MG45F-51-3H8	nei ✓	\$ 50.00
28	LHS BOOT LID LAMP	1	MG45F-51-3G0B	?	\$ 732.10
29	RHS BOOT LID LAMP	1	MG45F-51-3F0B	X	\$ 732.10
30	GROMMET, BOOT LID LAMP	2	MGA7B-51-146	?	\$ 6.20

31	MAZDA, EMBLEM	1	MGHK1-51-711	net ✓	\$ 27.50
32	6, EMBLEM	1	MGHK1-51-721	net ✓	\$ 15.70
33	MASCOT, REAR	1	MGHK1-51-730	net ✓	\$ 46.80
34	SKYACTIV, EMBLEM	1	MGHK1-51-771	net ✓	\$ 71.10
35	SILENCER, EXHAUST	1	MPE23-40-100B	X	\$ 1,745.70
36	GASKET, SILENCER	1	MPE23-40-305	X	\$ 24.10
37	CONVERTER, EXHAUST	1	MPE78-20-55XB	X	\$ 1,865.30
38	GASKET, CONVERTER	1	MPE23-40-305	X	\$ 24.10
39	TRIM, BOOT END	1	MGHK1-68-89XA	X	\$ 116.40
TOTAL PARTS					\$ 12,877.40
LESS 10%					\$ 1,287.74
TOTAL PARTS COST					\$ 11,589.66

Labour Description

1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1575	\$ 3,780.00
2	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	1500	\$ 3,000.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	X	\$ 350.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	315	\$ 630.00
6	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	315	\$ 630.00
7	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	315	\$ 630.00
8	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NETT X	\$ 70.00
9	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY.	X	\$ 1,260.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
12	MZ-BR-SUNDRI	SUNDRIES.	30 NETT	\$ 100.00

Tanphuk 97495749
-wp-
19/12/17 @ 3pm.
Resurvey before paint
sure@lkkauto.com.
6-7 days

TOTAL LABOUR	\$ -	\$ 11,300.00
TOTAL PARTS	\$ -	\$ 11,589.66
TOTAL	\$ -	\$ 22,889.66
LESS EXCESS	\$ -	\$ -

TOTAL AFTER EXCESS	\$	-	
GST 7%	\$	-	\$ -
GRAND TOTAL	\$	-	\$ -

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: