

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

116

Name : Syed Abdillah Bin Said Ali

Accident Date : 18-Nov-17

Vehicle No : FBM 4138 T

Vehicle Model : Piaggio Vespa

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 160.00
1	Front fork assy	\$ 780.00?
1	Front shock absorber	\$ 310.00 ?
1	Front fork chrome cover	\$ 48.00?
1	Front fork side cover	\$ 119.00
1	Front brake disc	\$ 150.00
1	Front sport rim	\$ 280.00
1	Front cowling top	\$ 328.00
1	Front cowling moulding	\$ 95.00
1	Front cowling inner panel	\$ 387.00
1	Headlamp	\$ 370.00
1	Headlamp chrome moulding	\$ 120.00
1	Front signal -L/H	\$ 75.00
1	Side mirror -L/H	\$ 85.00
1	Handle bar	\$ 320.00
1	Hand grip (1 set)	\$ 40.00
1	Clutch lever	\$ 18.00
1	Lower belly panel	\$ 198.00
1	Rider footstep panel	\$ 550.00
1	Rider footstep rear cover	\$ 45.00
1	Step board rubber	\$ 70.00
1	Rear footrest garnish	\$ 68.00
1	Main stand	\$ 135.00
1	Engine mounting bracket	\$ 380.00
1	Air filter tube assy	\$ 120.00
1	Seat lower panel	\$ 480.00
1	Transmission chrome logo cover	\$ 48.00
1	Transmission side cover housing	\$ 375.00
1	Clutch side outer cover	\$ 375.00
		\$ 6,529.00
	Less 10%	\$ 652.90
		\$ 5,876.10

Not Allowed
H/S
7 days
14/12/17
to be paid. After 14/12

11

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Syed Abdillah Bin Said Ali

Accident Date : 18-Nov-17

Vehicle No : FBM 4138 T

Vehicle Model : Piaggio Vespa

Estimated Repair Costs

<u>Special Nett Items</u>		
1	Number plate (1 set)	\$ <i>net</i> 28.00 <i>10</i>
1	Steering cone (1 set)	\$ 120.00 <i>?</i>
1	"VESPA" emblem	\$ <i>net</i> 48.00 <i>✓</i>
1	Rear box	\$ <i>cur</i> 650.00 <i>450</i>
1	Rear box bracket	\$ <i>n</i> 280.00 <i>x</i>
1	Clutch outer cover gasket	\$ <i>net</i> 22.00 <i>✓</i>
1	Engine mounting bush	\$ 75.00 <i>?</i>
		<u>\$ 1,223.00</u>

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service.	\$ <i>35</i> 45.00
2	To check wiring and reset headlamp focusing.	\$ <i>n</i> 80.00 <i>x</i>
3	To provide labour.	\$ <i>300</i> 380.00
4	To respray painting.	\$ <i>600</i> 800.00
5	To repair body frame.	\$ <i>300</i> 350.00
		<u>\$ 1,655.00</u>

Grand Total

\$ 8,754.10

Dollars: Eight Thousand Seven Thousand Fifty-Four And Ten Cents Only.



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: