

Growth

Tougher

REF: MSIG

ASSIGNMENT

From: _____ Date: 18/12/17

Estimated Cost: _____

☒ TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No: SKT 6452 D

at Workshop m/s Hitachi Capital
of No. 8 Fourth Lokyang Rd, 629705

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: \$750.00
(Client's Record)

Make of Veh: _____

Early Morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$76K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKT 6452D Yr Regn: 2015 June

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jun35 CC 1498

Colour: Black A/C Insured / Std / NI / NA

Sp. Reading: 45898 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3H MGK 5850 FX 203/18

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R16

R: 24

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A.

Survey held at: Hitachi Capital 18/12/17 11:55

Des. of Damages: Frt / Rear ☒ O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/8/18 @ 10:29am 3rd revert to Jocelyn Ng via Messenger. (Supplementary)

31/8/18 @ 1:41pm Kenny Ong informed C/A at \$5337.30 via Messenger.

Final sig \$5337.30 (Red \$3915.90, 42%)

RECEIVED 1 AUG 2018

30/8/2018

Data/Time: File Pass to?

☐ : Prelim. Report☐ : Final Report

Data/Time: File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee

Transportation

B-P-C

Photo

Notes

Add Fee:

☐ Site Insp \$☐ Interview \$☐ Tech Insp \$☐ Weekend \$

Report Format: MET-00

Lump Sum / I.B.I: \$5337.30

200

10

210

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 31 Aug 2018

Preliminary Advice

Vehicle No	: SKT6452D	Accident Date	: 11/12/2017
Make	: HONDA JAZZ	Policy No.	: MSD/VPCP/17-001409-00
Assignment Date	: 14/12/2017	Excess	: S\$750.00
Date of Inspection	: 18/12/2017	Est. Duration of Repair	: 10.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,253.20	(ESTIMATE \$9,222.40 + SUPPLEMENTARY 2 \$30.80)
Revised Amount	:S\$	5,337.30	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	5,337.30	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	76,000.00
COE / PARF Rebate	:S\$	53,383.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,617.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Dec 2017 10:23	Cim Veh Model Changed	(204273) HONDA JAZZ 1.5 VTIR CVT (A).	[I] Jocelyn Ng Shin Bun
2	13 Dec 2017 10:23	Cim Created	Reg No: SKT6452D. Policy No: MSD/VPCP/17-001409-00. Acct Date: 2017/12/11. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status = > Notification. Created from SAS:MIT117163529	[I] Jocelyn Ng Shin Bun
3	13 Dec 2017 16:56	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[I] Grant Chong Kean Yap
4	13 Dec 2017 17:09	Cim Submitted	9084.90.	[R] Grant Chong Kean Yap
5	14 Dec 2017 10:19	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):a if c	[I] Keny Ong Thiam Beng
6	14 Dec 2017 10:19	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/15	[I] Keny Ong Thiam Beng
7	14 Dec 2017 10:19	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Keny Ong Thiam Beng
8	14 Dec 2017 14:07	Assignment 1st Accessed		[A] Pauline Soh Li Ping
9	14 Dec 2017 14:45	Adj Assignment Cancelled	IHS unable to attend (ET & DC-Appt full, AL-Paperwork)	[I] Jocelyn Ng Shin Bun
10	14 Dec 2017 14:45	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Jocelyn Ng Shin Bun
11	14 Dec 2017 14:49	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert, thank you. Car in, Grant request to survey today.	[I] Jocelyn Ng Shin Bun
12	14 Dec 2017 14:49	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/15	[I] Jocelyn Ng Shin Bun
13	14 Dec 2017 14:49	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
14	14 Dec 2017 15:19	Assignment 1st Accessed		[A] Nivitha Govindasamy
15	14 Dec 2017 17:08	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH	[A] Nivitha Govindasamy
16	18 Dec 2017 17:00	Adj Rpt Initiated		[A] SHIAU CHAN
17	18 Dec 2017 17:06	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/13	[A] SHIAU CHAN
18	18 Dec 2017 17:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/13	[A] SHIAU CHAN
19	18 Dec 2017 17:07	Adj Mandate Request	Cur.Reg:5997.30:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. PENDING F OR SOME PARTS PRICES. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	19 Dec 2017 09:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/13. Mandate Remarks: a if c	[I] Keny Ong Thiam Beng
21	19 Dec 2017 09:44	Adj Mandate Set	Approved:5658.50:a if c	[I] Keny Ong Thiam Beng
22	21 Mar 2018 21:23	Cim Supp Created (S:693762)		[R] Grant Chong Kean Yap
23	21 Mar 2018 21:26	Cim Submitted (S:693762)	137.50.	[R] Grant Chong Kean Yap
24	21 Mar 2018 21:26	Adj Co Assigned (S:693762)	LKK Auto Consultants Pte Ltd (HQ):	[I] Merimen Administrator
25	22 Mar 2018 16:05	Supp Combined (S:693762)		[A] SHIAU CHAN
26	30 Aug 2018 10:38	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/13	[A] SHIAU CHAN
27	30 Aug 2018 10:38	Adj Mandate Request	Cur.Reg:5306.50:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. KINDLY APP ROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
28	30 Aug 2018 14:23	Cim Supp Created (S:738399)		[R] JAMILAH BEGUM BINTE MOHD KASSIM
29	30 Aug 2018 14:24	Cim Submitted (S:738399)	30.80.	[R] JAMILAH BEGUM BINTE MOHD KASSIM
30	30 Aug 2018 14:24	Adj Co Assigned (S:738399)	LKK Auto Consultants Pte Ltd (HQ):	[I] Merimen Administrator
31	31 Aug 2018 09:39	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/13. Mandate Remarks: a if c	[I] Keny Ong Thiam Beng
32	31 Aug 2018 09:39	Adj Mandate Set	Approved:5306.50:a if c	[I] Keny Ong Thiam Beng
33	31 Aug 2018 10:11	Supp Combined (S:738399)		[A] SHIAU CHAN

Date From



Date To



Audit Type None

Go

ACTIVITY

[14/12/2017 14:40] Pauline Soh Li Ping:

Car in, Grant request to survey today. IHS unable to attend (ET & DC-Appt full, AL-Paperwork)

[14/12/2017 14:39] Pauline Soh Li Ping:

No one pick call

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1667339	13/12/2017 16:56	Motor	Hitachi Capital Asia Pacific Pte. Ltd	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	SKT6452D		xx.xx
1671848	18/12/2017 17:00	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKT6452D		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 30 Aug 2018

Preliminary Advice

Vehicle No	: SKT6452D	Accident Date	: 11/12/2017
Make	: HONDA JAZZ	Policy No.	: MSD/VPCP/17-001409-00
Assignment Date	: 14/12/2017	Excess	: S\$750.00
Date of Inspection	: 18/12/2017	Est. Duration of Repair	: 10.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,222.40	(ESTIMATE \$9,084.90 + SUPPLEMENTARY \$137.50)
Revised Amount	:S\$	5,306.50	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	5,306.50	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	76,000.00
COE / PARF Rebate	:S\$	53,383.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,617.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 19 December, 2017 2:14 PM
To: KeanYap, Chong
Cc: SUR
Subject: VEHICLE SKT 6452D (DOA: 11/12/2017)

Dear Grant,

As instructed by our client MSIG insurance, please proceed to repair the insured vehicle SKT **6452D (Excess \$750)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Dec 2017 10:23	Cim Veh Model Changed	(204273) HONDA JAZZ 1.5 VTIR CVT (A).	[I] Jocelyn Ng Shin Bun
2	13 Dec 2017 10:23	Cim Created	Reg No: SKT6452D. Policy No: MSD/VPCP/17-001409-00. Acct Date: 2017/12/11. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS: MJT117163529	[I] Jocelyn Ng Shin Bun
3	13 Dec 2017 16:56	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] Grant Chong
4	13 Dec 2017 17:09	Cim Submitted	9084.90.	[R] Grant Chong
5	14 Dec 2017 10:19	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):a if c	[I] Keny Ong Thiam Beng
6	14 Dec 2017 10:19	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/15	[I] Keny Ong Thiam Beng
7	14 Dec 2017 10:19	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Keny Ong Thiam Beng
8	14 Dec 2017 14:07	Assignment 1st Accessed		[A] Pauline Soh Li Ping
9	14 Dec 2017 14:45	Adj Assignment Cancelled	IHS unable to attend (ET & DC-Appt full, AL-Paperwork)	[I] Jocelyn Ng Shin Bun
10	14 Dec 2017 14:45	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Jocelyn Ng Shin Bun
11	14 Dec 2017 14:49	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert, thank you. Car in, Grant request to survey today.	[I] Jocelyn Ng Shin Bun
12	14 Dec 2017 14:49	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/15	[I] Jocelyn Ng Shin Bun
13	14 Dec 2017 14:49	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
14	14 Dec 2017 15:19	Assignment 1st Accessed		[A] Nivitha Govindasamy
15	14 Dec 2017 17:08	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH	[A] Nivitha Govindasamy
16	18 Dec 2017 17:00	Adj Rpt Initiated		[A] SHIAU CHAN
17	18 Dec 2017 17:06	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/13	[A] SHIAU CHAN
18	18 Dec 2017 17:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/13	[A] SHIAU CHAN
19	18 Dec 2017 17:07	Adj Mandate Request	Cur.Reg:5997.30:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. PENDING FOR SOME PARTS PRICES. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	19 Dec 2017 09:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/13. Mandate Remarks: a if c	[I] Keny Ong Thiam Beng
21	19 Dec 2017 09:44	Adj Mandate Set	Approved:5658.50:a if c	[I] Keny Ong Thiam Beng

ACTIVITY

[14/12/2017 14:40] Pauline Soh Li Ping:
Car in, Grant request to survey today. IHS unable to attend (ET & DC-Appt full, AL-Paperwork)
[14/12/2017 14:39] Pauline Soh Li Ping:
No one pick call

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1667339	13/12/2017 16:56	Motor	Hitachi Capital Asia Pacific Pte. Ltd	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	SKT6452D		xx.xx
1671848	18/12/2017 17:00	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKT6452D		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:189607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 18 Dec 2017

Preliminary Advice

Vehicle No	: SKT6452D	Accident Date	: 11/12/2017
Make	: HONDA JAZZ	Policy No.	: MSD/VPCP/17-001409-00
Assignment Date	: 14/12/2017	Excess	: S\$750.00
Date of Inspection	: 18/12/2017	Est. Duration of Repair	: 10.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,084.90
Revised Amount	:S\$	5,658.50
Check Items (Estimated)	:S\$	338.80
Total	:S\$	5,997.30
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	76,000.00
COE / PARF Rebate	:S\$	53,383.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,617.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
PENDING FOR SOME PARTS PRICES.
WE HAVE NOT AUTHORISE REPAIR.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0399N
Vehicle Details	
Vehicle No.:	SKT6452D
Vehicle to be Exported:	No
Intended De-registration Date:	18 Dec 2017
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15B31000522
Chassis No.:	JHMGK5850FX203118
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$15,189.00
Original Registration Date:	18 Jun 2015
First Registration Date:	18 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$5,189.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jun 2025
PARF Rebate Amount:	\$3,891.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,000.00
COE Rebate Amount:	\$49,492.00
Total Rebate Amount:	\$53,383.00

The information contained herein is correct as at 18 Dec 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2017 16:03
Date Of Accident	11/12/2017 19:40
Exact Location Of Accident	CAR PARK @ LIANG COURT BASEMENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT6452D
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64663022

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.5 VTIR CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	MSD/VPCP/17-001409-00
Cover Note Number	

Driver

Name of Driver	YOSHIYUKI ENDO
NRIC No	S2592174G
Date Of Birth	03/10/1958
Occupation	OUTDOOR
Date Of Driving Pass	05/12/1990
Driving Experience	27 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - LESSEE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? NO
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I, SKT6452D was driving from gubale to basenest capot.

There was a yellow porche drive with fast speed.

I try to avoid collision and my car swerved to right side. Accidentally hit the wall on my right side.

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

HITACHI
 Inspire the Next

 INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MSD/VPCP/17-001409-00	Date of Loss:	11/12/2017
Vehicle Reg. No.:	SKT6452D	Driveable?	
Driver Age/Info:	59 / MALE	Party At Fault:	UNKNOWN
TP Injury	NO	Third Party	NO
Involved?		Involved?	
Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD			
Driver:	YOSHIYUKI ENDO		
Make/Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Vehicle Reg. Date:	18/06/2015
Vehicle Colour:	BLACK	Chassis No:	JHMGK5850FX203118
Engine No:	L15B31000522		
Odometer:	30000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

Tauphin 774 55749

Ex 9750

Revert

15/12/17 @ 1155

10 days.

Resurvey before paint

20/12/17

COST OF CLAIMS

	Amount
Parts	3,034.90
Miscellaneous Items	0.00
Labour	6,050.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	9,084.90
- Excess (S\$)	750.00
(S\$)	8,334.90
+ GST 7.00% (S\$)	583.44
Nett Amount (S\$)	8,918.34

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

 This claim is handled by: **GRANT CHONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Dec 2017)

Parts: 144 HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKT6452D/13/12/2017 17:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Driver door	0.00	0.00	*520.00 F At
2	1		*Driver door sticker set	0.00	0.00	*30.00 F At
3	2		*Driver door hinge top and bottom	0.00	0.00	*56.00 F Ry
4	1		*Driver door checker	0.00	0.00	*30.00 F Ry
5	1		*Driver door handle	0.00	0.00	*200.00 F At
6	1		*Driver door handle knob	0.00	0.00	- Ry
7	1		*Driver door key retainer base	0.00	0.00	- Ry
8	1		*Driver door lock	0.00	0.00	*160.00 F ? Ry
9	1		*Rear door RH	0.00	0.00	*500.00 F bt
10	1		*Rear door sticker set RH	0.00	0.00	*30.00 F At
11	2		*Rear door hinge top and bottom RH	0.00	0.00	*60.00 F ? bt
12	1		*Rear door checker RH	0.00	0.00	*30.00 F ? Ry
13	3		*Rear door weatherstripe RH	0.00	0.00	*75.00 F Ry
14	1		*Rear fender RH	0.00	0.00	*400.00 F bt
15	1		*Rear fender shield RH	0.00	0.00	*38.00 F ? Ry
16	10		*Rear fender shield clips RH	0.00	0.00	*20.00 F ? Ry
17	1		*Rear bumper	0.00	0.00	*180.00 F Ry
18	1		*Door Center Pillar RH	0.00	0.00	-
			Repair and respray			
19	1		*Rocker panel RH	0.00	0.00	*150.00 F Ry
20	1		*Rocker panel garnish (side skirt) RH	0.00	0.00	*280.00 F de

F=Franchise part.

Sub Total (S\$)	2,759.00
+ Margin on L,N Items 10.00% (S\$)	275.90
Total Parts (S\$)	3,034.90

Hitachi Capital Asia Pacific Pte. Ltd/SKT6452D/13/12/2017 17:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New 1400	2,000.00
2	Putty, blend and paint affected area	New 1400	2,000.00
3	Check Wiring and ensure proper function	New 30	100.00
4	Remove & reinstall bumper sensors	New 30	120.00
5	Cavity Treatment to apply sealant on New Parts (Front and rear door, fender and rocker panel)	New 100	250.00
6	Conduct four wheel alignment / side slip test	New 80	150.00
7	Transfer front and rear door lock & mechanism to new door	New 120	300.00
8	Conduct water seepage test	New 40	80.00
9	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New 100	200.00
10	Diagnostic Check & Reset	New 120	250.00
11	Remove Upholstery Trim and Cushion	New m x	350.00
12	Panel beat and spray paint Door center pillar	New included in labor 1st row	250.00
Gross Labour Cost (S\$)			6,050.00

Hitachi Capital Asia Pacific Pte. Ltd./SKT6452D/13/12/2017 17:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6486 3022 Fax: (65) 6896 6591

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Mar 2018)

Parts: 144 HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKT6452D/21/03/2018 21:26

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear door sub seal RH rear	0.00	0.00	*25.00 F
2	1		*Rear door sub seal RH Front	0.00	0.00	*25.00 F
3	1		*Rear door lower seal (R&L)	0.00	0.00	*25.00 F
4	1		*Front door sub seal RH	0.00	0.00	*25.00 F
5	1		*Front door lower seal (R&L)	0.00	0.00	*25.00 F

F=Franchise part.

Sub Total (S\$) 125.00

+ Margin on L,N Items 10.00% (S\$) 12.50

Total Parts (S\$) 137.50

Hitachi Capital Asia Pacific Pte. Ltd/SKT6452D/21/03/2018 21:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

(SUPPLEMENTARY)

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MSD/VPCP/17-001409-00	Date of Loss:	11/12/2017
Vehicle Reg. No.:	SKT6452D	Driveable?	
Driver Age/Info:	59 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD		
Driver:	YOSHIYUKI ENDO		
Make/Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Vehicle Reg. Date:	18/06/2015
Vehicle Colour:	BLACK		
Engine No:	L15B31000522	Chassis No:	JHMGK5850FX203118
Odometer:	30000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

COST OF CLAIMS	Amount
Parts	30.80
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	30.80
+ GST 7.00% (S\$)	2.16
Nett Amount (S\$)	32.96
+ Previous Estimates (S\$)	9,065.47
Claim Total (S\$)	9,098.43

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2018)**Parts:** 144 HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Hitachi Capital Asia Pacific Pte. Ltd/SKT6452D/30/08/2018 14:24**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*DR Cyl. Garnish	0.00	0.00	*28.00 F
F=Franchise part.						
Sub Total (S\$)						28.00
+ Margin on L,N Items 10.00% (S\$)						2.80
Total Parts (S\$)						30.80

Hitachi Capital Asia Pacific Pte. Ltd/SKT6452D/30/08/2018 14:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Hitachi Capital Asia Pacific Pte. Ltd./SKT6452D/30/08/2018 14:24. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

 **Hitachi Capital Asia Pacific Pte. Ltd. (Main Office)** Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835

www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

HITACHI
 Inspire the Next

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MSD/VPCP/17-001409-00	Date of Loss:	11/12/2017
Vehicle Reg. No.:	SKT6452D	Driveable?	
Driver Age/Info:	59 / MALE	Party At Fault:	UNKNOWN
TP Injury	NO	Third Party	NO
Involved?		Involved?	
Insured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD			
Driver:	YOSHIYUKI ENDO		
Make/Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Vehicle Reg. Date:	18/06/2015
Vehicle Colour:	BLACK	Chassis No:	JHMGK5850FX203118
Engine No:	L15B31000522		
Odometer:	30000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

Tampin 774 55749

Ex 9750

Revent.

18/12/17 @ 1155

10 days.

Reserving before paint

COST OF CLAIMS

	Amount
Parts	3,034.90
Miscellaneous Items	0.00
Labour	6,050.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	9,084.90
- Excess (S\$)	750.00
(S\$)	8,334.90
+ GST 7.00% (S\$)	583.44
Nett Amount (S\$)	8,918.34

This claim is handled by: GRANT CHONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Dec 2017)

Parts: 144 HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKT6452D/13/12/2017 17:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Driver door	0.00	0.00	✓ *520.00 F <i>At</i>
2	1		*Driver door sticker set	0.00	0.00	✓ *30.00 F <i>At</i>
3	2		*Driver door hinge top and bottom	0.00	0.00	X *56.00 F <i>Ry</i>
4	1		*Driver door checker	0.00	0.00	X *30.00 F <i>Ry</i>
5	1		*Driver door handle	0.00	0.00	✓ 200.00 F <i>At</i>
6	1		*Driver door handle knob	0.00	0.00	- ?
7	1		*Driver door key retainer base	0.00	0.00	- ?
8	1		*Driver door lock	0.00	0.00	X *160.00 F ?
9	1		*Rear door RH	0.00	0.00	✓ *500.00 F <i>btw</i>
10	1		*Rear door sticker set RH	0.00	0.00	✓ *30.00 F <i>At</i>
11	2		*Rear door hinge top and bottom RH	→ 0.00	0.00	✓ *60.00 F ? \$30
12	1		*Rear door checker RH	0.00	0.00	X *30.00 F ?
13	3		*Rear door weatherstripe RH (refer supplementary)	0.00	0.00	X *75.00 F <i>new</i> X
14	1		*Rear fender RH (repair)	← 0.00	0.00	X *400.00 F <i>btw</i> X
15	1		*Rear fender shield RH	0.00	0.00	X *38.00 F ?
16	10		*Rear fender shield clips RH	0.00	0.00	X *20.00 F ?
17	1		*Rear bumper	0.00	0.00	X *180.00 F <i>Ry</i>
18	1		*Door Center Pillar RH	0.00	0.00	-
			Repair and respray			
19	1		*Rocker panel RH	0.00	0.00	X *150.00 F <i>Ry</i>
20	1		*Rocker panel garnish (side skirt) RH	0.00	0.00	✓ *280.00 F <i>de</i>

F=Franchise part.

Sub Total (S\$) 2,759.00
 + Margin on L,N Items 10.00% (S\$) 275.90
 Total Parts (S\$) 3,034.90

Hitachi Capital Asia Pacific Pte. Ltd/SKT6452D/13/12/2017 17:09. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Emo Qiang
Resum y

Supplementary \$ 125 + 10% = \$ 137.50 29/12/17

parts \$ 1590 + 10% = \$ 1749

labour \$ 3420

* Total P/P \$ 5306.50 @ 10 day \$

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New 1400	2,000.00
2	Putty, blend and paint affected area	New 1400	2,000.00
3	Check Wiring and ensure proper function	New 30	100.00
4	Remove & reinstall bumper sensors	New 30	120.00
5	Cavity Treatment to apply sealant on New Parts (Front and rear door, fender and rocker panel)	New 100	250.00
6	Conduct four wheel alignment / side slip test	New 80	150.00
7	Transfer front and rear door lock & mechanism to new door	New 120	300.00
8	Conduct water seepage test	New 40	80.00
9	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New 100	200.00
10	Diagnostic Check & Reset	New 120	250.00
11	Remove Upholstery Trim and Cushion	New X	350.00
12	Panel beat and spray paint Door center pillar	New included X	250.00
			<i>in labour 1st row</i>
Gross Labour Cost (S\$)			6,050.00

Hitachi Capital Asia Pacific Pte. Ltd./SKT6452D/13/12/2017 17:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

GRANT

NO: HL19056367

PAGE: 1

DATE: 18/12/2017

A/C CODE: LDHC008

TERMS: CR

P/O NO: SKT 6452 D

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
1	H67010-T5A-306ZZ	FR.DOOR RH(J10ZZ)	HU3017-7	1	520.00	520.00
2	H67324-T5A-003	FR.DR.TAPE RH	H2K13	1	30.00	30.00
3	H72140-T5A-J01ZG	FR.DR.OUT.HANDLE RH	H2D3	1	200.00	200.00
4	H67510-T5A-N10ZZ	RR.DOOR RH	HU3-89	1	500.00	500.00
5	H67825-T5A-003	RR.DR.TAPE RH	H2K13	1	30.00	30.00
6	H67920-SWA-003ZZ	RR.DR.HINGE LO.RH(H11ZZ)	H1D3	1	30.00	30.00
7	H72824-T5A-003	RR.DR.SUB SEAL RH,RR	H2A4	1	25.00	25.00
8	H72825-T5A-013	RR.DR.SUB SEAL RH,FR(003)	H3A9-2	1	25.00	25.00
9	H72826-T5A-003	RR.DR.LOWER SEAL(R&L)	H2A4	1	25.00	25.00
10	H71800-T5B-003ZE	SIDE SKIRT ASSY RH	HDS	1	280.00	280.00
TOTAL QUANTITY:			10	TOTAL	SIN 1,665.00	
				ADD GST @ 7%	116.55	
				GRAND TOTAL	SIN 1,781.55	

Q/R 103874
71 TECK

Print / MCNK / 18/12/2017 3:01:43 PM

SALESMAN: MCNK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



GOODS RECEIVED BY



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

GRANT

NO: HLI9056427

PAGE: 1

DATE: 26/12/2017


A/C CODE: LDHC008

TERMS: CR

P/O NO: SKT 6452 D

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 H72324-T5A-003	FR.DR.SUB SEAL RH	H3A9-1	1	25.00	25.00
2 H72326-T5A-003	FR.DR.LOWER SEAL(R&L)	H3A9-1	1	25.00	25.00
TOTAL QUANTITY:			2	TOTAL	SIN 50.00
				ADD GST @ 7%	3.50
				GRAND TOTAL	SIN 53.50

O/R 103874
AH TECK



Print / MCNK / 26/12/2017 2:41:18 PM

SALESMAN: MCNK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E & O E

GOODS RECEIVED BY

Grant Ben



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717
Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE.LTD
8 FOURTH LOK YANG ROAD
SINGAPORE 629705
GRANT

NO: HLI9056631
PAGE: 1
DATE: 16/01/2018
A/C CODE: LDHC008
TERMS: CR
P/O NO: SKT 6452 D

Part No	Description	Location	Qty	Unit Price	Amount
1	H72146-T5A-003ZE	DR.CYL.GARNISH	1	SIN 28.00	SIN 28.00
TOTAL QUANTITY:			1	TOTAL	SIN 28.00
				ADD GST @ 7%	1.96
				GRAND TOTAL	SIN 29.96

O/R 103874
AH TECK

Reprint: 1 / MCNK / 16/01/2018 10:38:42 AM

SALESMAN: MCNK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E.&O.E.

GOODS RECEIVED BY

Grant Ben

16/01/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017 Sendback Est	13 Dec 2017 17:09 S\$9,084.90	14 Dec 2017 14:49 Edit Adj Rpt	S\$5,337.30 Edit Estimates	S\$5,337.30 View Rpt		Pending for Survey Report Cancel Case
Supp #1	21 Mar 2018 21:23	21 Mar 2018 21:26 S\$137.50	21 Mar 2018 21:26			(Combined)	Combined with Main Uncombine Suppl.
Supp #2	30 Aug 2018 14:23	30 Aug 2018 14:24 S\$30.80	30 Aug 2018 14:24			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: HITACHI CAPITAL ASIA PACIFIC PTE LTD , Co. Reg. No.: 199400399N									
Vehicle Reg. No.: SKT6452D		Date of Loss: 11/12/2017 19:00 - :59 [29 Months and 23 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / MSC/V/17-001920		Policy/Cover Note No.: MSD/VPCP/17-001409-00 (Comprehensive) Coverage: 18/06/2017 - 17/06/2018							
		Excess: S\$750.00							
Repairster: Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/01/2018]									
Driver/Custodian: YOSHIYUKI ENDO (59 / Male), NRIC: S2592174G									
Adj Asg. Remarks: Please revert, thank you. Car in, Grant request to survey today.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (31/08/2018): Alert - Adj Mandate Approved (S\$5337.30) - SKT6452D - Claim Handler: Jocelyn Ng ... - MSIG_SG (31/08/2018): Alert - Adj Mandate Approved (S\$5306.50) - SKT6452D - Claim Handler: Jocelyn Ng ... - MSIG_SG (13/06/2018): Please upload final survey report. Thank you. - MSIG_SG (19/12/2017): Alert - Adj Mandate Approved (S\$5658.50) - SKT6452D - Claim Handler: Jocelyn Ng ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKT6452D (MSC/V/17-001920)
 OD
 Dec 11 2017 7:00PM
 [HITACHI CAPITAL ASIA PACIFIC PTE LTD]
 Hitachi Capital Asia Pacific Pte. Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	12/12/17 17:13	Accident Statement	 Load HTM	☐
2	13/12/17 17:09	Repairer Estimates	 Load HTM	☐
3	21/03/18 21:26	Repairer Estimates Suppl. #1	 Load HTM	☐
4	30/08/18 14:24	Repairer Estimates Suppl. #2	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 17:06	Adjuster Immediate Advice	 Load HTM	☐
2	30/08/18 10:38	Adjuster Immediate Advice	 Load HTM	☐
3	31/08/18 10:29	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/08/18 10:33	General View	 Load JPG	☒
2	30/08/18 10:33	General View	 Load JPG	☒
3	30/08/18 10:33	General View	 Load JPG	☒
4	30/08/18 10:33	General View	 Load JPG	☒
5	30/08/18 10:33	General View	 Load JPG	☒
6	30/08/18 10:33	General View	 Load JPG	☒
7	30/08/18 10:33	General View	 Load JPG	☒
8	30/08/18 10:33	General View	 Load JPG	☒
9	30/08/18 10:33	General View	 Load JPG	☒
10	30/08/18 10:33	General View	 Load JPG	☒
11	30/08/18 10:33	General View	 Load JPG	☒
12	30/08/18 10:33	General View	 Load JPG	☒
13	30/08/18 10:33	General View	 Load JPG	☒
14	30/08/18 10:33	General View	 Load JPG	☒
15	30/08/18 10:33	Odometer Reading	 Load JPG	☒
16	30/08/18 10:33	General View	 Load JPG	☒
17	30/08/18 10:33	General View	 Load JPG	☒
18	30/08/18 10:33	Chassis Number	 Load JPG	☒
19	30/08/18 10:33	General View	 Load JPG	☒
20	30/08/18 10:33	General View	 Load JPG	☒
21	30/08/18 10:33	General View	 Load JPG	☒
22	30/08/18 10:33	General View	 Load JPG	☒
23	30/08/18 10:33	General View	 Load JPG	☒
24	30/08/18 10:33	General View	 Load JPG	☒
25	30/08/18 10:33	General View	 Load JPG	☒
26	30/08/18 10:33	General View	 Load JPG	☒
27	30/08/18 10:33	General View	 Load JPG	☒
28	30/08/18 10:33	General View	 Load JPG	☒
29	30/08/18 10:33	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
30	30/08/18 10:33	General View	 Load JPG	☒
31	30/08/18 10:33	General View	 Load JPG	☒
32	30/08/18 10:33	General View	 Load JPG	☒
33	30/08/18 10:33	General View	 Load JPG	☒
34	30/08/18 10:33	General View	 Load JPG	☒
35	30/08/18 10:33	General View	 Load JPG	☒
36	30/08/18 10:33	General View	 Load JPG	☒
37	30/08/18 10:33	General View	 Load JPG	☒
38	30/08/18 10:33	General View	 Load JPG	☒
39	30/08/18 10:33	General View	 Load JPG	☒
40	30/08/18 10:33	General View	 Load JPG	☒
41	30/08/18 10:33	General View	 Load JPG	☒
42	30/08/18 10:33	General View	 Load JPG	☒
43	30/08/18 10:33	General View	 Load JPG	☒
44	30/08/18 10:34	General View	 Load JPG	☒
45	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
46	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
47	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
48	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
49	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
50	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
51	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
52	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
53	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
54	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
55	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
56	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
57	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
58	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
59	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
60	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
61	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
62	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
63	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
64	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
65	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
66	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
67	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
68	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
69	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
70	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
71	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
72	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
73	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
74	30/08/18 10:34	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/12/17 10:28	PARF COE	 Load PDF	
2	13/12/17 10:28	Enquire Transfer Fee Details	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	18/12/17 17:06	WORKSHOP ESTIMATE	 Load PDF	
2	30/08/18 10:32	SUPPLEMENTARY LIST	 Load PDF	
3	30/08/18 10:32	REVISED ESTIMATE	 Load PDF	
4	31/08/18 10:25	SUPPLEMENTARY LIST 2	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	12/12/17 17:13	Accident Statement	 Load HTML	
Photos/Images			3 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	12/12/17 16:57	Accident Photo	 Load JPG	☒
2	12/12/17 16:57	Accident Photo	 Load JPG	☒
3	12/12/17 16:57	Accident Photo	 Load JPG	☒
4	12/12/17 16:57	Accident Photo	 Load JPG	☒
5	12/12/17 16:57	Accident Photo	 Load JPG	☒
6	12/12/17 16:57	Accident Photo	 Load JPG	☒
7	12/12/17 16:57	Accident Photo	 Load JPG	☒
8	12/12/17 16:57	Accident Photo	 Load JPG	☒
9	12/12/17 16:57	Accident Photo	 Load JPG	☒
10	12/12/17 16:57	Accident Photo	 Load JPG	☒
11	12/12/17 16:57	Accident Photo	 Load JPG	☒
12	12/12/17 16:57	Accident Photo	 Load JPG	☒
13	12/12/17 16:57	Accident Photo	 Load JPG	☒
14	12/12/17 16:57	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	12/12/17 17:13	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)  			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17023778/T1QD3E2

Date: 31/08/2018

REFERENCE

Insured/Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD	Policy No:	MSD/VPCP/17-001409-00	Claim No:	MSC/V/17-001920
Date of Loss:	11/12/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT6452D	Engine No:	L15B31000522
Make & Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Chassis No:	JHMGK5850FX203118
Reg. Date:	18/06/2015 (Man. Year: 2015)	Odometer:	45898 km
Colour:	Black		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$76,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,203.20	1,917.30	1,285.90	40.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,050.00	3,420.00	2,630.00	43.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,253.20	5,337.30	3,915.90	42.32
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	8,503.20	4,587.30	3,915.90	46.05
+ GST 7.00/7.00% (S\$)	595.23	321.11	274.12	46.05
Nett Amount (S\$)	9,098.43	4,908.41	4,190.02	46.05

INSPECTION

Date of Assignment:	14/12/2017	Present Location:	Hitachi Capital Asia Pacific Pte. Ltd (HQ)
Date Inspected:	18/12/2017	Inspected At:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road Singapore 629705
Estimated Period of Repair:	10.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2018)
Parts: 144	HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKT6452D)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Driver door (WCP)	Bent	520.00 F	*520.00 F
2	1		*Driver door sticker set (WCP)	Necessary	30.00 F	*30.00 F
3	2		*Driver door hinge top and bottom (WCP)	Repair	56.00 F	*- F
4	1		*Driver door checker (WCP)	Repair	30.00 F	*- F
5	1		*Driver door handle (WCP)	Cut	200.00 F	*200.00 F
6	1		*Driver door handle knob (WCP)	Not Necessary	-	*- F
7	1		*Driver door key retainer base (WCP)	Not Necessary	-	*- F
8	1		*Driver door lock (WCP)	Not Necessary	160.00 F	*- F
9	1		*Rear door RH (WCP)	Bent	500.00 F	*500.00 F
10	1		*Rear door sticker set RH (WCP)	Necessary	30.00 F	*30.00 F
11	2		*Rear door hinge top and bottom RH (WCP)	Bent	60.00 F	*30.00 F
12	1		*Rear door checker RH (WCP)	Not Necessary	30.00 F	*- F
13	3		*Rear door weatherstripe RH (WCP)	Not Necessary	75.00 F	*- F
14	1		*Rear fender RH (WCP)	Not Necessary	400.00 F	*- F
15	1		*Rear fender shield RH (WCP)	Not Necessary	38.00 F	*- F
16	10		*Rear fender shield clips RH (WCP)	Not Necessary	20.00 F	*- F
17	1		*Rear bumper (WCP)	Repair	180.00 F	*- F
18	1		*Door Center Pillar RH (WCP)	Repair	-	*- F
19	1		*Rocker panel RH (WCP)	Repair	150.00 F	*- F
20	1		*Rocker panel garnish (side skirt) RH (WCP)	Deformed	280.00 F	*280.00 F
Supplementary #1						
21	1		*Rear door sub seal RH rear (WCP)	Necessary	25.00 F	*25.00 F
22	1		*Rear door sub seal RH Front (WCP)	Necessary	25.00 F	*25.00 F
23	1		*Rear door lower seal (R&L) (WCP)	Necessary	25.00 F	*25.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	1		*Front door sub seal RH (WCP)	Necessary	25.00 F	*25.00 F
25	1		*Front door lower seal (R&L) (WCP)	Necessary	25.00 F	*25.00 F
Supplementary #2						
26	1		*DR Cyl. Garnish (WCP)	Cut	28.00 F	*28.00 F

F=Franchise part.

Sub Total (S\$)	2,912.00	1,743.00
+ Margin on L,N Items 10.00/10.00% (S\$)	291.20	174.30
Total Parts (S\$)	3,203.20	1,917.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	2,000.00	1,400.00
2	Putty, blend and paint affected area	New	2,000.00	1,400.00
3	Check Wiring and ensure proper function	New	100.00	30.00
4	Remove & reinstall bumper sensors	New	120.00	30.00
5	Cavity Treatment to apply sealant on New Parts (Front and rear door, fender and rocker panel)	New	250.00	100.00
6	Conduct four wheel alignment / side slip test	New	150.00	80.00
7	Transfer front and rear door lock & mechanism to new door	New	300.00	120.00
8	Conduct water seepage test	New	80.00	40.00
9	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New	200.00	100.00
10	Diagnostic Check & Reset	New	250.00	120.00
11	Remove Upholstery Trim and Cushion	New	350.00	0.00
12	Panel beat and spray paint Door center pillar	New	250.00	0.00
Gross Labour Cost (S\$)			6,050.00	3,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

ASSIGNED BY

REF CS/MSG17023778/T19 d3

Survivor

Meinmen

From (Person)

Tan Kich

Jocelyn Ng

ASSIGNMENT (Office)

MSIG

Date/Time

14

15/12/17 @ 2:49pm

Estimated Cost

Bill to

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SKT 6452D

Insured:

at Workshop m/s

Hitachi Capital

Tel:

6466 3022

of

No. 8 Fourth Lok Yang Rd, 629705

Policy No.

MSD/VPCP/17-001409-00

Claim No.

MSC/V/17-001920

Sum Insured

Excess

\$750.00

Make of Veh.

(Client's Record)

D.O.B.

11/12/17

CA (REV)

REP.

REV 24 HRS

18/12/17 Early Morning

H.O.D. Endorsement

Date/Time

3:45pm @ 14/12/17

Person Contacted

Grant Chong

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SKT 6452D x

18/12/17 @ 5:07pm revert to Jocelyn Ng via Meinmen.

19/12/17 @ 9:44am Kenny Ong informed C/A via Meinmen.

19/12/17 @ 2:14pm Informed Grant Chong C/A & ex: \$750 by email.

20/12/18 @ 10:38am 2nd revert to Jocelyn Ng via Meinmen. (supplementary)

31/8/18 @ 10:11am Kenny Ong informed C/A at \$5306.50 via Meinmen.