

15/5/2010

INS. CASE OWNER:

Shawn - PJ.
Hawman

CC 6 / AIG1702 37791, A26632

LKK:

IDAC:

Surveyor:

Hawman

DOI:

12/12/17

Date / Time:

14/12/17

Registered in Merimen:

14/12/17

Pre-assign / CCU / FTE

Insured Vehicle No.:

SK7 6416C

Name of Insured:

FOK WENT CHOW PETER

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

07/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

BERNARD FOK 319 MIN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

191761050584

Policy No.:

70046478-01000

Make / Model:

MERCEDES

Place of Accident:

TAMPINES AVE 2 TRIPS

SIMBL AVE

OI / IA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

STV4519K

INSRS:

WSP:

Tel:

Liability:

RMKS:

contact
wsi

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

15/12/17
DAN

STV4519K - X SK7 6416C - X

15/12/17 called OJD. spoke to Mr Germaine.

Inform about the claim. confirm the

accident. OJD over email to. Agreed

to settle. Amount of mcd issue.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

LITIGATION

Date/Time:

Confirm with:

Confirm by:

Fair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

LIT SETTLEMENT

Date/Time:

15/11/18

Confirm with:

CCI/ra

Email ☐ Call ☐

Liability:

SS

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Fair Cost:

SS

3635.39

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

48.00 (\$60 x 8 days)

Loss of Income (LOI):

SS

(\$ x days)

LOI only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

Global LTA Search

SS

2.00

Medical:

SS

X

Towage:

SS

X

(e.g. Tow/ Independent)

Fair Cost

SS

X

Total:

SS

4117.39

Global Sum \$S:

LIT PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Name 1:

SS

4117.39

Name 1:

Camyndeigns Engineering Pte Ltd

Name 2: (Strike if N.A.)

SS

X

Name 2:

Name 3: (Strike if N.A.)

SS

X

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17023779/zb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 14-12-2017		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 6416C	Veh. Inspected	SVJ 4519K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	14/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/12/2017	Inspection Date		
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD NO : 320 UBI ROAD 3 SINGAPORE 408649			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP-AIGVehicle No. : SJV4519KMake & Model : TOYOTA VIOSYear of Manufacture : 2009Chassis No. : MR053HY9305135328Engine No. : 1NZX987109Policy No. : SI17V00626/VPE/R02

Time of Accident : _____

Ins Company : LIBERTY

Excess : _____

Date of Accident : 02/12/2017

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : Jasmine Chng

Signature : _____

Contact No : _____

68438736 – Jasmine Chng

68438735- Anikka Lai

Parts (a) Cost / List Price Items \$ 3,170.91Plus/Less 20% \$ 634.18Total of Cost / List \$ 3,805.09(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 245.00Total Parts Cost (Appendix A) \$ 4,050.09Labour (Appendix B) \$ 2,550.00Total Repair Cost \$ 6,600.09

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature: _____

Date: _____

Name of Surveyor : Adrian LingCompany : LKKSurvey conducted on : 18/12/17 at 12pmRemarks By Surveyor(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 06 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ 865(e) Signature of surveyor : [Signature] Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SJV4519K Case Owner : Jasmine Chng

Make & Model : TOYOTA VIOS Year Manufacture : 2009

Chassis No : MR053HY9305135328 Engine No : 1NZX987109

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP-AIG

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR NUMBER PLATE <i>change Best</i>	1			45	\$ 45.00	✓
2	BOOTILD <i>Rebuilt</i>	1	465.93	\$ 582.42	✓		
3	BOOTLID LOCK <i>Rebuilt</i>	1	76.10	\$ 95.13	✓		
4	BOOTLID LOCK CATCH <i>Rebuilt</i>	1		\$ 28.55	+		
5	BOOTLID HINGE LH <i>Rebuilt</i>	1		\$ 56.71	+		
6	BOOTLID HINGE RH <i>Rebuilt</i>	1		\$ 56.71	+		
7	BOOTLID EMBLEM LOGO <i>2</i>	1	37.50	\$ 46.88	✓		
8	WORDING "VIOS" <i>Rebuilt</i>	1	42.99	\$ 53.74	✓		
9	WORDING "E" <i>Rebuilt</i>	1	42.99	\$ 53.74	✓		
10	BOOTLID WEATHERSTRIP <i>cut</i>	1	109.30	\$ 136.63	✓		
11	BOOTLID GARNISH <i>Rebuilt</i>	1	110.75	\$ 138.41	✓		
12	REAR BUMPER <i>Rebuilt</i>	1	309.94	\$ 387.43	✓		
13	REAR BUMPER CLIPS <i>Rebuilt</i>	10	40	\$ 50.00	✓		
14	REAR BUMPER INNER PANEL <i>Rebuilt</i>	1		\$ 576.46	2X		
15	REAR BUMPER RETAINER LH <i>Rebuilt</i>	1	73.18	\$ 91.47	✓		
16	REAR BUMPER RETAINER RH <i>Rebuilt</i>	1	73.18	\$ 91.47	✓		
17	REAR BUMPER TAILLAMP LH ASSY <i>Rebuilt</i>	1		\$ 212.75	+		
18	REAR BUMPER TAILLAMP RH ASSY <i>Rebuilt</i>	1		\$ 212.75	+		
19	REAR BUMPER TAILLAMP CLIPS <i>Rebuilt</i>	10		TBA	+		
20	REAR BUMPER BRACKET LH <i>Rebuilt</i>	1		\$ 68.14	+		
21	REAR BUMPER BRACKET RH <i>Rebuilt</i>	1		\$ 68.14	+		
22	REAR BUMPER SPONGE <i>Rebuilt</i>	1		TBA	+		
23	REAR BUMPER REINFORCEMENT <i>Rebuilt</i>	1		TBA	+		
24	REAR BUMPER REFLECTOR LH <i>Rebuilt</i>	1	65.35	\$ 81.69	✓		
25	REAR BUMPER REFLECTOR RH <i>Rebuilt</i>	1	65.35	\$ 81.69	✓		
26	REVERSE SENSOR <i>Damaged</i>	1			200	\$ 200.00	✓
27	0 Tailamp Assy LH	0		\$ 212.75			
28	0 Tailamp Assy RH	0		\$ 212.75			
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Labour

Vehicle No.	: <u>SJV4519K</u>	Case Owner	: <u>Jasmine Chng</u>
Make & Model	: TOYOTA VIOS	Year of Manufacture	: 2009

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 Fax:67436072

Supplementary 1

Vehicle No : SJV4519K Case Owner : Jasmine Chng
Make & Model : TOYOTA VIOS Year Manufacture : 2009
Chassis No : MR053HY9305135328 Engine No : 1NZX987109
Sales Order : 0 Supplier : 0
Order By : _____ Type of Claim : TP-AIG

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition E
1	Exhaust muffler (CHROME) <i>Best</i>	1	<i>60</i>	\$ 75.00	☒		
2	<i>no plate</i>						
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Dec 2017 Edit Reg		18 Dec 2017 00:00 Edit Adj Rpt	S\$3,397.56 Edit Estimates	S\$3,397.56 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	FOK WENG CHOY PETER, ID: S1409809G, Tel: +6591788166		
Main Claimant:	LIM NGAK CHOONG, ID: S1233700J		
Vehicle Reg. No.:	SJV4519K	Date of Loss:	02/12/2017 19:00 - :59
Claim Type:	TP / 1917610505SG	Policy/Cover Note No.:	2100449928-01000 (Comprehensive)
Vehicle Reg. No. (Insured):	SKZ6416C	Policy No. (Claimant):	S117V00626/VPE/R02
		Excess:	
Repairer:	ComfortDelGro Engineering Pte Ltd (Ubi) 320 UBI ROAD 3, 408649 Ubi - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijie.Wui@aig.com		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/12/2017]		
Driver/Custodian (Insured):	FOK WENG CHOY PETER (), NRIC: S1409809G, Tel: +6591788166		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV4519K (1917610505SG)

[SKZ6416C]

TP

LIM NGAK CHOONG

Dec 2 2017 7:00PM

[FOK WENG CHOY PETER]

ComfortDelGro Engineering Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser ▼
------------------	---------------	--------------------	--------------	--------------	------	-------------------

Letters/Correspondences				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Assessment Reports				1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	15/12/17 09:45	Accident Statement From: SC - Reg. No: SKZ6416C, Claimant: FOK WENG CHOY PETER	1	Load HTM	

Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/02/18 15:04	General View	1	Load JPG	☒
2	12/02/18 15:04	General View	1	Load JPG	☒
3	12/02/18 15:04	General View	1	Load JPG	☒
4	12/02/18 15:04	General View	1	Load JPG	☒
5	12/02/18 15:04	General View	1	Load JPG	☒
6	12/02/18 15:04	General View	1	Load JPG	☒
7	12/02/18 15:04	General View	1	Load JPG	☒
8	12/02/18 15:04	General View	1	Load JPG	☒
9	12/02/18 15:04	General View	1	Load JPG	☒
10	12/02/18 15:04	General View	1	Load JPG	☒
11	12/02/18 15:04	General View	1	Load JPG	☒
12	12/02/18 15:04	General View	1	Load JPG	☒
13	12/02/18 15:04	General View	1	Load JPG	☒
14	12/02/18 15:04	General View	1	Load JPG	☒
15	12/02/18 15:04	General View	1	Load JPG	☒
16	12/02/18 15:04	General View	1	Load JPG	☒
17	12/02/18 15:04	General View	1	Load JPG	☒
18	12/02/18 15:04	General View	1	Load JPG	☒
19	12/02/18 15:04	General View	1	Load JPG	☒
20	12/02/18 15:04	General View	1	Load JPG	☒
21	12/02/18 15:04	General View	1	Load JPG	☒
22	12/02/18 15:04	General View	1	Load JPG	☒
23	12/02/18 15:04	General View	1	Load JPG	☒
24	12/02/18 15:04	General View	1	Load JPG	☒
25	12/02/18 15:04	General View	1	Load JPG	☒
26	12/02/18 15:04	General View	1	Load JPG	☒
27	12/02/18 15:04	General View	1	Load JPG	☒

			1		☒
28	12/02/18 15:04	General View	1	Load JPG	☒
29	12/02/18 15:04	General View	1	Load JPG	☒
30	12/02/18 15:04	General View	1	Load JPG	☒
31	12/02/18 15:04	General View	1	Load JPG	☒
32	12/02/18 15:04	General View	1	Load JPG	☒
33	12/02/18 15:04	General View	1	Load JPG	☒
34	12/02/18 15:04	General View	1	Load JPG	☒
35	12/02/18 15:04	General View	1	Load JPG	☒
36	12/02/18 15:04	General View	1	Load JPG	☒
37	12/02/18 15:04	General View	1	Load JPG	☒
38	12/02/18 15:04	General View	1	Load JPG	☒
39	12/02/18 15:04	Chassis Number	1	Load JPG	☒
40	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
41	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
42	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
43	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
44	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
45	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
46	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
47	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
48	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
49	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
50	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
51	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
52	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
53	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
54	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
55	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
56	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
57	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
58	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒
59	12/02/18 15:04	Reinspection Photo	1	Load JPG	☒

Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/12/17 17:15	TP GIA REPORT	1 Load PDF	
2	14/12/17 17:15	TP ESTIMATE	1 Load PDF	
3	21/02/18 14:48	AUTHORISATION TO ACT	1 Load PDF	
4	21/02/18 14:48	GIA SEARCH	1 Load PDF	
5	21/02/18 14:48	LETTER TO OI	1 Load PDF	
6	21/02/18 14:48	RELEASE VOUCHER	1 Load PDF	
7	21/02/18 14:48	WORKSHOP INVOICE	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKZ6416C (Insd veh)	Model:	TOYOTA VIOS 1.5 (A)
	SJV4519K (TP veh)		
Date of Accident:	02/12/2017		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	6,463.77
Final Repair Cost	:	\$	3,635.39
Loss of Use	:	\$	480.00
Rental (if any)	:	\$	8.00 days at \$60.00 per day
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	4,117.39

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 27

BOLA Liability: 100 (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	:	\$ 4,117.39
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

21 Feb
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17023779/AZB3S2
Date: 21/02/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100449928-01000
Claimant Vehicle No: SJV4519K Insured Vehicle No: SKZ6416C
Date of Loss: 02/12/2017 Nature of Claim: TP Claim No: 1917610505SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJV4519K
Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 1NZX987109
Reg. Date: 26/01/2010 (Man. Year: 2009) Chassis No: MR053HY9305135328
Colour: Black Odometer: 0 km
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,490.91	1,817.56	1,673.35	47.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,580.00	970.00	38.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,040.91	3,397.56	2,643.35	43.76
+ GST 7.00/7.00% (S\$)	422.86	237.83	185.03	43.76
Nett Amount (S\$)	6,463.77	3,635.39	2,828.38	43.76
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,117.39		

INSPECTION

Date of Assignment: 18/12/2017
Date Inspected: 18/12/2017 Inspected At: ComfortDelGro Engineering Pte Ltd (Ubi)
320 UBI ROAD 3
Singapore 408649
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: ZAY YER LYNN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	582.42 F	*465.93 F
2	1		*BOOTLID LOCK	Damaged	95.13 F	*76.10 F
3	1		*BOOTLID LOCK CATCH	Not Necessary	28.55 F	*- F
4	1		*BOOTLID HINGE LH	Not Necessary	56.71 F	*- F
5	1		*BOOTLID HINGE RH	Not Necessary	56.71 F	*- F
6	1		*BOOTLID EMBLEM LOGO	Necessary	46.88 F	*37.50 F
7	1		*WORDING VIOS	Necessary	53.74 F	*42.99 F
8	1		*WORDING E	Necessary	53.74 F	*42.99 F
9	1		*BOOTLID WEATHERSTRIP	Cut	136.63 F	*109.30 F
10	1		*BOOTLID GARNISH	Deformed	138.41 F	*110.75 F
11	1		*REAR BUMPER	Deformed	387.43 F	*309.94 F
12	10		*REAR BUMPER CLIPS	Necessary	50.00 F	*40.00 F
13	1		*REAR BUMPER INNER PANEL	Repair	576.46 F	*- F
14	1		*REAR BUMPER RETAINER LH	Necessary	91.47 F	*73.18 F
15	1		*REAR BUMPER RETAINER RH	Necessary	91.47 F	*73.18 F
16	1		*REAR BUMPER TAILLAMP LH ASSY	Not Necessary	212.75 F	*- F
17	1		*REAR BUMPER TAILLAMP RH ASSY	Not Necessary	212.75 F	*- F
18	10		*REAR BUMPER TAILLAMP CLIPS (NPA)	Not Necessary	0.00 F	*- F
19	1		*REAR BUMPER BRACKET LH	Not Necessary	68.14 F	*- F
20	1		*REAR BUMPER BRACKET RH	Not Necessary	68.14 F	*- F
21	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 F	*- F
22	1		*REAR BUMPER REINFORCEMENT (NPA)	Not Necessary	0.00 F	*- F
23	1		*REAR BUMPER REFLECTOR LH	Cracked	81.69 F	*65.35 F
24	1		*REAR BUMPER REFLECTOR RH	Cracked	81.69 F	*65.35 F
25	1		*REAR NUMBER PLATE	Bent	45.00 FS	*45.00 FS
26	1		*REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
27	1		*EXHAUST MUFFLER (CHROME)	Bent	75.00 F	*60.00 F
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	3,490.91 1,817.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK, STRAIGHTEN AND RENEW DAMAGE PARTS AS REAR BOOTLID, REAR BUMPER & REAR TAILGATE ETC.	New	1,200.00	800.00
2	TO PUTTY AND SPRAY PAINTING ON BOOTLID AND REAR BUMPER.	New	1,200.00	700.00
3	TO CHECK WIRING TO RENEW REVERSE SENSOR.	New	100.00	50.00
4	TUFF COAT.	New	50.00	30.00
Gross Labour Cost (S\$)			2,550.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >