



ComfortDesGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TP-AIGVehicle No. : SJV4519KMake & Model : TOYOTA VIOSYear of Manufacture : 2009Chassis No. : MR053HY9305135328Ins Company : LIBERTYEngine No. : 1NZX987109

Excess : \_\_\_\_\_

Policy No. : SI17V00626/VPE/R02Date of Accident : 02/12/2017

Time of Accident : \_\_\_\_\_

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimates**Case Owner : Jasmine Chng

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 3,170.91Plus/Less 20% \$ 634.18Total of Cost / List \$ 3,805.09(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ 245.00Total Parts Cost (Appendix A) \$ 4,050.09Labour (Appendix B) \$ 2,550.00Total Repair Cost \$ 6,600.09

Contact No

68438736 – Jasmine Chng

68438735- Anikka Lai

*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
TEL :68438723/68438736 Fax:67436072

## Spare Parts

Vehicle No : SJV4519K Case Owner : Jasmine Chng

Make & Model : TOYOTA VIOS Year Manufacture : 2009

Chassis No : MR053HY9305135328 Engine No : 1NZX987109

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP-AIG

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR NUMBER PLATE	1				\$ 45.00	
2	BOOTLID	1		\$ 582.42			
3	BOOTLID LOCK	1		\$ 95.13			
4	BOOTLID LOCK CATCH	1		\$ 28.55			
5	BOOTLID HINGE LH	1		\$ 56.71			
6	BOOTLID HINGE RH	1		\$ 56.71			
7	BOOTLID EMBLEM LOGO	1		\$ 46.88			
8	WORDING "VIOS"	1		\$ 53.74			
9	WORDING "E"	1		\$ 53.74			
10	BOOTLID WEATHERSTRIP	1		\$ 136.63			
11	BOOTLID GARNISH	1		\$ 138.41			
12	REAR BUMPER	1		\$ 387.43			
13	REAR BUMPER CLIPS	10		\$ 50.00			
14	REAR BUMPER INNER PANEL	1		\$ 576.46			
15	REAR BUMPER RETAINER LH	1		\$ 91.47			
16	REAR BUMPER RETAINER RH	1		\$ 91.47			
17	REAR BUMPER TAILLAMP LH ASSY	1		\$ 212.75			
18	REAR BUMPER TAILLAMP RH ASSY	1		\$ 212.75			
19	REAR BUMPER TAILLAMP CLIPS	10		TBA			
20	REAR BUMPER BRACKET LH	1		\$ 68.14			
21	REAR BUMPER BRACKET RH	1		\$ 68.14			
22	REAR BUMPER SPONGE	1		TBA			
23	REAR BUMPER REINFORCEMENT	1		TBA			
24	REAR BUMPER REFLECTOR LH	1		\$ 81.69			
25	REAR BUMPER REFLECTOR RH	1		\$ 81.69			
26	REVERSE SENSOR	1				\$ 200.00	
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**ComfortDelGro Engineering Pte Ltd**

320 UBI ROAD 3 SINGAPORE 408649

Tel: 68438723/68438736 FAX : 67436072

## Labour

Vehicle No. : **SJV4519K**

Case Owner : **Jasmine Chng**

Make & Model : TOYOTA VIOS

Year of Manufacture : 2009

[illegible]

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*