



② 11/12/17

Third Party Insurer : AIG
 Insured's Veh No : GBA7921S
 Date of accident : 11.12.2017

Messrs Grab Rentals Pte Ltd

TP ALG
 Vic

Question mark
 (can ??)

Date : 13.12.2017

Estimate To Repair

Toyota Vios 1.5E CVT
 SLL9508M
 MHFB29F3002007645

Vehicle No :
 Chassis No :

Pages : 1 of 1

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	bonnet <i>Dented</i>	\$ 757.30	\$ 757.30 ✓
2	1 pc	bonnet lock <i>Byd</i>	\$ 128.90	\$ 128.90 ✓
3	2 ps	bonnet hinges <i>Not in Best.</i>	\$ 55.80	\$ 111.60 ✓
4	1 pc	front support panel <i>Byd</i>	\$ 494.80	\$ 494.80 ✓
5	1 pc	front support panel top cover <i>Dented</i>	\$ 244.50	\$ 244.50 ✓
6	10 ps	front support panel top cover clips <i>in</i>	\$ 4.30	\$ 43.00 ✓
7	1 pc	front bumper <i>Dented</i>	\$ 427.90	\$ 427.90 ✓
8	1 pc	front bumper reinforcement <i>2 items</i>	\$ 379.00	\$ 379.00 ✓
9	2 ps	front bumper chrome moulding <i>2 items</i>	\$ 66.70	\$ 133.40 ✓
10	1 pc	front bumper outer garnish <i>Cracked</i>	\$ 87.80	\$ 87.80 ✓
11	2 ps	front bumper side retainers <i>in</i>	\$ 65.40	\$ 130.80 ✓
12	10 ps	front bumper clips <i>in</i>	\$ 4.30	\$ 43.00 ✓
13	1 pc	front bumper emblem badge <i>in</i>	\$ 97.00	\$ 97.00 ✓
14	1 pc	front bumper centre air grille <i>2 items</i>	\$ 276.20	\$ 276.20 ✓
15	2 ps 1 pc	headlamps <i>2 items 1H cracked</i>	\$ 464.60	\$ 464.60 ✓
		Less 25%		\$ 4,284.40
				\$ 1,071.10
				\$ 3,213.30
SPECIAL NETT ITEMS				
16	1 set	sundries and clips <i>in</i>	\$ 100.00	\$ 100.00 ✓
LABOUR & MISC. CHARGES				
1		To rust proofing of the affected areas. <i>930</i>	\$ 100.00	\$ 100.00 ✓
2		To check electrical lighting concerned.	\$ 60.00	\$ 60.00 ✓
3		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 650.00	\$ 650.00 ✓
4		Putty and spray painting of the affected portion.	\$ 780.00	\$ 780.00 ✓
			\$ 1,590.00	\$ 1,590.00 ✓
		Grand Total		\$ 4,903.30

25134
 1885.05

30

930

Total: 2845.05

Adrian Gj

14/12/17. OA Byd.