

CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AIG ASIA PACIFIC INSURANCE

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
14/12/2017	MAIN	TBA

TP CLAIM (A&G/AIG)			
ESTIMATE COST OF REPAIR FOR VEHICLE NO: SKV4702K			
Make/Model	DOA	Policy No	Chassis No.
HONDA VEZEL 1.5X CVT	12/12/2017@1445	NIL	RU11100983 (2015)


Qty	Unit	Description	Amount
1.00	pc	Rear Windscreen Moulding	221.40
1.00	pc	Rear Boot	1,100.90
1.00	pc	Rear Boot Logo	38.70
1.00	pc	Rear Boot Emblem 'Vezel'	66.30
1.00	pc	Rear Boot Inner Board	345.20
1.00	pc	Rear Boot Rubber	116.70
1.00	pc	Rear Boot Inner Lock	230.10
1.00	pc	Rear Boot Reflector LH	298.50
1.00	pc	Rear Bumper	633.50
1.00	pc	Rear Bumper Retainer LH	32.50
1.00	pc	Rear Bumper Retainer RH	32.50
1.00	pc	Rear End Panel	515.80
1.00	pc	Rear End Panel Top Garnish	122.25
		Subtotal	3,754.35
		Discount 20%	-750.87
1.00	pc	Reverse Sensor (S/NETT)	200.00
1.00	pc	Sealant (S/NETT)	35.00
1.00	pc	Rear no. plate (S/NETT)	35.00
		Remove and install cushions, seats back rest, inner trim, garnish, roof lining and upholstery to facilitate repair.	180.00
		Labour to remove and replace reart windscreen	150.00
		Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel, rear boot, rear bumper, rear compartment and affected areas.	800.00

CHARN'S CUSTOMCRAFT

Subtotal

GST 7%

Total



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

GST Reg. No. M90367863L

AIG ASIA PACIFIC INSURANCE

ATTN: THE MOTOR CLAIM DEPT

Date	Estimate No.	Reg. No.
14/12/2017	MAIN	TBA

TP CLAIM (A&G/AIG)			
ESTIMATE COST OF REPAIR FOR VEHICLE NO: SKV4702K			
Make/Model	DOA	Policy No	Chassis No.
HONDA VEZEL 1.5X CVT	12/12/2017@1445	NIL	RU11100983 (2015)

Qty	Unit	Description	Amount
-----	------	-------------	--------

Note: The above is an estimate only. If other parts requested during the course of repair, we will inform you accordingly.

All new/O.E.M/used parts are subject to availability.

CHARN'S CUSTOMCRAFT

Subtotal	\$4,403.48
GST 7%	\$308.24
Total	\$4,711.72