



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department


Estimate No: MCS1102219
Date: 14 Dec 2017
Policy No: GA162946
Veh Reg No: SJZ7702G
Make/Model: VOLKSWAGEN GOLF
1.4 TSI

Your Ref No: S7M005NT
Claim Type:
Accident Date: 13/12/2017

Estimate Repair Cost to Vehicle No :SJZ7702G

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 FRONT BUMPER		1 PC	500.00	
2 FRONT BUMPER SIDE RETAINER LH		1 PC	18.00	
3 FRONT BUMPER SIDE RETAINER - RH		1 PC	18.00	
4 FRONT BUMPER CENTER RETAINER		1 PC	18.00	
5 FRONT BUMPER LOWER GRILLE WITH LOWER CHROME MOULDING		1 PC	220.00	
6 FRONT BUMPER REINFORCEMENT		1 PC	280.00	
7 FRONT BUMPER LOWER BEAM		1 PC	120.00	
8 FRONT BUMPER INNER SPONGE		1 PC	20.00	
9 FRONT BUMPER TOW COVER		1 PC	25.00	
10 FRONT BUMPER LOWER GARNISH		1 PC	190.00	
11 FOGLAMP LH COVER		1 PC	70.00	
12 FOGLAMP RH COVER		1 PC	70.00	
13 FOG LAMP LH		1 PC	20.00	
14 FOGLAMP RH		1 PC	20.00	
15 HEADLAMP LH		1 PC	320.00	
16 HEADLAMP RH		1 PC	320.00	
17 HEADLAMP TOP PLATE LH		1 PC	30.00	
18 HEADLAMP TOP PLATE RH		1 PC	30.00	
19 HEADLAMP LOWER BEAM LH		1 PC	30.00	
20 HEADLAMP LOWER BEAM RH		1 PC	30.00	
21 HEADLAMP BRACKET LH		1 PC	80.00	
22 HEADLAMP BRACKET RH		1 PC	80.00	
23 FRONT FENDER LH		1 PC	260.00	
24 FRONT FENDER RH		1 PC	260.00	
25 FRONT FENDER COWLING LH		1 PC	75.00	
26 FRONT FENDER COWLING RH		1 PC	75.00	
27 FRONT FENDER INNER BRACKET LH		1 PC	30.00	
28 FRONT FENDER INNER BRACKET RH		1 PC	30.00	
29 FRONT BONNET HINGE LH		1 PC	40.00	
30 FRONT BONNET HINGE RH		1 PC	40.00	
31 FRONT BONNET		1 PC	600.00	
32 FRONT BONNET INSULATOR		1 PC	160.00	
33 FRONT BONNET INSULATOR CLIP		5 PC	15.00	
34 FRONT BONNET RUBBER SEAL LH		1 PC	20.00	
35 FRONT BONNET RUBBER SEAL RH		1 PC	15.00	
36 FRONT BONNET STOPPER LH		1 PC	5.00	
37 FRONT BONNET STOPPER RH		1 PC	5.00	
38 FRONT BONNET DAMPER		1 PC	50.00	
39 FRONT BONNET LOCK - UPP		1 PC	40.00	





AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MCS1102219
Date: 14 Dec 2017
Policy No: GA162946
Veh Reg No: SJZ7702G
Make/Model: VOLKSWAGEN GOLF
1.4 TSI

Your Ref No: S7M005NT
Claim Type:
Accident Date: 13/12/2017

Estimate Repair Cost to Vehicle No :SJZ7702G


Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
40 FRONT BONNET LOCK		1 PC	100.00	
41 RADIATOR GRILLE WITH LOGO		1 PC	240.00	
42 RADIATOR SUPPORT PANEL		1 PC	500.00	
43 RADIATOR AIR GUIDE LH		1 PC	20.00	
44 RADIATOR AIR GUIDE RH		1 PC	20.00	
45 RADIATOR		1 PC	300.00	
46 RADIATOR FAN MOTOR		1 PC	320.00	
47 FAN COWLING		1 PC	120.00	
48 RADIATOR TOP BRACKET LH		1 PC	25.00	
49 RADIATOR TOP BRACKET RH		1 PC	25.00	
50 RADIATOR TOP BUSH LH		1 PC	15.00	
51 RADIATOR TOP BUSH RH		1 PC	15.00	
52 AIR CON CONDENSER		1 PC	300.00	
53 AIR CON CONDENSER FAN MOTOR		1 PC	240.00	
54 AIR INLET DUCT		1 PC	25.00	
55 RESONATOR DUCT		1 PC	25.00	
56 RESONATOR COVER		1 PC	25.00	
57 TURBO COOLER		1 PC	320.00	
58 TURBO COOLER INLET HOSE		1 PC	140.00	
59 TURBO COOLER INLET PIPE -TO COOLER		1 PC	180.00	
60 TURBO COOLER OUTLET PIPE - TO ENGINE		1 PC	18.00	
61 AIR FILTER BOX		1 PC	240.00	
62 BATTERY TRAY		1 PC	80.00	
63 ALTERNATOR		1 PC	1,300.00	
64 ENGINE LOWER COVER		1 PC	95.00	
65 WIPER GARNISH		1 PC	95.00	
66 FRONT WINDSCREEN SIDE MOULDING RH		1 PC	90.00	
67 STEERING AIR BAG		1 PC	1,750.00	
68 KNEE AIR BAG		1 PC	800.00	
69 PASSENGER AIR BAG		1 PC	2,000.00	
70 SEAT BELT LH		1 PC	440.00	
71 SEAT BELT RH		1 PC	440.00	
72 AIR BAG CONTROL MODULE		1 PC	860.00	
73 DASHBOARD		1 PC	2,200.00	
74 FRONT WINDSCREEN		1 PC	400.00	

17,992.00



Special Nett

75 RADIATOR COOLANT - 1.5L 1 PC 18.00



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MCS1102219
Date: 14 Dec 2017
Policy No: GA162946
Veh Reg No: SJZ7702G
Make/Model: VOLKSWAGEN GOLF
1.4 TSI

Your Ref No: S7M005NT
Claim Type:
Accident Date: 13/12/2017

Estimate Repair Cost to Vehicle No :SJZ7702G

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
76 FRONT BUMPER SENSOR		4 PC	380.00	
77 BUMPER SENSOR 'O' RING		4 PC	12.00	
78 WINDSCREEN SEALANT		2 PC	30.00	
79 FRONT NO. PLATE		1 PC	35.00	
				475.00

LABOUR

80 TO CHECK WIRING AND REFOCUS HEADLAMP	1 EA	30.00	
81 TO REMOVE AND REPLACE A/C CONDENSER, PIPES AND RADIATOR, VACUUM A/C SYSTEM AS WELL AS	1 EA	120.00	
82 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	1 EA	80.00	
83 LABOUR TO REMOVE & REFIT FRONT WINDSCREEN	1 EA	120.00	
84 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.	1 EA	380.00	
85 TO DISMANTLE & INSTALL TURBO COOLER PIPING, AIR FILTER BOX & BATTERY TRAY	1 EA	120.00	
86 TO DISMANTLE & INSTALL STEERING WHEEL, AIR BAG PASSENGER AIR BAGM SEAT BELT & AIR BAG CONTROL BOX	1 EA	260.00	
87 LAB TO RESET SENSOR	1 EA	120.00	
88 TO DISMANTLE & INSTALL THE FONTAL DAMAGED PARTS, TO REMOVE & REFIT FRONT SUPPORT PANEL, TO JACK & STRAIGHTERN FRONT CHASSIS LH & TO REFIT LISTED PARTS BACK SAME	1 RA	1,500.00	
89 TO SPRAY FRONT BUMPER, FRONT FENDER LH.RH, BONNET, FRONT CHASSIS LH & FRONT DOOR LH/RH	1 EA	1,500.00	
			4,230.00

Amount Before Excess	S\$ 22,697.00
Add GST @ 7%	1,588.79
Total Amount payable	<u>S\$ 24,285.79</u>

TOTAL: SINGAPORE DOLLAR TWENTY FOUR THOUSAND TWO HUNDRED EIGHTY FIVE AND CENTS SEVENTY NINE ONLY



For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE