

2000000

ASS: REC BY:

REF: CS/MSG17023813 / T1qd3

Special Instructions:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Muhammad Ashik

of

MSIG

Date/Time:

14/12/17 @ 10:11am

Estimated Cost:

Bill to:

OD: TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 3752B

Insured:

SGR 89895

at Workshop n/s:

Trans Eurokars

Tel:

6395 7877

of

5 ubi close - 408605

Policy No:

A80405500QMY

Claim No:

539999

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 6/12/2017

CA / REV / REP. / REV 24 HRS

(wp)

R.O.D. Endorsement

Date/Time

10:38am @ 14/12/17

Person Contacted

Vion

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLS 3752B-X

SGR 89895-X

20/12/17 @ 2:21pm revised to Ashik via Mentimen.

31/11/18 @ 1:30am confirmed with Catharine final fig \$9266.84, 9 days.

(Red \$6443.85, 392.)

Singer

Tang Jiah

REF: MSIG

## ASSIGNMENT

From: \_\_\_\_\_ Date: 19/12/17

Estimated Cost: \_\_\_\_\_

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS 3752 B

at Workshop m/s TransEurokars

of 5 ubi close, 408605

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLS 3752 B Yr Regn: 2017 Sep

Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 5 Wagon. C.C. 1998

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 7255 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6CW1071H0126225

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ SRM / STD A/Rim or

Tyre Size: F: 225/55 R17

R: ^ ^

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 19/12/17 @ 1540

Survey held at TransEurokars

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 01 AUG 2018

Amun to

31/7/2018

Date/Time, File Pass to?

1) oil &amp; tyre

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 9

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS S:

Phone:

Other:

TOTAL:

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Insp. (\$)☐ Weekend (\$)

Report Format: ALCA-TP

Lump Sum / I.B.I. (\$) 9266.84



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17023813/T1qd3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-12-2017



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGR 8989S	Veh. Inspected	SLS 3752B
Policy No.	A80405500QMY	Coverage (\$)	0.00
Claim No.	539999	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	15/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	06/12/2017	Inspection Date
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605	

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Dec 2017		14 Dec 2017 10:11 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NGIAN TECK LAN, ID: S0211721E		
Main Claimant:	TEO ZHI MING BENJAMIN, ID: S8706849H		
Vehicle Reg. No.:	SLS3752B	Date of Loss:	06/12/2017 21:00 - :59
Claim Type:	TP / 539999	Policy/Cover Note No.:	A80405500QMY (Comprehensive) Coverage: 06/07/2017 - 05/07/2018
Vehicle Reg. No. (Insured):	SGR8989S	Policy No. (Claimant):	
		Excess:	
Repairer:	Trans Eurokars Pte Ltd ( ) NO. 5 UBI CLOSE, SINGAPORE, 408605 Ubi - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/12/2017]		
Driver/Custodian (Insured):	CHAN SEE MUN ( ), NRIC: S9319588D, Tel: +6581020154		
Adj Asg. Remarks:	Survey appt today, anytime after 3pm.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## Muhd Ashik B Madi

**From:** Muhd Ashik B Madi  
**Sent:** Friday, 8 December, 2017 3:07 PM  
**To:** eric.pau@eurokars.com.sg  
**Cc:** 'vion.lim@eurokars.com.sg'; 'jess.francis@eurokars.com.sg';  
'ronald.yap@eurokars.com.sg'; catherinechua@eurokars.com.sg;  
'kevin.lee@eurokars.com.sg'  
**Subject:** RE: YOUR REF: SGR8989S / OUR REF: SLS3752B THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Eric,

Liability is clear & we can proceed with Direct Settlement.

Kindly allow our surveyor to survey your client's vehicle.

Thank you.

Ashik Madi

Executive, Claims Services (Motor)

Direct line +65 6594 2548 | Direct fax +65 6225 7402 | [ashik\\_madi@sg.msig-asia.com](mailto:ashik_madi@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** [eric.pau@eurokars.com.sg](mailto:eric.pau@eurokars.com.sg) [<mailto:eric.pau@eurokars.com.sg>]

**Sent:** Friday, December 08, 2017 11:57 AM

**To:** Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>; [vion.lim@eurokars.com.sg](mailto:vion.lim@eurokars.com.sg)

**Cc:** [jess.francis@eurokars.com.sg](mailto:jess.francis@eurokars.com.sg); [ronald.yap@eurokars.com.sg](mailto:ronald.yap@eurokars.com.sg); [catherinechua@eurokars.com.sg](mailto:catherinechua@eurokars.com.sg);  
[kevin.lee@eurokars.com.sg](mailto:kevin.lee@eurokars.com.sg)

**Subject:** YOUR REF: SGR8989S / OUR REF: SLS3752B THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

**YOUR REF: SGR8989S / OUR REF: SLS3752B THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)**

Dear Sir/Mdm,

Kindly arrange the survey of our client's vehicle.

Attached is the ESTIMATE, SAS REPORT, SKETCH PLAN for your perusal.

Liaise with Vion for survey arrangement.

Best Regards,

**Eric Pau**

Insurance Claims Officer

**TRANS EUROKARS PTE LTD**

5 Ubi Close, Singapore 408605

D: (65) 6395 8685 H: (65) 9618 5991

E: [eric.pau@eurokars.com.sg](mailto:eric.pau@eurokars.com.sg)

*This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

**From:** [mazdacanone@mazda.com.sg](mailto:mazdacanone@mazda.com.sg) [<mailto:mazdacanone@mazda.com.sg>]

**Sent:** Friday, December 8, 2017 12:06 PM

**To:** Eric Pau <[eric.pau@eurokars.com.sg](mailto:eric.pau@eurokars.com.sg)>

**Subject:** Attached Image

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 31 July 2018 11:30 AM  
**To:** 'catherinechua@eurokars.com.sg'; Taufikh (LKKAuto)  
**Cc:** vion.lim@eurokars.com.sg; SUR  
**Subject:** RE: SLS3752B - FINALISATION OF COR

Dear Catherine,

WITHOUT PREJUDICE

Confirm final fig \$9,266.84 before GST and 9 repair days.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** catherinechua@eurokars.com.sg <catherinechua@eurokars.com.sg>  
**Sent:** Wednesday, 27 June 2018 2:59 PM  
**To:** Taufikh (LKKAuto) <taufikh@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Cc:** vion.lim@eurokars.com.sg  
**Subject:** FW: SLS3752B - FINALISATION OF COR

Dear Taufikh/Shiau Chan

This is a reminder for you to finalize the COR with us.

Our COR computation is attached again for easy reference.

Thanks n Regards  
Catherine Chua  
Insurance Claims Executive  
Trans Eurokars Pte Ltd  
DID: 6603 6121  
FAX: 6476 7417

*This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

---

**From:** Siew Guek Catherine Chua  
**Sent:** Wednesday, May 2, 2018 1:06 PM  
**To:** 'Taufikh (LKK Auto)' <taufikh@lkkauto.com>  
**Subject:** RE: SLS3752B - FINALISATION OF COR

Hi Taufikh

Here they are.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 4 January, 2018 1:30 PM  
**To:** Muhd Ashik B Madi; Taufikh (LKKAUTO)  
**Cc:** SUR  
**Subject:** RE: Motor Accident Claim: Ngian Teck Lan / SGR8989A / DOA 06.12.2017

Dear Ashik,

Based on the accident report and the inspection done, the damages are consistent to the accident.

The damages to the TP vehicle seen in the scene photographs correspond to the damage at the time of inspection.

*Wishes you a Happy New Year 2018*

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 27 December, 2017 9:18 AM  
**To:** Muhd Ashik B Madi <[ashik\\_madi@sg.msiga-asia.com](mailto:ashik_madi@sg.msiga-asia.com)>; Taufikh (LKKAUTO) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: Motor Accident Claim: Ngian Teck Lan / SGR8989A / DOA 06.12.2017

Dear Ashik,

Thank you for the email.

Dear Taufikh,

FYNA. Our ref: [CS/MSG17023813/T1qd3](#)

*Wishes you a Happy New Year 2018*

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Muhd Ashik B Madi [[mailto:ashik\\_madi@sg.msiga-asia.com](mailto:ashik_madi@sg.msiga-asia.com)]  
**Sent:** Tuesday, 26 December, 2017 5:32 PM  
**To:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** FW: Motor Accident Claim: Ngian Teck Lan / SGR8989A / DOA 06.12.2017



## Shiau Chan (LKKAUTO)

**From:** Muhd Ashik B Madi <ashik\_madi@sg.msig-asia.com>  
**Sent:** Tuesday, 26 December, 2017 5:32 PM  
**To:** Shiau Chan (LKKAUTO)  
**Cc:** SUR  
**Subject:** FW: Motor Accident Claim: Ngian Teck Lan / SGR8989A / DOA 06.12.2017

Dear Shiau Chan,

Enclosed the photos provided by our insured.

Please forward to the attending surveyor to check for consistency.

Kindly reduce on the parts & labour strenuously.

Thank you.

*Based on the accident report and the inspection done,  
the damages is consistent to the accident.*

Ashik Madi  
Executive, Claims Services (Motor)  
Direct line +65 6594 2548 | Direct fax +65 6225 7402 | [ashik\\_madi@sg.msig-asia.com](mailto:ashik_madi@sg.msig-asia.com)

*The damages to the TP vehicle seen in the scene*



Insurer Claims  
Team of the Year  
2016

*photographs corresponds  
to the damage at the time  
of inspection.*

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** L-J Insurance Agency [mailto:customerservice@lj.com.sg]  
**Sent:** Tuesday, 26 December, 2017 5:25 PM  
**To:** Muhd Ashik B Madi <ashik\_madi@sg.msig-asia.com>  
**Subject:** Motor Accident Claim: Ngian Teck Lan / SGR8989A / DOA 06.12.2017

Dear Ashik

Please find appended for your reference.

Thank you

Regards  
L-J Insurance Agency Pte Ltd

**From:** Levonne Chan [<mailto:levonnechan@gmail.com>]

**Sent:** Tuesday, 12 December, 2017 4:53 PM

**To:** [hilary@jealian.com.sg](mailto:hilary@jealian.com.sg)

**Subject:** RE: Mazda 5 damage images

Hi Hilary,


Please find attached images of the car crash on 6




Dec.









Cheers,  
Levonne

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 20 Dec 2017

## Preliminary Advice

Insured Vehicle No	: SGR8989S	Accident Date	: 06/12/2017
TP Vehicle No	: SLS3752B	Assignment Date	: 14/12/2017
Make	: MAZDA 5	Est. Duration of Repair	: 7.00
Date of Inspection	: 19/12/2017		
Inspection At	: TRANS EUROKARS PTE LTD NO. 5 UBI CLOSE, SINGAPORE SINGAPORE 408605		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,310.69
Revised Amount	:S\$	8,924.75
Check Items (Estimated)	:S\$	1,286.28
Total	:S\$	10,211.03

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/12/2017 13:33
Date Of Accident	06/12/2017 21:10
Exact Location Of Accident	CTE ALONG ANG MO KIO
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLS3752B
Insured/Policyholder	
Name Of Registered Owner	TEO ZHI MING BENJAMIN
NRIC No	S8706849H
Email Address	BENJAMINTEO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90239135
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	MAZDA
Model	5-2.0 5 DR WAGON (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700064126
Cover Note Number	
Driver	
Name of Driver	TEO ZHI MING BENJAMIN
NRIC No	S8706849H
Date Of Birth	20/03/1987
Occupation	INDOOR
Date Of Driving Pass	06/01/2014
Driving Experience	3 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90239135
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	BENJAMINTEO@GMAIL.COM

Address	BLK 361 YISHUN RING ROAD #03-1664
Postcode	760361
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGR8989S
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Trans Eurokars Pte Ltd  
5 Ubi Close  
Singapore 408663  
Tel: 6474 3043 / 6489 4333  
Fax: 6474 3043  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO: SL3752B

ACCIDENT DATE: 6 DECEMBER 2017

CONTACT NUMBER: 90239135

ACCIDENT TIME: ~~8:45~~ 2110 HRS

EMAIL: benjaminteo@gmail.com

LOCATION: CTE ALONG ANG MO KIO

I was travelling along CTE along Ang mo kio towards Tio Chu Keng exit. Traffic was slow on the left lane and I was following the traffic. Suddenly I was hit at the rear by another car (SGR8989S).

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE: ( ) CLAIM OWN POLICY ☒ CLAIM THIRD PARTY ( ) REPORTING ONLY

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**TRANS EUROKARS PTE LTD**  
**NO:5 UBI CLOSE, SINGAPORE 408605**  
**ESTIMATE COST OF REPAIRS**



MSIG INSURANCE SINGAPORE P/L 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 ATTN.: MOTOR CLAIMS FAX :		NAME : Mr Teo Zhi Ming Benjamin ADDRESS : 361 Yishun Ring Road #03-1664 Singapore 760361 TEL : 90239135		WIP : 49834 EXCESS : DATE: 8-Dec-17	
VEH NO :	SLS3752B	DATE IN :		CONTACT PERSON :	VION 6395 7877
CHASSIS NO :	JM6CW1071H0126225	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	21-Sep-17	POLICY NO. :	
<b>NATURE OF WORKS</b>					
<b>Parts Description</b>					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MC513-50-221EBB	de✓	\$ 915.40
2	RETAINER(LHS), REAR BUMPER	1	MC513-50-2J1C	X M	\$ 45.30
3	RETAINER(RHS), REAR BUMPER	1	MC513-50-2H1B	X M	\$ 45.30
4	BRACKET(LHS), REAR BUMPER	1	MC513-51-077A	X M	\$ 5.40
5	BRACKET(RHS), REAR BUMPER	1	MC513-51-067A	X M	\$ 5.40
6	GUARD(LHS), REFLECTOR	1	MC513-50-371	X M	\$ 20.50
7	REFLECTOR LHS	1	MD350-51-5L0E	X M	\$ 50.40
8	GUARD(RHS), REFLECTOR	1	MC513-50-361	X M	\$ 20.50
9	REFLECTOR RHS	1	MD350-51-5M0E	X M	\$ 50.40
10	REAR REINFORCEMENT	1	MC235-56-B9XC	? M	\$ 148.00
11	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	nei✓	\$ 6.00
12	RIVET, REAR BUMPER	4	MBN8F-50-355	nei✓	\$ 21.60
13	GROMMET, REAR BUMPER	1	M9991-00-501	nei✓	\$ 2.80
14	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	nei✓	\$ 10.00
15	GROMMET, REAR BUMPER	2	MC235-50-ES1	nei✓	\$ 8.80
16	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	nei✓	\$ 6.60
17	PANEL, REAR END	1	MCG15-70-750B	Z M	\$ 491.10
18	TAILGATE	1	MCGY3-62-02XF	bt✓	\$ 1,559.00
19	VALVE ONEWAY, TAILGATE	2	MGHP9-58-867	X M	\$ 22.80
20	WEATHERSTRIP, TAILGATE	1	MC513-62-761C	X M	\$ 169.00
21	TAPE PROTECTOR, TAILGATE	2	MBR55-56-994	nei✓	\$ 14.40
22	TAPE PROTECTOR, TAILGATE	2	MTK48-62-864	nei✓	\$ 14.00
23	TRIM LOWER, TAILGATE	1	MC513-68-960B	X M	\$ 411.40
24	LOCK, TAILGATE	1	MC513-62-310A	X M	\$ 244.00
25	MAZDA, EMBLEM	1	MCGY0-51-711	nei✓	\$ 43.10
26	S, EMBLEM	1	MCGY0-51-721	nei✓	\$ 34.50
27	SKYACTIV, EMBLEM	1	MC597-51-771	nei✓	\$ 76.10
28	MOULD, REAR WINDSCREEN	1	MC513-50-611	nei✓	\$ 57.60
29	FASTENER, REAR WINDSCREEN	2	MD204-50-896A	nei✓	\$ 5.20
30	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	nei✓	\$ 6.80

31	FASTENER, REAR WINDSCREEN	2	MC273-50-896	net	\$ 15.60
32	SPACER, REAR WINDSCREEN	4	MG16A-50-897	net	\$ 48.40
33	PIN, STUD, REAR WINDSCREEN	1	MG21E-63-938B	X n	\$ 10.50
34	PROTECTOR, REAR SPOILER	2	MC514-51-979B	X n	\$ 10.40
35	PROTECTOR, REAR SPOILER	2	MC514-51-982B	X n	\$ 22.80
36	PROTECTOR, REAR SPOILER	2	MC514-51-972B	X n	\$ 26.80
37	CLIP, REAR SPOILER	3	MC514-51-958A	net	\$ 21.90
38	CLIP, REAR SPOILER	1	MC525-51-958A	net	\$ 8.20
39	GASKET(LHS), TAILGATE LAMP	1	MC513-51-3J8	net	\$ 90.80
40	GASKET(RHS), TAILGATE LAMP	1	MC513-51-3H8	net	\$ 90.80
41	TRIM, BOOT END	1	MC513-68-89XD	X n	\$ 76.50
TOTAL PARTS					\$ 4,934.10
LESS 10%					\$ 493.41
TOTAL PARTS COST					\$ 4,440.69

Labour Description				
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	2520.	\$ 3,780.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. <i>* photo</i>	1800.	\$ 3,000.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	100.	\$ 350.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	120.	\$ 250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	315	\$ 630.00
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.	NETT	\$ 560.00
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NETT	\$ 120.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	315	\$ 630.00
9	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	315	\$ 630.00
10		TO SUPPLY EXHAUST TIP MUFFLER.	nm NETT X	\$ 150.00
11	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	nm NETT X	\$ 70.00
12	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.	\$ 250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180.	\$ 350.00

14	MZ-BR-SUNDRI	SUNDRIES. <i>Ken</i>	20.1 NETT	\$ 100.00
			TOTAL LABOUR	\$ - \$ 10,870.00
			TOTAL PARTS	\$ - \$ 4,440.69
			TOTAL	\$ - \$ 15,310.69
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:  
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD  
 THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF  
 REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING  
 CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED  
 WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED  
 ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS  
 PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

*Taufik 97495749*  
*WP*  
*19/12/17 R 1340.*  
*Resurvey before paint*  
*sur@lkkanto.com*  
*9 days.*  
*[Signature]*  
*5/1/18*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:





**TRANS EUROKARS PTE LTD**  
**NO:5 UBI CLOSE, SINGAPORE 408605**  
**FINALISED COST OF REPAIRS**



<b>MSIG INSURANCE SINGAPORE P/L</b> 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 <b>ATTN. :</b> MOTOR CLAIMS <b>FAX :</b>		<b>NAME :</b> Mr Teo Zhi Ming Benjamin <b>ADDRESS :</b> 361 Yishun Ring Road #03-1664 Singapore 760361 <b>TEL :</b> 90239135		<b>WIP :</b> 49834 <b>EXCESS :</b> <b>DATE:</b> 8-Dec-17	
<b>VEH NO :</b>	<b>SLS3752B</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	VION 6395 7877
<b>CHASSIS NO :</b>	JM6CW1071H0126225	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	THIRD PARTY CLAIM
<b>MODEL :</b>	MAZDA5	<b>DATE REG.:</b>	21-Sep-17	<b>POLICY NO. :</b>	
<b>NATURE OF WORKS</b>					
<b>Parts Description</b>					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MC513-50-221E8B	\$ 915.40	\$ 915.40
2	RETAINER(LHS), REAR BUMPER	1	MC513-50-2J1C		\$ 45.30
3	RETAINER(RHS), REAR BUMPER	1	MC513-50-2H1B		\$ 45.30
4	BRACKET(LHS), REAR BUMPER	1	MC513-51-077A		\$ 5.40
5	BRACKET(RHS), REAR BUMPER	1	MC513-51-067A		\$ 5.40
6	GUARD(LHS), REFLECTOR	1	MC513-50-371		\$ 20.50
7	REFLECTOR LHS	1	MD350-51-SLOE		\$ 50.40
8	GUARD(RHS), REFLECTOR	1	MC513-50-361		\$ 20.50
9	REFLECTOR RHS	1	MD350-51-5M0E		\$ 50.40
10	REAR REINFORCEMENT	1	MC235-56-B9XC		\$ 148.00
11	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	\$ 6.00	\$ 6.00
12	RIVET, REAR BUMPER	4	MBN8F-50-355	\$ 21.60	\$ 21.60
13	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80	\$ 2.80
14	GROMMET, REAR BUMPER	4	MBHN1-50-021A	\$ 10.00	\$ 10.00
15	GROMMET, REAR BUMPER	2	MC235-50-ES1	\$ 8.80	\$ 8.80
16	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	\$ 6.60	\$ 6.60
17	PANEL, REAR END	1	MCG15-70-750B		\$ 491.10
18	TAILGATE	1	MCGY3-62-02XF	\$ 1,559.00	\$ 1,559.00
19	VALVE ONEWAY, TAILGATE	2	MGHP9-58-867		\$ 22.80
20	WEATHERSTRIP, TAILGATE	1	MC513-62-761C		\$ 169.00
21	TAPE PROTECTOR, TAILGATE	2	MBR55-56-994	\$ 14.40	\$ 14.40
22	TAPE PROTECTOR, TAILGATE	2	MTK48-62-864	\$ 14.00	\$ 14.00
23	TRIM LOWER, TAILGATE	1	MC513-68-960B		\$ 411.40
24	LOCK, TAILGATE	1	MC513-62-310A		\$ 244.00
25	MAZDA, EMBLEM	1	MCGY0-51-711	\$ 43.10	\$ 43.10
26	S, EMBLEM	1	MCGY0-51-721	\$ 34.50	\$ 34.50
27	SKYACTIV, EMBLEM	1	MC597-51-771	\$ 76.10	\$ 76.10
28	MOULD, REAR WINDSCREEN	1	MC513-50-611	\$ 57.60	\$ 57.60
29	FASTENER, REAR WINDSCREEN	2	MD204-50-896A	\$ 5.20	\$ 5.20
30	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	\$ 6.80	\$ 6.80
31	FASTENER, REAR WINDSCREEN	2	MC273-50-896	\$ 15.60	\$ 15.60



32	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897	\$ 48.40	\$ 48.40
33	PIN,STUD, REAR WINDSCREEN	1	MG21E-63-9388		\$ 10.50
34	PROTECTOR, REAR SPOILER	2	MC514-51-979B		\$ 10.40
35	PROTECTOR, REAR SPOILER	2	MC514-51-982B		\$ 22.80
36	PROTECTOR, REAR SPOILER	2	MC514-51-972B		\$ 26.80
37	CLIP, REAR SPOILER	3	MC514-51-958A	\$ 21.90	\$ 21.90
38	CLIP, REAR SPOILER	1	MC525-51-958A	\$ 8.20	\$ 8.20
39	GASKET(LHS), TAILGATE LAMP	1	MC513-51-3J8	\$ 90.80	\$ 90.80
40	GASKET(RHS), TAILGATE LAMP	1	MC513-51-3H8	\$ 90.80	\$ 90.80
41	TRIM, BOOT END	1	MC513-68-89XD		\$ 76.50
TOTAL PARTS				\$ 3,057.60	\$ 4,934.10
LESS 10%				\$ 305.76	\$ 493.41
TOTAL PARTS COST				\$ 2,751.84	\$ 4,440.69
Labour Description					
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 2,520.00	\$ 3,780.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.		\$ 1,800.00	\$ 3,000.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		\$ 100.00	\$ 350.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 120.00	\$ 250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		\$ 315.00	\$ 630.00
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.		\$ 560.00	\$ 560.00
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.		\$ 120.00	\$ 120.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		\$ 315.00	\$ 630.00
9	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		\$ 315.00	\$ 630.00
10		TO SUPPLY EXHAUST TIP MUFFLER.			\$ 150.00
11	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.			\$ 70.00
12	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 150.00	\$ 250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 180.00	\$ 350.00
14	MZ-BR-SUNDRI	SUNDRIES.		\$ 20.00	\$ 100.00
TOTAL LABOUR				\$ 6,515.00	\$ 10,870.00

TOTAL PARTS	\$ 2,751.84	\$ 4,440.69
TOTAL	\$ 9,266.84	\$ 15,310.69
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ 9,266.84	
GST 7%	\$ 648.68	\$ -
GRAND TOTAL	\$ 9,915.52	\$ -

REMARKS: SLS3752B

11 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Dec 2017		14 Dec 2017 10:11 <a href="#">Edit Adj Rpt</a>	<b>S\$9,266.84</b> <a href="#">Edit Estimates</a>	<b>S\$9,266.84</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>NGIAN TECK LAN</b> , ID: S0211721E									
Main Claimant: <b>TEO ZHI MING BENJAMIN</b> , ID: S8706849H									
Vehicle Reg. No.: <b>SLS3752B</b>		Date of Loss: 06/12/2017 21:00 - :59 [2 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 539999</b>		Policy/Cover Note No.: A80405500QMY (Comprehensive) Coverage: 06/07/2017 - 05/07/2018							
Vehicle Reg. No. (Insured): <b>SGR8989S</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Trans Eurokars Pte Ltd ( )</b> NO. 5 UBI CLOSE, SINGAPORE, 408605 Ubi - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 13/01/2018]									
Driver/Custodian (Insured): <b>CHAN SEE MUN ( )</b> , NRIC: S9319588D, Tel: +6581020154									
Adj Asg. Remarks: Survey appt today, anytime after 3pm.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLS3752B (539999)  
[SGR8989S]**

**TP  
TEO ZHI MING BENJAMIN  
Dec 6 2017 9:00PM  
[NGIAN TECK LAN]  
Trans Eurokars Pte Ltd**

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	04/01/18 13:47	Video - Accident Third party video						Load MP4		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	08/12/17 13:51	Accident Statement From: SC - Reg. No: SGR8989S, Claimant: NGIAN TECK LAN						Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	20/12/17 14:21	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
2	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
3	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
4	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
5	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
6	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
7	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
8	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
9	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
10	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
11	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
12	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
13	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
14	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
15	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
16	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
17	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
18	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
19	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
20	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
21	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
22	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
23	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
24	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
25	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
26	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
27	31/07/18 11:28	General View						Load JPG	<input checked="" type="checkbox"/>	
28	31/07/18 11:28	Odometer Reading						Load JPG		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
29	31/07/18 11:28	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
30	31/07/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	31/07/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	31/07/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/12/17 13:51	SLS37528 E-FILE REPORT, POLICY, DL & IC From: SC - Reg. No: SGR89885, Claimant: NGIAN TECK LAN	Load PDF	
2	08/12/17 14:04	ESTIMATE	Load PDF	
3	08/12/17 15:08	Email to third party workshop for direct settlement	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023813/QD3Q2

Date: 03/08/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80405500QMY

Claimant Vehicle No : SLS3752B

Insured Vehicle No : SGR8989S

Date of Loss: 06/12/2017

Nature of Claim: TP

Claim No: 539999

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLS3752B

Make &amp; Model: MAZDA 5, 2.0 5 DR WAGON (A)

Engine No: PE10521541

Reg. Date: 21/09/2017 (Man. Year: 2017)

Chassis No: JM6CW1071H0126225

Colour: White

Odometer: 7255 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,760.69	2,771.84	1,988.85	41.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,550.00	6,495.00	4,055.00	38.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,310.69</b>	<b>9,266.84</b>	<b>6,043.85</b>	<b>39.47</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,071.75</b>	<b>648.68</b>	<b>423.07</b>	<b>39.47</b>
<b>Nett Amount (S\$)</b>	<b>16,382.44</b>	<b>9,915.52</b>	<b>6,466.92</b>	<b>39.47</b>

## INSPECTION

Date of Assignment: 14/12/2017

Date Inspected: 19/12/2017 Inspected At:

Trans Eurokars Pte Ltd  
NO. 5 UBI CLOSE, SINGAPORE  
Singapore 408605

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 02 Aug 2018)	
<b>Parts:</b>	N/A	MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLS3752B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	915.40 FL	*915.40 FL
2	1		*RETAINER (LHS),REAR BUMPER	Not Necessary	45.30 FL	*- FL
3	1		*RETAINER (RHS),REAR BUMPER	Not Necessary	45.30 FL	*- FL
4	1		*BRACKET (LHS),REAR BUMPER	Not Necessary	5.40 FL	*- FL
5	1		*BRACKET (RHS),REAR BUMPER	Not Necessary	5.40 FL	*- FL
6	1		*GUARD (LHS) ,REFLECTOR	Not Necessary	20.50 FL	*- FL
7	1		*REFLECTOR LHS	Not Necessary	50.40 FL	*- FL
8	1		*GUARD (RHS) ,REFLECTOR	Not Necessary	20.50 FL	*- FL
9	1		*REFLECTOR RHS	Not Necessary	50.40 FL	*- FL
10	1		*REAR REINFORCEMENT	Not Necessary	148.00 FL	*- FL
11	2		*FASTENER ,REAR BUMPER	Necessary	6.00 FL	*6.00 FL
12	4		*RIVET ,REAR BUMPER	Necessary	21.60 FL	*21.60 FL
13	1		*GROMMET ,REAR BUMPER	Necessary	2.80 FL	*2.80 FL
14	4		*GROMMET ,REAR BUMPER	Necessary	10.00 FL	*10.00 FL
15	2		*GROMMET ,REAR BUMPER	Necessary	8.80 FL	*8.80 FL
16	2		*TAPE PROTECTOR ,REAR BUMPER	Necessary	6.60 FL	*6.60 FL
17	1		*PANEL ,REAR END	Not Necessary	491.10 FL	*- FL
18	1		*TAILGATE	Bent	1,559.00 FL	*1,559.00 FL
19	2		*VALVE ONEWAY ,TAILGATE	Not Necessary	22.80 FL	*- FL
20	1		*WEATHERSTRIP ,TAILGATE	Not Necessary	169.00 FL	*- FL
21	2		*TAPE PROTECTOR,TAILGATE	Necessary	14.40 FL	*14.40 FL
22	2		*TAPE PROTECTOR,TAILGATE	Necessary	14.00 FL	*14.00 FL
23	1		*TRIM LOWER ,TAILGATE	Not Necessary	411.40 FL	*- FL
24	1		*LOCK ,TAILGATE	Not Necessary	244.00 FL	*- FL
25	1		*MAZDA ,EMBLEM	Necessary	43.10 FL	*43.10 FL
26	1		*5,EMBLEM	Necessary	34.50 FL	*34.50 FL
27	1		*SKYACTIV ,EMBLEM	Necessary	76.10 FL	*76.10 FL
28	1		*MOULD ,REAR WINDSCREEN	Necessary	57.60 FL	*57.60 FL
29	2		*FASTENER ,REAR WINDSCREEN	Necessary	5.20 FL	*5.20 FL
30	1		*SPACER ,REAR WINDSCREEN	Necessary	6.80 FL	*6.80 FL
31	2		*FASTENER ,REAR WINDSCREEN	Necessary	15.60 FL	*15.60 FL
32	4		*SPACER ,REAR WINDSCREEN	Necessary	48.40 FL	*48.40 FL
33	1		*PIN ,STUD ,REAR WINDSCREEN	Not Necessary	10.50 FL	*- FL
34	2		*PROTECTOR ,REAR SPOILER	Not Necessary	10.40 FL	*- FL
35	2		*PROTECTOR ,REAR SPOILER	Not Necessary	22.80 FL	*- FL
36	2		*PROTECTOR ,REAR SPOILER	Not Necessary	26.80 FL	*- FL
37	3		*CLIP ,REAR SPOILER	Necessary	21.90 FL	*21.90 FL
38	1		*CLIP ,REAR SPOILER	Necessary	8.20 FL	*8.20 FL
39	1		*GASKET (LHS),TAILGATE LAMP	Necessary	90.80 FL	*90.80 FL

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*GASKET (RHS),TAILGATE LAMP	Necessary	90.80 FL	*90.80 FL
41	1		*TRIM ,BOOT END	Not Necessary	76.50 FL	*- FL
42	1		*EXHAUST TIP MUFFLER	Not Necessary	150.00 FS	*- FS
43	1		*NUMBER PLATE	Not Necessary	70.00 FS	*- FS
44	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,254.10</b>	<b>3,077.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>493.41</b>	<b>305.76</b>
<b>Total Parts (\$\$)</b>	<b>4,760.69</b>	<b>2,771.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPE ,REAR REINFORCEMENT ,REAR END PANEL AND TAILGATE ,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	3,780.00	2,520.00
2	TO RESPRAY REAR BUMPER,REAR REINFORCEMENT ,REAR END PANEL AND TAILGATE	New	3,000.00	1,800.00
3	TO SUPPLY SPARAY TEROSTAT SEALANT ON THE CUTTING	New	350.00	100.00
4	TO CARRY -OUT BODY CAVITY PRESERVATION	New	250.00	120.00
5	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	630.00	315.00
6	TO REMOVE & REFIT THE WINDSCREEN GLASS	New	560.00	560.00
7	TO SUPPLY SEALER ON THE WINDSCREEN GLASS	New	120.00	120.00
8	TO TRANSFER REVERSE CAMERA	New	630.00	315.00
9	TO TRANSFER REVERSE SENSORS	New	630.00	315.00
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,550.00</b>	<b>6,495.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >