

22/03/2002

ASS. REC. BY:

REF: CS/CTI17023814/Ggd302

Special Instruction:

Surveyor:
Menmen

GO

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

14/12/17 @ 6:00pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 9433E

Insured:

GX 2344K

at Workshop m/s

TransEurokars

Tel:

6395 7874

of

5 Ubi Close

Policy No:

DMCVSN3041611701

Claim No:

SNM17D07 064C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/12/17

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:30am @ 15/11/17

Person Contacted:

JERS

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SLJ 9433E - X

GX 2344K - CS/LAWOR0006435/Vin

D.O.A: 30/04/2027

24/5/18 @

10:20am Catherine Chea informed that the owner consent to 2D claim

25/5/18

Submit Preli. report.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Dec 2017		14 Dec 2017 18:00 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)
CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	TOH YEW EIK, ID: S7706822H		
Vehicle Reg. No.:	SLJ9433E	Date of Loss:	11/12/2017 19:00 - :59
Claim Type:	TP / SNM17D07064C02	Policy/Cover Note No.:	DMCVSN3041611701
Vehicle Reg. No. (Insured):	GX2344K	Policy No. (Claimant):	2100495577
		Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hul Ping - 638986192]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/12/2017]		
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED
[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17023814/Gqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 15-12-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 2344K	Veh. Inspected	SLJ 9433E
Policy No.	DMCVSN3041611701	Coverage (\$)	0.00
Claim No.	SNM17D07064C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	15/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Engine No.	HIDDEN	Accident Date	11/12/2017	Inspection Date	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605				

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 14 December, 2017 5:44 PM
To: jess.francis@eurokars.com.sg; assignments@lkkauto.com
Cc: eric.pau@eurokars.com.sg; ronald.yap@eurokars.com.sg;
kevin.lee@eurokars.com.sg; admin-d@lkkauto.com; assignments@lkkauto.com
Subject: CTP REF NO. GX2344K E REF NO. SLJ9433E - ACCIDENT INVOLVING GX2344K AND
SLJ9433E ON 11 DECEMBER 2017

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and the email below.

Please assist to get your surveyor, Marcus Chua to liaise with Trans Eurokas.

Regards

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: jess.francis@eurokars.com.sg [mailto:jess.francis@eurokars.com.sg]
Sent: Thursday, 14 December, 2017 4:55 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Cc: eric.pau@eurokars.com.sg; ronald.yap@eurokars.com.sg; kevin.lee@eurokars.com.sg; admin-d@lkkauto.com
Subject: RE: CTP REF NO. GX2344K E REF NO. SLJ9433E - ACCIDENT INVOLVING GX2344K AND SLJ9433E ON 11
DECEMBER 2017

Hi Ms Irene,

Referring to your email below.

We choose Marcus Chua for this case.

Kindly do the necessary arrangement.

Regards.

Jess Francis Carlos
Insurance Claim Executive
TRANS EUROKARS PTE LTD
5 Ubi Close
Singapore 408605

DID: 465 63957874

From: Irene Tay [<mailto:irene.tay@sg.cntaiping.com>]

Sent: Wednesday, December 13, 2017 12:17 PM

To: Eric Pau <eric.pau@eurokars.com.sg>

Subject: CTP REF NO. GX2344K E REF NO. SLJ9433E - ACCIDENT INVOLVING GX2344K AND SLJ9433E ON 11 DECEMBER 2017

Without Prejudice

Save As To Costs

Dear Sir/Mdm,

We refer to your pre-repair survey request / email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

Here are the list of surveyors :

**Tay Beng Hee
See Chew Seng
Dereck Oh Siong Wee
Kalvin Ang
Bryan Ang
Steven Foong
Adrian Ling
Marcus Chua **
Kenneth Kong
Henry Ng**

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAuto)

From: catherinechua@eurokars.com.sg
Sent: Thursday, 24 May 2018 10:20 AM
To: Shiau Chan (LKKAuto); jess.francis@eurokars.com.sg; Admin-D (LKKAuto);
jessicahs@eurokars.com.sg
Cc: SUR
Subject: RE: YOUR REF: GX2344K / OUR REF: SLJ9433E THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Shiau Chan

Customer had reverted to OD claim with AIG.

Thanks n Regards
Catherine Chua
Insurance Claims Executive
Trans Eurokars Pte Ltd
DID: 6603 6121
FAX: 6476 7417

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, May 22, 2018 4:03 PM
To: Jess Francis <jess.francis@eurokars.com.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Siew Guek Catherine Chua <catherinechua@eurokars.com.sg>; Jessica Harry Shastri <jessicahs@eurokars.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: YOUR REF: GX2344K / OUR REF: SLJ9433E THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Jess,

Kindly provide us the final bill for finalise.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jess.francis@eurokars.com.sg [mailto:jess.francis@eurokars.com.sg]
Sent: Friday, 15 December 2017 4:32 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: FW: YOUR REF: GX2344K / OUR REF: SLJ9433E THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Hi Catherine,

Refer to the docs.

MTE117163343 / Trans Eurokars Pte Ltd - Sungei Kadut
ENTRY DATE & TIME: 12/12/2017 13:30

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2017 13:30
Date Of Accident	11/12/2017 19:15
Exact Location Of Accident	ALONG TPE NEAR EXIT ELIAS ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ9433E
Insured/Policyholder	
Name Of Registered Owner	TOH YEW EIK
NRIC No	S7706822H
Email Address	YEWEIK77@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91902655
Alternative Phone No	Others-91902655
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA 2 SEDAN
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100495577
Cover Note Number	
Driver	
Name of Driver	TOH YEW EIK
NRIC No	S7706822H
Date Of Birth	12/03/1977
Occupation	INDOOR
Date Of Driving Pass	22/02/2010
Driving Experience	7 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91902655
Fax Number	

Contact Number	OTHERS-91902655
E-Mail Address	YEWEIK77@GMAIL.COM
Address	BLK 120C RIVERVALE DRIVE #13-402
Postcode	543120
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX2344K
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	OI ZHI SHENG
NRIC/Passport Number	
Contact Number	97518359
Address	
Postcode	
Insurance Company Name	China Taiping Insurance (Singapore) Pte. Ltd.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false report(s) may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared /disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

R/R/A




Reporting Person's Signature
Name:
NRIC/FIN No.:

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 11/12/2017 at about 7:15pm, I was driving along TPE near the exit of Elias road in the 2nd lane. It was raining. When I saw the car in front of me ~~braked~~ braked, I stop my car. When I was behind the front car. When I saw the car in front of me started moving, I started moving my car. It was at this moment when a van behind my car hit the rear of my car. After the accident, I slowly drove my car to the shoulder of the road.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Company's Signature
 Name:
 NRIC/FIN No.:

12/12/17



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



CHINA TAIPING INSURANCE P/L		NAME : Mr Toh Yew Eik		WIP : 50695	
3 ANSON ROAD		ADDRESS : Blk 120c Rivervale Drive		EXCESS :	
#16-00 SPRINGLEAF TOWER		#13-402		DATE: 13-Dec-17	
SINGAPORE 079909		Singapore 543120			
ATTN : MOTOR CLAIMS		TEL : 91902655			
FAX :					
VEH NO :	SLJ9433E	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	MM6DL2SAAGW186215	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA2	DATE REG.:	30-Dec-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER / <i>RL</i>	1	MDB7A-50-221B8B \$ 909.00
2	RFTAINFR(I HS), RFAR BUMPFER / <i>MCL</i>	1	MDB7A-50-2J1 \$ 21.70
3	RETAINER(RHS), REAR BUMPER X <i>NN</i>	1	MDB7A-50-2H1 \$ 21.70
4	BRACKET LOWER, REAR BUMPER / <i>MCL</i>	1	MDB7H-50-251 \$ 23.20
5	BRACKET CENTER, REAR BUMPER / <i>MCL</i>	1	MKD53-50-251 \$ 5.10
6	STAY, REAR BUMPER / <i>MCL</i>	2	MDB7A-50-271 \$ 24.60
7	REFLECTOR LHS X <i>NN</i>	1	MD350-51-5L0E \$ 50.40
8	REFLECTOR RHS X <i>NN</i>	1	MD350-51-5M0E \$ 50.40
9	TAPE PROTECTOR, REAR BUMPER / <i>MCL</i>	3	MG51D-50-EM1A \$ 24.30
10	FASTENER, REAR BUMPER / <i>MCL</i>	7	MB45A-56-146A \$ 19.60
11	CLIP, REAR BUMPER / <i>MCL</i>	1	MGJ21-50-049 \$ 3.20
12	GROMMET, REAR BUMPER / <i>MCL</i>	1	M9991-00-501 \$ 2.80
13	GROMMET, REAR BUMPER / <i>MCL</i>	4	MBHN1-50-0Z1A \$ 10.00
14	PANEL, REAR END ?	1	MDBYA-70-75Z \$ 624.70
15	BOOT LID / <i>MCL</i>	1	MDAY0-52-61X \$ 820.70
16	HINGE(LHS), BOOT LID ?	1	MDB7A-52-720A \$ 118.00
17	HINGE(RHS), BOOT LID ?	1	MDB7A-52-710A \$ 110.00
18	WEATHERSTRIP, BOOT LID ?	1	MDB7A-56-951 \$ 107.50
19	LOCK, BOOT LID ?	1	MDB7A-56-820A \$ 181.80
20	GASKET(LHS), TAILLAMP / <i>MCL</i>	1	MDB7A-51-163 \$ 31.90
21	GASKET(RHS), TAILLAMP / <i>MCL</i>	1	MDB7A-51-153 \$ 31.90
22	LHS TAILLAMP ?	1	MDB7A-51-160A \$ 376.40
23	RHS TAILLAMP ?	1	MDB7A-51-150A \$ 376.40
24	FASTENER, TAILLAMP / <i>MCL</i>	2	MKD53-51-146B \$ 7.80
25	GROMMET, TAILLAMP / <i>MCL</i>	2	MGJ6A-51-14Y \$ 29.80
26	GASKET(LHS), BOOT LID LAMP / <i>MCL</i>	1	MDB7A-51-3J8 \$ 46.20
27	GASKET(RHS), BOOT LID LAMP / <i>MCL</i>	1	MDB7A-51-3H8 \$ 46.20
28	LHS BOOT LID LAMP ?	1	MDB7A-51-3G0B \$ 198.20
29	RHS BOOT LID LAMP ?	1	MDB7A-51-3F0B \$ 198.10
30	GROMMET, BOOT LID LAMP / <i>MCL</i>	2	MGA7B-51-146 \$ 6.20

31	CLIP, ANTENNA ?	2	MKD45-67-6NYA		\$ 5.00
32	TRIM, BOOT END ?	1	MDB7G-68-89X 02		\$ 54.80
33	BEZEL, LOCK ?	1	MDB7G-68-894 02		\$ 5.40
34	TRIM(LHS), BOOT ?	1	MDB7G-68-870C02		\$ 173.80
35	TRIM(RHS), BOOT ?	1	MDB7G-68-850C02		\$ 173.00
36	MAT, SPARE TYRE ?	1	MDB7G-68-81X 04		\$ 278.30
37	TOOLS TRAY ?	1	MDB7G-68-831		\$ 156.00
38	ANTENNA, KEYLESS ?	1	MKD47-67-6NXA		\$ 105.80
				TOTAL PARTS	\$ 5,429.90
				LESS 10%	\$ 542.99
				TOTAL PARTS COST	\$ 4,886.91

Labour Description

1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1890-2520	\$ 3,150.00
2	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	2100	\$ 2,400.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	150	\$ 350.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	315	\$ 630.00
6	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	315	\$ 630.00
7	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	315	\$ 630.00
8	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NETT ?	\$ 70.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
11	MZ-BR-SUNDRI	SUNDRIES.	30	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 8,810.00
TOTAL PARTS	\$ -	\$ 4,886.91
TOTAL	\$ -	\$ 13,696.91
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

7 - 8 Days.

before paint photos.

Guo Qiang - 82880282

15/12/17


19/12/2017.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Dec 2017		14 Dec 2017 18:00 Edit Adj Rpt	S\$8,082.78 Edit Estimates	S\$8,082.78 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	TOH YEW EIK, ID: S7706822H								
Vehicle Reg. No.:	SLJ9433E	Date of Loss:	11/12/2017 19:00 - :59 [11 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM17D07064C02	Policy/Cover Note No.:	DMCVSN3041611701						
Vehicle Reg. No. (Insured):	GX2344K	Policy No. (Claimant):	2100495577						
		Excess:	S\$0.00						
Repairer:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/12/2017]								
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION								
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All	Search Tasks						
		Create New Task	Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ9433E (SNM17D07064C02)
 [GX2344K]
 TP
 TOH YEW EIK
 Dec 11 2017 7:00PM
 [-]
 Trans Eurokars Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page v <input checked="" type="checkbox"/>	
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	12/12/17 13:44	Video - Accident [Linked Accident Report Documents]	Load MP4	<input type="checkbox"/>
2	12/12/17 13:44	Video - Accident [Linked Accident Report Documents]	Load MP4	<input type="checkbox"/>
Assessment Reports			1 per page v <input checked="" type="checkbox"/>	
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	12/12/17 13:49	Accident Statement	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page v <input checked="" type="checkbox"/>	
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	12/12/17 13:47	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	12/12/17 13:47	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	12/12/17 13:47	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	12/12/17 13:47	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	12/12/17 13:47	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	24/05/18 17:46	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
22	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
23	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
24	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
25	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
26	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
27	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
28	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
29	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
30	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
31	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
32	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
33	24/05/18 17:46	General View	Load JPG	<input checked="" type="checkbox"/>
34	24/05/18 17:46	Chassis Number	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/12/17 18:00	EMAIL FROM TE(1)	Load PDF	
2	14/12/17 18:00	EMAIL FROM TE(2)	Load PDF	

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	12/12/17 13:38	Sketch Plan <small>[Linked Accident Report Documents]</small>	Load TIF	

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	12/12/17 13:44	Video - Accident	Load MP4	
2	12/12/17 13:44	Video - Accident	Load MP4	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	12/12/17 13:49	Accident Statement	Load HTM	
2	02/01/18 14:35	Addendum Sheet	Load TIF	
3	02/01/18 14:36	Accident Statement Addm. #1	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	12/12/17 13:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	12/12/17 13:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	12/12/17 13:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	12/12/17 13:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	12/12/17 13:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	12/12/17 13:38	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117023814/GQD3E2

Date: 30/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN3041611701	
Claimant Vehicle No: SLJ9433E	Insured Vehicle No: GX2344K	
Date of Loss: 11/12/2017	Nature of Claim: TP	Claim No: SNM17D07064C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ9433E	Engine No: P520341601
Make & Model: MAZDA 3, 1.5 SEDAN (A)	Chassis No: MM6DL2SAAGW186215
Reg. Date: 30/12/2016 (Man. Year: 2016)	Odometer: 15474 km
Colour: Blue	
Engine Capacity: 1496 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,986.91	1,887.78	3,099.13	62.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,710.00	6,195.00	2,515.00	28.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,696.91	8,082.78	5,614.13	40.99
+ GST 7.00/7.00% (S\$)	958.78	565.79	392.99	40.99
Nett Amount (S\$)	14,655.69	8,648.57	6,007.12	40.99

INSPECTION

Date of Assignment:	14/12/2017	
Date Inspected:	15/12/2017	Inspected At: TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605
Estimated Period of Repair:	8.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$2,988.88 NETT)

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 May 2018)
Parts: 143 MAZDA 3 1.5 SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLJ9433E)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	909.00 FL	*909.00 FL
2	1		*RETAINER (LHS), REAR BUMPER	Necessary	21.70 FL	*21.70 FL
3	1		*RETAINER (RHS), REAR BUMPER	Not Necessary	21.70 FL	*- FL
4	1		*BRACKET LOWER,REAR BUMPER	Necessary	23.20 FL	*23.20 FL
5	1		*BRACKET CENTER, REAR BUMPER	Necessary	5.10 FL	*5.10 FL
6	2		*STAY, REAR BUMPER	Necessary	24.60 FL	*24.60 FL
7	1		*REFLECTOR LHS	Not Necessary	50.40 FL	*- FL
8	1		*REFLECTOR RHS	Not Necessary	50.40 FL	*- FL
9	3		*TAPE PROTECTOR, REAR BUMPER	Necessary	24.30 FL	*24.30 FL
10	7		*FASTENER, REAR BUMPER	Necessary	19.60 FL	*19.60 FL
11	1		*CLIP, REAR BUMPER	Necessary	3.20 FL	*3.20 FL
12	1		*GROMMET, REAR BUMPER	Necessary	2.80 FL	*2.80 FL
13	4		*GROMMET, REAR BUMPER	Necessary	10.00 FL	*10.00 FL
14	1		*PANEL, REAR END	* Check	624.70 FL	*- FL
15	1		*BOOT LID	Buckled	820.70 FL	*820.70 FL
16	1		*HINGE (LHS), BOOT LID	* Check	118.00 FL	*- FL
17	1		*HINGE (RHS), BOOT LID	* Check	110.00 FL	*- FL
18	1		*WEATHERSTRIP, BOOT LID	* Check	107.50 FL	*- FL
19	1		*LOCK, BOOT LID	* Check	181.80 FL	*- FL
20	1		*GASKET (LHS), TAILLAMP	Necessary	31.90 FL	*31.90 FL
21	1		*GASKET (RHS), TAILLAMP	Necessary	31.90 FL	*31.90 FL
22	1		*LHS TAILLAMP	* Check	376.40 FL	*- FL
23	1		*RHS TAILLAMP	* Check	376.40 FL	*- FL
24	2		*FASTENER, TAILLAMP	Necessary	7.80 FL	*7.80 FL
25	2		*GROMMET, TAILLAMP	Necessary	29.80 FL	*29.80 FL
26	1		*GASKET (LHS), BOOT LID LAMP	Necessary	46.20 FL	*46.20 FL
27	1		*GASKET (RHS), BOOT LID LAMP	Necessary	46.20 FL	*46.20 FL
28	1		*LHS BOOT LID LAMP	* Check	198.20 FL	*- FL
29	1		*RHS BOOT LID LAMP	* Check	198.10 FL	*- FL
30	2		*GROMMET, BOOT LID LAMP	Necessary	6.20 FL	*6.20 FL
31	2		*CLIP, ANTENNA	* Check	5.00 FL	*- FL
32	1		*TRIM, BOOT END	* Check	54.80 FL	*- FL
33	1		*BEZEL, LOCK	* Check	5.40 FL	*- FL
34	1		*TRIM (LHS), BOOT	* Check	173.80 FL	*- FL
35	1		*TRIM (RHS), BOOT	* Check	173.00 FL	*- FL
36	1		*MAT, SPARE TYRE	* Check	278.30 FL	*- FL
37	1		*TOOLS TRAY	* Check	156.00 FL	*- FL
38	1		*ANTENNA, KEYLESS	* Check	105.80 FL	*- FL
39	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					5,529.90	2,094.20
- List Item Discount on L Items 10.00/10.00% (S\$)					542.99	206.42
Total Parts (S\$)					4,986.91	1,887.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	3,150.00	2,520.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID	New	2,400.00	2,100.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	New	350.00	150.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
5	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	630.00	315.00
6	TO TRANSFER REVERSE CAMERA	New	630.00	315.00
7	TO TRANSFER REVERSE SENSORS	New	630.00	315.00
8	TO SUPPLY NUMBER PLATE (* Check)	New	70.00	0.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (\$\$)			8,710.00	6,195.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >