



Your Ref : CLMOMVC000001956

Date: 26th December 2017

Our Ref : CS/GA117023815/Uqbs2

M/s Great American Insurance Company

3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GU 7682S
ACCIDENT ON 14/12/2017**

Instruction was received to inspect the vehicle Reg. No. GU 7682S. The inspection was conducted on 18/12/2017 at the premises of M/s Hock Wah Motor Workshop Pte Ltd, 3011 Bedok Industrial Park E #01-2008 Singapore 489977.

The following vehicle information was recorded:

Registration Number	: GU 7682S
Make/Model	: Mercedes Benz VITO
Year of Registration	: 2000
Body Colour	: White
Chassis Number	: VSA63809423293876
Engine Capacity	: 2151cc
Speedometer Reading	: Burnt

The vehicle caught fire. (Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as "**Total Loss**".

Market Value	S\$ 22,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 20,957.00)
Nett Liability	<u>S\$ 1,043.00</u>

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K. LAU CPT (RET)
BEng(Hons), B.Bus, MBA, PEng(UK), PE(USA),
MASME(USA), MInstAEA(UK), MIRTE, MCI Arb
REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.