

ASS. REC. BY:

REF: CS/FCI17023817/R1rd3n2

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

CWS

From (Person): Serene Ter

of FCI

Date/Time: 8:20am @ 15/12/17

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKF 2227M

Insured: SHA 1959 C

at Workshop m/s: Progressive

Tel: 6741 5336

of Blk 3022A Ubi Road 1 # 01-45/46

Policy No:

Claim No: D170 11517 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 8:57am @ 15/12/17

Person Contacted:

Pei Wen

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKF 2227M - X
	SHA 1959C - CC3/AIG17014248/K1eb3s2 D.O.A: 20/07/2017
	sent preli through email



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023817/R1rd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 15-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1959C	Veh. Inspected	SKF 2227M
Policy No.		Coverage (\$)	0.00
Claim No.	D17011517MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	15/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/12/2017	Inspection Date
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	14-12-2017	Our Ref No.	D17011517MFSH
Accident Date	14-12-2017	Claim Type.	Third Party
Insured Vehicle	SHA1959C	Third Party Vehicle.	SKF2227M
Survey Location	BLK 3022A UBI ROAD 1 #01-45/46		
Contact Person.	PEIWEN		
Contact No.	67415336/ 0	Fax No.	67417208
Survey Type	DIRECT SETTLEMENT: EST. COR - \$1,704.63		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE AUTOMOTIVE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SERENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011517MFSH

Our Ref: CS/FCI17023817/R1rd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKF 2227M.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/12/2018 at the premises of M/s PROGRESSIVE AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 1,593.11 .
Revised Estimate Amount	: S\$ 938.16 .
"Check" Items Amount	: S\$.
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at o/s front portion.



Yours faithfully
RASUL
Automotive Assessor

PROGRESSIVE AUTOMOTIVE PTE LTD

Bik 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : U-MING MARINE TRANSPORT (SINGAPORE)
 5 LITTLE ROAD #08-01 CEMTEX BUILDING
 SINGAPORE 536983

ATTN: FIRST CAPITAL INSURANCE

Your Ref No: TP 1217-4875
 Claim Type: Third Party
 Accident Date: 14/12/2017
 TP Veh Reg No: SHA 1959 C

Estimate No: EST1503084
Date: 14 Dec 2017
Policy No: A27879923 MCY
Veh Reg No: SKF2227M
Make/Model: TOYOTA CAMRY 2.5
 AUTO
Chassis No: MR053AK5004000145
Engine No: 2AR0634269
Reg. Date: 09/05/2012

Estimate Repair Cost to Vehicle No :SKF2227M

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 SIDE MIRROR - RH	685.40	1 PC	685.40	850 ✓
2 SIDE MIRROR OUTER COVER - RH	72.14	1 PC	72.14	80 ✓
3 FRONT DOOR GLASS - RH	359.80	1 PC	359.80	2 ✓
4 FRONT DOOR OUTER CHROME MOULDING	140.14	1 PC	140.14	100 ✓
			1,257.48	
		Less 25%	314.37	943.11
Labour				
5 TO KNOCK OUT DENTS, RH FRONT DOOR, REMOVE, REPLACE ACCIDENT PARTS	250.00	1 JOB	250.00	150
6 TO RESPRAY PAINT ON ACCIDENT PORTIONS	300.00	1 JOB	300.00	200
7 TO CHECK WIRING	20.00	1 JOB	20.00	✓
8 TO REMOVE, REPLACE RH FRONT DOOR GLASS	80.00	1 JOB	80.00	100 ✓
			650.00	650.00
			Total	SS 1,593.11
			Add GST @ 7%	111.52
			Total Amount Payable	SS 1,704.63

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SEVEN HUNDRED AND FOUR AND CENTS SIXTY THREE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Rasul
 Hp 90010068
 3 days
 p/p

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

15/12/17 P 1600

Repay by bank

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023817/R1rd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-03-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1959C	Veh. Inspected	SKF 2227M	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011517MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	15/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY 2.5 A	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	MR053AK5004000145	Colour	BLACK	
Odometer	117023	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/12/2017	Inspection Date	15/12/2017	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 2227M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SIDE MIRROR-RH	BROKEN	685.40	685.40
1	SIDE MIRROR OUTER COVER-RH	SCRATCHED	72.14	72.14
1	FRONT DOOR GLASS-RH	TO REPAIR SEE LABOUR	359.80	-
1	FRONT DOOR OUTER CHROME MOULDING	SERVICEABLE	140.14	-
	LESS 25% DISCOUNT		-314.37	-189.38
			943.11	568.16
LABOUR				
	TO KNOCK OUT DENTS,RH FRONT DOOR,REMOVE,REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR GLASS-RH.		250.00	150.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		300.00	200.00
	TO CHECK WIRING.		20.00	20.00
	TO REMOVE,REPLACE RH FRONT DOOR GLASS.	NOT NECESSARY	80.00	-
			650.00	370.00
GRAND TOTAL			1,593.11	938.16
RECOMMENDED COST OF REPAIRS				938.16

Report Ref No. CS/FCI17023817/R1rd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.