

ASS. REC. BY:

REF: CS/MSG17023818/Avd312

Special Instruction:

Surveyor:  
merimen

Adnan

ASSIGNMENT (Office)

From (Person): Catherine Thia

of

MSG

Date/Time: 15/12/17 @ 10:12am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJA2969T

Insured:

SLT 45Z

at Workshop m/s

8K Automobile

Tel:

6789 5155

of

23 kaki Bukit Ave 4, #03-01, 415933

Policy No:

A29025980MPQ

Claim No:

540620

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/12/2017

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time: 10:25am 015/12/17

Person Contacted:

Huey Lee

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SJA2969T - NBA/EQT17023738/Y	D.O.A: 12/12/2017
	SLT45Z - NBA/EQT17023738/Y	D.O.A: 12/12/2017
12/12/17	Informed Catherine pending est from repaire by merimen	
15/8/18	Adrian confirmed LS \$ 1050 (Red 11, 215.93, 91/1)	
15/8/18	Send preli revised via merimen	

Case No.

REF: MSIG

# ASSIGNMENT

From: \_\_\_\_\_ Date: 15/12/17

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJA 2969T

at Workshop m/s Sk Automobile

of 23 kaki Bukit Ave 4 # 03-01

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SJA 2969T. Yr Regn: 12 07

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis. cc 1598

Colour: Silver. A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRO53ZEC 107 152767

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195/55R15

R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 15/12/17

Survey held at Sk

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TP ms/G.

RECEIVED 16 AUG 2018

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2) 16/8 - typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RE - SI

Photo

Others

Report Format: mer, men

Lump Sum / I.B.I: (S 1050/-)

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Weekend (\$

TOTAL

300

10

310

*[Signature]*  
15/8/2018

## Survey Department Check List (Case Handler)

Reference No. : CS/MSG 17023818/Avd3  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

### (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

### (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

### (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

### (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

### (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 15/8/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17023818/Avd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-12-2017



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLT 45Z	Veh. Inspected	SJA 2969T
Policy No.	A29025980MPQ	Coverage (\$)	0.00
Claim No.	540620	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	15/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	12/12/2017	Inspection Date	15/12/2017
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 15 Aug 2018

**Preliminary Advice**

Insured Vehicle No	: SLT45Z	Accident Date	: 12/12/2017
TP Vehicle No	: SJA2969T	Assignment Date	: 15/12/2017
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 3.00
Date of Inspection	: 15/12/2017		
Inspection At	: SK AUTOMOBILE PTE LTD (HQ) 23 KAKI BUKIT AVENUE 4, #03-01 VICOM INSPECTION CENTRE SINGAPORE 415933		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,265.93
Revised Amount	:S\$	1,050.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,050.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is economical/not economical for repair.

( x ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017		15 Dec 2017 10:12 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SO CHOI CHU, ID: S2613552D		
Main Claimant:	TAJUDDIN BIN GULAM MOHAMAD, ID: S1397437C		
Vehicle Reg. No.:	SJA2969T	Date of Loss:	12/12/2017 02:00 - :59
Claim Type:	TP / 540620	Policy/Cover Note No.:	A29025980MPQ (Comprehensive) Coverage: 22/09/2017 - 21/09/2018
Vehicle Reg. No. (Insured):	SLT45Z	Policy No. (Claimant):	
		Excess:	
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/12/2017]		
Driver/Custodian (Insured):	CHAN MAN WAI (), NRIC: S7570809B, Tel: +6587161313		
Adj Asg. Remarks:	Please assign to Adrian Ling		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Sent Message

This mail is associated with :

**\*SJA2969T (540620)**

**[SLT45Z]**

TP

TAJUDDIN BIN GULAM MOHAMAD

Dec 12 2017 2:00AM

[SO CHOI CHU]

SK Automobile Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **18/12/2017 16:21 PM.**

**To** MSI\_TSY

**Subject** TP SURVEY SJA 2969T

Dear Catherine,

Please be informed that we have inspected the vehicle SJA 2969T on 15/12/2017.

We are pending estimate from repairer.

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.



**Nur Amirah Binte Mohamed Yunos**

---

**From:** Tan Jin Hao  
**Sent:** Thursday, December 14, 2017 4:14 PM  
**To:** Nur Amirah Binte Mohamed Yunos  
**Subject:** FW: Arrange surveyor for SJA2969T Your Ref:SLT45Z  
**Attachments:** SJA2969T GIA.PDF; SJA2969T ARRANGE.pdf

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

---

**From:** Agnes Lee  
**Sent:** Thursday, December 14, 2017 3:39 PM  
**To:** Woon Choo Kwok <WoonChoo\_Kwok@sg.msig-asia.com>  
**Subject:** FW: Arrange surveyor for SJA2969T Your Ref:SLT45Z

**From:** SK Admin [mailto:admin@skauto.com.sg]  
**Sent:** 14 December 2017 14:51  
**To:** Claims <claims@sg.msig-asia.com>  
**Cc:** JING XIONG KHOO <xiongskauto@gmail.com>  
**Subject:** Arrange surveyor for SJA2969T Your Ref:SLT45Z

Dear Sir / Mdm,

We the repairers of motor vehicle no. SJA2969T  
Please provide a list of surveyor for further inspection.

Location : 8 Kaki Bukit Ave 4#08-46  
Premier @ Kaki Bukit  
Singapore 415875

Contact No : 8121 0478 Xiong

We appreciate your early reply.  
Thanks.

--  
Regards,  
Huey Lee  
SK Automobile Pte Ltd  
Tel: 6789 5155 Fax: 6783 5155

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7437C
<b>Vehicle Details</b>	
Vehicle No.:	SJA2969T
Vehicle to be Exported:	No
Intended De-registration Date:	15 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	3ZZ4683952
Chassis No.:	MR053ZEC107152767
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,757.00
Original Registration Date:	03 Dec 2007
First Registration Date:	03 Dec 2007
Transfer Count:	2
Actual ARF Paid:	\$16,233.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$20,997.00
COE Rebate Amount:	\$18,022.00
<b>Total Rebate Amount:</b>	<b>\$18,022.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Aug 2018

OK

> Back to OneMotoring

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.:	SJA2969T
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Chassis No.:	MR053ZEC107152767
Propellant:	Petrol
Engine No.:	3ZZ4683952
Engine Capacity:	1598 cc
Maximum Power Output:	81.0 kW (108 bhp)
Maximum Laden Weight:	1600 kg
Unladen Weight:	1115 kg
Year Of Manufacture:	2007
Original Registration Date:	03 Dec 2007
Lifespan Expiry Date:	-
COE Category:	A - Car (1600cc & below)
PQP Paid:	\$20,997.00
COE Expiry Date:	30 Nov 2022
Road Tax Expiry Date:	02 Dec 2018
Inspection Due Date:	02 Dec 2018
Intended Transfer Date:	15 Aug 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/12/2017 12:47
Date Of Accident	12/12/2017 02:00
Exact Location Of Accident	JUNCTION OF PUNGGOL EAST/SLIP ROAD OF TEBING LANE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJA2969T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAJUDDIN BIN GULAM MOHAMAD
NRIC No	S1397437C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97952415
Alternative Phone No	OTHERS-97952415

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ17-006109
Cover Note Number	

### Driver

Name of Driver	TAJUDDIN BIN GULAM MOHAMAD
NRIC No	S1397437C
Date Of Birth	11/06/1959
Occupation	INDOOR
Date Of Driving Pass	06/08/1991
Driving Experience	26 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97952415
Fax Number	
Contact Number	OTHERS-97952415
Email Address	NOEMAIL

Address	BLK 670 JALAN DAMAI #03-43
Postcode	410670
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN (TYPE OF COLLISION IS HEAD TO SIDE)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT45Z
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

#### DETAILS OF INJURED PERSON 1

Name	TAJUDDIN BIN GULAM MOHAMAD
------	----------------------------

Approximate Age

Injuries Sustain

NECK,BACK AND CHEST PAIN

Injured person in which vehicle?

SJA2969T

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.



#### B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:   
NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12-12-2017 at about 02:00hrs, I was travelling along Punggol East. As I was heading straight, a vehicle from slip rd of Tebing Lane (SLT 452) make a sudden dash out. I was on the major road - the said vehicle didn't check <sup>blindspot</sup> and collided with my vehicle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]  
Policyholder's Signature  
Date & Time:

[Signature]  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

[Signature] 14/12/2017  
Reporting Centre Personnel's Signature  
Name: [Signature]  
NRIC/FIN No.: [Signature]



**Tel: 6789 5155 Fax : 6783 5155**

THIRD PARTY REQUESTOR / CONTACT : XIONG 8121 0478

### QUOTATION SUMMARY

## CLAIM DETAIL : PARTS

✕  
 ✕  
 ✕  
 ✕  
 —  
 —  
 ✕  
 72  
 5 329.30  
 ✕  
 ✕  
 ✕  
 ✕  
 ✕  
 ✕

16	AIR CONDENSOR	1	\$ 1,400.00	\$ 1,400.00	x
17	AIR DUCT	1	\$ 110.00	\$ 110.00	x
18	FUSE BOX (ASSY)	1	\$ 854.00	\$ 854.00	x
19	FRONT FENDER LH	1	\$ 290.00	\$ 290.00	x
20	FRONT FENDER INNER COWLING LH	1	\$ 55.00	\$ 55.00	x

842.20  
631.65

TOTAL PRICE \$ 10,459.90  
LESS 25% \$ 2,614.98  
SUB TOTAL PRICE \$ 7,844.93

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE	1	\$ 50.00	\$ 50.00	x
2	FRONT BUMPER CLIPS	12	\$ 6.50	\$ 78.00	30
3	FRONT BUMPER UNDER COVER GARNISH CLIP	10	\$ 6.50	\$ 65.00	15
4	BONNET SEALANT	1	\$ 80.00	\$ 80.00	x
5	BONNET INSULATOR CLIP	10	\$ 6.50	\$ 65.00	x
6	BONNET STICKER	1	\$ 40.00	\$ 40.00	x
7	FRONT GRILLE CLIP	4	\$ 6.50	\$ 26.00	45
8	FRONT FENDER SEALANT LH	1	\$ 80.00	\$ 80.00	x
9	FRONT FENDER COWLING CLIPS	18	\$ 6.50	\$ 117.00	x
10	BATTERY NS60	1	\$ 200.00	\$ 200.00	x
11	RADIATOR COOLANT	1	\$ 80.00	\$ 80.00	x

TOTAL \$ 881.00

#### CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,500.00	300	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	300	
3	Tuff Coat	\$ 250.00	x	
4	WIRING CHECK	\$ 80.00	30	
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	x	
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	x	
7	REFOCUS HEADLAMP BEAM	\$ 60.00	x	

630

8	FRONT CHASSIS ALIGNMENT	\$	250.00	X	
---	-------------------------	----	--------	---	--

**TOTAL**

**\$3,540.00**

TOTAL PARTS COST : \$ 8,725.93  
TOTAL LABOUR COST : \$ 3,540.00  
TOTAL REPAIR COST : \$ 12,265.93

**APPROVED DETAILS**

EXCESS :  
NO. OF WORKING DAYS :  
RE-SURVEY :  
PART BY PART OR LUMP SUM :  
DATE & TIME OF SURVEY :  
SURVEYED BY :  
CONTACT NUMBER :  
FAX NUMBER :

total: 1306.65  
L/S: 1050.  
03Days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023818/AVD3N2

Date: 16/08/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29025980MPQ
Claimant Vehicle No :	SJA2969T	Insured Vehicle No :	SLT45Z
Date of Loss:	12/12/2017	Nature of Claim:	TP
		Claim No:	540620

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJA2969T	Engine No:	3ZZ4683952
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEC107152767
Reg. Date:	03/12/2007 (Man. Year: 2007)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,725.92	676.65	8,049.27	92.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	630.00	2,910.00	82.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,265.92</b>	<b>1,306.65</b>	<b>10,959.27</b>	<b>89.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,050.00</b>		
<b>(S\$)</b>	<b>12,265.92</b>	<b>1,050.00</b>	<b>11,215.92</b>	<b>91.44</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>858.61</b>	<b>73.50</b>	<b>785.11</b>	<b>91.44</b>
<b>Nett Amount (S\$)</b>	<b>13,124.53</b>	<b>1,123.50</b>	<b>12,001.03</b>	<b>91.44</b>

## INSPECTION

Date of Assignment: 15/12/2017

Date Inspected: 15/12/2017 Inspected At:

SK Automobile Pte Ltd (HQ)  
23 Kaki Bukit Avenue 4, #03-01 Vicom  
Inspection Centre  
Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2018)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJA2969T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,450.00 FL	*- FL
2	1		*BONNET STOPPER	Not Necessary	25.00 FL	*- FL
3	2		*BONNET HINGE	Not Necessary	111.20 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	77.80 FL	*- FL
5	1		*FRONT BUMPER	Distorted	385.90 FL	*385.90 FL
6	1		*FRONT BUMPER UNDER COVER GARNISH LH	Torn	55.00 FL	*55.00 FL
7	1		*FRONT BUMPER FOG LIGHT LH	Not Necessary	365.00 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER	Necessary	110.00 FL	*72.00 FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	421.00 FL	*329.30 FL
10	1		*HEADLAMP LH	Not Necessary	548.00 FL	*- FL
11	1		*FRONT SUPPORT PANEL	Repair	2,180.00 FL	*- FL
12	1		*FRONT GRILLE	Not Necessary	385.00 FL	*- FL
13	1		*FRONT GRILLE LOGO	Not Necessary	45.00 FL	*- FL
14	1		*RADIATOR	Not Necessary	1,050.00 FL	*- FL
15	1		*AIR CLEANER BOX	Not Necessary	542.00 FL	*- FL
16	1		*AIR CONDENSOR	Not Necessary	1,400.00 FL	*- FL
17	1		*AIR DUCT	Not Necessary	110.00 FL	*- FL
18	1		*FUSE BOX (ASSY)	Not Necessary	854.00 FL	*- FL
19	1		*FRONT FENDER LH	Not Necessary	290.00 FL	*- FL
20	1		*FRONT FENDER INNER COWLING LH	Not Necessary	55.00 FL	*- FL
21	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
22	12		*FRONT BUMPER CLIPS	Necessary	78.00 FS	*30.00 FS
23	10		*FRONT BUMPER UNDER COVER GARNISH CLIP	Necessary	65.00 FS	*15.00 FS
24	1		*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
25	10		*BONNET INSULATOR CLIP	Not Necessary	65.00 FS	*- FS
26	1		*BONNET STICKER	Not Necessary	40.00 FS	*- FS
27	4		*FRONT GRILLE CLIP	Not Necessary	26.00 FS	*- FS
28	1		*FRONT FENDER SEALANT LH	Not Necessary	80.00 FS	*- FS
29	18		*FRONT FENDER COWLING CLIPS	Not Necessary	117.00 FS	*- FS
30	1		*BATTERY NS60	Not Necessary	200.00 FS	*- FS
31	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,340.90</b>	<b>887.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,614.98</b>	<b>210.55</b>
<b>Total Parts (\$\$)</b>	<b>8,725.92</b>	<b>676.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,500.00	300.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	300.00
3	TUFF COAT	New	250.00	-
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	-
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	-
7	REFOCUS HEADLAMP BEAM	New	60.00	-
8	FRONT CHASSIS ALIGNMENT	New	250.00	-
Gross Labour Cost (\$\$)			<b>3,540.00</b>	<b>630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >