

Tues 06/02 1.30pm
SLR

SKU3566Z

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

15 DEC 2017

Estimate No. : b1 45159	Page No. : 1 of 2
Date Estimated : 15/12/2017	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Thien Sook Kyen 185 Westwood Avenue Singapore 648265	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU3566Z	NS38775	29/05/2015	316iA/4	0

DESCRIPTION	VALUE
To replace front bumper & attachments including to knock out dented area caused by the accident	850 1,275.00
To respray front bumper	934 1,038.00
To replace right headlight including program and conduct tests for proper function.	451 531.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
Sundries.	? 80.00

Total Labour 1: 3,101.00

DESCRIPTION	QTY	PRIC	VALUE
SHEET METAL NUT SELF-LOCKING	10	1.00	10.00
RIVET	10	0.50	5.00
FRONT SHOCK ABSORBER	1	40.15	40.15
# FRT BUMPER TRIM PRIMED (SRA)	1	958.80	958.80
RH COVER SPRAY NOZZLE PRIMED	1	30.75	30.75
TELESCOPING NOZZLE RH	1	152.10	152.10
RH HEADLIGHT (XENON)	1	2,083.75	2,083.75

Total Parts : 3,280.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45159
Date Estimated : 15/12/2017
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU3566Z	NS38775	29/05/2015	316iA/4	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 6/2/18 1530 Excess S\$ _____

Surveyor's Name tanjun Sign [Signature]

Surveyor's Tel 97495149 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanjun@lukandsun

No. of Working Days Recommend 3 days

Labour 1	:	3,101.00
Parts	:	3,280.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	446.71
Grand Total	:	<u>6,828.26</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **