Menimen Toutikh From (Person): Irene Tar	ASSIGN	MENT (Office) MSIG	Special Instruction Date/Time:	15/10/2017@
Estimated Cost		Bill to		
OD (TP) WS / TP RES / OD To Inspect Vehicle No:	FRE 8346		Insured: SIM	23764
at Workshop m/s	H.S. Phoon	-	Tel: 651	0770
of BIK 36 70h Gue	an Road East	# 01-35		
Policy No: 2893947	4 AVW		539519	
Sum Insured:		Excess:	0 30	
Make of Veh: (Client's Record)			D.O.A. 0	1112/2017
CA / REV / REP. / REV 2	4 HRS (wp)		H.O.D. End	
Date/Time 1.52pm @ 15/1	2/17 Person Contacts	d Mei	Vehicle (N)	lour
Date/Time Action/Instructi	on () Estima	to		1
FBE 834				
SIM 23 75				
11/17@ 4.48m m		e Tan via	Menne	
All I am a second		the second secon	The state of the s	Loups, by even

Surrence taught REF: MSIG	*
ASSI	ONMENI
From Date 20/12/20/7	Veh No. FISE 83464 Yr Regn. 2016 Sep
Estimated Cost:	Type: M.Car / M.Oycle / Bus / Van / Lorry / Taxl / Prima Mover /
OD TP WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No: FBE 83 46 A	Make Yawaha RXZ ac (33
at Workshop m/s A·S· Phoon	Colour Maroun A/C Insured / Std / NI / NA
of BIK36-76h Guan Rd East # 01-35	Sp.Reading 22071 TRadio Insured / Std / NI / NA
Insured	Eng/No.
Policy No.	C/No: pmyspv10046032710
Claims No.	Gen. Cond. Good Fair / Poor / Burnt
Sum insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: (Nil)S/Rim / STD A/Rim or
	Tyre Size: F: 80/908/8.
(Palicy Condition)	R: 4, 4
Remark: The veh had commenced its N/S 0/S 2	BS /DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Sal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal 5 mm R/Bal 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. mm L/Bal. mm
Est. Repairs: 6 days Res.: Yes or No	D.O.A. D.O.I. 20/12/12 P/350
Lum Sum: % 3 Val.: Yes or No	Survey held at MS Pluson Toly Gua
CA / REV / REP. / 24 HRS (Up)	Des. of Damages (FA) Rear I (O)S (N)S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Parts price duk typis 20/7	magnife
RECEIVED 2 4 JU	L 2018.
	2111/20
OsterTime, File Pass to? : Prell, Report	Days Of Repair:
174 2 MMHY : Final Report	Resurvey No. of Trip: Survey Fee
Cate/Time, File Return to?	Transportation
Add Fee	
	Interview (\$) Photos
Report Format: MER-TP	: Tech Invs (\$) Coes
Lump Sum / I.B.1; (\$ 3,750	Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (S	INGAPORE) PTE LTD	Ref : CS/MSG17023	828/T1qd3	
16 RAFFLES QUAY #24-01 HONG LEONG	BLDG SINGAPORE 048581	Date: 15-12-2017 Code: MSG		
	Policy Particulars	:- THIRD PARTY CLAI	M	
Insured Veh.	SLM 2375U	Veh. Inspected	FBE 8346A	
Policy No.	28939474AVW	Coverage (\$)	0.00	
Claim No.	539519	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	15/12/2017	
2.	Vehicle Parti	culars & Condition		
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	9	Steering		
Brakes		Modification		
General				
3.	Condit	ions of Tyres		
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
	Descripti	on of Damages		
5. Symmette	Genera	I Information		
Accident Date	01/12/2017	Inspection Date	15/12/2017	
Survey held at	A.S. PHOON PTE LTD	The artists are perfort with the passions	and contract (CO)	
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	BLK 36 TOH GUAN ROAD EAS #01-35 SINGAPORE 608580	т		
5a.	CAMER	emarks		
A)THE INSPECTION	ON WAS CONDUCTED ON A"WIT	HOUT PREJUDICE" BAS	S.	
BJIN ACCORDANG	CE TO YOUR INSTRUCTIONS, W	E HAVE NOT AUTHORIS	ED REPAIRS.	

...CLAIM SUBFOLDER...(New Assignment)

LAIM SUE	FOLDER TRACE	KING					
Case	Notified	Est Submitted	Adj Assigned	Adi Rpt	Adj Submitted	Ins Auth ed	Status
Main	02 Dec 2017		15 Dec 2017 13:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETA	ILS		[Created by in	surer]
Insured:	YEOH WOOI GAN, ID: S7	1769871	4.5000000000000000000000000000000000000	
Main Claimant:	MILZAM BIN ABDUL GHA	NI, ID: S96443423		
Vehicle Reg. No.:	FBE8346A	Date of Loss:	01/12/2017 00:	00 - :59
Claim Type:	TP / 539519	Policy/Cover Note No.:	[10] [10] [10] [10] [10] [10] [10] [10]	Comprehensive) 3/2017 - 23/03/2018
Vehicle Reg. No. (Insured):	SLM2375U	Policy No. (Claimant):		
		Excess:	S\$1,500.00	
Repairer:	A S Phoon Pte Ltd (toh Go Jurong Island - Tel:	uan) (HQ) BLK 36 TOH GUAN RC	AD EAST ENTERPRISE HU	B #01-35, 408701
Handling Insurer:	MSIG Insurance (Singapo 6594 2541]	ore) Pte. Ltd. (HQ) - Tel: +65 68	27 7888 [Handled by I	rene Tan Gek Ing -
Addition	LVV Auto Consultante Dto	Ltd (HQ) - Tel: 6256-3561 [1	mm Advice due 16/1	- in
Adjuster:	LKK Auto Consultants Pte	Fra (114)	HILLIAM ALCE DOE TO!	[2/2017]
	CHEAH YEE HOOI (/ Female		mmi.Advice dde 10/1	12/2017]
Driver/Custodian (Insured):		e), NRIC: S7176988G	inni.Advice dde 10/1	12/2017]
Driver/Custodian (Insured): Adj Asg. Remarks:	CHEAH YEE HOOI (/ Female Please Assign to Surveyor M	e), NRIC: S7176988G	View All	
Adjuster: Driver/Custodian (Insured): Adj Asg. Remarks: ASSOCIATED MAIL RECEI There are no mail for this cas	CHEAH YEE HOOI (/ Female Please Assign to Surveyor M	e), NRIC: S7176988G	17.	Compose Case Mail
Driver/Custodian (Insured): Adj Asg. Remarks: ASSOCIATED MAIL RECEI	CHEAH YEE HOOI (/ Female Please Assign to Surveyor M IVED	e), NRIC: S7176988G	View All	Compose Case Mail
Driver/Custodian (Insured): Adj Asg. Remarks: ASSOCIATED MAIL RECEI There are no mail for this cas	CHEAH YEE HOOI (/ Female Please Assign to Surveyor M	e), NRIC: S7176988G arcus View All	View All Search Tasks Create N	Compose Case Mail

TAN CHIN HOE & CO

ADVOCATES & SOLICITORS GST No. & UEN: 53131160X

24 Raffles Place #24-01 Clifford Centre Singapore 048621

Tel: 5538 2687 Facsimile: 5538 0287 Email: info@tanchinhos.com.sg

Your Ref.

SLM 2375U

Our Ref:

RT/MP/526/2017/pi

1 4 DEC 2017

539519

12 December 2017

MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

BY FAX & HAND Fax No: 6225 6371

Attn: Motor Claims Department

Dear Sirs

ACCIDENT INVOLVING FBE 8346A AND SLM 2375U ON 1 DECEMBER 2017

- We are instructed by Mr Milzam Bin Abdul Ghani to notify you of a road traffic accident on 1 December 2017 at about 2.45 pm at 1 Jurong West Street 51 involving our client's motor vehicle registration number FBE 8346A and vehicle registration number SLM 2375U driven by your insured at the material time.
- 2. We will let you have our client's quantification in due course.
- In the meantime, our client's motorcycle is at the premises of A S Phoon Pte Ltd at Blk 36 Toh Guan Road East #01-35 Singapore 608580. Please contact Mr Kee at 65150770 for an appointment to survey the motorcycle within 2 days, falling which A S Phoon Pte Ltd will proceed to carry out the repairs.

Yours faithfully

Richard Tan / Michelle Peh

oc 1. client

- Manjra Services
 641 Pasir Ris Drive 1
 #03-512
 Singapore 510641
- A S Phoon Pte Ltd Fex No: 65150779

Shiau Chan (LKKAuto)

From:

Sent:	Tuesday, 26 June 2018 3:05 PM
To: Cc:	Shiau Chan (LKKAuto) SUR; Taufikh (LKKAuto); Taufikh
Subject:	Re: FBE8346A GIA REPORT & REPAIR ESTIMATE
Dear Shiau Chan ,	
OK.	
Please proceed .	
Thank you .	
Sincerely,	
Kee Ger Ong	
Motor Claim Dept	
A.S.Phoon Pte Ltd	
Blk 36 Toh Guan Road East	
Enterprise Hub # 01-35	
Singapore 608580	
T: 6515 0770	
F: 6515 0779	
E: kee@asphoon.com	
W: www.asphoon.com	
On 31 May 2018 at 17:12, Shiau	Chan (LKKAuto) < siewsc@lkkauto.com > wrote:
Dear Kee,	
Offer Lump Sum \$3,250.00 and	6 repair days.

kee kee <kee@asphoon.com>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Irene Tan Gek Ing

Date: 21 Dec 2017

Preliminary Advice

Insured Vehicle No : SLM2375U

TP Vehicle No

: FBE8346A

Accident Date

: 01/12/2017

Make

: YAMAHA RXZ

Assignment Date

: 15/12/2017

Date of Inspection : 20/12/2017

Est. Duration of Repair

: 6.00

Inspection At

: A S PHOON PTE LTD (TOH GUAN) (HQ)

BLK 36 TOH GUAN ROAD EAST ENTERPRISE HUB #01-35

SINGAPORE 408701

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,948.00
Revised Amount	:S\$	4,109.20
Check Items (Estimated)	:S\$	526.50
Total	:S\$	4,635.70

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

į) The vehicle is	economical/not eco	nomical for repair
---	------------------	--------------------	--------------------

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4342J
Vehicle Details	
Vehicle No.:	FBE8346A
Vehicle to be Exported:	No
Intended De-registration Date:	21 Dec 2017
Vehicle Make:	УАМАНА
Vehicle Model:	RXZ
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	5PV032790
Chassis No.:	PMY5PV100A0032790
Maximum Power Output:	
Open Market Value:	\$2,305.00
Original Registration Date:	29 Sep 2010
First Registration Date:	29 Sep 2010
Transfer Count:	6
Actual ARF Paid:	\$346.00
Intended PARF Rebate D	etails
PARF Eligibility:	No
PARF Eligibility Expiry Date:	*
PARF Rebate Amount:	\$0.00
Intended COE Rebate De	tails
COE Expiry Date:	28 Sep 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,452.00
COE Rebate Amount:	\$402.00
Total Rebate Amount:	\$402.00

The information contained herein is correct as at 21 Dec 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 5. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCID	CAIT	4.0	7-7	1-7-16
ACCID	E N I	SIA	E IV	

Date Of Report 04/12/2017 14:17 Date Of Accident 01/12/2017 14:45

Exact Location Of Accident ALONG JURONG WEST ST 51 YELLOW BOX AREA

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBE8346A

Insured/Policyholder

Name Of Registered Owner MILZAM BIN ABDUL GHANI

NRIC No S9644342J Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-81011947 Alternative Phone No OTHERS-81011947

Vehicle Particulars

Manufacturer YAMAHA

Model RXZ-133CC (M)

Exact Purpose for which vehicle was being used at PRIVATE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

MOTORCYCLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage THIRD PARTY

Fleet Policy NO

Policy Number 5078752258-01

Cover Note Number

Driver

MUHAMMAD FARHAN BIN MOHAMED OMAR Name of Driver

NRIC No S9911400B Date Of Birth 19/04/1999

Occupation INDOOR Date Of Driving Pass 05/09/2017

0 YEAR AND 2 MONTH Driving Experience

Gender MALE

Mobile Number Fax Number Contact Number

MHDFRHNOMAR@GMAIL.COM EMail Address

90836679.

Enther

BLK 373 JURONG EAST STREET 32 Address

#08-428 600373

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Postcode

OTHER - NAMED RIDER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO YES Was any body injured in the Accident?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name JURONG WEST NEIGHBOURHOOD POLICE CENTRE

NO

NO

ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: Police Station Address

SINGAPORE

Police Station Contact TEL NO: 1800-2689999 - FAX NO: 62672438

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO : T/20171202/2101

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES.

Remarks/ Reasons:

VIDEO IS WITH THE CAR OWNER

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

SLM2375U

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name MUHAMMAD FARHAN BIN MOHAMED OMAR

Approximate Age 18

Injuries Sustain SERIOUS Injured person in which vehicle? FBE8346A

Were seat belts worn? NO
Was injured conveyed to hospital by ambulance? YES

Address BLK 373 JURONG EAST STREET 32

#08-428

Postcode 600373

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers 'universylaw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (b) the information so collected under (d) above may be shared / disclosed
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

0.4 DEC 2017

59911400

8 4 DEC 2017

1-19pm-

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Reporting Centre Personnel's Signature

Name

Sketch Plan #2

ETCH PLAN		
		Mong Durring Grant SA SI
		Yellow for even
		Δ
	19 bil	A - FRE 8346A
100	1 \ 1	
		A SLM23754
	1777	A - 21622424
	CA	
		Bus
ESCRIBE CIRCUMSTAN	CES OF THE ACCIDENT	
	*	
	*	
ECLARATION	*	
CLARATION		0 4 052 7011
CLARATION		04 050 2017 04 050 2017 991 1400 B 2 2 2017









Police Report





T/20171202/2101

1 of 3 Report No. (7/20171202/2101)

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999

Date/Time Report Made: 02/12/2017 16:17		Vide Report No.:	Station Diary No.		
Informa	nt's Partic	ulars			
Name of Informant: MUHAMMAD FARHAN BIN MOHAMED OMAR		Address: APT BLK 373 JURONG EAST STREET 32 #08-428 SINGAPORE 600373			
ID Type / ID No.: NRIC NO / S9911400B		Contact No.: Home/Office: Mobile: 88202742			
National SINGAP	ity: PORE CITIZ	EN	Email:	alk lar	
Sex: Male	Age:	Date of Birth: 19/04/1999	Type of Informant: Rider	1 1	
Race: Indian			Language: English	Institution / School Name:	
Occupation: DOMINO'S PIZZA RIDER		Driving Licence Information: Class: 2B Date of Expiry:			

Type of Accident:	Injury Conveyed By Ambulance		Drink Drive: No	Date/Time of Accident: 01/12/2017 14:45	Type of Location Straight Road	
	ST STREET 51					
YELLOW BOX AREA Weather: Clear		Road	Surface:	A.E. A	Road Speed Limit:	
Clear		Traffic Flow: Traffic				
Traffic Flow:		0.0000000000000000000000000000000000000	c Control: controlled		Traffic Volume: Heavy	

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenge
FBE8346A	Motorcycle	YAMAHA		Maroon	Seriously Damaged	1,547
SLM2375U	Car	VOLKSWAGO N		Grey	Slightly	0

Details of V	ehicle Insurance			MILITAN SON
Vehicle No.	Insurance Company	insurance No	Effective	Expiry Date
FBE8346A	NTUC Income Insurance Co-Operative Limited	507875225801	29/03/2017	28/03/2018

Police Report





Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999 2 of 3 Report No. T/20171202/2101

CONTINUATION OF REPORT

Details of Perso	n Involved	CENTR	Mark Barrier	AV000	13.26	CCV-VALUE ON
Any Pedestrian Ir	nvolved: No				13.34	INSTRUMENT OF STREET
No. of Pedestrian	s Injured: NIL		Use of P	edestrian	Cross	ing: NA
Rider		1300			SAMO	THE STATE OF THE S
Name	MUHAMMAD FARHAN BIN MOHAMED OMAR		ID No		S9911400B	
Related Vehicle	FBE8346A (Motorcycle)			Contact No. 8820		88202742
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL			Class Drivin Licens Expiry	g ce &	Class: 2B Date of Expiry: NIL
Date Treatment	01/12/2017		Date Dis	charge	02/12	/2017
No. of Days gran	ted Medical Leave	11		of Injury		

Brief Details.

On 1/12/2017 at about 1445hpours, I was riding my RXZ motorcycle bearing plate number FBE8346A along Jurong West St 51 heading towards Jurong West Ave 1. At that point of time, I was riding on a straight road of the two-lane road and was at the yellow box area when suddenly, there was a car bearing plate number SLM2375U which was coming out from B/501 Jurong West St 51 had collided on to my motorcycle. I then fell on the car's front bonnet and rolled down to the road. A female Chinese passer-by then came to assist me. I then get up and went to the side of the road. I then started to feel pain from my right leg.

Shortly after, ambulance and TP came to scene and after making checks on me, I was then conveyed to Ng Teng Fong Hospital with condition conscious. I then received eleven days MC. I suffered injuries on my right leg and soreness on my whole body. My motorcycle sustained damages on the front fork and mainly the main head of the motorcycle. I am unsure if there is any CCTV located around the vicinity.

TP IO: IO Christopher Ong DID: 65476436 / 92783566

Police Report





T/20171202/2101

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999 CONTINUATION OF REPORT

3 of 3 Report No. T/20171202/2101

Sketch Plan


Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report J / Staff Sgt NUR SYAFIQAH BINTE ABDUL LATIFF	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 02/12/2017 16:17
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt ONG YONG HOCK Contact No : 65476436	Classification Of Case:
Authentication Stamp NP168	B. S.
Stamman Police	Transfer of the second

Accident Photo







潘發展私人有限公司

A. S. PHOON PTE LTD

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263 Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250 Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779

Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBE8346A YAMAHA RXZ (5PV) RED REPAIR ESTIMATE

ITEM	DESCRIPTION	AMOUNT SGD
1	FRONT COWLING	\$165.0004
2	STAY . FRONT COWLING	\$95.00 1-6
3	WINDSHIELD	\$38.00
4	FRONT LICENCE PLATE	\$12.00
5	HEADLAMP COMP	\$110.0004
6	HEADLAMP BULB	\$12.00 009
7	SOCKET HEADLAMP	\$20.00 \$114
8	FRONT SIGNAL RH & LH @\$48	\$96.00
9	METER ASSY	\$450.00000
10	METER BRACKET	\$55.00 64-
11	HANDLEBAR RH & LH	\$190.00 60
12	BALANCER X2	\$50.00 out
13	HANDLE GRIP	\$30.00 art
14	FRONT MUDGUARD	\$68.00 04
15	FRONT WHEEL ASSY	\$280.00 dd
16	FRONT WHEEL AXLE	\$28.00 × nn
17	FRONT TYRE	\$80.00 purched
18	FRONT FORK ASSY RH & LH @\$210	\$420.00 66
19	STEM STEERING	\$185.00 bt
20	CONE BEARING SET	\$60.00 00
21	FRONT BRAKE DISC	\$145.00 % 44
22	FRONT BRAKE CALIPER	\$250.00 × m
23	BRAKE LEVER	\$22.00 66
24	SIDE MIRROR	\$50.00 cut
25	HORN	\$40.00 <i>b</i> t
26	EXHAUST COMP	\$575.00 kg
27	GASKET X1	\$12.00 × ~~
28	HEAT PROTECTION - CHOME	\$48.00 at
29	HEAT PROTECTION - BLACK	\$48.00%15
30	FUEL TANK COMP	\$450.00 dd
31	RIDER SEAT	\$185.00 at
32	SIDE FAIRING RH	\$95.00 de
33	SIDE FAIRING LH	\$95.00 ant -
34	TAILLAMP ASSY	\$95.00
35	TAIL COVER	\$25.00 de
36	REAR LICENCE PLATE	\$18.00 ht
37	FRONT FOOTREST ASSY RH	\$65.00 art
38	REAR FOOTREST ASSY RH	\$38.00 cit
39	FOOTREST BRACKET RH	\$130.00 TX NN



潘發展私人有限公司

A. S. PHOON PTE LTD

Head Off Ubi

: 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263

: Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250 Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779

Website

: www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBE8346A YAMAHA RXZ (5PV) RED REPAIR ESTIMATE ITEM DESCRIPTION

11 CW	DESCRIPTION	AMOUNT SGD
40	BRAKE PEDAL	\$68.00
41	STRIPE SET	\$150.00 Me
42	TRANSPORTATION TP-IDAC- SHOP @\$50	\$100.00
43	WORKMANSHIP	\$350.00 250
44	BODY CHASSIS REPAIR	\$350.00 200
45	TRANSPORTATION 2 WAY TO REPAIR CHASSIS @\$50	\$100.00 80

TOTAL \$

\$5,948.00

LKK Auto Consultants hence notify

the Repairer of the following: . To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis
- No rilegal modification(s) is allowed
- . Supplementary dem(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

sure [Weato.com

Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case 1	latified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status	
Main	02 Dec 2017 15 Dec 2017 \$\$3,2		S\$3,250.00 Edit Estimat				Report	Pending for Survey	
м	ain	∏ R	eference	Claim	Details		Document		Show All
CLAIM SUB	FOLDER DE	TAILS			-	[Created I	oy insurer]		
Insured:	YEOH WO	YEOH WOOI GAN, ID: S71769871							
Main Claimant:	MILZAM E	AILZAM BIN ABDUL GHANI, ID: 596443423							
Vehicle Reg. No.:	FBE8346A			Dat	e of Loss:		00:00 - :59 and 2 Days Fron	n LTA Reg Da	te (Man Yr)]
Claim Type:	TP / 539519				cy/Cover e No.:		VW (Comprehens 24/03/2017 - 23/		
Vehicle Reg. No. (Insured):	SLM2375U				cy No. imant):				
				Exc	Charles in the second	5\$1,500.00			
Repairer:	A S Phoor	Pte Ltd (toh Gi	an) (HQ) BLK 36	TOH GUAN ROA	D EAST E	NTERPRISE H	JB #01-35, 4087	01 Jurong Isla	and - Tel:
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (HQ)	- Tel: +65 682	7 7888	[Handled by	Irene Tan Gek 1	i ng - 6594 25	41]
Adjuster:	14/01/20		Ltd (HQ) - Tel: 62	56-3561 [Hai	idled by I	MOHD TAUF	KH BIN HAMID] [Final I	Rpt due
Driver/Custo dian (Insured):		E HOOI (/ Female), NRIC: S717698	8G					
Ad) Asg. Remarks:	Please Ass	ign to Surveyor M	arcus						
ASSOCIATE	D MAIL RE	CEIVED					Vie	w All Con	npose Case Ma
There are no	mail for this	case,							
ALL ASSOC	IATED TAS	ks⊟				View All S	earch Tasks C	reate New Tas	ik Complet
Due Date No results.	Priority	Type Task	Group Subjec	t Handler	Assign	ned By	Completed On	Created	On Don

Merimen e-Claims Page 1 of 4

Claim Documents

*FBE8346A (539519)

[SLM2375U]

TP

MILZAM BIN ABDUL GHANI
Dec 1 2017 12:00AM

[YEOH WOOI GAN]

A S Phoon Pte Ltd (toh Guan)

Ass	essment Reports	100	1 per page	V	7
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Total Marie Control of the Control o	umbnail	10000011100
1	21/12/17 16:48	Adjuster Immediate Advice	1 Lo	ad HTM	
Pho	otos/Images		3 per page	V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		umbnail	-
1	23/07/18 17:44	General View		and JPG	3
2	23/07/18 17:44	General View		and JPG	V
3	23/07/18 17:44	General View	O La	ad JPG	V
4	23/07/18 17:44	General View	O Lo	ad JPG	V
5	23/07/18 17:44	General View		ad JPG	V
6	23/07/18 17:44	General View	O to	oad JPG	V
7	23/07/18 17:44	General View	O to	ad JPG	V
8	23/07/18 17:44	General View		ad JPG	V
9	23/07/18 17:44	General View	O Lo	and JPG	V
10	23/07/18 17:44	General View	O Lo	ad JPG	V
11	23/07/18 17:44	General View	O Lo	ad JPG	N.
12	23/07/18 17:44	General View	O La	ad JPG	V
13	23/07/18 17:44	General View	0 Lo	ad JPG	V
14	23/07/18 17:44	General View	1 La	ad JPG	V
15	23/07/18 17:44	General View	1 Lo	ad JPG	V
16	23/07/18 17:44	General View	O Lo	ad JPG	V
17	23/07/18 17:44	General View	O Lo	ad JPG	V
18	23/07/18 17:44	General View	① Lo	ad JPG	V
19	23/07/18 17:44	General View	0 Lo	ad JPG	V
20	23/07/18 17:44	General View	① Lo	ad JPG	V
21	23/07/18 17:44	General View	0 Lo	ad JPG	V
22	23/07/18 17:44	General View	0 to	ad JPG	V
23	23/07/18 17:44	General View	3 Lo	ad JPG	V
24	23/07/18 17:44	General View	10 Lo	ad JPG	V
25	23/07/18 17:44	General View	3 Lo	ad JPG	V
26	23/07/18 17:44	General View	0 Lo	ad JPG	V
27	23/07/18 17:44	General View	① Lo	ad JPG	V
28	23/07/18 17:44	General View	1 to	ad JPG	V
29	23/07/18 17:44	General View		ad JPG	V
30	23/07/18 17:44	General View	0 Lo	ad JPG	V
31	23/07/18 17:44	General View	0 Lo	ad JPG	V
32	23/07/18 17:44	General View	0 Lo	ad JPG	V
33	23/07/18 17:44	General View	0 to	ad JPG	7
34	23/07/18 17:44	General View	O Lo	ad JPG	

Ass	ssessment Reports			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	and the same
				V
35	23/07/18 17:44	General View	1 Load JPG	
36	23/07/18 17:44	General View	1 Load 3PC	_
37	23/07/18 17:44	General View	1 Load JPC	
38	23/07/18 17:44	General View	1 Load JPG	-
39	23/07/18 17:44	General View	3 Load JPC	_
40	23/07/18 17:44	General View	1 Load JPC	-
41	23/07/18 17:44	General View	1 Load JPG	-
42	23/07/18 17:44	General View	Load JPG	₩.
43	23/07/18 17:44	General View	■ Load 3PG	V
44	23/07/18 17:44	General View	■ Load JPG	V
45	23/07/18 17:44	General View	Load 3PG	2
46	23/07/18 17:44	General View	Load JPG	V
47	23/07/18 17:44	General View	€ Load JPG	V
48	23/07/18 17:44	General View	Load JPG	V
49	23/07/18 17:44	General View	€ Load JPG	2
50	23/07/18 17:44	General View	Load 3PG	V
51	23/07/18 17:44	General View	■ Load JPG	V
52	23/07/18 17:44	General View	€ Load JPG	2
53	23/07/18 17:44	General View	Eoad JPG	V
54	23/07/18 17:44	General View	1 Load JPG	V
55	23/07/18 17:44	General View	£oed 3PG	V
56	23/07/18 17:44	General View	■ Load JPG	V
57	23/07/18 17:44	General View	■ Load JPG	V
58	23/07/18 17:44	General View	1 Load JPG	V
59	23/07/18 17:44	General View	■ Load 3PG	V
60	23/07/18 17:44	General View	■ Load JPG	V
61	23/07/18 17:44	General View	■ Load JPG	V
62	23/07/18 17:44	General View	1 Load JPG	and the
63	23/07/18 17:44	General View	■ Load 3PG	F-72
64	23/07/18 17:44	General View	Load JPG	-
65	23/07/18 17:44	General View	■ Load JPG	V
66	23/07/18 17:44	General View	■ Load JPG	-
67	23/07/18 17:44	General View	■ Load JPG	Z)
58	23/07/18 17:44	General View	Load JPG	-
69	23/07/18 17:44	General View	Load JPG	-
70	23/07/18 17:44	General View	1 Load JPG	-
71	23/07/18 17:44	General View	Load JPG	-
72	23/07/18 17:44	General View	Load JPG	-
73	23/07/18 17:44	General View	■ Load JPG	C-3
74	23/07/18 17:44	General View	Load JPG	-
75	23/07/18 17:44	General View	■ Load JPG	press.
76	23/07/18 17:44	General View	Load JPG	array.
77	23/07/18 17:44	General View	1 Load JPG	2000
78	23/07/18 17:44	General View	Load JPG	printer.
79	23/07/18 17:44	General View	1 Load JPG	_
30	23/07/18 17:44	General View	1 Load JPG	(mag)
31	23/07/18 17:44	General View	1 Load JPG	-
32	23/07/18 17:44	General View	1 Load JPG	p=191
33	23/07/18 17:44	General View	1 Load JPG	

Merimen e-Claims Page 3 of 4

Ass	essment Reports	W-3112-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	1 per page	V	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Ilanda	-
84	23/07/18 17:44	General View		d JPG	2
85	23/07/18 17:44	General View	1 Loan	JPG	5
86	23/07/18 17:44	General View	1 Load	d JPG	5
37	23/07/18 17:44	General View	♠ Loai	JPG	6
38	23/07/18 17:44	General View	■ Load	JPG	6
89	23/07/18 17:44	General View	● Load	d JPG	5
90	23/07/18 17:44	General View	O Load	d JPG	6
91	23/07/18 17:44	General View	O Load	d JPG	6
92	23/07/18 17:44	General View	€ Load	JPG.	5
93	23/07/18 17:44	General View	O Load	d JPG	5
94	23/07/18 17:44	General View	D Load	JPG	5
95	23/07/18 17:44	General View	1 Load	JPG	5
96	23/07/18 17:44	General View	① Load	J JPG	5
97	23/07/18 17:44	General View	1 Load	J JPG	Б
98	23/07/18 17:44	General View	1 Load	JPG	5
99	23/07/18 17:44	General View		d JPG	5
100	23/07/18 17:44	General View		JPG	5
101	23/07/18 17:44	General View	€ Load	JPG	5
102	23/07/18 17:44	General View		I JPG	5
103	23/07/18 17:44	General View)PG	6
104	23/07/18 17:44	General View		i JPG	5
05	23/07/18 17:44	General View		i JPG	5
106	23/07/18 17:44	General View		1 JPG	5
107	23/07/18 17:44	General View		JPG	5
108	23/07/18 17:44	General View		JPG	5
109	23/07/18 17:44	General View		1 JPG	5
110	23/07/18 17:44	General View		1 JPG	5
111	23/07/18 17:44	General View		1 JPG	5
12	23/07/18 17:44	General View		JPG	5
13	23/07/18 17:44	General View		1 JPG	5
11000		25 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		JPG	-
114	23/07/18 17:44	Reinspection Photo	The state of the s	-	5
-	23/07/18 17:44	Reinspection Photo		JPG	2
	23/07/18 17:44	Reinspection Photo) JPG	4
117	23/07/18 17:44	Reinspection Photo	The second secon	1 JPG	¥
18	23/07/18 17:44	Reinspection Photo		JPG	2
19	23/07/18 17:44	Reinspection Photo		JPG	2
20	23/07/18 17:44	Reinspection Photo		1 JPG	2
21	23/07/18 17:44	Reinspection Photo		JPG	<u>-</u>
22	23/07/18 17:44	Reinspection Photo		JPG	Ex.
23	23/07/18 17:44	Reinspection Photo		JPG	~
	23/07/18 17:44	Reinspection Photo	The second extension	JPG	Y
25	23/07/18 17:44	Reinspection Photo		JPG	2
26	23/07/18 17:44	Reinspection Photo		JPG	V
27	23/07/18 17:44	Reinspection Photo		IPG	×
28	23/07/18 17:44	Reinspection Photo		JPG	¥
29	23/07/18 17:44	Reinspection Photo		JPG	¥
30	23/07/18 17:44	Reinspection Photo		JPG	4
31	23/07/18 17:44	Reinspection Photo	The second section is a second section of	JPG	¥
32	23/07/18 17:44	Reinspection Photo	O Load	JPG	¥
33	23/07/18 17:44	Reinspection Photo	€ Load	JPG	¥

Merimen e-Claims Page 4 of 4

Ass	essment Reports		1 per page		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
134	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
135	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
136	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
137	23/07/18 17:44	Reinspection Photo	0	Load JPG	7
138	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
139	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
140	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
141	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
142	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
143	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
144	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
145	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
146	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
147	23/07/18 17:44	Reinspection Photo	0	Load JPG	V
Doc	umentation		1 per s	page 🔽	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	14/12/17 15:56	PRI	0	Load PDF	
2	14/12/17 15:56	TP GIA REPORT	0	Load PDF	
3	14/12/17 15:57	Accident Report From:OD - Reg. No: SLM2375U, Claimant: YESH WOOI GAN	0	Load PDF	
4	15/12/17 13:05	Email from TP agree SJE	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

Page 1 of 5 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023828/T1QD3Q2

24/07/2018 Date:

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28939474AVW

Claimant Vehicle FBE8346A No:

Insured Vehicle No: SLM2375U

Date of Loss:

01/12/2017

Nature of Claim:

Claim No: 539519

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FBE8346A

Make & Model:

YAMAHA RXZ, 133cc (M)

29/09/2010 (Man. Year: 2010)

Engine No: Chassis No: Odometer:

TP

5PV032790 PMY5PV100A0032790

Reg. Date: Colour:

Engine Capacity:

Sum Insured (S\$):

Maroon 133 cc

Market Value/New Car Price: N/A

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

39079 km

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

80/90 R18

Rear Tyre Size:

80/90 R18

Front Left Side: Front Right Side: Dunlop 5 mm 0 mm

Rear Left Side: Rear Right Side: Dunlop 5 mm 0 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
5,048.00	3,499.20	1,548.80	30.68
0.00	0.00	0.00	
900.00	610.00	290.00	32.22
0.00	0.00	0.00	
0.00	0.00	0.00	
5,948.00	4,109.20	1,838.80	30.91
	3,250.00		
5,948.00	3,250.00	2,698.00	45.36
416.36	227.50	188.86	45.36
6,364.36	3,477.50	2,886.86	45.36
	5,048.00 0.00 900.00 0.00 0.00 5,948.00 5,948.00 416.36	5,048.00 3,499.20 0.00 0.00 900.00 610.00 0.00 0.00 0.00 0.00 5,948.00 4,109.20 3,250.00 5,948.00 3,250.00 416.36 227.50	5,048.00 3,499.20 1,548.80 0.00 0.00 0.00 900.00 610.00 290.00 0.00 0.00 0.00 0.00 0.00 0.00 5,948.00 4,109.20 1,838.80 3,250.00 2,698.00 416.36 227.50 188.86

INSPECTION

Date of Assignment:

15/12/2017

Date Inspected:

20/12/2017 Inspected At:

A S Phoon Pte Ltd (toh Guan) (HQ) BLK 36 TOH GUAN ROAD EAST ENTERPRISE HUB #01-35

Singapore 408701

Estimated Period of Repair:

6.0 days

Adjuster Report Page 2 of 5

Adjuster: MOHD TAUFIKH BIN HAMID Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Jul 2018)

Parts: N/A YAMAHA RXZ 133cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBE8346A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT COWLING	Cracked	165.00 F	*165.00 FL
2	1	*STAY .FRONT COWLING	Bent	95.00 F	*95.00 FL
3	1	*WINDSHIELD	Cracked	38.00 F	*38.00 FL
1	1	*FRONT LICENCE PLATE	Necessary	12.00 F	*12.00 FL
5	1	*HEADLAMP COMP	Cracked	110.00 F	*110.00 FL
3	1	*HEADLAMP BULB	Cracked	12.00 F	*12.00 FL
7	1	*SOCKET HEADLAMP	Not Necessary	20.00 F	*- FL
3	2	*FRONT SIGNAL RH & LH	Cracked	96.00 F	*96.00 FL
9	1	*METER ASSY	Cracked	450.00 F	*450.00 FL
10	1	*METER BRACKET	Bent	55.00 F	*55.00 FL
11	2	*HANDLEBAR RH & LH	Bent	190.00 F	*190.00 FL
12	2	*BALANCER	Cut	50.00 F	*50.00 FL
13	1	*HANDLE GRIP	Cut	30.00 F	*30.00 FL
14	1	*FRONT MUDGUARD	Cracked	68.00 F	*68.00 FL
15	1	*FRONT WHEEL ASSY	Dented	280.00 F	*280.00 FL
16	1	*FRONT WHEEL AXLE	Not Necessary	28.00 F	*- FL
17	1	*FRONT TYRE	Punctured	80.00 F	*80.00 FL
18	2	*FRONT FORK ASSY LH & RH	Bent	420.00 F	*420.00 FL
19	1	*STEM STEERING	Bent	185.00 F	*185.00 FL
20	1	*SET CONE BEARING	Necessary	60.00 F	*60.00 FL
21	1	*FRONT BRAKE DISC	Not Necessary	145.00 F	*-FL
22	1	*FRONT BRAKE CALIPER	Not Necessary	250.00 F	*-FL
23	1	*BRAKE LEVER	Bent	22.00 F	*22.00 FL
24	1	*SIDE MIRROR	Cut	50.00 F	*50.00 FL
25	1	*HORN	Bent	40.00 F	*40.00 FL
26	1	*EXHAUST COMP	Repair	575.00 F	*-FL
27	1	*GASKET	Not Necessary	12.00 F	*-FL
28	1	*HEAT PROTECTION -CHOME	Cut	48.00 F	*48.00 FL
29	1	*HEAT PROTECTION -BLACK	Missing	48.00 F	*48.00 FL
30	1	*FUEL TANK COMP	Dented	450.00 F	*450.00 FL
31	1	*RIDER SEAT	Cut	185.00 F	*185.00 FL
32	1	*SIDE FAIRING RH	Deformed	95.00 F	*95.00 FL
33	1	*SIDE FAIRING LH	Cut	95.00 F	*95.00 FL
34	1	*TAILLAMP ASSY	Cracked	95.00 F	*95.00 FL
35	1	*TAIL COVER	Deformed	25.00 F	*25.00 FL
36	1	*REAR LICENCE PLATE	Bent	18.00 F	*18.00 FL
37	1	*FRONT FOOTREST ASSY RH	Cut	65.00 F	*65.00 FL
38	1	*REAR FOOTREST ASSY RH	Cut	38.00 F	*38.00 FL
39	1	*FOOTREST BRACKET RH	Not Necessary	130.00 F	*-FL

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*BRAKE PEDAL	Dented	68.00 F	*68.00 FL
41	1		*SET STRIPE	Necessary	150.00 F	*150.00 FL
F=Fra	anchise	part. L=Listite:	mDisc.	PONE SOCIETA DE LA SECUCIÓN DESCRIPTION DE LA SECUCIÓN DE LA SECUC	CONTROL OF COMME	-0000000000000000000000000000000000000
				Sub Total (S\$)	5,048.00	3,888.00
			- List Item Di	scount on L Items 0.00/10.00% (S\$)_	0.00	388.80
				Total Parts (S\$)	5,048.00	3,499.20
			Report was u	unsubmitted during this print-out.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TRANSPORTATION TP-IDAC -SHOP	New	100.00	80.00
2	WORKMANSHIP	New	350.00	250.00
3	BODY CHASSIS REPAIR	New	350.00	200.00
4	TRANSPORTATION 2 WAY TO REPAIR CHASSIS	New	100.00	80.00
	Gross	Labour Cost (S\$)	900.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >