

REPAIR ESTIMATE*

VEHICLE NO : SHC 3802Y

DATE 14/12/2017 9:53

MAKE :

Lamy

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Door Glass (LH) ✓			\$ 379.55	
	Front Door Outer Handle (LH) ✕ Repair			\$ 53.00	
	Front Door Outer Moulding (LH) ✓			\$ 63.70	
	Front Door Mirror (LH) ✓			\$ 980.50	
	Rear Door Outer Handle (LH) ✕ Repair				
	SUB TOTAL			\$ 1,476.75	
	LESS 20%			\$ 295.35	
	DISCOUNTED TOTAL			\$ 1,181.40	
	Front Door Comfort Logo (LH) ✕			\$ 75.00	Nett
	Labour Charge			200	
	Panel Beating			\$ 300.00	
	Spray Painting Charge			\$ 400.00	150
	Wiring Charge			\$ 50.00	20
	TOTAL LABOUR			\$ 750.00	
	ESTIMATE TOTAL			\$ 2,006.40	
1 Kalvin LUKY 14/12/17 1000 hrs. 2 Days 4/5 After Repair					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					