

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Dec-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1189 D

1 pc	Rear bumper <i>x repair</i>	\$	447.00
1 pc	Rear bumper sponge <i>x</i>	\$	79.20
1 pc	Rear bumper reinforcement <i>x</i>	\$	815.64
1 pc	Rear bumper reinforcement centre <i>x</i>	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 <i>y</i>	\$	104.40
		\$	1,525.44
	Less 20%	\$	305.09
		\$	1,220.35

S/NETT

1 set	Rear bumper clips <i>x</i>	\$	48.00
1 set	Reverse sensor <i>x</i>	\$	280.00 200
	Sundry	\$	50.00 20
	To dismantle and replace reverse sensor and test system	\$	80.00 20
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of end panel, etc.	\$	550.00 200
	To putty and spray painting on the rear bumper, end panel <i>x</i>	\$	450.00 180
	To apply rustproofing on the repaired and replaced panels	\$	120.00 <i>x</i>
	Total	\$	2,798.35

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin LKK
14/12/17 1605hrs
2 Days
PIP
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: