

Hsiao Tong (LKKAuto)

From: Loh Kok Chi <kcloh@familymedicare.com>
Sent: Thursday, 8 February 2018 9:50 AM
To: Hsiao Tong (LKKAuto)
Subject: RE: Accident involving SKW803Z and SHD 9795P on 11 Dec 2017

Thanks Mr Chew.

I have also sent you the summons just received from traffic police.

Mr Zaimi from your office has kindly agreed that we should settle the fine with the TP.

Appreciate your kind assistance in the negotiations.

It does appear from the video that the cab that hit my car was driving very fast and unable to stop unlike the other vehicle what was ahead of him managed to. The speed of his vehicle certainly contributed to the severity of the damage.

Best regards,

Loh Kok Chi
SKW803Z

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Thursday, 8 February 2018 9:00 AM
To: Loh Kok Chi <kcloh@familymedicare.com>
Subject: RE: Accident involving SKW803Z and SHD 9795P on 11 Dec 2017

Hi Mr Loh,

Thank you for your video and email.

Based on all available information on hand, liability is not our driver favour. We will proceed to negotiate for an amicable settlement with the Third Party.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loh Kok Chi [<mailto:kcloh@familymedicare.com>]
Sent: Wednesday, 7 February 2018 10:46 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Accident involving SKW803Z and SHD 9795P on 11 Dec 2017

Dear Mr Chew,

I will be sending you the dash-cam video clip via WeTransfer. You will receive the link to download via a separate email.

My daughter (driver of my vehicle at the time of the accident) also received a traffic police summons just a few days ago. It is attached herein.

Best regards,

Loh Kok Chi
SKW803Z

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]
Sent: Thursday, 1 February 2018 10:59 AM
To: Loh Kok Chi <kcloh@familymedicare.com>
Subject: RE: Accident involving SKW803Z and SHD 9795P on 11 Dec 2017

Dear Mr Loh,

Thank you for your photos.

As for the video clip, will you able to come down to our office for submission?

Please call us if you have any queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loh Kok Chi [<mailto:kcloh@familymedicare.com>]
Sent: Wednesday, 31 January 2018 6:09 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Accident involving SKW803Z and SHD 9795P on 11 Dec 2017

<<...>> <<...>> <<...>> <<...>> <<...>> <<...>> <<...>> <<...>>

Dear Mr Chew,

Please refer to your letter dated 24 January 2018 (Ref CC3/ASM17023839/Kpa3) requesting for the information attached.

Police Report, Driver's Particulars and photos are included in the pdf document. More photos taken at the scene are also attached.

We have not received any summons or info from the police.

A video clip from our car camera was submitted to the police and returned to us. We have the clip but it is too big a file to send so I have it put on an SD Card. Will you be able to pick that up from me?

Thank you for attending to this case.

Kindly let me know once you have received this email.

Best regards,

Loh Kok Chi

Owner of

SKW803Z



Virus-free. www.avg.com

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 15 September 2018 9:24 AM
To: 'jasminetan@transcab.com.sg'; 'Ng Wai Yin'; 'Zhe Wei' (zhewei.kek@transcab.com.sg); claims@transcab.com.sg
Subject: AFTER REPAIR/ AFTER PAINT PHOTOS FOR SHD 9795P (DOA: 11/12/2017) - AAD1712- 116

Your ref: **AAD1712 - 116 (SHD 9795P)**
Our ref: CC3/ASM17023839/Kpa3

Without Prejudice

Hi Sirs/Mdm,

We refer to the above matter.

We are seeking mandate approval from AXA.

Kindly advise if there is any **after repair/ after paint photos for SHD 9795P (DOA: 11/12/2017)**. If so, kindly let us have a copy of the photos.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

« Re:Direct Settlement - Accident Involving SKW803Z (OI : AXA - S7M005H) and SHD 9795P (TP : LKK REF - CC3/AXA17023839/Kpa3) on 11.12.2017

Type

📧 Question

Message

please advise the repair limit of TP vehicle. Also, TP vehicle was damaged on the front portion but the COR is so high. kindly advise

Reply

TP Veh	SHD 9795P
Date of Reg	14.04.2014
DOA	11.12.2017
COE Expiry Date	13.04.2022

\$

<u>(I) Estimated Book Value</u>	
Unit Cost	38,000.00 (est)
Import Duty	3,999.60 OMV x15%
Registration Fee	140.00
PQP Paid	59,871.00
ARF Paid	12,498.00
Estimated Per Taxi Purchase Price	114,508.60
Estimated Per Taxi Purchase Price	114,508.60
Less 60% of ARF Paid	7,498.80
Estimated Full Lifespan Depreciation	107,009.80
Estimated Full Lifespan Depreciation	107,009.80
Times Balance Life (52/96 months)	57,963.64
Add 60% of ARF Paid	7,498.80
Estimated Book Value	65,462.44

58692.69

<u>(II) Adjusted LTA Rebate</u>	
PARF Rebate	9,373.00
PQP Paid	59,871.00
Times Balance Life (52/96 months)	
Adjusted COE Rebate	32,430.13
PARF Rebate	9,373.00
Add Adjusted COE Rebate	32,430.13
Adjusted LTA Rebate	41,803.13

<u>(Summary) Estimated Nett Value</u>	
Estimated Book Value	65,462.44
Less Adjusted LTA Rebate	41,803.13
Estimated Net Value	23,659.31



Wearnes Automotive Pte. Ltd.
23 Ling Kee Road
Singapore 159105

Telephone: +65 6471 3313
Facsimile: +65 6471 3303
Internet: www.renault.com.sg

Sample / ref.

GST Reg No. : M2-8920628X
Tax Invoice No. : R1015351-1015400
Date : 27/12/2013
ST: R

Invoice to:
r05417
TRANS-CAB SERVICES PTE LTD
58 DEFU LANE 1
DEFU INDUSTRIAL ESTATE
SINGAPORE 539498

Deliver To:
r05417
TRANS-CAB SERVICES PTE LTD
58 DEFU LANE 1
DEFU INDUSTRIAL ESTATE
SINGAPORE 539498

Model:
Latitude 2.0A Diesel

Colour:
NXD/ / ORIENTAL RED

VSB:
Refer to Attached

Order No:
r05417

Engine No:
Refer To Attached

Chassis No.
Refer To Attached

Sales Consultant:
Jay Tan

Reg No.
Refer To Attached

Description	Value/ Unit	Unit	GST (7%) @ 50 unit	Amount (S\$)
Vehicle Price	38,953.40	50	92,594.00	2,040,254.00
Road Tax	2,907.00	50	-	145,350.00
Registration Fee	140.00	50	-	7,000.00
COE Quote Premium	62,740.00	50	-	3,137,000.00
Custom Duty	3,999.60	50	13,996.50	213,976.50
Insurance	1,926.00	50	-	96,300.00
Equipment- Taximeter	600.00	50	2,100.00	32,100.00

Vehicle Total Price incl GST

DOWNPAYMENT

Amount payable by Trans-Cab Services Pte Ltd

5,671,992.50
5,104,793.00
567,199.50

This is a computer-generated invoice. No signature is required

E. & O. E.

	Supply	GST
TRANS-CAB SERVICES PTE CBS BANK LIMITED	1,552,750.00	108,692.50
Taxable	1,552,750.00	108,692.50
Non-taxable	4,010,550.00	-
	5,563,300.00	108,692.50

Please quote this invoice number when making payment.
Please remit payment to:
Oversea-Chinese Banking Corporation Limited
OCBC Centre Branch
85 Chulia Street, Singapore 049513
Bank Code: 7133
Branch Code: 501
Bank Account Name: Wearnes Automotive Pte Ltd
Bank Account: 296727-001
SWIFT CODE: OCB-SCG66
Cheques should be crossed and made payable to "Wearnes Automotive Pte Ltd"



<SEEK MANDATE> - S7M005H1 [ACCIDENT INVOLVING SKW 803Z(OI) & SHD 9795P(TP) ON 11/12/2017]

Type

🔗 Question

Message

Liability: 100%. Insured made right turn and collided with third party who was driving straight. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate up to \$20,850.79(all-in). IA with mandate had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong – 11 Oct 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVENUE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 11.10.2018

Survey Details:

Date of loss	11.12.2017
Date of appointment	14.12.2017
Date of survey	14.12.2017
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHD 9795P
Make and Model	Renault Latitude (1995cc)
Date of registration	14.04.2014
Excess	NIL
Market Value/ Book Value	\$ 59,400.00 (est)
Parf/COE Rebate	\$ 41,823.00 (est)
Nett Loss	\$ 17,577.00 (est)

Repair details:

Initial Estimate	\$ 88,960.27
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 29,530.27
Check items (estimate)	NIL
Labour	\$ 2,630.00
Supplementary	NIL
Total	\$ 32,160.27
Lump Sum(if applicable)	\$ 17,500.00

Number of days for repair	<u>10</u>
---------------------------	-----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date:

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 18,725.00	
Loss of use	NIL	
Loss of rental	\$ 1,420.44	(14days x \$101.46)
Loss of income	\$ 700.00	(14days x \$50.00)
LTA/GIA search fees	\$ 5.35	
Others	NIL	
Proposed Total	\$ 20,850.79	



Re:RE: Re:<SEEK MANDATE> - S7M005H1 [ACCIDENT INVOLVING SKW 803Z(OI) & SHD 9795P(TP) ON 11/12/2017]

Type

🔗 Question

Message

PLS PROCEED

Reply

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 18 May 2019 9:37 AM
To: 'jasminetan@transcab.com.sg'; Ng Wai Yin; claims@transcab.com.sg
Subject: Your ref: AAD1712-116 (SHD 9795P) *Our Ref: CC3/ASM17023839/Kpa3 [ACCIDENT INVOLVING SKW 803Z(AXA) AND SHD 9795P ON 11/12/2017]

Your ref: **AAD1712-116 (SHD 9795P)**
Our Ref: CC3/ASM17023839/Kpa3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SKW 803Z(AXA) AND SHD 9795P ON 11/12/2017

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$20,800.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Tuesday, 21 May 2019 7:03 PM
To: Hsiao Tong (LKKAUTO); 'Ng Wai Yin'; claims@transcab.com.sg
Subject: RE: Your ref: AAD1712-116 (SHD 9795P) *Our Ref: CC3/ASM17023839/Kpa3 [ACCIDENT INVOLVING SKW 803Z(AXA) AND SHD 9795P ON 11/12/2017]

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, 18 May 2019 9:37 AM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg
Subject: Your ref: AAD1712-116 (SHD 9795P) *Our Ref: CC3/ASM17023839/Kpa3 [ACCIDENT INVOLVING SKW 803Z(AXA) AND SHD 9795P ON 11/12/2017]

Your ref: **AAD1712-116 (SHD 9795P)**
Our Ref: CC3/ASM17023839/Kpa3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SKW 803Z(AXA) AND SHD 9795P ON 11/12/2017

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$20,800.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1712-116

Your Ref : SKW803Z

Date : 03.June 2019

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SHD9795P AND SKW803Z ON 11/12/17 09:20 AM ALONG TAMPINES AVE 2 TOWARDS TAMPINES STREET 31

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	18,725.00
2.	Loss of Rental for <u>14</u> days @ \$ <u>101.46</u> per day	\$	1,420.44
3.	Loss of Income for <u>14</u> days @ \$ <u>50.00</u> per day	\$	700.00
4.	LTA Search Fee	\$	5.35
5.	Survey Fee	\$	0.00
	Total	\$	20,850.79

We enclose a copy of the following documents for your consideration :-


GIA report lodged by our driver
Certificate of Insurance
Original final repair bill

Rental rate and mileage records
Authorization To Act
LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKW 803Z (Insd veh)	Model:	RENAULT LATITUDE (A)
	SHD 9795P (TP veh)		
Date of Accident:	11/12/2017		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$		95,187.49
Final Repair Cost	:	\$		18,725.00
Loss of Token Sum	:	\$		700.00
				14 days at \$50.00 per day
Rental (if any)	:	\$		1,420.44
				14 days
LTA / GIA Search Fee	:	\$		5.35

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum (GOLBAL SUM)	:	\$	20,800.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: 5

BOLA Liability: 100 (%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST 63 SINGAPORE 569111

Payment Instruction: Payee's Breakdown			
1)	TRANS-CAB AUTO SERVICES PTE LTD	:	\$ 20,800.00

NUR SHAQILAH BTE ABDOL
WAHAB

21/06/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/ASM17023839/Kpa3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 21-06-2019



ATTN: STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKW 803Z	Veh. Inspected	SHD 9795P
Policy No.	GA276256	Coverage (\$)	0.00
Claim No.	S7M005H1	Excess (\$)	0.00
Assign From		Assign Date	14/12/2017

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC277284	Colour	METALLIC WHITE / RED
Odometer	337344	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	FALKEN	6 mm
L/H Front Tyre	215/60R16	FALKEN	6 mm
R/H Rear Tyre	215/60R16	LING LONG	5 mm
L/H Rear Tyre	215/60R16	LING LONG	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2017	Inspection Date	14/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9795P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER FRT (CONSISTENT)	BENT	1,259.42	1,259.42
1	BUMPER SPOILER FRT (CONSISTENT)	DISTORTED	181.75	181.75
1	BUMPER ABSORBER FRT (CONSISTENT)	MISSING	394.68	394.68
1	BUMPER RETAINER FRT LH (CONSISTENT)	CRACKED	151.41	151.41
1	BUMPER SUPPORT FRT (CONSISTENT)	DISTORTED	123.88	123.88
1	BUMPER RETAINER FRT RH (CONSISTENT)	DISTORTED	150.77	150.77
1	BUMPER SUPPORT FRT (CONSISTENT)	REPEATED	123.88	-
1	BUMPER UNDERTRAY FRT (CONSISTENT)	MISSING	472.83	472.83
1	BUMPER GRILLE LOWER FRT (CONSISTENT)	DISTORTED	266.80	266.80
1	BUMPER FOG LAMP GRILLE LH (CONSISTENT)	MISSING	207.21	207.21
1	BUMPER BEAM FRT (CONSISTENT)	BENT	914.08	914.08
1	TOW COVER FRT (CONSISTENT)	SERVICEABLE	28.61	-
1	RADIATOR GRILLE (CONSISTENT)	CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT' (CONSISTENT)	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME (CONSISTENT)	BROKEN	1,353.75	1,353.75
1	FRAME FULL SUPPORT PANEL (CONSISTENT)	CRACKED	615.90	615.90
1	FRAME FULL SUPPORT BRACKET (CONSISTENT)	BENT	89.79	89.79
1	FRONT BRACE PANEL (CONSISTENT)	BENT	177.22	177.22
1	HORN (CONSISTENT)	SERVICEABLE	314.17	-
1	HORN BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH (CONSISTENT)	CRACKED	1,184.43	1,184.43
1	HEADLAMP RH (CONSISTENT)	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH (CONSISTENT)	BENT	152.15	152.15
1	HEADLAMP PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-
1	BONNET (CONSISTENT)	BENT	1,941.63	1,941.63
1	BONNET INSULATOR (CONSISTENT)	DEFORMED	405.73	405.73
1	BONNET STRUT LH (CONSISTENT)	SERVICEABLE	88.61	-
1	BONNET STRUT RH (CONSISTENT)	SERVICEABLE	88.61	-
1	BONNET HINGE LH (CONSISTENT)	DISTORTED	348.31	348.31

Report Ref No. CC3/ASM17023839/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK (CONSISTENT)	BENT	305.48	305.48
1	BONNET CABLE (CONSISTENT)	SERVICEABLE	119.19	-
1	BONNET CABLE COVER (CONSISTENT)	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER (CONSISTENT)	SERVICEABLE	92.36	-
1	BONNET SEAL INNER (CONSISTENT)	SERVICEABLE	157.28	-
1	CHASSIS PANEL REINFORCEMENT FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,095.24	-
1	FENDER PANEL FRT LH (CONSISTENT)	BUCKLED	783.83	783.83
1	FENDER PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH (CONSISTENT)	CRACKED	278.84	278.84
1	WHEELARCH FRT RH (CONSISTENT)	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH (CONSISTENT)	BENT	15.79	15.79
1	FENDER BRACKET LOWER RH (CONSISTENT)	TO REPAIR SEE LABOUR	15.79	-
1	FENDER INSULATOR LH (CONSISTENT)	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH (CONSISTENT)	SERVICEABLE	130.84	-
1	LOWER ARM LH (CONSISTENT)	SERVICEABLE	685.76	-
1	KNUCKLE ARM LH (CONSISTENT)	SERVICEABLE	846.98	-
1	KNUCKLE HUB+BEARING LH (CONSISTENT)	SERVICEABLE	497.69	-
1	ABSORBER FRT LH (CONSISTENT)	SERVICEABLE	360.54	-
1	AIR CLAENER LOWER (CONSISTENT)	CRACKED	271.26	271.26
1	AIR CLEANER HOSE (CONSISTENT)	DENTED	76.14	76.14
1	AUTO COMPUTER (CONSISTENT)	SERVICEABLE	5,032.17	-
1	STEERING PUMP ELECTRIC (CONSISTENT)	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK (CONSISTENT)	TO REPAIR SEE LABOUR	4,413.11	-
1	ENGINE HARNESS (CONSISTENT)	SERVICEABLE	4,084.54	-
1	SUBFRAME OUTER FRT (CONSISTENT)	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH (CONSISTENT)	TO REPAIR SEE LABOUR	92.36	-
1	SUBFRAME BRACKET OUTER RH (CONSISTENT)	TO REPAIR SEE LABOUR	92.36	-

Report Ref No. CC3/ASM17023839/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ENGINE UNDERTRAY (CONSISTENT)	REPEATED	564.98	-
1	BASE BATTERY TRAY (CONSISTENT)	SERVICEABLE	363.40	-
1	AIR CLEANER BOX (CONSISTENT)	SERVICEABLE	464.20	-
1	A/C CONDENSER (CONSISTENT)	BENT	2,020.37	2,020.37
1	A/C CONDENSER GARNISH LH UPPER (CONSISTENT)	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER (CONSISTENT)	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH (CONSISTENT)	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH (CONSISTENT)	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR (CONSISTENT)	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPANSION VALVE (CONSISTENT)	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR (CONSISTENT)	SERVICEABLE	334.29	-
1	A/C PIPE (CONSISTENT)	SERVICEABLE	658.72	-
1	A/C COMPRESSOR (CONSISTENT)	SERVICEABLE	2,684.61	-
1	AIR COOLER (CONSISTENT)	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG) (CONSISTENT)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT) (CONSISTENT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER (CONSISTENT)	SERVICEABLE	1,219.30	-
1	TRANSFERMISSION COOLER PAD (CONSISTENT)	SERVICEABLE	17.96	-
1	RADIATOR (CONSISTENT)	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER (CONSISTENT)	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER (CONSISTENT)	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER (CONSISTENT)	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING (CONSISTENT)	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH (CONSISTENT)	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH (CONSISTENT)	SERVICEABLE	1,479.46	-
1	RADIATOR TANK (CONSISTENT)	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER (CONSISTENT)	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER (CONSISTENT)	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE (CONSISTENT)	SERVICEABLE	61.18	-
1	WINDSCREEN FRT (CONSISTENT)	SERVICEABLE	1,364.06	-
1	SEATBELT LH (CONSISTENT)	JAMMED	2,937.80	2,937.80
1	SEATBELT RH (CONSISTENT)	JAMMED	2,925.37	2,925.37

Report Ref No. CC3/ASM17023839/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SEATBELT BUCKLE LH (CONSISTENT)	SERVICEABLE	984.13	-
1	SEATBELT BUCKLE RH (CONSISTENT)	SERVICEABLE	949.80	-
1	PASSENGER AIRBAG (CONSISTENT)	BURST	3,412.40	3,412.40
1	STEERING AIRBAG (CONSISTENT)	SERVICEABLE	2,525.75	-
1	AIRBAG COMPUTER (CONSISTENT)	SERVICEABLE	1,259.82	-
1	AIRBAG SENSOR (CONSISTENT)	NECESSARY	724.63	724.63
1	AIRBAG SENSOR (CONSISTENT)	NECESSARY	289.30	289.30
1	ROTARY SWITCH (CONSISTENT)	NECESSARY	1,253.11	1,253.11
1	DASHBOARD (CONSISTENT)	TORN	4,900.54	4,900.54
	LESS 10% DISCOUNT		-8,126.42	-3,251.97
			73,137.87	29,267.77
	<u>SPECIAL NETT ITEMS</u>			
1	SET RADIATOR GRILLE FRAME CLIP (SN) (CONSISTENT)	NECESSARY	52.00	52.00
1	SET BUMPER CLIP FRT (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN) (CONSISTENT)	NOT NECESSARY	14.50	-
1	SET RADIATOR GRILLE SCREW (SN) (CONSISTENT)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN) (CONSISTENT)	NECESSARY	69.00	69.00
1	SET FRAME FULL SUPPORT PANEL CLIP (SN) (CONSISTENT)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN) (CONSISTENT)	SERVICEABLE	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN) (CONSISTENT)	SERVICEABLE	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN) (CONSISTENT)	NECESSARY	30.50	30.50
1	SET WHEELARCH CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	29.40	-
1	CAP HUB LH FRT (SN) (CONSISTENT)	SERVICEABLE	35.00	-
1	RIM LH FRT (SN) (CONSISTENT)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN) (CONSISTENT)	SERVICEABLE	330.00	-
1	CAP HUB RH FRT (SN) (CONSISTENT)	SERVICEABLE	35.00	-
1	RIM RH FRT (SN) (CONSISTENT)	SERVICEABLE	385.00	-

Report Ref No. CC3/ASM17023839/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TYRE RH FRT (SN) (CONSISTENT)	SERVICEABLE	330.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN) (CONSISTENT)	DENTED	80.00	45.00
1	DOOR STICKER "6555-3333" LH (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	DOOR STICKER "6555-3333" RH (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
			2,182.40	262.50
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF HORN BRACKET, HEADLAMP PANEL FRT RH, BONNET HINGE RH, CHASSIS PANEL REINFORCEMENT FRT LH, FENDER PANEL FRT RH, FENDER BRACKET LOWER RH, STEERING PINION RACK, SUBFRAME BRACKET OUTER LH AND SUBFRAME BRACKET OUTER RH.		4,200.00	900.00
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	1,100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.		480.00	240.00
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-

Report Ref No. CC3/ASM17023839/Kpa3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.		440.00	60.00
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO REPLACE , REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.		170.00	50.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			13,640.00	2,630.00
GRAND TOTAL			88,960.27	32,160.27

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			17,500.00
--	--	--	-----------

Report Ref No. CC3/ASM17023839/Kpa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.