

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9795P - AXA**AAD1712-116***Not Authorized
L/Sy &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD9795P - JHOW

VF1ABL15AUC277284

RENAULT

LATITUDE

11.12.2017

AXA

PART			LIST		
1	1	BUMPER COVER FRT	\$	<i>Ry</i> 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>Diy</i> 181.75	✓
3	1	BUMPER ABSORBER FRT	\$	<i>M.Y</i> 394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	<i>CM</i> 151.41	✓
5	1	BUMPER SUPPORT FRT	\$	<i>Diy</i> 123.88	✓
6	1	BUMPER RETAINER FRT RH	\$	<i>Diy</i> 150.77	✓
7	1	BUMPER SUPPORT FRT	\$	<i>Reform</i> 123.88	X
8	1	BUMPER UNDERTRAY FRT	\$	<i>M.Y</i> 472.83	✓
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Diy</i> 266.80	✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>M.Y</i> 207.21	✓
11	1	BUMPER BEAM FRT	\$	<i>Ry</i> 914.08	✓
12	1	TOW COVER FRT	\$	<i>Sm</i> 28.61	X
13	1	RADAIOR GRILLE	\$	<i>CM</i> 1,707.78	✓
14	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Nu</i> 225.36	✓
15	1	RADAIOR GRILLE FRAME	\$	<i>Bu</i> 1,353.75	✓
16	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90	✓
17	1	FRAME FULL SUPPORT BRACKET	\$	<i>Bu</i> 89.79	✓
18	1	FRONT BRACE PANEL	\$	<i>Bu</i> 177.22	✓
19	1	HORN	\$	<i>Sm</i> 314.17	X
20	1	HORN BRACKET	\$	<i>N</i> 40.45	X
21	1	HEADLALMP LH	\$	<i>CM</i> 1,184.43	✓
22	1	HEADLALMP RH	\$	<i>Sm</i> 1,184.43	X
23	1	HEADLAMP PANEL FRT LH	\$	<i>Ry</i> 152.15	✓
24	1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15	X
25	1	BONNET	\$	<i>Ry</i> 1,941.63	✓
26	1	BONNET INSULATOR	\$	<i>Reform</i> 405.73	✓
27	1	BONNET STRUT LH	\$	<i>Sm</i> 88.61	X
28	1	BONNET STRUT RH	\$	<i>Sm</i> 88.61	X
29	1	BONNET HINGE LH	\$	<i>Diy</i> 348.31	✓
30	1	BONNET HINGE RH	\$	<i>N</i> 348.31	X
31	1	BONNET LOCK	\$	<i>Ry</i> 305.48	✓
32	1	BONNET CABLE	\$	<i>Sm</i> 119.19	X
33	1	BONNET CABLE COVER	\$	<i>Sm</i> 161.03	X
34	1	BONNET SEAL OUTER	\$	<i>Sm</i> 92.36	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9795P - AXA**AAD1712-116**

35	1	BONNET SEAL INNER	\$	157.28	X
36	1	CHASSIS PANEL REINFORCEMENT FRT LH	\$	1,095.24	X
37	1	FENDER PANEL FRT LH	\$	783.83	✓
38	1	FENDER PANEL FRT RH	\$	783.83	X
39	1	WHEELARCH FRT LH	\$	278.84	✓
40	1	WHEELARCH FRT RH	\$	278.84	X
41	1	FENDER BRACKET LOWER LH	\$	15.79	✓
42	1	FENDER BRACKET LOWER RH	\$	15.79	X
43	1	FENDER INSULATOR LH	\$	130.84	X
44	1	FENDER INSULATOR RH	\$	130.84	X
45	1	LOWER ARM LH	\$	685.76	X
46	1	KUNCKLE ARM LH	\$	846.98	X
47	1	KUNCKLE HUB+BEARING LH	\$	497.69	X
48	1	ABSORBER FRT LH	\$	360.54	X
49	1	AIR CLEANER LOWER	\$	271.26	✓
50	1	AIR CLEANER HOSE	\$	76.14	✓
51	1	AUTO COMPUTER	\$	5,032.17	?
52	1	STEERING PUMP ELECTRIC	\$	2,306.90	?
53	1	STEERING PINION RACK	\$	4,413.11	X
54	1	ENGINE HARNESS	\$	4,084.54	?
55	1	SUBFRAME OUTER FRT	\$	2,652.45	?
56	1	SUBFRAME BRACKET OUTER LH	\$	92.36	X
57	1	SUBFRAME BRACKET OUTER RH	\$	92.36	X
58	1	ENGINE UNDERTRAY	\$	564.98	X
59	1	BASE BATTERY TRAY	\$	363.40	?
60	1	AIR CLEANER BOX	\$	464.20	X
61	1	A/C CONDENSER	\$	2,020.37	✓
62	1	A/C CONDENSER GARNISH LH UPPER	\$	39.67	X
63	1	A/C CONDENSER GARNISH RH UPPER	\$	39.67	X
64	1	A/C CONDENSER GARNISH LH	\$	58.81	X
65	1	A/C CONDENSER GARNISH RH	\$	59.60	X
66	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39	X
67	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72	X
68	1	A/C PIPE COMPRESSOR	\$	334.29	X
69	1	A/C PIPE	\$	658.72	?
70	1	A/C COMRPRESSOR	\$	2,684.61	X
71	1	AIR COOLER	\$	792.60	?
72	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	?
73	1	AIR INTERCOOLER HOSE (Short)	\$	375.14	?
74	1	TRANSMISSION COOLER	\$	1,219.30	X
75	1	TRANSMISSION COOLER PAD	\$	17.96	X
76	1	RADIATOR	\$	1,202.20	?

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9795P - AXA**AAD1712-116**

77	2	RADIATOR STUD UPPER	\$	14.41	X
78	2	RADIATOR BUSH UPPER	\$	50.12	X
79	2	RADIATOR MTG LOWER	\$	55.85	X
80	1	RADIATOR FAN COWLING	\$	820.54	?
81	1	RADIATOR FAN MOTOR LH	\$	967.36	?
82	1	RADIATOR FAN MOTOR RH	\$	1,479.46	?
83	1	RADIATOR TANK	\$	324.62	?
84	1	RADIATOR HOSE UPPER	\$	240.56	?
85	1	RADIATOR HOSE LOWER	\$	491.18	?
86	1	RADIATOR TANK HOSE	\$	61.18	X
87	1	WINDSCREEN FRT	\$	1,364.06	X
88	1	SEATBELT LH	\$	2,937.80	✓
89	1	SEATBELT RH	\$	2,925.37	✓
90	1	SEATBELT BUCKLE LH	\$	984.13	?
91	1	SEATBELT BUCKLE RH	\$	949.80	?
92	1	PASSENGER AIRBAG	\$	3,412.40	✓
93	1	STEERING AIRBAG	\$	2,525.75	?
94	1	AIRBAG COMPUTER	\$	1,259.82	?
95	1	AIRBAG SENSOR	\$	724.63	✓
96	1	AIRBAG SENSOR	\$	289.30	✓
97	1	ROTARY SWITCH	\$	1,253.11	✓
98	1	DASHBOARD	\$	4,900.54	✓

TOTAL	\$	81,264.30
10%	\$	8,126.43
	\$	73,137.87

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00	X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	X
7	1	TOW COVER FRT	\$	14.50	X
8	1SET	RADIATOR GRILLE SCREW	\$	16.00	X
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	✓
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	X
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	X
13	1SET	WHEELARCH CLIP FRT LH	\$	30.50	✓
14	1SET	WHEELARCH CLIP FRT RH	\$	29.40	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9795P - AXA**AAD1712-116**

15	1	CAP HUB LH FRT	\$	Sn	35.00	X
16	1	RIM LH FRT	\$	Sn	385.00	X
17	1	TYRE LH FRT	\$	Sn	330.00	X
18	1	CAP HUB RH FRT	\$	Sn	35.00	X
19	1	RIM RH FRT	\$	Sn	385.00	X
20	1	TYRE RH FRT	\$	Sn	330.00	X
21	1SET	Front licence plate with holder	\$	Pl	80.00	45Sn
22	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00	X
23	1	DOOR STICKER "6555-3333" RH	\$	nn	80.00	X

TOTAL	\$	2,182.40
TOTAL PARTS	\$	75,320.27

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	90d
Towing Fees.	\$	120.00	5d
To apply paint protection system (PPS) maintain and enhancement	\$	nn	380.00 X
Putty and spray painting of the affected portion.	\$	4,500.00	110d
To rust-proofing of the affected areas.	\$	170.00	6d
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn	380.00 X
To check steering geometry and computer wheel alignment	\$	nn	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	2d
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	} ?
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	
To remove and refit air bag system and reset.	\$	480.00	24d

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9795P - AXA**AAD1712-116**

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nn</i> 380.00 <i>X</i>
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 <i>601</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>nn</i> 380.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	380.00 <i>1001</i>
To replace, refix and top up coolant for radiator	\$	170.00 <i>501</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 <i>501</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>

TOTAL	\$	13,640.00
Over All Total	\$	88,960.27

< parts by parts > Repair Days

*15 DAYS**9 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: