

ASS. REC. BY

REF: CS / MSG17023842 / Ktd321

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time:

15/12/17 @ 2:58pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW900B

Insured:

GW2595H

at Workshop m/s:

Lim Tan Motor

Tel:

6462 0893

of Blk 176 Sin Ming Drive #03-09/10, 575721

Policy No:

A26737899 TMV

Claim No:

540891

Sum insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13/12/2017

CA / REV / REF. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

3:14pm @ 15/12/17

Person Contacted

Richard

Vehicle: IN PORT

Date/Time

Action/Instruction

(✓) Estimate

SKW900B - x

GW2595H - Colours 1122 / K17502

D.O.A. 13/12/17

Part by Part \$21541 - Cred: 1500.90 (41%)

ASS. REC. BY:

REF:

MSG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 60 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKW900B Yr Regn: 08, 09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes 3 c.c. 1500Colour: Black A/C: Insured / Std / NI / NASp. Reading: 78138 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BL1081A0710737Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 13/12/17

Rear

R/Bal. 5 mmL/Bal. 5 mmD.O.I. 15/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/12 File pass to Customer

Date/Time, File Pass to?

11/10/17 Typist

Date/Time, File Return to?

2

Report Format: TPLump Sum / I.B.I.: \$ 21541☐ : Prell. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)Survey Fee: 200

Transportation: _____

S - RS: _____

Photos: 10

Others: _____

TOTAL

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17023842/Ktd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 2595H	Veh. Inspected	SKW 900B
Policy No.	A26737899TMV	Coverage (\$)	0.00
Claim No.	540891	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	15/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/12/2017	Inspection Date	15/12/2017
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

View	Notified	Est. Settlement	Adj. Assigned	Adj. Not	Adj. Submitted	Imm. Advice	Status
Main	15 Dec 2017 10:43	15 Dec 2017 12:09	15 Dec 2017 14:58				New Assignment Cancel Case
	Sendback Est	S\$3,478.90	Assign				

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: SHIMAYA TRADING PTE LTD, Co. Reg. No.: 199001589M									
Main Claimant: B&E LEASING, Co. Reg. No.: 53290083M									
Vehicle Reg. No.: SKW900B		Date of Loss: 13/12/2017 09:00 - :59							
Claim Type: TP / 540891		Policy/Cover Note No.: A26737899TMV (Third Party Only)	Coverage: 03/05/2017 - 02/05/2018						
Vehicle Reg. No. (Insured): GW2595H		Policy No. (Claimant): SI17V13415/VPE/R02	Excess:						
Repairer: Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]									
Claimant's Insurer: Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm. Advice due 16/12/2017]									
Driver/Custodian (Insured): SARAVANAN A/L SELLVEM (34 / Male), NRIC: G7474108N, Tel: +6588189759		Vehicle Source: Drive/Walk-in							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/12/2017 10:21
Date Of Accident	13/12/2017 09:50
Exact Location Of Accident	SLE TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW900B
Insured/Policyholder	
Name Of Registered Owner	B&E LEASING
Co Reg No	53290083M
Email Address	ESTHEROEI@BEGROUP.COM.SG
Mobile Phone No	(LOCAL) +65-98442820
Alternative Phone No	Office-67536882

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3 1.6L SDN

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? **NO**

If No, Please state action to be taken **THIRD PARTY**

Vehicle Category **PRIVATE CAR**

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SH17V13415A/PE/R02
Cover Note Number	

Driver


Name of Driver	LIM BUAY TIANG
NRIC No	S0135754I
Date Of Birth	26/01/1954
Occupation	INDOOR
Date Of Driving Pass	25/08/1979
Driving Experience	38 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90232966
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL
Address	BLK 148 LORONG 1 TOA PAYOH #08-911

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the **accident** to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow our insurance companies to **revoke policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA), for archiving and that copies of this report will for a fee be made available upon application by a interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of the report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - a. My insurer, my workshop and the General Insurance Association of Singapore (GIA) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form (together with other personal information provided by me or possessed by my insurer (collectively the "Personal Information"), and disclose and transfer such Personal Information to all insured(s) who have insured vehicle(s) involved in this accident (all insured(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers" or the Insurers, Lawyers/Law firms, the Monetary Authority of Singapore and any relevant government agency/ authority in this policy), for the purpose(s) of:
 - i. processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - ii. investigating the accident and/or my claims;
 - iii. carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - iv. administering my claims including the making of a legal declaration, statement, evidence, receipt or notices to me, which may involve disclosure of certain personal data/information to help about discovery of the facts as well as on the material aspects of my responsibility (package(s)), and/or;
 - v. complying with any civil law or administrative, processing, handling and/or dealing with my claims including the Purpose(s).
 - b. Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers, Lawyers/Law firms, may are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes and:
 - c. My Personal Information may be disclosed by myself, the Insurers and/or GIA to their third parties, including providers of legal services (including the lawyers/Law firms), which may be collected outside of Singapore, for one or more of the above purposes;
 - d. My Personal Information may be collected, stored and used to complete claims to date for the purpose of the data subject's compensation and may be used in present and all future claims;
 - e. I understand that I have voluntarily agreed to my Personal Information:
 - i. to be used for one or more of the above purposes that are not including any sharing of the data with any third party (except the Insurers, Lawyers/Law firms and government agencies as reasonably required for the purposes stated);
 - ii. to be collected, stored and/or processed under any applicable laws or regulations.


Lim Keng Hong
Policyholder's Signature
14 Dec 2017
H. Lim




Lim Keng Hong
Authorized Driver's Signature
(if driver is not the policyholder)
14 DEC 2017
H. Lim


Ang Wei Guang
Ang Wei Guang
14 DEC 2017
ANG WEI GUANG
S6410708F

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Business
Owner ID	0083M

Vehicle Details

Vehicle No.	SKW900B
Vehicle to be Exported	Yes
Intended De-registration Date	14 Dec 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 1.6L SDN
Primary Colour	Red
Manufacturing Year	2009
Engine No.	Z6802414
Chassis No.	JM6BL1QZ1A0110737
Maximum Power Output	77.0 kW (103 bhp)
Open Market Value	\$19,925.00
Original Registration Date	26 Aug 2009
First Registration Date	26 Aug 2009
Transfer Count	2
Actual ARF Paid	\$19,925.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	25 Aug 2019
PARF Rebate Amount	\$10,958.00

Intended COE Rebate Details

COE Expiry Date	25 Aug 2019
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$15,019.00
COE Rebate Amount	\$2,547.00
Total Rebate Amount	\$13,505.00

The information contained herein is correct as at 14 Dec 2017

OK



Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721

Tel : 65-64520893 Fax : 65-64589127 Email : sales@ltm.sg

Website : www.ltm.sg

Co.Reg No. : 199307277D GST Reg No. : M2-0119086-0

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

UNKNOWN

UNKNOWN

Singapore

Survey By

Date : Time 15 DEC 2017

Claimant Insurer: Liberty Insurance Pte Ltd

3.30pm

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY

Policy No:

Vehicle Reg. No.: SKW900B

Party At Fault: UNKNOWN

Driver (TP): LIM BUAY TIANG

Ref. No:

Date of Loss: 13/12/2017

Driveable?

Driver (Insured): SARAVANAN A/L SELVEM

Make/Model: MAZDA 3, 1.6 L (A)

Vehicle Colour: RED

Engine No: Z6802414

Odometer: 78138 KM

Vehicle Reg. Date: 26/08/2009

Chassis No: JM6BL10Z1A0110737

Paint Type:

Total Loss? NO

Est. Duration of Repair (day)

10 4 days

NOT AUTHORIZED

Recovery B/P pending

Description of Accident/Loss

ON THE ABOVE DATE, TIME & LOCATION, I WAS DRIVING MY COMPANY VEHICLE (A - SKW900B) AND WAS TRAVELLING ALONG SLE TOWARDS CTE. TRAFFIC WAS HEAVY AND CONGESTED. AS THE FRONT VEHICLES SLOWED DOWN AND STOPPED, I FOLLOW ACCORDINGLY. WHILE MY VEHICLE WAS AT STATIONARY POSITION, I FELT A STRONG IMPACT COMING FROM THE REAR OF MY VEHICLE. I THEN REALISED THAT THERE WAS A LORRY (B - GW2595H) COLLIDED ONTO MY VEHICLE REAR. NO INJURIES WERE INVOLVED. THAT'S ALL.

Present Location: LIM TAN MOTOR PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	2,088.90
Miscellaneous Items	0.00
Labour	690.00
Paintwork Labour	700.00
Towing	0.00
Gross Total (S\$)	3,478.90
+ GST 7.00% (S\$)	243.52
Nett Amount (S\$)	3,722.42

This claim is handled by: ANG WEI GUANG, RICHARD

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Dec 2017)
 Parts: 143 MAZDA 3 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lim Tan Motor Pte Ltd/SKW900B/15/12/2017 12:09
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	0.00	0.00	B *370.00 F ✓
2	2		*REAR BUMPER RETAINER	0.00	0.00	Sm *44.00 F X
3	2		*REAR BUMPER REFLECTOR	0.00	0.00	Sm *50.00 F X
4	10		*REAR BUMPER CLIPS	0.00	NV 0.00	Sm *20.00 F X
5	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	R *190.00 F ?
6	1		*REAR END PANEL	0.00	0.00	R *125.00 F X
7	1		*REAR END PANEL GARNISH	0.00	0.00	Sm *75.00 F X
8	1		*REAR BOOT LID	0.00	0.00	pull/wrap 300 *400.00 F ✓
9	2		*REAR BOOT HINGE	0.00	0.00	X *110.00 F X
10	1		*REAR BOOT TOP LOCK	0.00	0.00	X *65.00 F X
11	1		*REAR BOOT CENTRE EMBLEM	0.00	0.00	R *26.00 F ✓
12	1		*REAR BOOT MAZDA 3 EMBLEM	0.00	0.00	Sm *24.00 F ✓
13	1		*REAR BUMPER REVERSE CAMERA	0	0.00	svc *200.00 FS ?
14	1		*REAR BUMPER REVERSE SENSOR	0	0.00	svc *200.00 FS ?
15	1		*REAR NUMBER PLATE	0	0.00	Sm *40.00 FS X

t=Franchise part. S=Spec/Netl.

Sub Total (\$\$) 1,939.00
 + Margin on L,N Items 10.00% (\$\$) 15% 149.90
 Total Parts (\$\$) 2,088.90

Lim Tan Motor Pte Ltd/SKW900B/15/12/2017 12:09. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hereby notify the Repairer of the following:

- To review the terms, conditions, of claim
- To disclose a high level of liability to the repairer
- Particulars of the claim and the amount
- Third party claim system without prejudice basis
- High level of liability to the repairer
- Supplemental claim to be reviewed and is subject to the approval from the relevant Company

Agreement to policy number
 Signature
 Date

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY AND SPRAY PAINTING.	New	700.00 <i>500</i>
<u>Labour Items</u>			
2	TO CHECK REAR WIRING AND WATER LEAKAGE.	New	30.00 <i>20</i>
3	TO ANTI-RUST.	New	60.00 <i>30</i>
4	LABOUR CHARGES.	New	600.00 <i>500</i>
Gross Labour Cost (S\$)			1,390.00

Lim Tan Motor Pte Ltd/SKW900B/15/12/2017 12:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS**Reference***Supplementary*

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 16 Dec 2017)

Parts: 143

MAZDA 3 1.6 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Lim Tan Motor Pte Ltd/SKW900B/16/12/2017 11:27

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	S1	*KEYLESS ANTENNA	0.00	0.00	CD 100.00 F
2	1	S2	*REAR NUMBER PLATE LAMP	0.00	0.00	CD 60.00 F
Sub Total (S\$)						160.00
+ Margin on L,N Items 10.00% (S\$)						16.00
Total Parts (S\$)						176.00

F=Franchise part

Lim Tan Motor Pte Ltd/SKW900B/16/12/2017 11:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

R DETAILS

reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Dec 2017)
 Parts: 143 MAZDA 3 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard 1.0)
 Print Code: Lim Tan Motor Pte Ltd/SKW900B/15/12/2017 12:09
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1✓	1	*REAR BUMPER			
2	2	2	*REAR BUMPER RETAINER	0.00	0.00	370.00 F ✓
3	2	3	*REAR BUMPER REFLECTOR	0.00	0.00	44.00 F ✓
4	10	4	*REAR BUMPER CLIPS	0.00	0.00	50.00 F ✓
5	1	5	*REAR BUMPER REINFORCEMENT	0.00	0.00	20.00 F ✓
6	1	6	*REAR END PANEL	0.00	0.00	190.00 F ✓
7	1	7	*REAR END PANEL GARNISH	0.00	0.00	125.00 F ✓
8	1✓	8	*REAR BOOT LID	0.00	0.00	75.00 F ✓
9	2	9	*REAR BOOT HINGE	0.00	0.00	400.00 F ✓
10	1	10	*REAR BOOT TOP LOCK	0.00	0.00	110.00 F ✓
11	1✓	11	*REAR BOOT CENTRE EMBLEM	0.00	0.00	05.00 F ✓
12	1✓	12	*REAR BOOT MAZDA 3 EMBLEM	0.00	0.00	26.00 F ✓
13	1	13	*REAR BUMPER REVERSE CAMERA	0.00	0.00	24.00 F ✓
14	1	14	*REAR BUMPER REVERSE SENSOR	0	0.00	200.00 FS ✓
15	1	15	*REAR NUMBER PLATE	0	0.00	200.00 FS ✓
Sub Total (S\$)						1,939.00
+ Margin on L,N Items 10.00% (S\$)						149.90
Total Parts (S\$)						2,088.90

Lim Tan Motor Pte Ltd/SKW900B/15/12/2017 12:09. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Parts \$800.00

Supp \$160.00

\$960.00

+15% \$114.00

\$1101.00

labour \$1050.00

grp \$2151.00

APPROVED

04 days

ates on Miscellaneous Items e no new miscellaneous items selected.

Estimate Report

Estimates on Labour

No Particulars

	Lab.Type	Amount
<u>Paintwork Labour</u>		
1 TO PUTTY AND SPRAY PAINTING.		
<u>Labour Items</u>		
2 TO CHECK REAR WIRING AND WATER LEAKAGE.	New	700.00 <i>500</i>
3 TO ANTI-RUST.	New	30.00 <i>20</i>
4 LABOUR CHARGES.	New	60.00 <i>30</i>
	New	600.00 <i>500</i>
Gross Labour Cost (S\$)		1,390.00

Lim Tan Motor Pte Ltd/SKW9008/15/12/2017 12:09. Not valid without Reference section.
 Generated using Merimon e-Claims IEAS

< END OF ESTIMATES >



Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721

Tel : 65-64580893 Fax : 65-64589127 Email : sales@lim.sg

Website : www.ltm.sg

Co. Reg No. : 199307277D GST Reg No. : MZ-0119086-0

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

UNKNOWN
UNKNOWN
Singapore

Survey By Kenneth (UKK)

Date / Time 15 DEC 2017

Claimant Insurer: Liberty Insurance Pte Ltd

3:30pm

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	13/12/2017
Vehicle Reg. No.:	SKW900B	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LIM BUAY TIANG	Driver (Insured):	SARAVANAN A/L SELLVEM
Make/Model:	MAZDA 3, 1.6 L (A)	Vehicle Reg. Date:	26/08/2009
Vehicle Colour:	RED	Chassis No:	JM6BL10Z1A0110737
Engine No:	Z6802414		
Odometer:	78138 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4 days		

*Not Authenticated
Permy Bpms*

Description of
Accident/Loss

ON THE ABOVE DATE, TIME & LOCATION, I WAS DRIVING MY COMPANY VEHICLE (A - SKW900B) AND WAS TRAVELLING ALONG SLE TOWARDS CTE. TRAFFIC WAS HEAVY AND CONGESTED. AS THE FRONT VEHICLES SLOWED DOWN AND STOPPED, I FOLLOW ACCORDINGLY. WHILE MY VEHICLE WAS AT STATIONARY POSITION, I FELT A STRONG IMPACT COMING FROM THE REAR OF MY VEHICLE. I THEN REALISED THAT THERE WAS A LORRY (B - GW2595H) COLLIDED ONTO MY VEHICLE REAR. NO INJURIES WERE INVOLVED. THAT'S ALL.

Present Location: LIM TAN MOTOR PTE LTD (HQ)

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	2,088.90
Labour	0.00
Paintwork Labour	690.00
Towing	700.00
	0.00
Gross Total (S\$)	3,478.90
+ GST 7.00% (S\$)	243.52
Nett Amount (S\$)	3,722.42

This claim is handled by: ANG WEI GUANG, RICHARD



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGAI KAOUI AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaaauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDUPPER 10.45A
Dept Direct: 6417 8791 / 6745 9429

Arrange By
Driver MIC



Wiper blade: NWB (Nippon Wiper Blade), Siper (Made in Korea)
Front (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

JIM TAN MOTOR PTE LTD
76 SIN MING AUTO CARE
103-09 SIN MING INDUSTRIAL

SINGAPORE 575644
TEL: 64520893 FAX: 64589127
ATTN: THOMAS

TAX INVOICE AR201712-09127
DATE: 15/12/2017
CUSTOMER ID: LJM002
VEH REG. NO.: SKW900B
TERMS: 30 DAYS
PO NO.:
PAGE NO.: Page 1 of 1
CURR: SGD

SQ STOCKID	DESCRIPTION	SL/Loc	QTY	U/PRICE	AMOUNT
1. BM4-50-221 MBR MZ3 SD 09--	RR BUMPER (STD)	PA PL4-G1-01	1	370.00	370.00
2. BBY4-52-61 XD MZ3 BL SD 09--	RR BOOT W/O SPOILER	PA PL3-H1-0213	1	380.00	380.00
3. BM2-67-6ND MZ3 BL 09-12	ANTENNA "D" KEYLESS (RELAY)	PA PL3-G1-06A	1	100.00	100.00

15/12/2017 4:45:24PM

Goods Sold are not refundable for Cash
Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

SUB-TOTAL: 850.00
ADD GST 7.00 % 59.50

TOTAL AMOUNT SGD: 909.50

[E] 15/12/2017 4:38:22PM

JAE Auto Pte Ltd.
Sales Executive: ALAN



This is computer generated document.
Signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGAI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

LIM TAN MOTOR PTE LTD
176 SIN MING AUTO CARE
#03-09 SIN MING IND EST

SINGAPORE 575644

TEL : 64520893 FAX : 64589127

ATTN : THOMAS

JM6BL10Z1A0110737

WIPER BLADES DENSO
Dept Direct: 6417 8707 / 8745 9659



Dept Direct: 6305 8810

Dept Direct: 6305 9611

Dept Direct: 6412 9182



Dept Direct: 6417 8707

Dept Direct: 6417 8707

Dept Direct: 6417 9186

Dept Direct: 6417 9186

Wiper blade: NWB3 (Nipper Wiper Blade, Sealed, Made in Germany)
Furch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE AR201712-0913
DATE 15/12/2017
CUSTOMER ID LIM00
VEH REG. NO. SKW900
TERMS 30 DAY
PO NO.
PAGE NO. Page 1 of
CURR. SGI

SQ STOCKID DESCRIPTION

1. BBY4-51-721/BBM4 MZ3 BL 09- 3 LOGO RR
2. BBM4-51-710(BBY4) MZ3 SD 09- MAZDA RR
3. BBM4-51-730 MZ3 SD 09- MASCOT RR
4. BBM5-51-270D MZ3 BL 09- LICENSE LAMP

StkLoc	QTY	U/PRICE	AMOUNT
U1	1	12.00	12.00
U1L2-SD4-D8			
U1	1	12.00	12.00
U1L2-SD4-C8			
U1	1	26.00	26.00
U1L2-SD4-C7			
U1	1	60.00	60.00
MZ-A38			

SUB-TOTAL 110.00
ADD GST 7.00 % 7.70

[P] 15/12/2017 4:48:14PM

E. & O.E

TOTAL AMOUNT SGD 117.70

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 15/12/2017 4:44:54PM

JAE Auto Pte. Ltd.

Sales Executive : ALAN



* AR 201712-09135 *

This is computer generated document.
No signature is required.

ORIGINAL.

Goods Received in Good Order

Signature / Co Stamp / Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Dec 2017 10:43	15 Dec 2017 12:09	15 Dec 2017 14:58	\$52,154.00	\$52,154.00		Pending for Survey Report Cancel Case
	Sendback Est	\$53,478.90	Edit Adj Rpt	Edit Estimates	View Rpt		
Supp #1	16 Dec 2017 11:24	16 Dec 2017 11:27	16 Dec 2017 11:27			(Combined)	Combined with Main Uncombine Suppl.
		\$5176.00					

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	SHIMAYA TRADING PTE LTD , Co. Reg. No.: 199001589M		
Main Claimant:	B&E LEASING , Co. Reg. No.: S3290083M		
Vehicle Reg. No.:	SKW900B	Date of Loss:	13/12/2017 09:00 - :59
Claim Type:	TP / 540891	Policy/Cover Note No.:	A26737899TMV (Third Party Only) Coverage: 03/05/2017 - 02/05/2018
Vehicle Reg. No. (Insured):	GW2595H	Policy No. (Claimant):	SI17V13415/VPE/RD2
		Excess:	
Repairer:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gak Ing - 6594 2541]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8511		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/01/2018]		
Driver/Custodian (Insured):	SARAVANAN A/L SELVEM (34 / Male), NRIC: G7474108N, Tel: +6588189759		
	Vehicle Source:	Drive/Walk-In	

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKW900B (540891)
[GW2595H]
TP
B&E LEASING
Dec 13 2017 9:00AM
[SHIMAYA TRADING PTE LTD]
Lim Tan Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View In Browser		
Assessment Reports			1 per page	☒	
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)		Thumbnail	Print
1	14/12/17 14:47	Accident Statement	1	Load HTM	
2	15/12/17 12:09	Repairer Estimates	1	Load HTM	
3	16/12/17 11:27	Repairer Estimates Suppl. #1	1	Load HTM	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	15/12/17 14:31	Accident Statement From: SC - Reg. No: GW2595H, Claimant: SHIMAYA TRADING PTE LTD	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/12/17 14:45	Adjuster Immediate Advice	1	Load HTM	
Photos/Images			3 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/01/18 16:31	General View	1	Load JPG	☒
2	10/01/18 16:31	General View	1	Load JPG	☒
3	10/01/18 16:31	General View	1	Load JPG	☒
4	10/01/18 16:31	General View	1	Load JPG	☒
5	10/01/18 16:31	General View	1	Load JPG	☒
6	10/01/18 16:31	General View	1	Load JPG	☒
7	10/01/18 16:31	General View	1	Load JPG	☒
8	10/01/18 16:31	General View	1	Load JPG	☒
9	10/01/18 16:31	General View	1	Load JPG	☒
10	10/01/18 16:31	General View	1	Load JPG	☒
11	10/01/18 16:31	General View	1	Load JPG	☒
12	10/01/18 16:31	General View	1	Load JPG	☒
13	10/01/18 16:31	General View	1	Load JPG	☒
14	10/01/18 16:31	General View	1	Load JPG	☒
15	10/01/18 16:31	General View	1	Load JPG	☒
16	10/01/18 16:31	General View	1	Load JPG	☒
17	10/01/18 16:36	Reinspection Photo	1	Load JPG	☒
18	10/01/18 16:36	Reinspection Photo	1	Load JPG	☒
19	10/01/18 16:36	Reinspection Photo	1	Load JPG	☒
20	10/01/18 16:36	Reinspection Photo	1	Load JPG	☒
21	10/01/18 16:36	Reinspection Photo	1	Load JPG	☒
22	10/01/18 16:36	Reinspection Photo	1	Load JPG	☒
23	10/01/18 16:36	Reinspection Photo	1	Load JPG	☒
24	10/01/18 16:36	Reinspection Photo	1	Load JPG	☒
25	10/01/18 16:36	Reinspection Photo	1	Load JPG	☒
26	10/01/18 16:36	Reinspection Photo	1	Load JPG	☒

Linked Accident Report Documents

View View In Browser

Assessment Reports			1 per page	☒
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	14/12/17 14:47	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	14/12/17 14:13	Accident Photo		Load JPG ☒
2	14/12/17 14:13	Accident Photo		Load JPG ☒
3	14/12/17 14:13	Accident Photo		Load JPG ☒
4	14/12/17 14:13	Accident Photo		Load JPG ☒
5	14/12/17 14:13	Accident Photo		Load JPG ☒
6	14/12/17 14:13	Accident Photo		Load JPG ☒
7	14/12/17 14:13	Accident Photo		Load JPG ☒
8	14/12/17 14:13	Accident Photo		Load JPG ☒
9	14/12/17 14:13	Accident Photo		Load JPG ☒
10	14/12/17 14:13	Accident Photo		Load JPG ☒
11	14/12/17 14:15	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	14/12/17 14:17	Sketch Plan		Load JPG ☒
2	14/12/17 14:17	Sketch Plan #2		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties			

LKK Auto Consultants Pte Ltd (Co Reg No 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023842/KTD3E2

Date: 11/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A26737899TMV
 Claimant Vehicle No: SKW900B Insured Vehicle No: GW2595H
 Date of Loss: 13/12/2017 Nature of Claim: TP Claim No: 540891

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW900B
 Make & Model: MAZDA 3, 1.6 L (A) Engine No: Z6802414
 Reg. Date: 26/08/2009 (Man. Year: 2009) Chassis No: JM6BL10Z1A0110737
 Colour: Metallic Red Odometer: 78138 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,264.90	1,104.00	1,160.90	51.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	690.00	550.00	140.00	20.29
Paintwork Labour	700.00	500.00	200.00	28.57
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,654.90	2,154.00	1,500.90	41.07
+ GST 7.00/7.00% (\$\$)	255.84	150.78	105.06	41.06
Nett Amount (\$\$)	3,910.74	2,304.78	1,605.96	41.07

INSPECTION

Date of Assignment: 15/12/2017 Present Location: Lim Tan Motor Pte Ltd (HQ)
 Date Inspected: 15/12/2017 Inspected At: Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care
 Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Jan 2018)
 Parts: 143 MAZDA 3 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKW900B)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Bent	370.00 F	*370.00 F
2	2		*REAR BUMPER RETAINER (WCP)	Serviceable	44.00 F	*- F
3	2		*REAR BUMPER REFLECTOR (WCP)	Serviceable	50.00 F	*- F
4	10		*REAR BUMPER CLIPS (WCP)	Not Necessary	20.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT (WCP)	Repair	190.00 F	*- F
6	1		*REAR END PANEL (WCP)	Repair	125.00 F	*- F
7	1		*REAR END PANEL GARNISH (WCP)	Serviceable	75.00 F	*- F
8	1		*REAR BOOT LID (WCP)	Dented / Warped	400.00 F	*380.00 F
9	2		*REAR BOOT HINGE (WCP)	Repair	110.00 F	*- F
10	1		*REAR BOOT TOP LOCK (WCP)	Repair	65.00 F	*- F
11	1		*REAR BOOT CENTRE EMBLEM (WCP)	Necessary	26.00 F	*26.00 F
12	1		*REAR BOOT MAZDA 3 EMBLEM (WCP)	Necessary	24.00 F	*24.00 F
13	1		*REAR BUMPER REVERSE CAMERA	Serviceable	200.00 FS	*- FS
14	1		*REAR BUMPER REVERSE SENSOR	Serviceable	200.00 FS	*- FS
15	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
Supplementary #1						
16	1		*KEYLESS ANTENNA (WCP)	Cracked	100.00 F	*100.00 F
17	1		*REAR NUMBER PLATE LAMP (WCP)	Cracked	60.00 F	*60.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,099.00	960.00
+ Margin on L,N Items 10.00/15.00% (\$\$)	165.90	144.00
Total Parts (\$\$)	2,264.90	1,104.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO PUTTY AND SPRAY PAINTING.	New	700.00	500.00
<u>Labour Items</u>				
2	TO CHECK REAR WIRING AND WATER LEAKAGE.	New	30.00	20.00
3	TO ANTI-RUST.	New	60.00	30.00
4	LABOUR CHARGES.	New	600.00	500.00
Gross Labour Cost (\$\$)			1,390.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >