

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CQ/GST REG NO. 201019626G

SHC5355H - AIG**AAD1712-130***Not Authorised*
11 Sep 8320d

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5355H - CANDY

VF1ABL15AUC279374

RENAULT

LATITUDE

13.12.2017

AIG**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bumper</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
4	1	BUMPER RETAINER FRT LH	\$	<i>Div</i> 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
13	1	TOW COVER FRT	\$	<i>SL</i> 28.61
14	1	RADAIOR GRILLE	\$	<i>SL</i> 1,707.78
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
16	1	RADAIOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
17	1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22
20	1	HORN	\$	<i>SL</i> 314.17
21	1	HORN BRACKET	\$	<i>R</i> 40.45
22	1	HEADLAMP LH	\$	<i>mgmt</i> 1,184.43 ✓
23	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15
24	1	BONNET	\$	<i>R</i> 1,941.63
25	1	BONNET INSULATOR	\$	<i>SL</i> 405.73
26	1	BONNET STRUT LH	\$	<i>SL</i> 88.61
27	1	BONNET STRUT RH	\$	<i>SL</i> 88.61
28	1	BONNET HINGE LH	\$	<i>R</i> 348.31
29	1	BONNET HINGE RH	\$	<i>R</i> 348.31
30	1	BONNET LOCK	\$	<i>R</i> 305.48
31	1	BONNET CABLE	\$	<i>SL</i> 119.19
32	1	BONNET CABLE COVER	\$	<i>SL</i> 161.03
33	1	BONNET SEAL OUTER	\$	<i>SL</i> 92.36
34	1	FENDER PANEL FRT LH	\$	<i>Bu</i> 783.83 ✓

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-130**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CQ/GST REG NO. 201019626G

SHC5355H - AIG

35	1	WHEELARCH FRT LH	\$	<i>sn</i> 278.84 X
36	1	FENDER BRACKET LOWER LH	\$	<i>sn</i> 15.79 X
37	1	FENDER INSULATOR LH	\$	<i>sn</i> 130.84 X
38	1	AIR CLEANER LOWER	\$	<i>sn</i> 271.26 X
39	1	AIR CLEANER HOSE	\$	<i>sn</i> 76.14 X

TOTAL	\$	15,799.50
10%	\$	1,579.95
	\$	14,219.55

Specical Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	<i>nn</i> 52.00 X
2	1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00 ✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	<i>nn</i> 12.00
4	1	BUMPER SUPPORT CLIP FRT LH	\$	<i>nn</i> 10.50
5	1	BUMPER BRACKET CLIP FRT RH	\$	<i>nn</i> 12.00
6	1	BUMPER SUPPORT CLIP FRT RH	\$	<i>nn</i> 10.50
7	1	TOW COVER FRT	\$	<i>sn</i> 14.50
8	1SET	RADAIOR GRILLE SCREW	\$	<i>nn</i> 16.00
9	1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>nn</i> 70.00
11	2	FRAME FULL SUPPORT PANEL NUT	\$	<i>sn</i> 20.00
12	2	FRAME FULL SUPPORT PANEL STUD	\$	<i>sn</i> 30.00
14	1SET	WHEELARCH CLIP FRT LH	\$	<i>nn</i> 29.40
15	1	CAP HUB LH FRT	\$	<i>sn</i> 35.00
16	1	RIM LH FRT	\$	<i>sn</i> 385.00
17	1	TYRE LH FRT	\$	<i>sn</i> 330.00

TOTAL	\$	1,161.90
TOTAL PARTS	\$	15,381.45

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 *400*

Towing Fees.

\$ *nn* 120.00 X

To apply paint protection system (PPS) maintain and enhancement

\$ *nn* 380.00 X

To rust-proofing of the affected areas.

\$ 170.00 *300*

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5355H - AIG**AAD1712-130**

Putty and spray painting of the affected portion.	\$	3,000.00	4401
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00	X
TOTAL	\$	7,580.00	
Over All Total	\$	22,961.45	

< parts by parts > Repair Days

~~10 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: