

REPAIR ESTIMATE

14/12/2017 13:44

PbyP
AXA

VEHICLE NO : SHB 2668E

MAKE :

MODEL : TOYOTA PRIUS

Larry

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER <i>X repair</i>			\$ 922.50
REAR TRUNK LID LOCK X			\$ 447.70
REAR TRUNK LID RUBBER X			\$ 357.00
REAR TRUNK LID GLASS (BLACK COLOR) X			\$ 721.30
BOARD ASSY, BACK DOOR TRIM repair ?			\$ 246.90
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>X repair</i>			\$ 889.70
REAR TRUNK LID LOGO(PRIUS) /			\$ 60.80
REAR TRUNK LID LOGO(HYBRID) /			\$ 52.40
REAR TRUNK LID LOGO(TOYOTA STAR) /			\$ 52.90
REAR BUMPER /			\$ 458.60
REAR BUMPER RE-INFORCEMENT /			\$ 318.80
REAR BUMPER UNDER COVER /			\$ 552.60
REAR BUMPER SIDE RETAINER ?			\$ 112.70
REAR BUMPER SPONGE X			\$ 143.40
REAR BUMPER UNDER SIDE COVER (RH) <i>X repair</i>			\$ 167.60
REAR BUMPER UNDER SIDE COVER (LH) /			\$ 232.00
REAR BUMPER UNDER SIDE CENTRE COVER /			\$ 552.60
REAR BUMPER TOWING COVER /			\$ 82.70
REAR BUMPER CLIPS /			\$ 22.00
RETAINER, REAR BUMPER, UPPER SIDE ?			\$ 30.70
RETAINER, REAR BUMPER, SIDE, RH ?			\$ 94.80
RETAINER, REAR BUMPER, SIDE, LH ?			\$ 94.80
SEAL, REAR BUMPER SIDE, RH ?			\$ 148.40
SEAL, REAR BUMPER SIDE, LH ?			\$ 148.40
REAR END PANEL <i>X repair</i>			\$ 602.10
REAR END PANEL GARNISH ?			\$ 121.60
SUB TOTAL			\$ 7,635.00
LESS 25%			\$ 1,908.75
DISCOUNTED TOTAL			\$ 5,726.25
REAR TRUNK LID APPS STICKER /			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER /			\$ 60.00
			\$ 100.00
LABOUR CHARGE			\$ 600
Panel Beating			\$ 850.00
Spray Painting Charge			\$ 580
Wiring Charge			\$ X 50.00
Tuff Kote			\$ 20
Remove/Refix Reverse Sensor			\$ 20
TOTAL LABOUR			\$ 1,670.00
ESTIMATE TOTAL			\$ 7,496.25

LKK Auto Consultancy
 the Repairer of this vehicle
 • To resolve any disputes arising
 • To display a copy of this survey
 • Part of the repair cost
 • Third party insurance on a "No Fault" basis
 • No cash payment is allowed
 • All parts and materials supplied and
 is subject to the applicable terms and conditions of the Company

SUB TOTAL
LESS 25%
DISCOUNTED TOTAL

Acknowledged by Repairer
 Date:

Katun LKK
 15/12/17 11.5 hr.
 4 Days
 PIP
 Before Part p4

NETT
NETT

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.