

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9518J -**AAD1712-129***Not Authorised*
11 Dec @ 2050

Vehicle No.:

SHB9518J - JHOW

Chassis No.:

KL1LA69RJB124289

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

13.12.2017

Third Party Insurer :

AXA

		PART	LIST
1	1	Front Bumper	\$ <i>Per/m</i> 1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$ <i>Su</i> 180.00 ✗
3	1	Front Bumper Reinforcement	\$ <i>R</i> 356.00 ✗
4	1	Front Bumper Retainer LH	\$ <i>Su</i> 102.00 ✗
5	1	Front Bumper Retainer LH	\$ <i>Su</i> 102.00 ✗
6	1	Front Bumper Lower Grille	\$ <i>Su</i> 78.00 ✗
7	1	Front Bumper Lower Stiffener	\$ <i>R</i> 134.37 ✗
8	1	Bumper Fog Lamp Cover LH	\$ <i>Per</i> 32.40 ✓
9	1	Front Fender LH	\$ <i>R</i> 837.60 ✗
10	1	Front Fender Liner LH	\$ <i>Su</i> 47.00 ✗
11	1	Bonnet	\$ <i>R</i> 1,250.00 ✗
12	1	Front Support Panel Assy	\$ <i>R</i> 1,222.32 ✗
13	1	Headlamp LH	\$ <i>CM</i> 816.00 ✓
14	1	Resonator (B/S Fender LH) AIR BOX	\$ <i>Su</i> 134.67 ✗
15	1	Resonator Hose	\$ <i>Su</i> 37.00 ✗
16	1	Radiator Grille (Grille A-Rad)	\$ <i>Su</i> 367.00 ✗
17	1	Front Door LH	\$ <i>R</i> 1,133.00 ✗

TOTAL	\$	8,031.36
10%	\$	803.14
	\$	7,228.22

Specical Nett

1	1 Set	Front Bumper Fastener Clip	\$ <i>Per</i> 24.00 ✓
2	1 Set	Front licence plate with holder	\$ <i>Su</i> 192.00 ✗
3	1 Set	Radiator Grille clip	\$ <i>~</i> 35.00 ✗
4	1 Set	Front Fender Liner clip	\$ <i>~</i> 30.00 ✗
5	2	Bonnet stopper	\$ <i>Su</i> 15.00 ✗
6	1	Front Wheel Rim Hub Cap LH	\$ <i>Su</i> 166.30 ✗
7	1	Front Tyre LH	\$ <i>Su</i> 180.00 ✗

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9518J -**AAD1712-129**

8 1 Front Tyre Rim LH

\$ 126.00 X

TOTAL \$ 768.30**TOTAL PARTS \$ 7,996.52**

To Check Electrical Lighting Concerned.

\$ 170.00 201

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 2,800.00 301

Putty and spray painting of the affected portion.

\$ 2,700.00 401

To check steering geometry and computer wheel
alignment

\$ 220.00 X

Towing fees

\$ 120.00 X

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 X

TOTAL \$ 6,350.00**Over All Total \$ 14,346.52****Repair Days**~~10 Days~~

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: