

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5988G - AXA

AAD1712-128

Not Attached
Missing B&P

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5988G - CANDY
 VF1ABL15AUC280994
 RENAULT
 LATITUDE
 13.12.2017
AXA

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Pr</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Not in</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Pr</i> 113.47 X
4	1	BUMEP R BRACKET SIDE RH REAR	\$	<i>Pr</i> 135.97 X
5	1	BUMEP R RETAINER RH REAR	\$	<i>Pr</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Pr</i> 43.61 X
7	1	BUMEP R BRACKET SIDE LH REAR	\$	<i>Pr</i> 135.97 X
8	1	BUMEP R RETAINER LH REAR	\$	<i>Pr</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Pr</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Pr</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	225.95 ✓
13	1	BOOT REAR	\$	<i>Pr</i> 2,872.68 ✓
14	1	BOOT FINISHER	\$	<i>Pr</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>Pr</i> 323.05 X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Pr</i> 493.35 X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35 ✓
18	1	BOOT BADGE 'RENAULT'	\$	<i>Pr</i> 225.36 ✓
19	1	BOOT BADGE	\$	<i>Pr</i> 225.36 ✓
20	1	BOOT SWITCH	\$	<i>Pr</i> 168.13
21	1	BOOT LOCK	\$	<i>Pr</i> 202.67
22	1	BOOT LOCK CATCH	\$	<i>Pr</i> 74.40
23	2	LICENCE PLATE LAMP	\$	<i>Pr</i> 50.52
24	2	BOOT RUBBER PLUG	\$	<i>Pr</i> 221.81
25	1	FENDER PANEL REAR LH	\$	<i>Pr</i> 3,299.13
26	1	FENDER PANEL REAR RH	\$	<i>Pr</i> 3,299.13
27	1	TAILLAMP RH	\$	<i>Pr</i> 552.55
28	1	TAILLAMP PANEL RH	\$	<i>Pr</i> 986.70
29	1	TAILLAMP LH	\$	<i>Pr</i> 552.55
30	1	TAILLAMP PANEL LH	\$	<i>Pr</i> 986.70
31	1	OUTER PANEL REAR (End Panel)	\$	<i>Pr</i> 1,471.77
32	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Pr</i> 404.56
33	1	EXHAUST REAR	\$	<i>Pr</i> 7,489.05
34	1	EXHAUST CAP REAR	\$	<i>Pr</i> 230.49

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5988G - AXA**AAD1712-128**

TOTAL	\$	28,762.72
10%	\$	2,876.27
	\$	25,886.45

Specical Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	45.00	} X
15	1	TAILLAMP CLIP RH	\$	5.00	
16	1	TAILLAMP CLIP LH	\$	5.00	
17	2	REAR WINDSCREEN SELANT	\$	80.00	
18	1	WINDSCREEN MOULDING	\$	100.00	
19	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	} X
20	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	
21	1	SPARE TYRE	\$	330.00	

TOTAL	\$	2,099.02
TOTAL PARTS	\$	27,985.47

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	5401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	5001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-128**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5988G - AXA

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>601</i>
To repair and realign rear exhaust pipe.	\$	<i>112</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>112</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 <i>601</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>112</i> 380.00 <i>X</i>
Towing Fees	\$	<i>112</i> 120.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>112</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>112</i> 220.00 <i>X</i>

TOTAL	\$	7,710.00
Over All Total	\$	35,695.47

(PARTS BY PARTS)**Repair Days****10 Days***3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: