

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Your ref :

Our Ref

22/12/2017

M/S AIG

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLB6534J

TO SUPPLY :

- | | | | |
|-----|-------|----------------------------|---------|
| 01) | 1 PC | FRONT RH DOOR | 2.43.00 |
| 02) | 1 PC | FRONT RH DOOR RUBBER | 1.1 |
| 03) | 2 PCS | FRONT RH LOWER GARNISH | 3.00.00 |
| 04) | 1 PC | REAR RH DOOR | 2.43.00 |
| 05) | 1 PC | REAR RH DOOR RUBBER | 1.1 |
| 06) | 1 PC | REAR RH DOOR LOWER GARNISH | 1.1 |

less ~~10%~~ 20%

Labour Charge

- | | |
|-----|----------------------------------|
| 07) | SPRAY PAINTING (4 PORTION) |
| 08) | LABOUR CHARGE |
| 09) | WIRING AND TRANSFER DOOR FITTING |
| 10) | TUFF KOTING |

8 NETT ITEM	
\$	920.00
\$	195.00
\$	216.00
\$	920.00
\$	195.00
\$	216.00
\$	2,662.00
\$	(266.20)
\$	2,395.80
\$	520.00
\$	480.00
\$	160.00
\$	100.00
\$	3,655.80

2797.6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

not Acknowledged
L/S \$2200/-
3 days
26/12/17
take place after repair