

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5107H -

AAD1712-136

Not Authorised
8675.00

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5107H - JHOW
 VF1ABL15AUC276178
 RENAULT
 LATITUDE
 13.12.2017
III

		PART		LIST
1	1	BUMPER COVER FRT	\$	1,259.42
2	1	FENDER PANEL FRT RH	\$	783.83
3	1	WHEELARCH FRT RH	\$	278.84
4	1	DOOR PANEL FRT RH	\$	2,844.66
5	1	DOOR HINGE UPPER RH	\$	274.50
6	1	DOOR HINGE LOWER RH	\$	300.55
7	1	DOOR CHECK FRT RH	\$	194.77
8	1	DOOR LOCK FRT RH	\$	908.75
9	1	DOOR CATCH FRT RH	\$	131.23
10	1	DOOR HANDLE OUTER FRT RH	\$	258.12
11	1	DOOR HANDLE CAP FRT RH	\$	26.44
12	1	DOOR HANDLE SEAL FRT RH	\$	7.89
13	1	DOOR HANDLE COVER FRT RH	\$	13.22
14	1	DOOR HANDLE MODULE FRT RH	\$	133.60
15	1	DOOR FINISHER FRT RH	\$	515.06
16	1	DOOR MOULDING FRT RH	\$	176.82
17	1	DOOR GRAB HANDLE FRT RH	\$	210.96
18	1	DOOR MIRROR RH	\$	1,483.40
19	1	DOOR MIRROR GLASS RH	\$	148.20
20	1	DOOR MIRROR BACK COVER RH	\$	218.46
21	1	DOOR WHETHERSTRIP FRT RH	\$	474.21
22	1	DOOR SEAL FRT RH	\$	68.67
23	1	ROCKER PANEL OUTER RH	\$	987.49
24	1	DOOR PANEL REAR RH	\$	2,844.66

TOTAL	\$	14,543.76
10%	\$	1,454.38
	\$	13,089.39

Specical Nett

1	1SET	WHEELARCH CLIP FRT RH	\$	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	66.00	X
3	1	RIM RH FRT	\$	385.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-136**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5107H -

4	1	TYRE RH FRT	\$	<i>330.00</i> <i>X</i>
5	1	DOOR STICKER "Trans-cab"	\$	<i>80.00</i> <i>60.00</i>
6	1	DOOR STICKER "Classic"	\$	<i>30.00</i> <i>15.00</i>
7	1	DOOR STICKER "6555-3333"	\$	<i>80.00</i> <i>X</i>

TOTAL	\$	1,037.00
TOTAL PARTS	\$	14,126.39

To Check Electrical Lighting Concerned.	\$	<i>170.00</i> <i>X</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>2,800.00</i> <i>200</i>
Putty and spray painting of the affected portion.	\$	<i>3,000.00</i> <i>400</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>170.00</i> <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>170.00</i> <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>220.00</i> <i>X</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>170.00</i> <i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>170.00</i> <i>X</i>
Towing fees	\$	<i>120.00</i> <i>X</i>
To rust-proofing of the affected areas.	\$	<i>170.00</i> <i>X</i>

TOTAL	\$	7,160.00
Over All Total	\$	21,286.39

(PARTS BY PARTS) Repair Days**10 Days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Admin. & Quality Control