

22/03/2002

ASS. REC. BY:

REF: CS/CTI17023856/KH6374

Special Instructions:

Surveyor:
Meinmen

Kalvin

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time: 15/12/17 @ 3:37pm

Estimated Cost:

Bill to:

OD-TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 9990Y

Insured:

EK 6996U

at Workshop m/s

Goldbell Engineering

Tel:

9755 7336

of

8 Kaki Bukit Ave 4 # 02-02 Premier

Policy No:

DMCVSN 3006881700

Claim No:

SNM17DO 6994C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/12/17

CA / REV / REP. / REV 24 HRS

(wp)

19/12/17 @ 10am

48 Changi South Street 1 - 486130

H.O.D. Endorsement

Date/Time:

4:10pm @ 15/12/17

Person Contacted:

William

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate
	SLM 9990Y - X	
	EK 6996U - CC7/AIC/12018322/Cob 3p1	D.O.A : 19/04/2012

REF: CTI

ASSIGNMENT

From: _____ Date: 19/12/17

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLM 9990 Yat Workshop m/s Goldbell Engineeringof 48 Changi South Street 1, 486130

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

10amRemark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLM 9990 Y Yr Regn: 5 Jan 2015Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan 5 0.5 1998Colour: white A/C: Ins Std / NI / NASp. Reading: 60493 T. Radio: Ins Std / NI / NA

Eng/No: _____

C/No: 5m 6CL1071FO119730Gen. Cond: Good / ☒ Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ R/Rim orTyre Size: F: 2.5 / 60 R16

R: _____

BS / DUN / EXNOVA / ☒ FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 6/12/17 D.O.I. 19/12/17Survey held at Goldbell (Changi)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/1/18 Confirmed P/P \$185832/ 2/19, Uled: 2343.28 (5590)P/P

Date/Time: File Pass to?



Preli. Report



Final Report

Date/Time: File Return to?

Days Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

LBS + PS \$:

Photos:

Others:

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Ins. (\$)☐ Weekend (\$)Report Format: TPLump Sum / I.B. / S 1858-32220220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Dec 2017		15 Dec 2017 15:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PETER LEE CHER KIANG, ID: S6831771A		
Main Claimant:	LIM TIAM HUAT, ID: S8315673B		
Vehicle Reg. No.:	SLM9990Y	Date of Loss:	06/12/2017 17:00 - :59
Claim Type:	TP / SNM17D06994C02	Policy/Cover Note No.:	DMPCSN3006881700 (Comprehensive) Coverage: 16/01/2017 - 17/01/2018
Vehicle Reg. No. (Insured):	EK6996U	Policy No. (Claimant):	10740601
		Excess:	S\$0.00
Repairer:	Goldbell Engineering Pte Ltd (HQ) 8 KAKI BUKIT AVENUE 4 #02-02 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 67981443		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hul Ping - 638986192]		
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/12/2017]		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS AND LET US HAVE YOUR RECOMMENDATION ON COST OF REPAIRS.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17023856/K1td3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 15-12-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	EK 6996U	Veh. Inspected	SLM 9990Y	
Policy No.	DMPCSN3006881700	Coverage (\$)	0.00	
Claim No.	SNM17D06994C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	15/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/12/2017	Inspection Date		
Survey held at	GOLDBELL ENGINEERING PTE LTD 48 CHANGI SOUTH STREET 1 SINGAPORE 486130			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/12/2017 17:01
Date Of Accident	06/12/2017 17:45
Exact Location Of Accident	ALONG TPE TOWARDS PIE AFTER EXIT 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM9990Y
Insured/Policyholder	
Name Of Registered Owner	LIM TIAM HUAT
NRIC No	S8315673B
Email Address	TIANFA_@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98253354
Alternative Phone No	OFFICE-98253354

Vehicle Particulars

Manufacturer	MAZDA
Model	5 2.0
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10740601
Cover Note Number	

Driver

Name of Driver	LIM TIAM HUAT
NRIC No	S8315673B
Date Of Birth	27/05/1983
Occupation	INDOOR
Date Of Driving Pass	09/12/2003
Driving Experience	13 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98253354
Fax Number	
Contact Number	OFFICE-98253354
EEmail Address	TIANFA_@HOTMAIL.COM

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. YES
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Driving along TPE/PIE was on the extreme left lane going straight. Upon approaching exit 4, suddenly a vehicle appeared from my right just dashed tried to exit. As a result the vehicle bumped onto my vehicle front right portion. Refer to video footage.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: NA
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number EK6996U
 Vehicle Make/Model/Colour MERCEDES BENZ E 250CGI /SILVER
 Details Of Properties
 Name of Driver UNKNOWN
 NRIC/Passport Number
 Contact Number UNKNOWN
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 2

Details of Witness

Name
 Phone Number
 Email Address

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers to the QIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report are for a fee be made available application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form; and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"), and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"; the insurers' lawyer/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or copies to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of enveloped/packaged), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/law firms) which may be based outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time


Driver's Signature / Driver is not the policyholder / Date & Time

WITNESSED BY ADJUSTING REPORTING OFFICER

ATTEST BY

Signature of

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

Driving along TPE/PIE was on the extreme left lane going straight. Upon approaching exit 4 ,suddenly a vehicle appeared from my right just dashed tried to exit. As a result the vehicle bumped onto my vehicle front right portion. Refer to video footage.

Taxi Voucher No..

Are you claiming your own insurance policy for the repair of your vehicle?

No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN



MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time

7 December, 2017 4:00 pm

7 December, 2017 4:00 pm



GOLDBELL ENGINEERING

GOLDBELL ENGINEERING PTE LTD

Main Office: 10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Industrial Vehicles.

20,000 Served. And Counting.

DATE : 12/12/17

TO : CHINA TAIPING INSURANCE (S)PTE LTD

ATTN : MOTOR CLAIMS DEPT

OFFICE / MOBILE :

EMAIL ADDRESS :

VEHICLE NO. : SLM9990Y

MODEL NO. : MAZDA 5

CHASSIS NO. : JM6CW1071F0119778

ENGINE NO. : PE30680841

REG. DATE : 05/01/15

FROM : GOLDBELL ENGINEERING PTE LTD (KAKI BUKIT)

ATTN : ERIC NG

MOBILE/ EMAIL : 9798 1443/65819237

FAX NO. : 65819237

REF. NO. : GBP/SVC/SALES-

D.O.A. : 06/12/17

POLICY NO. :

CLAIM TYPE : TP CLAIM

WORKSHOP : 8 KAKI BUKIT AVE 4 ,PREMIER, #02-02, SINGAPORE 415875

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1		FRONT BUMPER	1	\$ 1,155.40
2		FRONT BUMPER RETAINER LH	1	\$ 28.50
3		FRONT BUMPER RETAINER RH	1	\$ 28.50
4		FRONT BUMPER CLIPS	10	\$ 40.00
5		FRONT HEADLAMP ASSY RH	1	\$ 1,511.40
6		FRONT HEADLAMP LOWER BRACKET RH	1	\$ 48.20
7		FRONT FENDER INNER SHIELD CLIPS	10	\$ 40.00
8				

PARTS TOTAL : \$ 2,852.00

LESS: 20% : \$ 570.40

NETT PARTS TOTAL : \$ 2,281.60

SPECIAL-NETT ITEMS

1		FRONT BUMPER PARKING SENSOR	1	\$ 200.00
2		FRONT BUMPER LOWER SPOILER	1	\$ 580.00

SPECIAL-NETT ITEMS TOTAL : \$ 780.00

ALL PARTS TOTAL : \$ 3,061.60

LABOUR CHARGES

1	TO REMOVE & REFIX DAMAGED PARTS,PANEL BEAT,STRAIGHTEN & REALIGN,ETC	\$ 380.00
2	TO CHECK FOR & RECTIFY WIRING FAULTS,ETC	\$ 60.00
3	SUNDRIES	\$ 20.00
4	TO RUST PROOF ON AFFECTED AREAS	\$ 60.00
5	TO PUTTY,CLEAN,SPRAY PAINTING & POLISH,ETC ON AFFECTED AREAS	\$ 600.00
6	TO REMOVE & REFIT REVERSE SENSOR	\$ 20.00

LABOUR TOTAL : \$ 1,140.00

TOTAL AMOUNT (BEFORE GST) : \$ 4,201.60

PREPARED BY : ERIC NG

DATE/TIME : 19/12/17

SURVEYOR : Kalar LRY

MOBILE NO. : 96719399

OFFICE FAX NO. :

EMAIL ADDRESS :

REPAIR TYPE : PART-BY-PART / LUMP SUM

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 2 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display and handle during resurvey
- Parts and materials information
- Third party information
- No legal liability on 'Prejudice' basis
- Supplies and services
- Insurance and company

Acknowledged
Signature
Date

bigSAFE
S T R



Certificate No: AJA(S)01/Q1243

Certificate No: AJA01/2054

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Dec 2017		15 Dec 2017 15:37 Edit Adj Rpt	S\$1,858.32 Edit Estimates	S\$1,858.32 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------






























CLAIM SUBFOLDER DETAILS				[Created by insurer]		
Insured:	PETER LEE CHER KIANG, ID: S6831771A					
Main Claimant:	LIM TIAM HUAT, ID: S8315673B					
Vehicle Reg. No.:	SLM9990Y	Date of Loss:	06/12/2017 17:00 - :59			
Claim Type:	TP / SNM17D06994C02	Policy/Cover Note No.:	DMPCSN3006881700 (Comprehensive) Coverage: 16/01/2017 - 17/01/2018			
Vehicle Reg. No. (Insured):	EK6996U	Policy No. (Claimant):	10740601			
		Excess:	S\$0.00			
Repairer:	Goldbell Engineering Pte Ltd (HQ) 8 KAKI BUKIT AVENUE 4 #02-02 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 67981443					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]					
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 27/12/2017]					
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS AND LET US HAVE YOUR RECOMMENDATION ON COST OF REPAIRS.					

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													




















Claim Documents

*SLM9990Y (SNM17D06994C02)
[EK6996U]
TP
LIM TIAM HUAT
Dec 6 2017 5:00PM
[PETER LEE CHER KIANG]
Goldbell Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Photos/Images								3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
2	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
3	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
4	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
5	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
6	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
7	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
8	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
9	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
10	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
11	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
12	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
13	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
14	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
15	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
16	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
17	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
18	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
19	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
20	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
21	15/01/18 15:42	General View							Load JPG	<input checked="" type="checkbox"/>	
22	15/01/18 15:44	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
23	15/01/18 15:44	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
24	15/01/18 15:44	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
25	15/01/18 15:44	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
26	15/01/18 15:44	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
27	15/01/18 15:44	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
28	15/01/18 15:44	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
Documentation								1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	15/12/17 15:37	E-filed GIA report							Load PDF		

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	07/12/17 17:17	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
2	08/12/17 10:38	Addendum Sheet	 Load TIF	<input type="checkbox"/>
3	08/12/17 10:39	Accident Statement Addm. #1	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	07/12/17 17:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	07/12/17 17:16	Driving License	 Load JPG	<input checked="" type="checkbox"/>
14	07/12/17 17:16	Driving License	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	07/12/17 17:13	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	07/12/17 17:13	Sketch Plan #2	 Load TIF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT117023856/K1TD3E2**Date:** 17/01/2018**REFERENCE****Handling Insurer:** China Taiping Insurance
(Singapore) Pte. Ltd.**Policy No:** DMPCSN3006881700**Claimant Vehicle
No :** SLM9990Y**Insured Vehicle
No :** EK6996U**Date of Loss:** 06/12/2017**Nature of Claim:** TP**Claim
No:** SNM17D06994C02**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SLM9990Y**Make & Model:** MAZDA 5, 2.0 (A)**Engine No:** PE30680841**Reg. Date:** 05/01/2015 (Man. Year: 2014)**Chassis No:** JM6CW1071F0119778**Colour:** White**Odometer:** 60493 km**Engine Capacity:** 1998 cc**Market Value/New Car Price:** N/A**Sum Insured (\$\$):** Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES**Front Tyre Size:** 205/60 R16**Rear Tyre Size:** 205/60 R16**Front Left Side:** Goodyear 7 mm**Rear Left Side:** Goodyear 7 mm**Front Right Side:** Goodyear 7 mm**Rear Right Side:** Goodyear 7 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,081.60	1,008.32	2,073.28	67.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	850.00	270.00	24.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,201.60	1,858.32	2,343.28	55.77
+ GST 7.00/7.00% (\$\$)	294.11	130.08	164.03	55.77
Nett Amount (\$\$)	4,495.71	1,988.40	2,507.31	55.77

INSPECTION**Date of Assignment:** 15/12/2017**Date Inspected:** 19/12/2017 Inspected At:

Goldbell Engineering Pte Ltd (HQ)
8 KAKI BUKIT AVENUE 4 #02-02
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jan 2018)
Parts: M1-MPV MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLM9990Y)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,155.40 FL	*1,155.40 FL
2	1		*FRONT BUMPER RETAINER LH	Serviceable	28.50 FL	*- FL
3	1		*FRONT BUMPER RETAINER RH	Serviceable	28.50 FL	*- FL
4	10		*FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
5	1		*FRONT HEADLAMP ASSY RH	Serviceable	1,511.40 FL	*- FL
6	1		*FRONT HEADLAMP LOWER BRACKET RH	Serviceable	48.20 FL	*- FL
7	10		*FRONT FENDER INNER SHIELD CLIPS	Necessary	40.00 FL	*40.00 FL
8	1		*FRONT BUMPER PARKING SENSOR	Serviceable	200.00 FS	*- FS
9	1		*FRONT BUMPER LOWER SPOILER	Repair	580.00 FS	*- FS
10	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,652.00	1,255.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	570.40	247.08
Total Parts (\$\$)	3,081.60	1,008.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX DAMAGED PARTS, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	New	380.00	300.00
2	TO CHECK FOR & RECTIFY WIRING FAULTS, ETC	New	60.00	30.00
3	TO RUST PROOF ON AFFECTED AREAS	New	60.00	0.00
4	TO PUTTY, CLEAN, SPRAY PAINTING & POLISH, ETC ON AFFECTED AREAS	New	600.00	500.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	20.00	20.00
Gross Labour Cost (\$\$)			1,120.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >