

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG NO : 53105453E

Vehicle Number : JRL 6446
Vehicle Model : TOYOTA INNOVA
Accident Date : 13.12.2017
Original Reg Date : 15.04.2010

Date : 14.12.2017
Chassis : PN111NV4008621017
TP Ins. AXA

ESTIMATE

1	1 pc	Bonnet	R	X	998.60
2	1 pc	Front Grille		X	356.00
3	1 pc	Front Grille Badge		X	58.00
4	1 set	Front Grille Clips		X	30.00
5	2 pcs	Headlamps	OS CVA	695.00	1,390.00
6	2 pcs	Headlamps Bottom Retainers	OS DIS	45.00	90.00
7	2 set	Headlamps Clips		20.00	40.00
8	1 pc	Front Bumper	R	X	786.50
9	2 pcs	Front Bumper Side Retainers	gve	X	92.00
10	1 set	Front Bumper Clips	NIN	X	50.00
11	2 pcs	Front Bumper Fog Lamp	gve	X	624.00
12	2 pcs	Front Bumper Fog Lamp Base Bracket	nee	X	190.00
13	1 pc	Front Fender LH	DA	✓	462.50
14	1 pc	Front Fender Emblem VVTI LH	nee	✓	48.00
15	1 pc	Front Fender Inner Housing LH (Outer)	R	X	456.20
16	2 pcs	Front Fender Inner Shield	dis	✓	136.00
17	2 set	Front Fender Inner Shield Clips	nee	✓	30.00
18	1 pc	Front Wiper Garnish LH	gve	X	215.00
19	1 set	Front Wiper Garnish Clips	nee	✓	30.00
20	1 pc	Front Wiper Garnish Side Rubber RH	dis	✓	64.00
21	1 pc	Front Windscreen Glass		X	1,209.50
22	1 set	Front Windscreen Moulding	nee	✓	159.20
23	1 pc	Front Windscreen Inner Seal	NIN	X	60.00
24	1 pc	Front Door Pillar RH		7	856.70
25	1 pc	Front Door Pillar Quarter Glass RH	cvg	✓	216.50
26	1 pc	Front Door Pillar Quarter Glass Moulding RH	dis	✓	72.50
27	1 pc	Front Door Pillar Inner Trim RH		7	154.70
28	1 pc	Front Door Pillar Inner Trim Bottom Cover RH		X	86.00
29	1 pc	Front Door RH	dt	✓	1,206.50
30	1 pc	Front Door Wing Mirror RH	cvg	✓	725.00
31	1 pc	Front Door Outer Moulding RH	nee	✓	125.00
32	1 pc	Front Door Protector RH	dis	✓	125.50
33	1 pc	Front Door Protector Chrome Moulding RH	nee	✓	86.50

B/F

11,230.40

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG NO : 53105453E

Vehicle No : JRL 6446

B/F

11,230.40

1	2 pcs	Front Door Hinge RH	56.00		112.00
2	1 pc	Front Door Checker RH		X	62.00
3	1 pc	Front Door Inner Lock RH		X	395.20
4	1 pc	Front Door Weatherstrip RH			193.50
5	1 pc	Front Absorber RH		7	426.50
6	1 pc	Front Absorber Top Mounting RH		7	126.20
7	1 pc	Front Upper Arm RH		7	295.20
8	1 pc	Front Lower Arm RH		7	372.00
9	1 pc	Front Knuckle Arm RH		7	386.20
10	1 pc	Front Wheel Bearing RH		7	185.00
11	1 pc	Anti Roll Bar		X	387.80
12	2 pcs	Anti Roll Bar Bush	50.00	X	100.00
13	1 pc	Anti Roll Bar Link RH		7	212.40
14	1 pc	Steering Rack and Pinion RH		7	1,565.50
15	1 pc	Front Cross Member		7	1,710.30
					17,760.20
Less 25%					4,440.05
					13,320.15

C/F

13,320.15

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG NO : 53105453E

Vehicle No : JRL 6446

B/F

13,320.15

Special Nett

1	1 pc	Front Windscreen Sealant		X	60.00
2	1 pc	Front Bumper Lower Spoiler	sm	X	850.00
3	1 pc	Side Skirt RH	det	✓	700.00
4	1 set	Sun Visor	44	✓	320.00
5	1 pc	Front Door Wing Mirror Cover (Chrome)	HN	X	350.00
6	1 pc	Front Sport Rim RH (15")	cut	✓	600.00
7	1 pc	Front Tyre RH		✓	360.00

650

150

cut 80%

Labour charge

Panel Beating		2,000.00
Spray painting		1,800.00
Check Wiring		30 50.00
Anti rust		40 100.00
Remove and install front windscreen.		✓ 140.00
Remove and install front pillar glass		60 120.00
Remove and install front door parts.		60 90.00
Remove and install carpet and seat.		60 120.00
Remove and install dashboard		280 450.00
Remove and install front undercarriage.	?	350 450.00
To perform computerie wheel alignment.		80 90.00

1360

1300

120 ✓

\$ 21,970.15

LKK Auto will submit to and hence notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged parts during resurvey
- Parts must be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised
 HS Repair
 After Repair Photo
 15/12/2012
 19 wday
 LKK Auto (mm)