

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: emlautopteltd@gmail.com

COMPANY REG NO : 53105453E

Vehicle Number : JRL 6446
Vehicle Model : TOYOTA INNOVA
Accident Date : 13.12.2017
Original Reg Date : 15.04.2010

Date : 14.12.2017
Chassis : PN111NV4008621017
TP Ins. AXA

ESTIMATE

1	1 pc	Bonnet	R	X	998.60	X
2	1 pc	Front Grille	SVC	X	356.00	X
3	1 pc	Front Grille Badge	CVC	X	58.00	X
4	1 set	Front Grille Clips	NIN	X	30.00	X
5	2 pcs	Headlamps	OS CVC	695.00	1,390.00	X
6	2 pcs	Headlamps Bottom Retainers	OS DIS	45.00	90.00	X
7	2 set	Headlamps Clips	OS NEC	20.00	40.00	X
8	1 pc	Front Bumper		X	786.50	form ✓
9	2 pcs	Front Bumper Side Retainers	SVC	46.00	X 92.00	X
10	1 set	Front Bumper Clips	HHH	X	50.00	HO nec ✓
11	2 pcs	Front Bumper Fog Lamp	SVC	312.00	X 624.00	X
12	2 pcs	Front Bumper Fog Lamp Base Bracket	NEC	95.00	X 190.00	X
13	1 pc	Front Fender LH	DT	✓	462.50	✓
14	1 pc	Front Fender Emblem VVTI LH	NEC	✓	48.00	✓
15	1 pc	Front Fender Inner Housing LH (Outer)		✓	456.20	dt ✓
16	2 pcs	Front Fender Inner Shield	DIS	✓	136.00	✓
17	2 set	Front Fender Inner Shield Clips	NEC	✓	30.00	✓
18	1 pc	Front Wiper Garnish LH	DIS	✓	215.00	dis ✓
19	1 set	Front Wiper Garnish Clips	NEC	✓	30.00	✓
20	1 pc	Front Wiper Garnish Side Rubber RH	DIS	✓	64.00	✓
21	1 pc	Front Windscreen Glass		X	1,209.50	SVC X ✓
22	1 set	Front Windscreen Moulding	NEC	HHH	✓ 159.20	✓
23	1 pc	Front Windscreen Inner Seal	NIN	X	60.00	X
24	1 pc	Front Door Pillar RH		X	856.70	R X
25	1 pc	Front Door Pillar Quarter Glass RH	CVC	✓	216.50	✓
26	1 pc	Front Door Pillar Quarter Glass Moulding RH	DIS	✓	72.50	✓
27	1 pc	Front Door Pillar Inner Trim RH		✓	154.70	dis ✓
28	1 pc	Front Door Pillar Inner Trim Bottom Cover RH	SVC	X	86.00	X
29	1 pc	Front Door RH	dt	✓	1,206.50	✓
30	1 pc	Front Door Wing Mirror RH	CVC	✓	725.00	✓
31	1 pc	Front Door Outer Moulding RH	NEC	✓	125.00	✓
32	1 pc	Front Door Protector RH	DIS	✓	125.50	✓
33	1 pc	Front Door Protector Chrome Moulding RH	NEC	✓	86.50	✓

B/F

11,230.40

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG NO : 53105453E

Vehicle No : JRL 6446

B/F

11,230.40

1	2 pcs	Front Door Hinge RH	56.00	112.00	
2	1 pc	Front Door Checker RH		62.00	X
3	1 pc	Front Door Inner Lock RH		395.20	X
4	1 pc	Front Door Weatherstrip RH		193.50	X
5	1 pc	Front Absorber RH		426.50	bt
6	1 pc	Front Absorber Top Mounting RH		126.20	bt
7	1 pc	Front Upper Arm RH		295.20	bt
8	1 pc	Front Lower Arm RH		372.00	bt
9	1 pc	Front Knuckle Arm RH		386.20	bt
10	1 pc	Front Wheel Bearing RH		185.00	bt
11	1 pc	Anti Roll Bar		387.80	bt
12	2 pcs	Anti Roll Bar Bush	50.00	100.00	bt
13	1 pc	Anti Roll Bar Link RH		212.40	bt
14	1 pc	Steering Rack and Pinion RH		1,565.50	bt
15	1 pc	Front Cross Member		1,710.30	bt
				17,760.20	
				Less 25%	
				4,440.05	
				13,320.15	

C/F

13,320.15

(P)

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autoteld@gmail.com

COMPANY REG NO : 53105453E

Vehicle No : JRL 6446

B/F

13,320.15

Special Nett

1	1 pc	Front Windscreen Sealant	NIN	X	60.00	X
2	1 pc	Front Bumper Lower Spoiler	gm	X	850.00	X
3	1 pc	Side Skirt RH	Def	✓	700.00	650 ✓
4	1 set	Sun Visor	ya	✓	320.00	150 ✓
5	1 pc	Front Door Wing Mirror Cover (Chrome)	NIN	X	350.00	X
6	1 pc	Front Sport Rim RH (15")	cut	✓	600.00	250 ✓
7	1 pc	Front Tyre RH	224	✓	360.00	cut 80 ✓

Labour charge

Panel Beating		2,000.00	1300 ✓
Spray painting		1,800.00	1300 ✓
Check Wiring		30 50.00	✓
Anti rust		40 100.00	✓
Remove and install front windscreen.		✓ 140.00	120 ✓
Remove and install front pillar glass		60 120.00	✓
Remove and install front door parts.		60 90.00	✓
Remove and install carpet and seat.		60 120.00	✓
Remove and install dashboard		280 450.00	✓
Remove and install front undercarriage.	?	350 450.00	250 ✓
To perform computerie wheel alignment.		80 90.00	✓
		<u>\$ 21,970.15</u>	

980072
9wdaysew

LKK Auto must always notify the Repairer of the following:

- To resurvey or to spray painting
- To display damaged parts during resurvey
- Parts are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Not Authorised
Hk Repair
Office Repair Photo
15/12/2012
9wdaysew
LKK AUTO (M)