

15/5/2010

INS. CASE OWNER:

CC 4/AXA170

23867, Mleasr

LKK:

IDAC:

SMART

STMOOSLR

Surveyor:

DOI:

3-1-18

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKH 4600 U

Name of Insured:

WU SEN YUE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

12/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

JASON WU SEN JIE

Driver Tel No.:

91053426

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

BMW M5

PIE SUP RD EXIT PATA LOBAR

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SKP 9513M



INSRS:

WSP:

Tel:

Liability:

RMKS:

Em 1 Auto
PL

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

8/1/18

After

SKP 9513M - X: SKH 4600 U - X
Pending PA.

8/1/18 @ 11:25 am

called OI Mdm Wu Sen Yue, 91053426 and Mr. Jason OI
91053426 but no respond.

9/1/18 - 2:31 pm

called OI Mdm Wu Sen Yue, no respond.

12/1/18 @ 12:00 hrs

called OI, OI no response
TO SEND EMAIL.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 15/01/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 21-7-18

Confirm with: CHA

Confirm by: MCF

Repair Cost:

45 S\$ 7,700

(7 days)

Reduction:

51 %

Email

Call

FINAL SETTLEMENT

Date/Time: 12-10-18

Confirm with: CHA

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 21

If NO or B 28, Ass. Lia:

Repair Cost:

10/10/18

S\$ 8,229.00

OIO REAR ENDED TP

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$ 800.00

(\$' 100 x 8 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 5.35

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/Independent)

Legal Cost

S\$ -

Total:

S\$ 9,044.35

Global Sum S\$:

FINAL PAYMENT

Date/Time: 12-10-18

Confirm with: CHA

Email

Call

Payee 1:

S\$ 9,044.35

Name 1:

END AUTO PIE LTD.

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+350

COPY SENT
26/11/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM17023867/M1ea3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 15-12-2017		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKH 4600U	Veh. Inspected	SKP 9513M	
Policy No.		Coverage (\$)	0.00	
Claim No.	S7M005LR	Excess (\$)	0.00	
Assign From		Assign Date	15/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/12/2017	Inspection Date	03/01/2018	
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SKP 9513M

Vehicle Model : MAZDA

Accident Date : 13.12.2017

Original Reg Date : 24.10.2014

Date : 03.01.2018

Chassis : JM6CC1071F0106626

TP Ins. AXA

ESTIMATE

1	1 pc	Tailgate	✓ OA ✓		1615.00
2	1 pc	Tailgate Emblem (Skyactiv)	✓ ncr ✓		111.50
3	1 pc	Tailgate Outer Chrome Moulding	✓ ncr ✓		527.00
4	1 set	Tailgate Outer Clips	✓ ncr ✓		40.00
5	1 pc	Tailgate Pocket Handle	✗ gvc ✗		46.50
6	1 pc	Tailgate Inner Trim	?	✓	456.00
7	1 set	Tailgate Inner Trim Clip	✓ ncr ✓		40.00
8	1 pc	Tailgate Inner Lock	✓ ncr ✓		272.00
9	1 pc	Tailgate Auto Lock Actuator	✗ ncr ✗	✓	
10	1 pc	Tailgate Lock Catch	✓ ncr ✗		52.00
11	1 pc	Tailgate Weatherstrip	✓ ncr ✓		227.00
12	2 pcs	Tailgate Hinge	✗ ncr ✗	65.00	130.00
13	2 pcs	Tailgate Absorber	✗ gvc ✗	192.00	384.00
14	1 pc	Rear Windscreen Inner Seal	✓ ncr ✓		50.00
15	2 pcs	Taillamps	✗ gvc ✗	1319.00	2638.00
16	2 pcs	Taillamps Inner Sealer	?	✗ 38.00	76.00
17	2 set	Taillamp Clips	✗ ncr ✗	25.00	50.00
18	1 pc	Rear Bumper	✓ ncr ✓		1114.70
19	2 pcs	Rear Bumper Side Retainers	✓ ncr ✓	56.00	112.00
20	2 pcs	Rear Bumper Attachment Retainers	✓ ncr ✓	48.00	96.00
21	1 set	Rear Bumper Clips	✓ ncr ✓		50.00
22	1 pc	Rear Bumper Center Chrome Sticker	✓ ncr ✓		149.00
23	2 pcs	Rear Bumper Side Chrome Sticker	✓ ncr ✓	95.00	190.00
24	1 pc	End Panel	?	✓	495.70
25	1 pc	End Panel Top Trim	?	✓	129.40
26	1 set	End Panel Top Trim Clips	✓ ncr ✓		30.00
27	1 pc	Spare Tyre Panel Top Board	✗ gvc ✗		738.00
28	2 pcs	Rear Fender Inner Trim	?	✓ 605.00	1210.00
29	2 set	Rear Fender Inner Trim Clips	?	✓ 30.00	4060.00
30	1 pc	Tailgate Center lamp	?	✓	1922.00

CRA

} Short

NN

NN

VR

CRA

CRA

NEC

8973.30

CRA

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SKP 9513M

B/F

1	1 pc	Rear Exhaust Silencer	X 2 pc	1056.00
2	2 pcs	Rear Exhaust Mountings	X 2 pc 38.00	76.00
3	1 pc	Rear Exhaust Gasket	X 2 pc	46.00

14189.80

Less 20%

11351.84

Special Nett

1	1 pc	Rear Windscreen Sealant	✓ 40	60.00
2	1 pc	Rear Number Plate w/cover	✓ 40	40 -70.00
3	1 pc	Body Panel Joint Sealant	✓ 80	80 -120.00
4	1 set	Reverse Sensor	✓ 220	220 -250.00
5	1 pc	Reverse Camera	✓ 350	350 -450.00

750

950

Labour charge

Panel Beating	800	800	1,300.00
Spray painting (Pearl)	900	900	1,300.00
Check Wiring	30	30	50.00
Anti rust	60	60	100.00
Remove and install rear winscreen.	120	120	140.00
Remove and install tailgate parts.	60	60	90.00
Remove and install carpet and seat.	60	60	120.00
Remove and install reverse sensor	60	60	90.00
Remove and install reverse camera	80	80	150.00
Remove and install rear exhaust silencer.	—	X	120.00

2170

3460

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Abd. Authovic

L/S Repair

After part photo

Abd. Authovic

31/2017

7/1 day

15761.84

SKP 9513M

LABOUR

\$800.00
\$900.00
\$30.00
\$60.00
\$120.00
\$60.00
\$60.00
\$60.00
\$60.00
\$80.00

S/N PARTS

\$60.00
\$40.00
\$80.00
\$220.00
\$350.00

PARTS

\$1,615.00 ✓
\$111.50 ✓
\$527.00 ✓
\$40.00 ✓
\$456.00 ✓
\$40.00 ✓
\$272.00 ✓
\$227.00 ✓
\$50.00 ✓
\$1,114.70 ✓
\$112.00 ✓
\$96.00 ✓
\$50.00 ✓
\$149.00 ✓
\$190.00 ✓
\$129.40 ✓
\$30.00 ✓
\$1,210.00 ✓
\$40.00 ✓
\$1,922.00 ✓

\$2,170.00

\$750.00

\$8,381.60
\$1,676.32
\$6,705.28 ✓

Total: \$9,625.28 ✓

Lump Sum: \$7,700.22 ✓

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SKP 9513M

Vehicle Model : MAZDA

Accident Date : 13.12.2017

Original Reg Date : 24.10.2014

Date : 03.01.2018

Chassis : JM6CC1071F0106626

TP Ins. AXA

ESTIMATE

1	1 pc	Tailgate	✓ ok		
2	1 pc	Tailgate Emblem (Skyactiv)	✓ ok		
3	1 pc	Tailgate Outer Chrome Moulding	✓ ok		
4	1 set	Tailgate Outer Clips	✓ ok		
5	1 pc	Tailgate Pocket Handle	✗ ok		
6	1 pc	Tailgate Inner Trim	?		
7	1 set	Tailgate Inner Trim Clip	✓ ok		
8	1 pc	Tailgate Inner Lock	✓ ok		
9	1 pc	Tailgate Auto Lock Actuator	✗ ok		
10	1 pc	Tailgate Lock Catch	✗ ok		
11	1 pc	Tailgate Weatherstrip	✓ ok		
12	2 pcs	Tailgate Hinge	✗ ok		
13	2 pcs	Tailgate Absorber	✗ ok		
14	1 pc	Rear Windscreen Inner Seal	✓ ok		
15	2 pcs	Taillamps	✗ ok		
16	2 pcs	Taillamps Inner Sealer	?		
17	2 set	Taillamp Clips	✗		
18	1 pc	Rear Bumper	✓ ok		
19	2 pcs	Rear Bumper Side Retainers	✓ ok		
20	2 pcs	Rear Bumper Attachment Retainers	✓ ok		
21	1 set	Rear Bumper Clips	✓ ok		
22	1 pc	Rear Bumper Center Chrome Sticker	✓ ok		
23	2 pcs	Rear Bumper Side Chrome Sticker	✓ ok		
24	1 pc	End Panel	?		
25	1 pc	End Panel Top Trim	?		
26	1 set	End Panel Top Trim Clips	✓ ok		
27	1 pc	Spare Tyre Panel Top Board	✗ ok		
28	2 pcs	Rear Fender Inner Trim	?		
29	2 set	Rear Fender Inner Trim Clips	?		
30	1pc	Tailgate Center lamp	?		

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SKP 9513M

B/F

1	1 pc	Rear Exhaust Silencer	X 2pc	
2	2 pcs	Rear Exhaust Mountings	X 2pc	
3	1 pc	Rear Exhaust Gasket	X 2pc	

Less 20%

Special Nett

1	1 pc	Rear Windscreen Sealant	✓ 4pc	60.00
2	1 pc	Rear Number Plate w/cover	✓ 1pc	40 -70.00
3	1 pc	Body Panel Joint Sealant	✓ 2pc	80 -120.00
4	1 set	Reverse Sensor	✓ 2pc	220 -250.00
5	1 pc	Reverse Camera	✓ 1pc	250 -450.00

Labour charge

Panel Beating	800	1,300.00
Spray painting (Pearl)	900	1,300.00
Check Wiring	50	50.00
Anti rust	60	100.00
Remove and install rear winscreen.	120	140.00
Remove and install tailgate parts.	60	90.00
Remove and install carpet and seat.	60	120.00
Remove and install reverse sensor	60	90.00
Remove and install reverse camera	80	150.00
Remove and install rear exhaust silencer.	X	120.00

Not Authorize
L/S Repay.
After part photo
HBB Debt (MA)
3/12/2017
7-10 days

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 9 October 2018 3:38 PM
To: Chia Sin Muk
Subject: RE: LOD - SKP 9513M DOA 13.12.2017 - TP AXA *** LKK REF: CC4/ASM17023867/M1ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 8,239.00
2. Loss of Use (8 days x \$100)	\$ 800.00
3. LTA/GIA search fee	\$ 5.35
TOTAL	<u>\$ 9,044.35</u>

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Wednesday, 8 August 2018 2:03 PM
To: Chia Sin Muk <em1autopteltd@gmail.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: RE: LOD - SKP 9513M DOA 13.12.2017 - TP AXA *** LKK REF: CC4/ASM17023867/M1ea3

Dear Sir /Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CC4/ASM17023867/M1ea3	Asher - 6841 6051



Re:MANDATE REQUEST FOR S7M005LR

Type

🔗 Question

Message

PLS PROCEED

Reply

STAYKEY

 MANDATE REQUEST FOR S7M005LR

Type

 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$8,239.00 (w/GST) Loss of Use: \$800.00 (8days x \$100) GIA Search: \$5.35 Total: \$9,044.35 Immediate Advice with Mandate for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (13/08/2018)

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKH 4600U (Insd veh)	Model:	MAZDA BIANTE
	SKP 9513M (TP veh)		
Date of Accident:	13/12/2017		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	16,865.17
Final Repair Cost	:	\$	8,239.00
Loss of Use	:	\$	800.00
Rental (if any)	:	\$	8 days at \$100.00 per day
LTA / GIA Search Fee	:	\$	5.35

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	9,044.35

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown			
1)	EM-1 AUTO PTE LTD	:	\$ 9,044.35

NUR SHAQILAH BTE ABDOL
WAHAB

02/04/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM17023867/M1ea3s2	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: STACEY NG		Date : 02-04-2019 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKH 4600U	Veh. Inspected	SKP 9513M
Policy No.	CN858375	Coverage (\$)	0.00
Claim No.	S7M005LR	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	15/12/2017
2. Vehicle Particulars & Condition			
Make & Model	MAZDA BIANTE	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JM6CC1071F0106626	Colour	WHITE
Odometer	52541	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60R16	NEXEN	8 mm
L/H Front Tyre	215/60R16	NEXEN	8 mm
R/H Rear Tyre	215/60R16	NEXEN	8 mm
L/H Rear Tyre	215/60R16	NEXEN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/12/2017	Inspection Date	03/01/2018
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 9513M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE (CONSISTENT)	DENTED	1,615.00	1,615.00
1	TAILGATE EMBLEM (SKYACTIV) (CONSISTENT)	NECESSARY	111.50	111.50
1	TAILGATE OUTER CHROME MOULDING (CONSISTENT)	NECESSARY	527.00	527.00
1	SET TAILGATE OUTER CLIPS (CONSISTENT)	NECESSARY	40.00	40.00
1	TAILGATE POCKET HANDLE (CONSISTENT)	SERVICEABLE	46.50	-
1	TAILGATE INNER TRIM (CONSISTENT)	CRACKED	456.00	456.00
1	SET TAILGATE INNER TRIM CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	TAILGATE INNER LOCK (CONSISTENT) }	SHORTED	272.00	272.00
1	TAILGATE AUTO LOCK ACTUATOR (CONSISTENT) }		-	-
1	TAILGATE LOCK CATCH (CONSISTENT)	TO REPAIR SEE LABOUR	52.00	-
1	TAILGATE WEATHERSTRIP (CONSISTENT)	NECESSARY	227.00	227.00
2	TAILGATE HINGE @ \$65.00 (CONSISTENT)	TO REPAIR SEE LABOUR	130.00	-
2	TAILGATE ABSORBER @ \$192.00 (CONSISTENT)	SERVICEABLE	384.00	-
1	REAR WINDSCREEN INNER SEAL (CONSISTENT)	NECESSARY	50.00	50.00
2	TAILLAMPS @ \$1319.00 (CONSISTENT)	SERVICEABLE	2,638.00	-
2	TAILLAMPS INNER SEALER @ \$38.00 (CONSISTENT)	NOT NECESSARY	76.00	-
2	SET TAILLAMP CLIPS @ \$25.00 (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,114.70	1,114.70
2	REAR BUMPER SIDE RETAINERS @ \$56.00 (CONSISTENT)	NECESSARY	112.00	112.00
2	REAR BUMPER ATTACHMENT RETAINERS @ \$48.00 (CONSISTENT)	NECESSARY	96.00	96.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR BUMPER CENTER CHROME STICKER (CONSISTENT)	NECESSARY	149.00	149.00
2	REAR BUMPER SIDE CHROME STICKER @ \$95.00 (CONSISTENT)	NECESSARY	190.00	190.00
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	495.70	-
1	END PANEL TOP TRIM (CONSISTENT)	CRACKED	129.40	129.40
1	SET END PANEL TOP TRIM CLIPS (CONSISTENT)	NECESSARY	30.00	30.00

Report Ref No. CC4/ASM17023867/M1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE PANEL TOP BOARD (CONSISTENT)	SERVICEABLE	738.00	-
2	REAR FENDER INNER TRIM @ \$605.00 (CONSISTENT)	CRACKED	1,210.00	1,210.00
2	SET REAR FENDER INNER TRIM CLIPS @ \$30.00 (CONSISTENT)	NECESSARY	60.00	40.00
1	TOWOONE CENTER LAMP (CONSISTENT)	CRACKED	1,922.00	1,922.00
1	REAR EXHAUST SILENCER (CONSISTENT)	SERVICEABLE	1,056.00	-
2	REAR EXHAUST MOUNTINGS @ \$38.00 (CONSISTENT)	SERVICEABLE	76.00	-
1	REAR EXHAUST GASKET (CONSISTENT)	SERVICEABLE	46.00	-
	LESS 20% DISCOUNT		-2,837.96	-1,676.32
			11,351.84	6,705.28
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR NUMBER PLATE W/COVER (SN) (CONSISTENT)	BENT	70.00	40.00
1	BODY PANEL JOINT SEALANT (SN) (CONSISTENT)	NECESSARY	120.00	80.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	250.00	220.00
1	REVERSE CAMERA (SN) (CONSISTENT)	SHORTED	450.00	350.00
			950.00	750.00
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILGATE LOCK CATCH, TAILGATE HINGE AND END PANEL.		1,300.00	800.00
	SPRAY PAINTING (PEARL)		1,300.00	900.00
	CHECK WIRING.		50.00	30.00
	ANTI RUST.		100.00	60.00
	REMOVE AND INSTALL REAR WINDSCREEN.		140.00	120.00
	REMOVE AND INSTALL TAILGATE PARTS.		90.00	60.00
	REMOVE AND INSTALL CARPET AND SEAT.		120.00	60.00
	REMOVE AND INSTALL REVERSE SENSOR.		90.00	60.00
	REMOVE AND INSTALL REVERSE CAMERA.		150.00	80.00
	REMOVE AND INSTALL REAR EXHAUST SILENCER.	NOT NECESSARY	120.00	-
			3,460.00	2,170.00
	GRAND TOTAL		15,761.84	9,625.28

Report Ref No. CC4/ASM17023867/M1ea3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,700.00
---	--	--	----------

Report Ref No. CC4/ASM17023867/M1ea3s2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.