

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: emlautopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SKP 9513M

Vehicle Model : MAZDA

Accident Date : 13.12.2017

Original Reg Date : 24.10.2014

Date : 03.01.2018

Chassis : JM6CC1071F0106626

TP Ins. AXA

ESTIMATE

1	1 pc	Tailgate	✓ OK		
2	1 pc	Tailgate Emblem (Skyactiv)	✓ OK		
3	1 pc	Tailgate Outer Chrome Moulding	✓ OK		
4	1 set	Tailgate Outer Clips	✓ OK		
5	1 pc	Tailgate Pocket Handle	X OK		
6	1 pc	Tailgate Inner Trim	✓ OK		
7	1 set	Tailgate Inner Trim Clip	✓ OK		
8	1 pc	Tailgate Inner Lock	✓ OK		
9	1 pc	Tailgate Auto Lock Actuator	X OK		
10	1 pc	Tailgate Lock Catch	X OK		
11	1 pc	Tailgate Weatherstrip	✓ OK		
12	2 pcs	Tailgate Hinge	X OK		
13	2 pcs	Tailgate Absorber	X OK		
14	1 pc	Rear Windscreen Inner Seal	✓ OK		
15	2 pcs	Taillamps	X OK		
16	2 pcs	Taillamps Inner Sealer	✓ OK		
17	2 set	Taillamp Clips	X OK		
18	1 pc	Rear Bumper	✓ OK		
19	2 pcs	Rear Bumper Side Retainers	✓ OK		
20	2 pcs	Rear Bumper Attachment Retainers	✓ OK		
21	1 set	Rear Bumper Clips	✓ OK		
22	1 pc	Rear Bumper Center Chrome Sticker	✓ OK		
23	2 pcs	Rear Bumper Side Chrome Sticker	✓ OK		
24	1 pc	End Panel	✓ OK		
25	1 pc	End Panel Top Trim	✓ OK		
26	1 set	End Panel Top Trim Clips	✓ OK		
27	1 pc	Spare Tyre Panel Top Board	X OK		
28	2 pcs	Rear Fender Inner Trim	✓ OK		
29	2 set	Rear Fender Inner Trim Clips	✓ OK		
30	1 pc	Tailgate Center lamp.	✓ OK		

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SKP 9513M

B/F

1	1 pc	Rear Exhaust Silencer	X one	
2	2 pcs	Rear Exhaust Mountings	X one	
3	1 pc	Rear Exhaust Gasket	X one	

Less 20%

Special Nett

1	1 pc	Rear Windscreen Sealant	✓ one	60.00
2	1 pc	Rear Number Plate w/cover	✓ one	40 70.00
3	1 pc	Body Panel Joint Sealant	✓ one	80 120.00
4	1 set	Reverse Sensor	✓ 2 sets	220 250.00
5	1 pc	Reverse Camera	✓ 2 sets	350 450.00

Labour charge

Panel Beating	850	1,300.00
Spray painting (Pearl)	900	1,300.00
Check Wiring	50	50.00
Anti rust		60 100.00
Remove and install rear winscreen.		120 140.00
Remove and install tailgate parts.		60 90.00
Remove and install carpet and seat.		60 120.00
Remove and install reverse sensor		60 90.00
Remove and install reverse camera		80 150.00
Remove and install rear exhaust silencer.		X 120.00

Not Authorize
L/S Repair
After part photo
100% Best (MA)
31/2017
7 days