

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/EGI17023896/Wd3e2 ERGO INSURANCE PTE LTD 5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER Date: 18-04-2018 **FIVE SINGAPORE 038985** Code: EGI 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SGP 3670D** Veh. Inspected SLS 6935X Policy No. Coverage (\$) 0.00 DSMPC1702958 Excess (\$) 0.00 Claim No. **Assign From** YEE PEI LI 15/12/2017 **Assign Date** 2. **Vehicle Particulars & Condition** Make & Model **AUDI Q5** 1984 c.c **Engine No. HIDDEN** Year of Reg. 2011 WAUZZZ8R2CA028298 Chassis No. Colour **BLACK** 105943 KM Odometer **IN ORDER** Steering **IN ORDER** Brakes Modification SPORTS RIM GOOD General **Conditions of Tyres** 3. Size Make **Balance MICHELIN** 255/45 R20 3 mm R/H Front Tyre 255/45 R20 **MICHELIN** L/H Front Tyre 3 mm R/H Rear Tyre 255/45 R20 **MICHELIN** 3 mm 255/45 R20 **MICHELIN** 3 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. **General Information** 5. 18/12/2017 (11:27 AM) **Accident Date** 14/12/2017 Inspect Date / Time 6 SPEED AUTOWERKZ - 68 KAKI BUKIT AVE 6 #02-05 Survey held at

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,800-\$11,800

5b. **Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

Report Ref No. CS3/EGI17023896/Wd3e2

Inspected By

WILSON TEO CHENG MING

Automotive Assessor

Repairer

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.