

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 2332T

MAKE :

MODEL : HYUNDAI SONATA

DATE 15/12/2017

QBE Ins - 45
 LKK - Calvin
 P1/2
 T5

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid X repair			\$ 1,349.50
	Boot Lid Rubber X			\$ 110.90
	Boot Lid Lock Upper X			\$ 132.10
	Boot Lid Lock Lower X			\$ 30.30
	Boot Lid Sonata Plate X			\$ 43.60
	Boot Lid Hyundai Plate X			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Lamp (LH)			\$ 230.20
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (LH)			\$ 38.00
	Tail Lamp (LH)			\$ 344.00
	Tail Lamp Quarter Panel (LH)			\$ 93.80
	Rear Panel X repair			\$ 391.80
	Rear Panel Garnish ?			\$ 95.80
	Tail Lamp Panel Top (LH)			\$ 217.40
	Panel Assy-Rear Floor Side (LH) X repair			\$ 88.55
	Rear Fender (LH)			\$ 1,935.90
	Rear Fender Inner Lining (LH) ?			\$ 74.10
	Rear Fender Corner Hardboard Cover (LH) ?			\$ 204.30
	Rear Fender Mudflap (LH)			\$ 15.50
	Rear Windscreen Moulding			\$ 60.00
	Panel Assy-Rear Floor Side (LH) X repair			\$ 88.55
	SUB TOTAL			\$ 7,024.20
	LESS 20%			\$ 1,404.84
	DISCOUNTED TOTAL			\$ 5,619.36
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Boot Lid Advertisement Logo			\$ 100.00
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Fender Advertisement Logo (LH/RH)	\$	100.00	\$ 200.00
	Rear Fender Comfort Sticker (LH/RH)	\$	30.00	\$ 60.00
	Rear Windscreen Sealant			\$ 46.00
				\$ 571.70

Nett
 Nett
 Nett
 Nett
 Nett
 Nett

QBE-4sum

LKK Kalva

SHC 2332T

TS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge		P3/2	800
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 600.00 540
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 50
	Remove/Refix Rear Windscreen Glass			\$ 120.00 100
	Remove/Refix Reverse Sensor			\$ 120.00 X
	TOTAL LABOUR			\$ 2,290.00
	ESTIMATE TOTAL			\$ 8,481.06
K9/kk LKKK ✓ 15/12/17 1030 hrs 5 Days 4s After Repair photo				
LKK Auto Consultants hence notify the Repairer of the 'out of scope' items • To resurvey before after spray painting • To display damaged parts for resurvey • Parts prices are subject to negotiation • Third party survey is on a "without prejudice" basis • No illegal modifications as a condition of repair • Supplementary items must be approved and is subject to final approval from the insurance company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				