

INS. CASE OWNER:

CC3 / LCR170 23909, Kija3sr

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time:

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 3,850.00 (4 days) Reduction: 54%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 2f

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 4,119.50

Loss of Rental (LOR):

S\$ 491.25 (5 days) x 98.25

Loss of Use (LOU):

S\$ - (\$ x days)

Loss of Income (LOI):

S\$ 250.00 x 5 days

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☒ [Tick only one]

GIA/LTA Search

S\$ 5.35

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 4,866.10 Global Sum S\$: 4,850.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 4,850.00

Name 1:

COMFORTDELGRO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

Name 3:

X

RECEIVED 05 FEB 2010



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC3/LCR17023909/K1ja3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120			Date : 18-12-2017	
			Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 7048M	Veh. Inspected	SHC 1223G	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/12/2017	Inspection Date	15/12/2017	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Date : 22/12/17

Fax :

Vehicle Reg No. SHC1223G CTPL

14.12.17

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1223G

DATE 14/12/2017 11:17

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber			\$ 110.90
	Boot Lid Lock Upper			\$ 132.10
	Boot Lid Lock Lower			\$ 30.30
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge			\$ 137.40
	Rear Bumper Under Cover			\$ 185.80
	Rear Bumper Protector (LH/RH)		\$ 38.00	\$ 76.00
	Rear Panel			\$ 391.80
	Rear Panel Garnish			\$ 95.80
	Spare Tyre Holder			\$ 27.60
	Spare Tyre Panel			\$ 863.00
	Spare Tyre Panel Cushion			\$ 200.30
	Rear Towing Hook			\$ 135.30
	Member Assy- Rear Floor Centre			\$ 163.60
	Exhaust Pipe Insulator			\$ 56.10
	Exhaust Silencer			\$ 723.00
	Exhaust Pipe Hanger			\$ 56.10
	SUB TOTAL			\$ 5,934.90
	LESS 20% to Consultants hence notify the Repairer of the following:			\$ 1,186.98
	DISCOUNTED TOTAL			\$ 4,747.92
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Boot Lid Advertisement Logo			\$ 100.00
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
	Labour Charge			\$ 515.70
	Panel Beating			\$ 1,800.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Exhaust Pipe			\$ 150.00
	TOTAL LABOUR			\$ 3,170.00
	ESTIMATE TOTAL			\$ 8,433.62

Hbf/Kahm
LikeHsam
ALG

• To resurvey before and after painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party surveys on a "Without Prejudice" basis
 • No illegal modification is allowed
 • Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by:
 Signature:
 Date:

1/14/17 (1/14/17)
 15/12/17 1045hr
 4 Days
 L/S
 After Repair-pht

Nett
 Nett
 Nett
 Nett
 Nett

1000
 720
 20
 20
 X

Team: ARC Repair TP(CLS0)1 JOB CARD Sales Order: JC NO.305097936

CUSTOMER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (Q) (P)	REGN NO. SHC1223G	MILEAGE
	MAKE HYUNDAI	FUEL E.....1/2.....F
	MODEL SONATA	DATE/TIME IN 14.12.2017 10:35
	YR OF MANU. 30.04.2011	TARGET DATE
	CHASSIS CODE KMHE141VMB810160	COMPLETION DATE/TIME

AKG

Accident Date: 14.12.2017
Nature: 3P 14.12.2017

/NO LABOR CODE DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Acknowledgement Slip		Exit Pass	
No.: SHC1223G	LKE/KALVIN	Vehicle No.: SHC1223G	
Signature/Date	Name of Service Advisor	Date	
returned to Service Reception upon collection		To be kept by Security Guard	

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1223G

DATE 14/12/2017 11:17

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✕			\$ 110.90
	Boot Lid Lock Upper ✕			\$ 132.10
	Boot Lid Lock Lower ✕			\$ 30.30
	Boot Lid Sonata Plate ✓			\$ 43.60
	Boot Lid Hyundai Plate ✓			\$ 24.20
	Boot Lid 'H' Emblem ✓			\$ 26.10
	Boot Lid CRDI Plate ✓			\$ 22.70
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (LH/RH) ✕ repair		\$ 38.00	\$ 76.00
	Rear Panel ✓			\$ 391.80
	Rear Panel Garnish ✓			\$ 95.80
	Spare Tyre Holder ?			\$ 27.60
	Spare Tyre Panel ✕ repair			\$ 863.00
	Spare Tyre Panel Cushion ?			\$ 200.30
	Rear Towing Hook ?			\$ 135.30
	Member Assy- Rear Floor Centre ✕ repair			\$ 163.60
	Exhaust Pipe Insulator ?			\$ 56.10
	Exhaust Silencer ?			\$ 723.00
	Exhaust Pipe Hanger ?			\$ 56.10
SUB TOTAL				\$ 5,934.90
LESS 20%				\$ 1,186.98
DISCOUNTED TOTAL				\$ 4,747.92
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00 Nett
	Boot Lid Advertisement Logo ✓			\$ 100.00 Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00 Nett
Labour Charge				\$ 515.70
	Panel Beating			\$ 1,800.00 1000
	Spray Painting Charge			\$ 1,000.00 720
	Wiring Charge			\$ 50.00 30
	Tuff Kote			\$ 50.00 20
	Remove/Refix Reverse Sensor			\$ 120.00 20
	Remove/Refix Exhaust Pipe			\$ 150.00 X
TOTAL LABOUR				\$ 3,170.00
ESTIMATE TOTAL				\$ 8,433.62

DISCOUNTED TOTAL

LESS 20%

UKK Auto Consultancy Service notify

the Repairer and having:

• To resurvey the work done

• To display the work done

• Parts prices

• Third party survey on "no prejudice" basis

• No illegal modification

• Supplemental survey and

is subject to the insurance Company

Signature:

Date:

15/12/17 1045h

4 PWS

L/S

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

After Repair

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2017 Edit Reg		15 Dec 2017 00:00 Edit Adj Rpt	S\$3,850.00 Edit Estimates	S\$3,850.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201604597K		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHC1223G	Date of Loss:	14/12/2017 00:00 - :59
Claim Type:	TP / 9576637366SG	Policy/Cover Note No.:	0999995029
Vehicle Reg. No. (Insured):	SLG7048M	Policy No. (Claimant):	MCOM0016
		Excess:	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 28/12/2017]		
Driver/Custodian (Insured):	LAU YONG HOCK (), NRIC: S6929844C		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC1223G (9576637366SG)**
[SLG7048M]

TP
COMFORT TRANSPORTATION PTE LTD
Dec 14 2017 12:00AM
[LCRF PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser		
Letters/Correspondences			1 per page	☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit		
Assessment Reports			1 per page	☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	19/12/17 11:36	Accident Statement From:SC - Reg. No: SLG7048M, Claimant: LCRF PTE LTD	Load HTM		
Photos/Images			3 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	18/12/17 17:43	General View	Load JPG	☒	
2	18/12/17 17:43	General View	Load JPG	☒	
3	18/12/17 17:43	General View	Load JPG	☒	
4	18/12/17 17:43	General View	Load JPG	☒	
5	18/12/17 17:43	General View	Load JPG	☒	
6	18/12/17 17:43	General View	Load JPG	☒	
7	18/12/17 17:43	General View	Load JPG	☒	
8	18/12/17 17:43	General View	Load JPG	☒	
9	18/12/17 17:43	General View	Load JPG	☒	
10	18/12/17 17:43	General View	Load JPG	☒	
11	18/12/17 17:43	General View	Load JPG	☒	
12	18/12/17 17:43	General View	Load JPG	☒	
13	18/12/17 17:43	General View	Load JPG	☒	
14	18/12/17 17:43	General View	Load JPG	☒	
15	18/12/17 17:43	General View	Load JPG	☒	
16	18/12/17 17:43	General View	Load JPG	☒	
17	18/12/17 17:43	General View	Load JPG	☒	
18	18/12/17 17:43	General View	Load JPG	☒	
19	18/12/17 17:43	General View	Load JPG	☒	
20	18/12/17 17:43	General View	Load JPG	☒	
21	18/12/17 17:43	General View	Load JPG	☒	
22	18/12/17 17:43	General View	Load JPG	☒	
23	18/12/17 17:43	General View	Load JPG	☒	
24	19/12/17 07:49	Reinspection Photo	Load JPG	☒	
25	19/12/17 07:49	Reinspection Photo	Load JPG	☒	
26	19/12/17 07:49	Reinspection Photo	Load JPG	☒	
27	19/12/17 18:55	Reinspection Photo	Load JPG	☒	

			1	☒
28	19/12/17 18:55	Reinspection Photo	1	Load JPG ☒
29	19/12/17 18:55	Reinspection Photo	1	Load JPG ☒
30	19/12/17 18:55	Reinspection Photo	1	Load JPG ☒
Documentation				
			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/12/17 08:15	TP ESTIMATE - MARKED	1 Load PDF	
2	19/12/17 08:15	TP GIA REPORT	1 Load PDF	
3	20/12/17 12:12	LETTER TO INSURED	1 Load PDF	
4	09/02/18 16:48	AUTHORISATION TO ACT	1 Load PDF	
5	09/02/18 16:48	LTA SEARCH	1 Load PDF	
6	09/02/18 16:48	RELEASE VOUCHER	1 Load PDF	
7	09/02/18 16:48	RENTAL RECEIPT	1 Load PDF	
8	09/02/18 16:48	WORKSHOP INVOICE	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLG7048M (Insd veh)	Model:	HYUNDAI SONATA NF 2.0 2.0
	SHC1223G (TP veh)		CRDI AT ABS 2WD 4DR TURBO
Date of Accident:	14/12/2017		(A)

Global Sum Settlement	:	☒ [X]	Yes	☐ []	No
Repair Estimate	:	\$			9,023.97
Final Repair Cost	:	\$			4,850.00
Loss of Use	:	\$			5.00 days at \$50.00 per day
Rental (if any)	:	\$			5 days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (GLOBAL SUM)	:	\$			4,850.00
Is Third Party Workshop GIA Registered? ☒ [X] YES ☐ [] NO (Kindly indicate below)					
A) For Non GIA Registered Workshop:			Agreed Liability _____ (%)		
B) For GIA Registered Workshop:			BOLA Applicable: Yes/ No BOLA Scenario No: <u>27</u>		
BOLA Liability: <u>100</u> (%)			Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown

1)	ComfortDelGro Engineering Pte Ltd	:	\$	4,850.00
2)		:	\$	
3)		:	\$	
4)		:	\$	
5)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

09 Feb
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR17023909/K1JA3S2
Date: 09/02/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995029
Claimant Vehicle No: SHC1223G Insured Vehicle No: SLG7048M
Date of Loss: 14/12/2017 Nature of Claim: TP Claim No: 9576637366SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC1223G
Make & Model: HYUNDAI SONATA NF, 2.0 2.0 CRDI AT ABS 2WD 4DR TURBO (A) Engine No: D4EAA861506
Reg. Date: 30/04/2011 (Man. Year: 2011) Chassis No: KMHET41VMBA810160
Colour: Blue Odometer: 507477 km
Engine Capacity: 1991 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm
Front Right Side: West Lake 7 mm Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,263.62	3,055.54	2,208.08	41.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	1,760.00	1,410.00	44.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,433.62	4,815.54	3,618.08	42.90
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	8,433.62	3,850.00	4,583.62	54.35
+ GST 7.00/7.00% (S\$)	590.35	269.50	320.85	54.35
Nett Amount (S\$)	9,023.97	4,119.50	4,904.47	54.35
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$98.25/day) (S\$)		491.25		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		4,866.10		
Global Sum Settlement (S\$)		4,850.00		

INSPECTION

Date of Assignment: 15/12/2017
Date Inspected: 15/12/2017 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,349.50 FL	*1,349.50 FL
2	1		*BOOT LID RUBBER	Serviceable	110.90 FL	*- FL
3	1		*BOOT LID LOCK UPPER	Serviceable	132.10 FL	*- FL
4	1		*BOOT LID LOCK LOWER	Serviceable	30.30 FL	*- FL
5	1		*BOOT LID SONATA PLATE	Necessary	43.60 FL	*43.60 FL
6	1		*BOOT LID HYUNDAI PLATE	Necessary	24.20 FL	*24.20 FL
7	1		*BOOT LID H EMBLEM	Necessary	26.10 FL	*26.10 FL
8	1		*BOOT LID CRDI PLATE	Necessary	22.70 FL	*22.70 FL
9	1		*REAR BUMPER	Deformed	578.40 FL	*578.40 FL
10	1		*REAR BUMPER REINFORCEMENT	Cracked	483.30 FL	*483.30 FL
11	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
12	1		*REAR BUMPER SPONGE	Torn	137.40 FL	*137.40 FL
13	1		*REAR BUMPER UNDER COVER	Serviceable	185.80 FL	*- FL
14	2		*REAR BUMPER PROTECTOR (LH/RH)	Repair	76.00 FL	*- FL
15	1		*REAR PANEL	Dented	391.80 FL	*391.80 FL
16	1		*REAR PANEL GARNISH	Cracked	95.80 FL	*95.80 FL
17	1		*SPARE TYRE HOLDER	Serviceable	27.60 FL	*- FL
18	1		*SPARE TYRE PANEL	Repair	863.00 FL	*- FL
19	1		*SPARE TYRE PANEL CUSHION	Serviceable	200.30 FL	*- FL
20	1		*REAR TOWING HOOK	Serviceable	135.30 FL	*- FL
21	1		*MEMBER ASSY - REAR FLOOR CENTRE	Repair	163.60 FL	*- FL
22	1		*EXHAUST PIPE INSULATOR	Serviceable	56.10 FL	*- FL
23	1		*EXHAUST SILENCER	Serviceable	723.00 FL	*- FL
24	1		*EXHAUST PIPE HANGER	Serviceable	56.10 FL	*- FL
25	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
26	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
27	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
28	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
29	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,450.60	3,690.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,186.98	634.96
Total Parts (\$\$)	5,263.62	3,055.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	1,800.00	1,000.00
2	SPRAY PAINTING CHARGE.	New	1,000.00	720.00
3	WIRING CHARGE.	New	50.00	0.00
4	TUFF KOTE.	New	50.00	20.00
5	REMOVE / REFIX REVERSE SENSOR.	New	120.00	20.00
6	REMOVE / REFIX EXHAUST PIPE.	New	150.00	0.00
Gross Labour Cost (S\$)			3,170.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >