

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 1223G

DATE 14/12/2017 11:17

MAKE :

MODEL : HYUNDAI SONATA

| Qty              | Parts Description/ Labour                | Type | Unit Price  | Amount      |
|------------------|------------------------------------------|------|-------------|-------------|
|                  | Boot Lid ✓                               |      |             | \$ 1,349.50 |
|                  | Boot Lid Rubber ✕                        |      |             | \$ 110.90   |
|                  | Boot Lid Lock Upper ✕                    |      |             | \$ 132.10   |
|                  | Boot Lid Lock Lower ✕                    |      |             | \$ 30.30    |
|                  | Boot Lid Sonata Plate ✓                  |      |             | \$ 43.60    |
|                  | Boot Lid Hyundai Plate ✓                 |      |             | \$ 24.20    |
|                  | Boot Lid 'H' Emblem ✓                    |      |             | \$ 26.10    |
|                  | Boot Lid CRDI Plate ✓                    |      |             | \$ 22.70    |
|                  | Rear Bumper ✓                            |      |             | \$ 578.40   |
|                  | Rear Bumper Reinforcement ?              |      |             | \$ 483.30   |
|                  | Rear Bumper Clip ✓                       |      |             | \$ 22.00    |
|                  | Rear Bumper Sponge ?                     |      |             | \$ 137.40   |
|                  | Rear Bumper Under Cover ?                |      |             | \$ 185.80   |
|                  | Rear Bumper Protector (LH/RH) ✕ repair   |      | \$ 38.00    | \$ 76.00    |
|                  | Rear Panel ✓                             |      |             | \$ 391.80   |
|                  | Rear Panel Garnish ✓                     |      |             | \$ 95.80    |
|                  | Spare Tyre Holder ?                      |      |             | \$ 27.60    |
|                  | Spare Tyre Panel ✕ repair                |      |             | \$ 863.00   |
|                  | Spare Tyre Panel Cushion ?               |      |             | \$ 200.30   |
|                  | Rear Towing Hook ?                       |      |             | \$ 135.30   |
|                  | Member Assy- Rear Floor Centre ✕ repair  |      |             | \$ 163.60   |
|                  | Exhaust Pipe Insulator ?                 |      |             | \$ 56.10    |
|                  | Exhaust Silencer ?                       |      |             | \$ 723.00   |
|                  | Exhaust Pipe Hanger ?                    |      |             | \$ 56.10    |
| SUB TOTAL        |                                          |      |             | \$ 5,934.90 |
| LESS 20%         |                                          |      |             | \$ 1,186.98 |
| DISCOUNTED TOTAL |                                          |      |             | \$ 4,747.92 |
|                  | Boot Lid Comfort Logo & Tel No. Sticker  |      | \$ 30.00    | Nett        |
|                  | Boot Lid Advertisement Logo ✓            |      | \$ 100.00   | Nett        |
|                  | Rear Bumper Reverse Sensor ✓             |      | \$ 135.70   | Nett        |
|                  | Rear Bumper Advertisement Logo ✓         |      | \$ 50.00    | Nett        |
|                  | Rear Fender Advertisement Logo (LH/RH) ✓ |      | \$ 200.00   | Nett        |
| Labour Charge    |                                          |      |             | \$ 515.70   |
|                  | Panel Beating                            |      | \$ 1,800.00 | 1000        |
|                  | Spray Painting Charge                    |      | \$ 1,000.00 | 720         |
|                  | Wiring Charge                            |      | \$ 50.00    | 20          |
|                  | Tuff Kote                                |      | \$ 50.00    | 20          |
|                  | Remove/Refix Reverse Sensor              |      | \$ 120.00   | 20          |
|                  | Remove/Refix Exhaust Pipe                |      | \$ 150.00   | X           |
| TOTAL LABOUR     |                                          |      |             | \$ 3,170.00 |
| ESTIMATE TOTAL   |                                          |      |             | \$ 8,433.62 |

**DISCOUNTED TOTAL**

**LESS 20%**

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey the vehicle before painting
- To display damaged parts for resurvey
- Parts prices to be agreed on a "no prejudice" basis
- Third party's survey to be conducted on a "no prejudice" basis
- No illegal modification
- Supplementary survey to be resurveyed and approved by the Insurance Company

Acknowledged by Repairer:

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Kalvin (LKK)

15/12/17 1045h

4 Pairs

L/S

After Repair - p/h

1000

720

20

20

X