

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

15-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6453 B

1 pc	Rear o/s door ✓	\$	765.00
1 pc	Rear o/s door hinge upper X	\$	33.00
1 pc	Rear o/s door hinge lower X	\$	33.00
1 pc	Rear o/s door lock X	\$	289.00
1 pc	Rear o/s door checker X	\$	44.00
1 pc	Rear o/s door rubber weatherstrip X	\$	104.00
1 pc	Rear o/s fender X repair	\$	1,205.00
1 pc	Rear o/s fender inner shield X	\$	120.00
1 pc	Rear windscreen moulding X	\$	87.00

the Repairer will be following:
 • To resurvey: before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

S/NETT

1 set	Rear o/s fender inner shield clips X	\$	38.00
1 set	O/s door sticker ✓	\$	100.00
1 pc	Rear o/s fender sticker ✓	\$	60.00
1 pc	Windscreen sealant X	\$	50.00
	Sundry	\$	20
	To check wheel alignment	\$	50.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	80.00 X
	To dismantle / refit the rear o/s door & inner component into new shell door	\$	120.00 50
	To dismantle / refit rear windscreen to facilitate repairs	\$	150.00 50
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear bumper, etc.	\$	400
	To putty and spray painting on rear o/s door, rear o/s fender, rear bumper, o/s rocker panel garnish	\$	950.00
	To apply rustproofing on the repaired and replaced panels.	\$	850.00 720
		\$	150.00 20
		\$	5,130.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.