

15/5/2010

INS. CASE OWNER:

B/nine

CC 6/EQ11702

3914, T2 Wbhsr

LKK:

IDAC:

Surveyor:

Taufik

DOI:

ASSIGNMENT

15/12/14

Date / Time:

15/12/14

Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No.:

GR 9936M

Name of Insured:

IMB SERVICES

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

08/12/14

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Gan Teck Loon

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

DM17K00818-76

Policy No.:

DM17K00818-76

Make / Model:

HYUNDAI

Place of Accident:

PARKER ROAD KUYER.

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SFP 76080

INSRS:

WSP:

Tel:

Liability:

RMKS:

MAXIMUS

PARKER

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

14/12/14

VIC

SFP 76080 - X

GRANITE - Y

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

02/01/15 - 012

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

21/12/14

Sent By:

Taufik

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

HS

S\$

11,500.00 (10 days) Reduction: 54 %

Email

Call

TOTAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Total Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

200

If NO or B 28, Ass. Lia:

100

Repair Cost: (w/loss)

S\$

11,770.00

COI Unit, 3 JBM - G.C)

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

(\$ x days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

TOTAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

RECEIVED 03 JUL 2018

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

WP REPORT

3) Survey fee:

4300.00




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQI17023914/T1hb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 18-12-2017	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJQ 1746S	Veh. Inspected	SFP 2608D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/12/2017	Inspection Date	15/12/2017	
Survey held at	MAXIMUS RACING PTE LTD 7 SOON LEE STREET #05-05 SINGAPORE 627608			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/EQI17023914/T1hb3

Date: 18.12.2017

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SFP2608D


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.12.2017 at the premises of M/s Maximus Racing Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	23,908.55
Revised Estimate Amount	: S\$	11,289.65
"Check" Items Amount	: S\$	6,758.75
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

1,400.00		
1,600.00		
100.00		
30.00		
80.00		
300.00		
1,311.00		
76.00		
541.50		
408.50		
94.05	180.00	
522.5	550.00	1,615.00
712.5	750.00	74.10
	435.10	104.50
	304.00	109.25
	1,083.00	90.25
	39.90	919.60
	1,235.00	104.50
	237.50	209.00
	218.50	550.00
	76.00	750.00
	85.50	218.50
	94.05	370.50
	85.50	205.20
	94.05	451.25
	85.50	323.00
	20.00	435.10
	20.00	114.00
	11,354.65	6,823.75
	11,889.65	6,758.75
		18,173.40

(X) \$3740.15

Estimate: \$ 23908.55
 Revised: \$ 11889.65
 Check: \$ 6758.75

MAXIMUS RACING PTE LTD

MR Performance Centre, No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507894R

ESTIMATION FOR SFP2608D

Reference No: Q-17-086

Requested By: EQ Insurance - Motor Claim Department

Date: 12/12/2017

Address: 5 Maxwell Rd #17-00 Tower Block MND Complex Singapore 01 Terms: Cash

Tel: +65 6223 9433

PAGE 1

Item	Description	Qty	Unit Price	Disc %	Total Price
Policy No // Accident Date: 2100287626-05000 // 8/12/2017 Report in: 8/12/2017 Vehicle Make/Model: Audi A4 Quattro 2.0 Vehicle Number: SFP 2608 D Manufacturing Year: 2011 Engine: 07886713N54B30A Chassis No: WAUZZZ8K9CA100021					
Labour Charges:					
1	Remove and renew damaged parts, straighten and realign				1400 / \$ 2,000.00
2	Respray affected areas.				1600 / \$ 2,600.00
3	To apply cavity wax coating on affected areas				100 / \$ 250.00
4	Labour To Check Front Lightings, Headlamp, Water Leakage & Headlamp Washer				7 / \$ 180.00
5	Wheel Balancing				20 / \$ 80.00
6	Computerised 4 Wheel Alignment				80 / \$ 120.00
7	General Diagnostics to Reset, Re-calibrate using Volkswagen Original Software *Headlight, Taillight, Side Mirror & Reverse Sensors				300 / \$ 600.00
Material & Fluid Charges:					
8	Front Bumper <i>del</i>				
9	Front Bumper Center Grill <i>X un</i>	1	\$ 1,380.00	5%	\$ 1,311.00
10	Front Bumper Lower Spoiler <i>X un</i>	1	\$ 490.00	5%	\$ 465.50
11	Front Bumper Lower Panel <i>X un</i>	1	\$ 270.00	5%	\$ 256.50
12	Front Bumper Foam Absorber <i>X un</i>	1	\$ 150.00	5%	\$ 142.50
13	Front Bumper Reinforcement Bar <i>X un</i>	1	\$ 80.00	5%	\$ 76.00
14	Front Bumper Reinforcement Bar Bracket <i>X un</i>	1	\$ 480.00	5%	\$ 437.00
15	Front Bumper Side Bracket <i>del</i>	2	\$ 160.00	5%	\$ 304.00
16	Front Headlamp Housing (LH) <i>? cut</i>	2	\$ 40.00	5%	\$ 76.00
17	Front Headlamp Bracket (LH) <i>? del</i>	1	\$ 1,700.00	5%	\$ 1,615.00
18	Front Headlamp Mounting (LH) <i>? del</i>	1	\$ 78.00	5%	\$ 74.10
19	Front Foglamp (LH) <i>X un</i>	1	\$ 110.00	5%	\$ 104.50
20	Front Foglamp Cover (LH) <i>X un</i>	1	\$ 198.00	5%	\$ 188.10
		1	\$ 115.00	5%	\$ 109.25
21	Front Fender (LH) <i>bt</i>				
22	Front Fender Cross Support (LH) <i>X un</i>	1	\$ 570.00	5%	\$ 541.50
23	Front Wheel Housing Cover (LH) <i>X un</i>	1	\$ 95.00	5%	\$ 90.25
		1	\$ 189.00	5%	\$ 179.55
24	Side Mirror Cover (LH) <i>at</i>				
25	Side Mirror Assembly With Motor (LH) <i>? cut</i>	1	\$ 430.00	5%	\$ 408.50
26	Side Mirror Turn Signal (LH) <i>at</i>	1	\$ 988.00	5%	\$ 919.60
		1	\$ 99.00	5%	\$ 94.05
27	Front Tie Rod (LH) <i>X un</i>				
28	Front Tie Rod End (LH) <i>X un</i>	1	\$ 110.00	5%	\$ 104.50
		1	\$ 220.00	5%	\$ 209.00
29	Rear Inner Taillight <i>LH - X RH - cut</i>	2 <i>PC</i>	\$ 550.00	5%	\$ 1,045.00
30	Rear Outer Taillight <i>LH - X RH - cut</i>	2 <i>PC</i>	\$ 750.00	5%	\$ 1,425.00
31	Rear Parking Sensor <i>mis</i>	1	\$ 458.00	5%	\$ 435.10

PAGE 1

MAXIMUS RACING PTE LTD

MR Performance Centre, No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

ESTIMATION FOR SFP2608D

Reference No: Q-17-086

Requested By: EQ Insurance - Motor Claim Department

Date: 12/12/2017

Address: 5 Maxwell Rd #17-00 Tower Block MND Complex Singapore 06 Terms: Cash

Tel: +65 6223 9433



PAGE 2

Item	Description	Qty	Unit Price	Disc %	Total Price
32	Rear Trunk Lid <i>bt</i>	1	1,500.00		
33	Rear Trunk Hinge <i>bt</i>	2	150.00	5%	\$ 304.00
34	Rear Trunk Hinge Cover <i>bt</i>	2	125.00	5%	\$ 237.50
35	Rear Trunk Lock <i>bt</i>	2	225.00	5%	\$ 427.50
36	Rear Trunk Lock Cover <i>bt</i>	2	115.00	5%	\$ 218.50
37	Rear Trunk Lock Striker <i>bt</i>	2	570.00	5%	\$ 1,083.00
38	Rear Trunk Lock Switch <i>bt</i>	2	540.00	5%	\$ 1,026.00
39	Rear Trunk Stopper <i>bt</i>	1	390.00	5%	\$ 370.50
40	Rear License Plate Light <i>bt</i>	2	21.00	5%	\$ 39.90
		2	108.00	5%	\$ 206.20
41	Rear Bumper <i>de</i>	1	1,300.00	5%	\$ 1,235.00
42	Rear Bumper Lower Spoiler <i>de</i>	1	250.00	5%	\$ 237.50
43	Rear Bumper Lower Spoiler Mesh <i>de</i>	1	230.00	5%	\$ 218.50
44	Rear Bumper Side Bracket Small <i>de</i>	2	40.00	5%	\$ 76.00
45	Rear Bumper Side Bracket Big <i>de</i>	2	45.00	5%	\$ 85.50
46	Rear Reinforcement Bar <i>bt</i>	1	475.00	5%	\$ 451.25
47	Rear Reinforcement Bar Bracket <i>bt</i>	2	170.00	5%	\$ 323.00
48	Rear Parking Sensor <i>bt</i>	1	458.00	5%	\$ 435.10
49	Front Fender Emblem (LH) <i>bt</i>	1	99.00	5%	\$ 94.05
50	Rear A4 Emblem <i>bt</i>	1	90.00	5%	\$ 85.50
51	Rear Audi Circles Emblem <i>bt</i>	1	98.00	5%	\$ 94.05
52	Rear 2.0 Emblem <i>bt</i>	1	90.00	5%	\$ 85.50
53	Vehicle Plate Frame <i>bt</i>	1	20.00	S.Nett	\$ 20.00
54	Vehicle Plate Number <i>bt</i>	1	20.00	S.Nett	\$ 20.00
55	Miscellaneous - Bolts, Nuts, Screws, Clips, etc <i>bt</i>	1	120.00	5%	\$ 114.00

Taufik 97495749

15/12/17 RU20.

Repairing before paint.
10 days.

SVC @ lkkauto.com

taufik @ lkkauto.com.

PRICE BEFORE GST

ADD GST 7%

Grand Total:

\$ 23,908.55

\$ 1,673.80

\$ 25,582.15

Validity of the estimates is 2 weeks based from the date of quote. Estimated costs quoted are excluding GST. We would mention based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you.

Please be informed that a deposit of 50% of full amount is payable before commencement of work.

Authorised By:

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 9 February 2018 6:01 PM
To: 'Guo Li Seah'
Cc: Vic (LKKAUTO); Daphne Tan; Taufikh (LKKAUTO)
Subject: RE: AUDI A4 SFP2608D ACCIDENT LKK REF CC6/EQI17023914/T1hb3

WITHOUT PREJUDICE

Hi Arry,

We refer to the above matter.

Our surveyor have finalise COR at \$11,000.00 (exclude gst) 10 days.

In order to expedite the claim process, please forward all relevant documents for us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Guo Li Seah [<mailto:enquiry@maximusracing.com>]
Sent: Thursday, 8 February 2018 6:43 PM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Cc: Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Daphne Tan <daphne@maximusracing.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: Fw: AUDI A4 SFP2608D ACCIDENT LKK REF CC6/EQI17023914/T1hb3

Regards,

Arry Seah
Operation Executive
Maximus Racing Team Support

----- Forwarded Message -----

From: Guo Li Seah <enquiry@maximusracing.com>
To: Asher Sng (LKKAUTO) <ashersng@lkkauto.com>
Sent: Thursday, 8 February 2018, 18:05
Subject: Fw: AUDI A4 SFP2608D ACCIDENT LKK REF CC6/EQI17023914/T1hb3

Hi Asher,

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

**FINALISATION FOR SFP2608D**

Reference No: Q-17-086

Requested By: EQ Insurance - Motor Claim Department

Date: 12/12/2017

Address: 5 Maxwell Rd #17-00 Tower Block MND Complex Singapore 01 Terms:

Cash

Tel: +65 6223 9433

PAGE 1

Item	Description	Qty	Unit Price	Disc %	Total Price
	Policy No // Accident Date: 2100287626-05000 // 8/12/2017 Report In: 8/12/2017 Vehicle Make/Model: Audi A4 Quattro 2.0 Vehicle Number: SFP 2608 D Manufacturing Year: 2011 Engine: 07866713N54B30A Chassis No: WAUZZZ8K9CA100021				
	<u>Labour Charges:</u>				
1	Remove and renew damaged parts, straighten and realign				\$ 1,400.00
2	Respray affected areas.				\$ 1,600.00
3	To apply cavity wax coating on affected areas				\$ 100.00
4	Wheel Balancing				\$ 30.00
5	Computerised 4 Wheel Alignment				\$ 80.00
6	General Diagnostics to Reset, Re-calibrate using Volkswagen Original Software *Headlight, Taillight, Side Mirror & Reverse Sensors				\$ 300.00
	<u>Material & Fluid Charges:</u>				
7	Front Bumper	1	\$ 1,380.00	5%	\$ 1,311.00
8	Front Bumper Side Bracket	2	\$ 40.00	5%	\$ 76.00
9	Front Headlamp Housing (LH)	1	\$ 1,700.00	5%	\$ 1,615.00
10	Front Headlamp Bracket (LH)	1	\$ 78.00	5%	\$ 74.10
11	Front Headlamp Mounting (LH)	1	\$ 110.00	5%	\$ 104.50
12	Front Fender (LH)	1	\$ 570.00	5%	\$ 541.50
13	Side Mirror Cover (LH)	1	\$ 430.00	5%	\$ 408.50
14	Side Mirror Assembly With Motor (LH)	1	\$ 968.00	5%	\$ 919.60
15	Side Mirror Turn Signal (LH)	1	\$ 99.00	5%	\$ 94.05
16	Rear Inner Taillight	1	\$ 550.00	5%	\$ 522.50
17	Rear Outer Taillight	1	\$ 750.00	5%	\$ 712.50
18	Rear Trunk Lid	1	\$ 1,500.00	5%	\$ 1,425.00
19	Rear Trunk Lock Cover	1	\$ 570.00	5%	\$ 541.50
20	Rear Trunk Lock Switch	1	\$ 390.00	5%	\$ 370.50
21	Rear Trunk Stopper	2	\$ 21.00	5%	\$ 39.90
22	Rear License Plate Light	2	\$ 108.00	5%	\$ 205.20

PAGE 1

MAXIMUS RACING PTE LTD

MR Performance Centre, No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

**FINALISATION FOR SFP2608D**

Reference No: Q-17-086

Requested By: EQ Insurance - Motor Claim Department

Date: 12/12/2017

Address: 5 Maxwell Rd #17-00 Tower Block MND Complex Singapore 06 Terms: Cash

Tel: +65 6223 9433

PAGE 2

Item	Description	Qty	Unit Price	Disc %	Total Price
23	Rear Bumper	1	\$ 1,300.00	5%	\$ 1,235.00
24	Rear Bumper Lower Spoiler	1	\$ 250.00	5%	\$ 237.50
25	Rear Bumper Lower Spoiler Mesh	1	\$ 230.00	5%	\$ 218.50
26	Rear Bumper Side Bracket Small	2	\$ 40.00	5%	\$ 76.00
27	Rear Bumper Side Bracket Big	2	\$ 45.00	5%	\$ 85.50
28	Rear Reinforcement Bar	1	\$ 475.00	5%	\$ 451.25
29	Rear Reinforcement Bar Bracket	2	\$ 170.00	5%	\$ 323.00
30	Rear Parking Sensor	1	\$ 458.00	5%	\$ 435.10
31	Front Fender Emblem (LH)	1	\$ 99.00	5%	\$ 94.05
32	Rear A4 Emblem	1	\$ 90.00	5%	\$ 85.50
33	Rear Audi Circles Emblem	1	\$ 99.00	5%	\$ 94.05
34	Rear 2.0 Emblem	1	\$ 90.00	5%	\$ 85.50
35	Vehicle Plate Frame	1	\$ 20.00	S.Nett	\$ 20.00
36	Vehicle Plate Number	1	\$ 20.00	S.Nett	\$ 20.00
37	Lump Sum Discount	1	-20%		\$ (3,186.46)
PRICE BEFORE GST					\$ 12,745.84
ADD GST 7%					\$ 892.21
Grand Total:					\$ 13,638.05

Validity of the estimates is 2 weeks based from the date of quote. Estimated costs quoted are excluding GST. We would mention based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you.

Please be informed that a deposit of 50% of full amount is payable before commencement of work.

Authorised By:



LABOUR**s/n****PARTS**

\$1,400.00
\$1,600.00
\$100.00
\$30.00
\$80.00
\$300.00

\$20.00
\$20.00

\$1,380.00
\$80.00
\$1,700.00
\$78.00
\$110.00
\$570.00
\$430.00
\$968.00
\$99.00
\$550.00
\$750.00
\$1,500.00
\$570.00
\$390.00
\$42.00
\$216.00
\$1,300.00
\$250.00
\$230.00
\$80.00
\$90.00
\$475.00
\$340.00
\$458.00
\$99.00
\$90.00
\$99.00
\$90.00

\$3,510.00

\$40.00

\$13,034.00
-5% \$651.70
\$12,382.30

Total: \$15,932.30

Lump Sum: **\$12,745.84**

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

ESTIMATION FOR SFP2608D

Reference No: Q-17-086

Requested By: EQ Insurance - Motor Claim Department

Date: 12/12/2017

Address: 5 Maxwell Rd #17-00 Tower Block MND Complex Singapore 01 Terms: Cash

Tel: +65 6223 9433

PAGE 1

Item	Description	Qty	Unit Price	Disc %	Total Price
	Policy No // Accident Date: 2100287626-05000 // 8/12/2017 Report In: 8/12/2017 Vehicle Make/Model: Audi A4 Quattro 2.0 Vehicle Number: SFP 2608 D Manufacturing Year: 2011 Engine: 07866713N54B30A Chassis No: WAUZZZ8K9CA100021				
	<u>Labour Charges:</u>				
1	Remove and renew damaged parts, straighten and realign				\$ 1400 2,000.00
2	Respray affected areas.				\$ 1600 2,600.00
3	To apply cavity wax coating on affected areas				\$ 100 250.00
4	Labour To Check Front Lightings, Headlamp, Water Leakage & Headlamp Washer				\$? 180.00
5	Wheel Balancing				\$ 30. 60.00
6	Computerised 4 Wheel Alignment				\$ 80. 120.00
7	General Diagnostics to Reset, Re-calibrate using Volkswagen Original Software *Headlight, Taillight, Side Mirror & Reverse Sensors				\$ 300 600.00
	<u>Material & Fluid Charges:</u>				
8	Front Bumper <i>del</i>	1	\$ 1,380.00	5%	\$ 1,311.00
9	Front Bumper Center Grill <i>x</i>	1	\$ 490.00	5%	\$ 465.50
10	Front Bumper Lower Spoiler <i>x</i>	1	\$ 270.00	5%	\$ 256.50
11	Front Bumper Lower Panel <i>x</i>	1	\$ 150.00	5%	\$ 142.50
12	Front Bumper Foam Absorber <i>x</i>	1	\$ 80.00	5%	\$ 76.00
13	Front Bumper Reinforcement Bar <i>x</i>	1	\$ 460.00	5%	\$ 437.00
14	Front Bumper Reinforcement Bar Bracket <i>x</i>	2	\$ 160.00	5%	\$ 304.00
15	Front Bumper Side Bracket <i>del</i>	2	\$ 40.00	5%	\$ 76.00
16	Front Headlamp Housing (LH) ?	1	\$ 1,700.00	5%	\$ 1,615.00
17	Front Headlamp Bracket (LH) ?	1	\$ 78.00	5%	\$ 74.10
18	Front Headlamp Mounting (LH) ?	1	\$ 110.00	5%	\$ 104.50
19	Front Foglamp (LH) <i>x</i>	1	\$ 198.00	5%	\$ 188.10
20	Front Foglamp Cover (LH) ?	1	\$ 115.00	5%	\$ 109.25
21	Front Fender (LH) <i>bt</i>	1	\$ 570.00	5%	\$ 541.50
22	Front Fender Cross Support (LH) ?	1	\$ 95.00	5%	\$ 90.25
23	Front Wheel Housing Cover (LH) <i>x</i>	1	\$ 189.00	5%	\$ 179.55
24	Side Mirror Cover (LH) <i>at</i>	1	\$ 430.00	5%	\$ 408.50
25	Side Mirror Assembly With Motor (LH) ?	1	\$ 968.00	5%	\$ 919.60
26	Side Mirror Turn Signal (LH) <i>at</i>	1	\$ 99.00	5%	\$ 94.05
27	Front Tie Rod (LH) ?	1	\$ 110.00	5%	\$ 104.50
28	Front Tie Rod End (LH) ?	1	\$ 220.00	5%	\$ 209.00
29	Rear Inner Taillight <i>LH - ? RH - out</i>	2	\$ 550.00	5%	\$ 1,045.00
30	Rear Outer Taillight <i>LH - ? RH - out</i>	2	\$ 750.00	5%	\$ 1,425.00
31	Rear Parking Sensor <i>mis</i>	1	\$ 458.00	5%	\$ 435.10

PAGE 1

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

ESTIMATION FOR SFP2608D

Requested By: EQ Insurance - Motor Claim Department

Reference No: Q-17-086

Date: 12/12/2017

Address: 5 Maxwell Rd #17-00 Tower Block MND Complex Singapore 06 Terms: Cash

Tel: +65 6223 9433

PAGE 2

Item	Description	Qty	Unit Price	Disc %	Total Price
32	Rear Trunk Lid <i>br</i>	2	\$ 160.00	5%	\$ 304.00
33	Rear Trunk Hinge <i>br</i>	2	\$ 125.00	5%	\$ 237.50
34	Rear Trunk Hinge Cover <i>x</i>	2	\$ 225.00	5%	\$ 427.50
35	Rear Trunk Lock	1 <i>2</i>	\$ 115.00	5%	\$ 218.50
36	Rear Trunk Lock Cover <i>at</i>	1 <i>2</i>	\$ 570.00	5%	\$ 1,083.00
37	Rear Trunk Lock Striker	1 <i>2</i>	\$ 540.00	5%	\$ 1,026.00
38	Rear Trunk Lock Switch	1	\$ 390.00	5%	\$ 370.50
39	Rear Trunk Stopper <i>nei</i>	2	\$ 21.00	5%	\$ 39.90
40	Rear License Plate Light <i>?</i>	2	\$ 108.00	5%	\$ 205.20
41	Rear Bumper <i>de</i>	1	\$ 1,300.00	5%	\$ 1,235.00
42	Rear Bumper Lower Spoiler <i>de</i>	1	\$ 250.00	5%	\$ 237.50
43	Rear Bumper Lower Spoiler Mesh <i>get</i>	1	\$ 230.00	5%	\$ 218.50
44	Rear Bumper Side Bracket Small <i>nei</i>	2	\$ 40.00	5%	\$ 76.00
45	Rear Bumper Side Bracket Big <i>nei</i>	2	\$ 45.00	5%	\$ 85.50
46	Rear Reinforcement Bar <i>?</i>	1	\$ 475.00	5%	\$ 451.25
47	Rear Reinforcement Bar Bracket <i>?</i>	2	\$ 170.00	5%	\$ 323.00
48	Rear Parking Sensor <i>?</i>	1	\$ 458.00	5%	\$ 435.10
49	Front Fender Emblem (LH) <i>nei</i>	1	\$ 99.00	5%	\$ 94.05
50	Rear A4 Emblem <i>nei</i>	1	\$ 90.00	5%	\$ 85.50
51	Rear Audi Circles Emblem <i>nei</i>	1	\$ 99.00	5%	\$ 94.05
52	Rear 2.0 Emblem <i>nei</i>	1	\$ 90.00	5%	\$ 85.50
53	Vehicle Plate Frame <i>de</i>	1	\$ 20.00	S Nett	\$ 20.00
54	Vehicle Plate Number <i>?</i>	1	\$ 20.00	S Nett	\$ 20.00
55	Miscellaneous - Bolts, Nuts, Screws, Clips, etc <i>?</i>	1	\$ 120.00	5%	\$ 114.00
<i>Taufik 97495749</i> <i>WP</i> <i>15/12/17 RU20.</i> <i>Resurvey before paint.</i> <i>10 days.</i>					
<i>sur @ lkauto.com</i> <i>taufik @ lkauto.com</i>					
PRICE BEFORE GST					\$ 23,908.55
ADD GST 7%					\$ 1,673.60
Grand Total:					\$ 25,582.15

Validity of the estimates is 2 weeks based from the date of quote. Estimated costs quoted are excluding GST. We would mention based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you.

Please be informed that a deposit of 50% of full amount is payable before commencement of work.

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised By:

Shu Pei (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Monday, 19 March 2018 9:44 AM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GR9936M (OI : EQI - DM17HO02808-JG) AND SFP2608D (TP : LKK REF - CC6/EQI17023914/T1hb3) on 08.12.2017
Attachments: GR9936M.pdf

Dear Shu Pei

My apologies for the wrong attachment.

Best Regards,

Joel Goh
Executive - Claims



EQ Insurance Company Limited
5 Maybank Road #1710D Tower Block MND Complex Singapore 069110
did: 65 6223 6772 | tel: 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Joel Goh
Sent: Friday, March 16, 2018 11:23 AM
To: 'Shu Pei (LKKAUTO)'
Subject: RE: Direct Settlement - Accident Involving GR9936M (OI : EQI - DM17HO02808-JG) AND SFP2608D (TP : LKK REF - CC6/EQI17023914/T1hb3) on 08.12.2017

Dear Shu Pei

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh
Executive - Claims



EQ Insurance Company Limited

5 Maxwell Road, #17-00, Tower Block, MND Complex, Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

Website: www.eqinsurance.com.sg

ADMIN@EQINSURANCE.COM.SG



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAUTO) [<mailto:shupeil@lkkauto.com>]

Sent: Friday, March 16, 2018 11:14 AM

To: Joel Goh

Subject: RE: Direct Settlement - Accident Involving GR9936M (OI : EQI - TBA) AND SFP2608D (TP : LKK REF - CC6/EQI17023914/T1hb3) on 08.12.2017

Dear Joel,

We refer to the below email.

Please be informed that OI insured is should be GR 9936M.

Sorry for the inconvenience caused.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [<mailto:joel.goh@eqinsurance.com.sg>]

Sent: Friday, 16 March 2018 10:07 AM

To: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SJQ1746S (OI : EQI - TBA) AND SFP2608D (TP : LKK REF - CC6/EQI17023914/T1hb3) on 08.12.2017

Dear Shu Pei

Based on our records, SJQ1746S is not insured with EQ.
A search reveals that it is insured with AXA.

NCD Enquiry

<< Back to Home

History

ENQUIRY DETAILS

NRIC/FIN or Co. Reg. No.

Vehicle No.

SQ17465

Policy Details

Req. By	Req. Date	Insured	NRIC/Co Reg No	Vehicle No.	Insurer	Policy No.	Period of Insurance	Cancellation Eff. Date	Ex
Joel Goh [EQ Insurance Company Ltd]	16/03/2018 10:04	KANG GILLIAN	S1634103G	SQ17465	AXA Insurance Pte Ltd	P1250448	27/04/2017-26/04/2018		

Accident Reports

Ref. No.	Accident Date	Vehicle Reg. No.	Insured Name	Driver's Name	Driver's IC	Vehicle Make	3rd Party Involved?
MSNH17161910	08/12/2017 11:20	SQ17465	KANG GILLIAN	KANG MAUREEN VALERIE NEE PAWLE MAUREEN VALERIE	S0878773E	VOLKSWAGEN	Y
Accident Date		TP Vehicle Reg. No.		TP Vehicle Make			
08/12/2017 11:10		SFP2608D		AUDI		AXA Insurance Pte Ltd	
08/12/2017 11:30		GR9936M		HYUNDAI		AXA Insurance Pte Ltd	

Policy Details

Req. By	Req. Date	Insured	NRIC/Co Reg No	Vehicle No.	Insurer	Policy No.	Period of Insurance	Cancellation Eff. Date	Ex
Joel Goh [EQ Insurance Company Ltd]	16/03/2018 10:04	KANG GILLIAN	S1634103G	SQ17465	AXA Insurance Pte Ltd	P1250448	27/04/2016-26/04/2017		

Policy Details

Req. By	Req. Date	Insured	NRIC/Co Reg No	Vehicle No.	Insurer	Policy No.	Period of Insurance	Cancellation Eff. Date	Ex
Joel Goh [EQ Insurance Company Ltd]	16/03/2018 10:04	KANG GILLIAN	S1634103G	SQ17465	AXA Insurance Pte Ltd	P1250448	27/04/2015-26/04/2016		

Policy Details

Req. By	Req. Date	Insured	NRIC/Co Reg No	Vehicle No.	Insurer	Policy No.	Period of Insurance	Cancellation Eff. Date	Ex
Joel Goh [EQ Insurance Company Ltd]	16/03/2018 10:04	KANG GILLIAN	S1634103G	SQ17465	AXA Insurance Pte Ltd	P1250448	27/04/2014-26/04/2015		

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAUTO) [<mailto:shupeil@lkkauto.com>]

Sent: Monday, March 12, 2018 11:36 AM

To: Joel Goh

Subject: FW: Direct Settlement - Accident Involving SJQ1746S (OI : EQI - TBA) AND SFP2608D (TP : LKK REF - CC6/EQI17023914/T1hb3) on 08.12.2017

WITHOUT PREJUDICE

Dear Joel,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you,

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)

Sent: Tuesday, 13 February 2018 1:56 PM

To: Elaine Cheong <elaine.cheong@eginsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SJQ1746S (OI : EQI - TBA) AND SFP2608D (TP : LKK REF - CC6/EQI17023914/T1hb3) on 08.12.2017

WITHOUT PREJUDICE

URGENT

Dear Elaine,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)

Sent: Monday, 29 January 2018 11:02 AM

To: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Asher Sng (LKKAUTO)

<AsherSng@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SJQ1746S (OI : EQI - TBA) AND SFP2608D (TP : LKK REF - CC6/EQI17023914/T1hb3) on 08.12.2017

WITHOUT PREJUDICE

Dear Elaine,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)

Sent: Wednesday, 20 December 2017 3:34 PM

To: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Asher Sng (LKKAUTO)

<AsherSng@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SJQ1746S (OI : EQI - TBA) AND SFP2608D (TP : LKK REF - CC6/EQI17023914/T1hb3) on 08.12.2017

WITHOUT PREJUDICE

Dear Sir / Madam,

Attached here with the estimated cost of repair and preliminary advice for your perusal.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)

Sent: Monday, 18 December, 2017 5:14 PM

To: Elaine Cheong <elaine.cheong@eginsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: Direct Settlement - Accident Involving SJQ1746S (OI : EQI - TBA) AND SFP2608D (TP : LKK REF - CC6/EQI17023914/T1hb3) on 08.12.2017

WITHOUT PREJUDICE

Dear Elaine,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SFP 2608D at M/s Maximus Racing Pte Ltd.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Our Ref: M-18-16039
Your Ref: -

Date: 12/2/2018

TO: EQ Insurance Company Ltd
5 Maxwell Rd #17-00
Tower Block MND Complex
Singapore 069110

ATTN: MOTOR CLAIMS DEPARTMENT

RE: **Accident Involving Motor Vehicle Nos:** SFP 2608D / SJQ 1746S
At/Along Farrer Flyover (Base) **On** 8/12/2017 **@** 1100 Hrs

I am the owner of vehicle SFP 2608D that was involved in an accident with your insured vehicle SJQ 1746S of the above accident.

As the accident was caused solely by your insured negligent driving, I am claiming from you for the following: -

1.	Cost of Repairs / Excess	\$ <u>11,770.00</u>
2.	Loss of Use: <u>12</u> days per day @ \$ <u>120</u> / Vehicle Rental	\$ <u>1,440.00</u>
3.	LTA/GIA Search Fee	\$ <u>5.35</u>
4.	Survey Fee	\$ <u>-</u>
5.	Others	\$ <u>-</u>
TOTAL:		\$ <u>13,215.35</u>

I hereby give you fourteen (14) days to comply with the above failing which I shall instruct my solicitors to commence legal action against you. If you have any query, please call **MAXIMUS RACING PTE LTD** at this **Telephone No: 62501198/96382477 (Daphne)** or **Fax No: 62501081**

I hereby give full authority to MAXIMUS RACING PTE LTD and their representative to negotiate/comprise settlement of the above claim on my behalf.

Your co-operation and immediate attention to the above will be appreciated. I hereby look forward to hearing from you soonest possible.

Yours Faithfully,


Name & Signature LIANG HSUEH LIN

Address: C/o MR Performance Centre,
7, Soon Lee Street, #05-05, iSpace.
Singapore 627608
CC: Daphne Tan
Email: daphne@maximusracing.com

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Monday, 2 April, 2018 3:08 PM
To: igangts@gmail.com
Cc: Admin A; Vic (LKKAUTO)
Subject: Your Ref: GR 9936M_ACCIDENT INVOLVING GR 9936M / SFP 2608D/ OTHERS ON 08/12/2017



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/EQI17023914/T1hb3

02 APRIL 20178

IMGG SERVICES

By Email Only

Dear Sir/Madam,

ACCIDENT INVOLVING GR 9936M / SFP 2608D/ OTHERS ON 08/12/2017

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



Maximus Racing Pte Ltd

Company Registration No: 200507694R

GST Reg No: 20-0507694-R

Date: 12/2/2018

EQ Insurance Company Ltd
5 Maxwell Rd #17-00
Tower Block MND Complex
Singapore 069110

Fax: _____

Subj: Claims for Loss of Use of Vehicle - SFP 2608D

Dear Sir / Mdm

I would like to claim for Loss of Use of Vehicle for 12 days on behalf of my customer who has authorised my company to undertake the case.

Calculation as following:

Loss of Use of Vehicle --- 12 days x \$ 120 /day = \$ 1440.00

Thank you.

Daphne Tan



AUTHORISATION TO ACT

In the matters of an accident involving my/our motor vehicle SFP 2608D
And others SJQ 1746S
on 8/12/2017 along Farrer Flyover (Base)

I / We LIANG Hsueh LIN D/Birth 11/8/1956 Sex F of
3 Camden Park S'pore 299793 Tel No: 98286541
Occupation — NRIC No S1173117B

hereby authorize and appoint MAXIMUS RACING PTE LTD to act for me/us for
the purpose of making a third party claim in respect of the abovementioned matter.

I / We further authorize the workshop to settle my/ our above mentioned claim in a manner that they
deem fit and the workshop is also authorized to receive any payment further to settlement of my
claim with payment cheque being made in favour of the workshop on my behalf.


I / We also knowledge that any settlement the workshop may reach on my/our behalf is on a "Without
Prejudice and without admission of liability" basis insofar as the driver/ owner/ insurers of the other
vehicle is concerned.

Date the 12 day of February month of 2018.



Interpreted and witnessed by

Name: Daphne Tan Siok Yin



Signature or Thumb Print

Name: Liang Hsueh Lin

**Maximus Racing Pte Ltd**

Company Registration No: 200507694R

GST Reg No: 20-0507694-R

TO: EQ Insurance Company Ltd
5 Maxwell Rd #17-00
Tower Block MND Complex
Singapore 069110

MOTOR VEHICLE CLAIM
OWNER'S SATISFACTION/DISCHARGE VOUCHER

VEHICLE OWNER: LIANG HSUEH LIN
MOTOR POLICY NO: 2100287626-05000
MAKE/MODEL: Audi A4 Quattro 2.0 REGISTRATION NO: SFP2608D
EXCESS: -
ACCIDENT DATE: 8/12/2017

REPAIRER NAME: **MAXIMUS RACING PTE LTD**
7, SOON LEE STREET,
#05-05, ISPACE,
SINGAPORE 627608

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that the payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

OWNER / INSURED SIGNATURE: DATE: 8 Dec 2017TIME: 1754 hours

8 December 2017

To Whom It May Concern,


I, Maureen Kang, NRIC S0878773E, was driving along Adam Road at approximately 11.20am on 8 December 2017 when I abruptly changed lanes just before the Adam Road Flyover.

My actions caused an Audi, registration number SFP2608D, to brake suddenly. A van, registration number GR9936M, travelling behind this Audi could not brake in time and hit into the back of the car.

The Audi did contact my car, registration number SJQ1746S, causing minor damage which I will bear the cost of repairs myself.

I acknowledge that both SFP2608D and GR9936M will claim against my auto insurance policy to cover their repairs.

Yours sincerely,


Maureen Kang

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, Singapore 627608.

Enquiry Hotline : +65 62501198 / Fax : +65 62501081

Company Registration No. : 200507694R

E-mail : sales@maximusracing.com

Tax Invoice No: M-18-16039

Reference No: Q-17-086

Date: 12/12/2017

Terms: Cash

**FINALISATION FOR SFP2608D**

Requested By: EQ Insurance - Motor Claim Department

Address: 5 Maxwell Rd #17-00 Tower Block MND Complex Singapore 069110

Tel: +65 6223 9433

Item	Description	Qty	Unit Price	Disc %	Total Price
	Policy No // Accident Date: 2100287626-05000 // 8/12/2017 Report In: 8/12/2017 Vehicle Make/Model: Audi A4 Quattro 2.0 Vehicle Number: SFP 2608 D Manufacturing Year: 2011 Engine: 07866713N54B30A Chassis No: WAUZZZ8K9CA100021				
1	Total Lump Sum Repair on Vehicle SFP2608D				\$ 11,000.00
E. & O.E.					
Sub-Total					\$ 11,000.00
ADD GST 7%					\$ 770.00
Grand Total:					\$ 11,770.00

Please Visit our website @ www.MaximusRacing.com**TERMS & CONDITIONS:**

Some products are made exclusively for off-road use, we do not accept any claims/liabilities from their usage.

Do not use the product except in specified car types. We reserve the rights to dispose of goods/parts unclaimed after 3 months.

Maximus Racing Pte Ltd will not accept any claims and/or responsibility arising therefrom.

Any Deposit paid are strictly non-refundable!

Payment by CHEQUES should be crossed and made payable to MAXIMUS RACING PTE LTD

Goods or Parts sold are not returnable nor refundable!

We reserve the rights to charge 1.5% interest per month on all overdue accounts.

Received and agreed to all above charges and sales terms.

Authorised By:

Receiver's Signature

Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 11 Dec 2017 / 18:05:14

Receipt Date/Time : 11 Dec 2017 / 18:05:14

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171211-001923

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - GR9936M

As at 08 Dec 2017/11:00:00

Insurance Co: EQ INSURANCE COMPANY LTD

1 Insurance Enquiry - GR9936M

Enquiry Fee

20171211180351014746

5.00 0.35 5.35

Sub-Total

5.00 0.35 5.35

Total Before Rounding

5.00 0.35 5.35

Rounding Difference

0.00

Total Amount Payable

5.35

Paid By

xxxxxxxxxxxx6290 Credit Card;
Visa/MasterCard 5.35

Total

5.35

Cash Change

0.00

Tendered Amount

5.35

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Vic (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Monday, 2 July, 2018 1:00 PM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving GR9936M (OI : EQI - DM17HO02808-JG) AND SFP2608D (TP : LKK REF - CC6/EQI17023914/T1hb3) on 08.12.2017

Dear Vic

Kindly assist to close and submit your final report to us ASAP.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Saturday, June 30, 2018 4:36 PM
To: Joel Goh
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GR9936M (OI : EQI - DM17HO02808-JG) AND SFP2608D (TP : LKK REF - CC6/EQI17023914/T1hb3) on 08.12.2017

Dear Joel,

We refer to your below email.

As per below instruction dated 02/04/2018, we had informed TP to redirect the claim to the insurer of the 1st vehicle.
Please refer to the attached email.

Till date, we have not receive any feedback/update from the TP.

In view of the above, please advise if we can close the matter and submit our WP report for your further action.

Thank you.

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Monday, 9 April, 2018 6:01 PM
To: Maximus Racing Daphne
Cc: Taufikh (LKKAUTO); Admin A; Asher Sng (LKKAUTO); Guo Li Seah; Vic (LKKAUTO)
Subject: RE: AUDI A4 SFP2608D ACCIDENT LKK REF CC6/EQI17023914/T1hb3

Without Prejudice

Dear Daphne,

We refer further to our below email.

Please be informed that we had highlighted the matter to our principal and we were instructed that based on the Admission Note of the 1st Vehicle (see below copy), we were informed that the claim should be redirected to the first vehicle.

As such, please forward your claim to the Insurer of **SJG 1746S** instead.

Thank you.

Sketch Plan #3

To Whom It May Concern,

I, Maureen Kang, NRIC S0878773E, was driving along Adam Road at approximately 11.20am on 8 December 2017 when I abruptly changed lanes just before the Adam Road Flyover.

My actions caused an Audi, registration number SFP2608D, to brake suddenly. A van, registration number GR9936M, travelling behind this Audi could not brake in time and hit into the back of the car.

The Audi did contact my car, registration number SJQ1746S, causing minor damage which I will bear the cost of repairs myself.

I acknowledge that both SFP2608D and GR9936M will claim against my auto insurance policy to cover their repairs.

Yours sincerely,


Maureen Kang

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Audi
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)

Sent: Monday, 2 April, 2018 2:26 PM

To: Maximus Racing Daphne

Cc: Taufikh (LKKAuto); Admin A; Vic (LKKAuto); Asher Sng (LKKAuto); Guo Li Seah

Subject: RE: AUDI A4 SFP2608D ACCIDENT LKK REF CC6/EQI17023914/T1hb3

Without Prejudice

Dear Daphne,

We refer to your below email and the contents were noted.

We will get back to you for an update the soonest time.

Kindly hold the matter first.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Audi
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Maximus Racing Daphne [<mailto:daphne@maximusracing.com>]

Sent: Monday, 2 April, 2018 2:16 PM

To: Asher Sng (LKKAuto); Guo Li Seah

Cc: Vic (LKKAuto); Taufikh (LKKAuto)

Subject: Re: AUDI A4 SFP2608D ACCIDENT LKK REF CC6/EQI17023914/T1hb3




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ17023914/T1hb3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 03-07-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GR 9936M	Veh. Inspected	SFP 2608D
Policy No.	DMCHHQ17-000245	Coverage (\$)	0.00
Claim No.	DM17HO02808-JG	Excess (\$)	0.00
Assign From		Assign Date	15/12/2017
2. Vehicle Particulars & Condition			
Make & Model	AUDI A4	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WAUZZZ8K9CA100021	Colour	GREY
Odometer	57323	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40R18	MICHELIN	6 mm
L/H Front Tyre	245/40R18	MICHELIN	6 mm
R/H Rear Tyre	245/40R18	MICHELIN	6 mm
L/H Rear Tyre	245/40R18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/12/2017	Inspection Date	15/12/2017
Survey held at	236 WHITLEY ROAD		
Repairer	MAXIMUS RACING PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFP 2608D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	1,380.00	1,380.00
1	FRONT BUMPER CENTER GRILL	NOT NECESSARY	490.00	-
1	FRONT BUMPER LOWER SPOILER	NOT NECESSARY	270.00	-
1	FRONT BUMPER LOWER PANEL	NOT NECESSARY	150.00	-
1	FRONT BUMPER FOAM ABSORBER	NOT NECESSARY	80.00	-
1	FRONT BUMPER REINFORCEMENT BAR	NOT NECESSARY	460.00	-
2	FRONT BUMPER REINFORCEMENT BAR BRACKET @ \$160.00	NOT NECESSARY	320.00	-
2	FRONT BUMPER SIDE BRACKET @ \$40.00	NECESSARY	80.00	80.00
1	FRONT HEADLAMP HOUSING (LH)	CUT	1,700.00	1,700.00
1	FRONT HEADLAMP BRACKET (LH)	NECESSARY	78.00	78.00
1	FRONT HEADLAMP MOUNTING	NECESSARY	110.00	110.00
1	FRONT FOGLAMP (LH)	NOT NECESSARY	198.00	-
1	FRONT FOGLAMP COVER (LH)	NOT NECESSARY	115.00	-
1	FRONT FENDER (LH)	BENT	570.00	570.00
1	FRONT FENDER CROSS SUPPORT (LH)	NOT NECESSARY	95.00	-
1	FRONT WHEEL HOUSING COVER (LH)	NOT NECESSARY	189.00	-
1	SIDE MIRROR COVER (LH)	CUT	430.00	430.00
1	SIDE MIRROR ASSEMBLY WITH MOTOR (LH)	CUT	968.00	968.00
1	SIDE MIRROR TURN SIGNAL (LH)	CUT	99.00	99.00
1	FRONT TIE ROD (LH)	NOT NECESSARY	110.00	-
1	FRONT TIE ROD END (LH)	NOT NECESSARY	220.00	-
2	REAR INNER TAILLIGHT @ \$550.00	N/S NOT NECESSARY / O/S CUT	1,100.00	550.00
2	REAR OUTER TAILLIGHT @ \$750.00	N/S NOT NECESSARY / O/S CUT	1,500.00	750.00
1	REAR PARKING SENSOR	NOT NECESSARY	458.00	-
1	REAR TRUNK LID	BENT	1,500.00	1,500.00
2	REAR TRUNK HINGE @ \$125.00	TO REPAIR SEE LABOUR	250.00	-
2	REAR TRUNK HINGE COVER @ \$225.00	NOT NECESSARY	450.00	-

Report Ref No. CC6/EQ17023914/T1hb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TRUNK LOCK	NOT NECESSARY	115.00	-
1	REAR TRUNK LOCK COVER	CUT	570.00	570.00
1	REAR TRUNK LOCK STRIKER	NOT NECESSARY	540.00	-
1	REAR TRUNK LOCK SWITCH	BENT	390.00	390.00
2	REAR TRUNK STOPPER @ \$21.00	NECESSARY	42.00	42.00
2	REAR LICENCE PLATE LIGHT @ \$108.00		216.00	216.00
1	REAR BUMPER	DEFORMED	1,300.00	1,300.00
1	REAR BUMPER LOWER SPOILER	DEFORMED	250.00	250.00
1	REAR BUMPER LOWER SPOILER MESH	DEFORMED	230.00	230.00
2	REAR BUMPER SIDE BRACKET SMALL @ \$40.00	NECESSARY	80.00	80.00
2	REAR BUMPER SIDE BRACKET BIG @ \$45.00	NECESSARY	90.00	90.00
1	REAR REINFORCEMENT BAR	BENT	475.00	475.00
2	REAR REINFORCEMENT BAR BRACKET @ \$170.00	BENT	340.00	340.00
1	REAR PARKING SENSOR	NOT WORKING	458.00	458.00
1	FRONT FENDER EMBLEM (LH)	NECESSARY	99.00	99.00
1	REAR A4 EMBLEM	NECESSARY	90.00	90.00
1	REAR AUDI CIRCLES EMBLEM	NECESSARY	99.00	99.00
1	REAR 2.0 EMBLEM	NECESSARY	90.00	90.00
1	MISCELLANEOUS - BOLTS, NUTS, SCREWS, CLIPS, ETC.	NOT NECESSARY	120.00	-
	LESS 5% DISCOUNT		-948.20	-651.70
			18,015.80	12,382.30
	SPECIAL NETT ITEMS			
1	VEHICLE PLATE FRAME (SN)	DEFORMED	20.00	20.00
1	VEHICLE PLATE NUMBER (SN)	BENT	20.00	20.00
			40.00	40.00
	LABOUR			
	REMOVE AND RENEW DAMAGES PARTS, STRAIGHTEN AND REALIGN. INCLUSIVE OF THE REPAIR OF REAR TRUNK HINGE.		2,000.00	1,400.00
	RESPRAY AFFECTED AREAS.		2,600.00	1,600.00
	TO APPLY CAVITY WAX COATING ON AFFECTED AREAS.		280.00	100.00
	LABOUR TO CHECK FRONT LIGHTINGS, HEADLAMP, WATER LEAKAGE & HEADLAMP WASHER.	NOT NECESSARY	180.00	-

Report Ref No. CC6/EQI17023914/T1hb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WHEEL BALANCING.		80.00	30.00
	COMPUTERISED 4 WHEEL ALIGNMENT.		120.00	80.00
	GENERAL DIAGNOSTICS TO RESET, RE-CALIBRATE USING VOLKSWAGEN ORIGINAL SOFTWARE HEADLIGHT, TAILLIGHT, SIDE MIRROR & REVERSE SENSORS.		600.00	300.00
			5,860.00	3,510.00
GRAND TOTAL			23,915.80	15,932.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CC6/EQ117023914/T1hb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.