

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

**ESTIMATION FOR SFP2608D**

Requested By: EQ Insurance - Motor Claim Department

Reference No: Q-17-086

Address: 5 Maxwell Rd #17-00 Tower Block MND Complex Singapore 01

Date: 12/12/2017

Tel: +65 6223 9433

Terms: Cash

					PAGE 1	
Item	Description	Qty	Unit Price	Disc %	Total Price	
Policy No // Accident Date: 2100287626-05000 // 8/12/2017 Report In: 8/12/2017 Vehicle Make/Model: Audi A4 Quattro 2.0 Vehicle Number: SFP 2608 D Manufacturing Year: 2011 Engine: 07866713N54B30A Chassis No: WAUZZZ8K9CA100021						
<u>Labour Charges:</u>						
1	Remove and renew damaged parts, straighten and realign					1400 \$ 2,000.00
2	Respray affected areas.					1600 \$ 2,600.00
3	To apply cavity wax coating on affected areas					100 \$ 250.00
4	Labour To Check Front Lightings, Headlamp, Water Leakage & Headlamp Washer					7 \$ 180.00
5	Wheel Balancing					20 \$ 60.00
6	Computerised 4 Wheel Alignment					80 \$ 120.00
7	General Diagnostics to Reset, Re-calibrate using Volkswagen Original Software *Headlight, Taillight, Side Mirror & Reverse Sensors					300 \$ 600.00
<u>Material & Fluid Charges:</u>						
8	Front Bumper <i>de</i>					
9	Front Bumper Center Grill <i>x</i>	1	\$ 1,380.00	5%	\$ 1,311.00	
10	Front Bumper Lower Spoiler <i>x</i>	1	\$ 490.00	5%	\$ 465.50	
11	Front Bumper Lower Panel <i>x</i>	1	\$ 270.00	5%	\$ 256.50	
12	Front Bumper Foam Absorber <i>x</i>	1	\$ 150.00	5%	\$ 142.50	
13	Front Bumper Reinforcement Bar <i>x</i>	1	\$ 80.00	5%	\$ 76.00	
14	Front Bumper Reinforcement Bar Bracket <i>x</i>	1	\$ 460.00	5%	\$ 437.00	
15	Front Bumper Side Bracket <i>de</i>	2	\$ 160.00	5%	\$ 304.00	
16	Front Headlamp Housing (LH) ?	2	\$ 40.00	5%	\$ 76.00	
17	Front Headlamp Bracket (LH) ?	1	\$ 1,700.00	5%	\$ 1,615.00	
18	Front Headlamp Mounting (LH) ?	1	\$ 78.00	5%	\$ 74.10	
19	Front Foglamp (LH) <i>x</i>	1	\$ 110.00	5%	\$ 104.50	
20	Front Foglamp Cover (LH) ?	1	\$ 198.00	5%	\$ 188.10	
		1	\$ 115.00	5%	\$ 109.25	
21	Front Fender (LH) <i>bt</i>					
22	Front Fender Cross Support (LH) ?	1	\$ 570.00	5%	\$ 541.50	
23	Front Wheel Housing Cover (LH) <i>x</i>	1	\$ 95.00	5%	\$ 90.25	
		1	\$ 189.00	5%	\$ 179.55	
24	Side Mirror Cover (LH) <i>ant</i>					
25	Side Mirror Assembly With Motor (LH) ?	1	\$ 430.00	5%	\$ 408.50	
26	Side Mirror Turn Signal (LH) <i>ant</i>	1	\$ 968.00	5%	\$ 919.60	
		1	\$ 99.00	5%	\$ 94.05	
27	Front Tie Rod (LH) ?					
28	Front Tie Rod End (LH) ?	1	\$ 110.00	5%	\$ 104.50	
		1	\$ 220.00	5%	\$ 209.00	
29	Rear Inner Taillight <i>LH - ? RH - ant</i>					
30	Rear Outer Taillight <i>LH - ? RH - ant</i>	2	\$ 550.00	5%	\$ 1,045.00	
31	Rear Parking Sensor <i>mis</i>	2	\$ 750.00	5%	\$ 1,425.00	
		1	\$ 458.00	5%	\$ 435.10	

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

**ESTIMATION FOR SFP2608D**

Requested By: EQ Insurance - Motor Claim Department

Reference No: Q-17-086

Address: 5 Maxwell Rd #17-00 Tower Block MND Complex Singapore 06 Terms: Cash

Tel: +65 6223 9433

PAGE 2

Item	Description	Qty	Unit Price	Disc %	Total Price
32	Rear Trunk Lid <i>bn</i>	1	1,500		
33	Rear Trunk Hinge <i>by</i>	2	\$ 160.00	5%	\$ 304.00
34	Rear Trunk Hinge Cover <i>x</i>	2	\$ 125.00	5%	\$ 237.50
35	Rear Trunk Lock	2	\$ 225.00	5%	\$ 427.50
36	Rear Trunk Lock Cover <i>at</i>	2	\$ 115.00	5%	\$ 218.50
37	Rear Trunk Lock Striker <i>x</i>	2	\$ 570.00	5%	\$ 1,083.00
38	Rear Trunk Lock Switch <i>?</i>	2	\$ 540.00	5%	\$ 1,026.00
39	Rear Trunk Stopper <i>nei</i>	1	\$ 390.00	5%	\$ 370.50
40	Rear License Plate Light <i>?</i>	2	\$ 21.00	5%	\$ 39.90
		2	\$ 108.00	5%	\$ 205.20
41	Rear Bumper <i>de</i>	1	\$ 1,300.00	5%	\$ 1,235.00
42	Rear Bumper Lower Spoiler <i>de</i>	1	\$ 250.00	5%	\$ 237.50
43	Rear Bumper Lower Spoiler Mesh <i>at</i>	1	\$ 230.00	5%	\$ 218.50
44	Rear Bumper Side Bracket Small <i>nei</i>	2	\$ 40.00	5%	\$ 76.00
45	Rear Bumper Side Bracket Big <i>nei</i>	2	\$ 45.00	5%	\$ 85.50
46	Rear Reinforcement Bar <i>?</i>	1	\$ 475.00	5%	\$ 451.25
47	Rear Reinforcement Bar Bracket <i>?</i>	2	\$ 170.00	5%	\$ 323.00
48	Rear Parking Sensor <i>?</i>	1	\$ 458.00	5%	\$ 435.10
49	Front Fender Emblem (LH) <i>nei</i>	1	\$ 99.00	5%	\$ 94.05
50	Rear A4 Emblem <i>nei</i>	1	\$ 90.00	5%	\$ 85.50
51	Rear Audi Circles Emblem <i>nei</i>	1	\$ 99.00	5%	\$ 94.05
52	Rear 2.0 Emblem <i>nei</i>	1	\$ 90.00	5%	\$ 85.50
53	Vehicle Plate Frame <i>de</i>	1	\$ 20.00	S.Nett	\$ 20.00
54	Vehicle Plate Number <i>79</i>	1	\$ 20.00	S.Nett	\$ 20.00
55	Miscellaneous - Bolts, Nuts, Screws, Clips, etc <i>?</i>	1	\$ 120.00	5%	\$ 114.00
<i>Taufik 97495749</i> <i>wp'</i> <i>15/12/17 Q120.</i> <i>Reserving before paint.</i> <i>10 days.</i> <i>su@lkkanto.com</i> <i>taufik@lkkanto.com.</i>					
PRICE BEFORE GST					\$ 23,908.55
ADD GST 7%					\$ 1,673.60
Grand Total:					\$ 25,582.15

Validity of the estimates is 2 weeks based from the date of quote. Estimated costs quoted are excluding GST. We would mention based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you.

Please be informed that a deposit of 50% of full amount is payable before commencement of work.

Authorised By: