

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

**FINALISATION FOR SFP2608D**

Reference No: Q-17-086

Requested By: EQ Insurance - Motor Claim Department

Date: 12/12/2017

Address: 5 Maxwell Rd #17-00 Tower Block MND Complex Singapore 06 Terms:

Cash

Tel: +65 6223 9433

PAGE 1

Item	Description	Qty	Unit Price	Disc %	Total Price
	Policy No // Accident Date: 2100287626-05000 // 8/12/2017 Report In: 8/12/2017 Vehicle Make/Model: Audi A4 Quattro 2.0 Vehicle Number: SFP 2608 D Manufacturing Year: 2011 Engine: 07866713N54B30A Chassis No: WAUZZZ8K9CA100021				
	<u>Labour Charges:</u>				
1	Remove and renew damaged parts, straighten and realign				\$ 1,400.00
2	Respray affected areas.				\$ 1,600.00
3	To apply cavity wax coating on affected areas				\$ 100.00
4	Wheel Balancing				\$ 30.00
5	Computerised 4 Wheel Alignment				\$ 80.00
6	General Diagnostics to Reset, Re-calibrate using Volkswagen Original Software *Headlight, Taillight, Side Mirror & Reverse Sensors				\$ 300.00
	<u>Material & Fluid Charges:</u>				
7	Front Bumper	1	\$ 1,380.00	5%	\$ 1,311.00
8	Front Bumper Side Bracket	2	\$ 40.00	5%	\$ 76.00
9	Front Headlamp Housing (LH)	1	\$ 1,700.00	5%	\$ 1,615.00
10	Front Headlamp Bracket (LH)	1	\$ 78.00	5%	\$ 74.10
11	Front Headlamp Mounting (LH)	1	\$ 110.00	5%	\$ 104.50
12	Front Fender (LH)	1	\$ 570.00	5%	\$ 541.50
13	Side Mirror Cover (LH)	1	\$ 430.00	5%	\$ 408.50
14	Side Mirror Assembly With Motor (LH)	1	\$ 968.00	5%	\$ 919.60
15	Side Mirror Turn Signal (LH)	1	\$ 99.00	5%	\$ 94.05
16	Rear Inner Taillight	1	\$ 550.00	5%	\$ 522.50
17	Rear Outer Taillight	1	\$ 750.00	5%	\$ 712.50
18	Rear Trunk Lid	1	\$ 1,500.00	5%	\$ 1,425.00
19	Rear Trunk Lock Cover	1	\$ 570.00	5%	\$ 541.50
20	Rear Trunk Lock Switch	1	\$ 390.00	5%	\$ 370.50
21	Rear Trunk Stopper	2	\$ 21.00	5%	\$ 39.90
22	Rear License Plate Light	2	\$ 108.00	5%	\$ 205.20

PAGE 1

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, iSpace , Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

**FINALISATION FOR SFP2608D**

Reference No: Q-17-086

Requested By: EQ Insurance - Motor Claim Department

Date: 12/12/2017

Address: 5 Maxwell Rd #17-00 Tower Block MND Complex Singapore 06

Terms: **Cash**

Tel: +65 6223 9433

PAGE 2

Item	Description	Qty	Unit Price	Disc %	Total Price
23	Rear Bumper	1	\$ 1,300.00	5%	\$ 1,235.00
24	Rear Bumper Lower Spoiler	1	\$ 250.00	5%	\$ 237.50
25	Rear Bumper Lower Spoiler Mesh	1	\$ 230.00	5%	\$ 218.50
26	Rear Bumper Side Bracket Small	2	\$ 40.00	5%	\$ 76.00
27	Rear Bumper Side Bracket Big	2	\$ 45.00	5%	\$ 85.50
28	Rear Reinforcement Bar	1	\$ 475.00	5%	\$ 451.25
29	Rear Reinforcement Bar Bracket	2	\$ 170.00	5%	\$ 323.00
30	Rear Parking Sensor	1	\$ 458.00	5%	\$ 435.10
31	Front Fender Emblem (LH)	1	\$ 99.00	5%	\$ 94.05
32	Rear A4 Emblem	1	\$ 90.00	5%	\$ 85.50
33	Rear Audi Circles Emblem	1	\$ 99.00	5%	\$ 94.05
34	Rear 2.0 Emblem	1	\$ 90.00	5%	\$ 85.50
35	Vehicle Plate Frame	1	\$ 20.00	S.Nett	\$ 20.00
36	Vehicle Plate Number	1	\$ 20.00	S.Nett	\$ 20.00
37	Lump Sum Discount	1	-20%		\$ (3,186.46)
PRICE BEFORE GST					\$ 12,745.84
ADD GST 7%					\$ 892.21
Grand Total:					\$ 13,638.05

Validity of the estimates is 2 weeks based from the date of quote. Estimatesd costs quoted are excluding GST. We would mention based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you.

Please be informed that a deposit of 50% of full amount is payable before commencement of work.

Authorised By:

