

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 234/IC/TCAC/CCR/2017
DATE : 14-DEC-2017

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MISS CHAN LI-MEI, KAREN
ADDRESS : 477 RIVER VALLEY ROAD
#03-02
S(248362)
TELEPHONE NO : 91278832

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100496036-00000
VEHICLE NO : SLJ9338Y
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2309715A
CHASSIS NO : SJNFEAJ11U1723337
MILEAGE : 3691 KM
DATE IN : 14/12/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 14/12/2017

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495749
WP

18/12/17 @ 1645

Resurvey before paint

5-6 days

sur@lkkauto.com

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLJ9338Y

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 CONT	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	✓
2 FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	✓
3 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	120.
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	✓
5 WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	X
6 ZZ/001	RENEW FRONT BUMPER, LEFT HEADLAMP, HOOD, LEFT FENDER, TRIM, LEFT FOG LAMP & COVER ETC PANELS & REPAIR.	2340.00	1170.
7 ZZ/002	RESPRAY FRONT BUMPER, HOOD, LEFT FENDER, LEFT DOOR ETC	1500.00	750.
8 ZZ/003	QC, RETUNE & CONSULT CHECK		
9 ZZ/004	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	130.00	X
TOTAL LABOUR CHARGES		4938.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ933BY

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	HOOD	F5100-4EAAA	961.40	Rx	
2	LEFT FENDER TRIM	63811-4EAOA	483.00	?	
3	LEFT FENDER PROTECTOR	63843-4EAOA	87.50	de✓	
4	FRONT LEFT FENDER	F3101-4EAMB	622.70	bt✓	
5	ENERGY ABSORBER	62090-4EA1B	195.70	?	
6	LOWER ARMATURE	62030-4EJ1A	337.70	?	
7	LEFT ENERGY ABSORBER	62090-4EA0C	62.20	?	
8	LEFT BUMPER BRACKET	62223-4EAOA	20.90	as✓	
9	FRONT BUMPER	62022-4EAOH	614.60	de✓	
10	TOW HOOK COVER	622A0-4EAOA	19.30	x	
11	LEFT FOG LAMP COVER	62257-4EA0C	74.70	cut✓	
12	LEFT FOG LAMP	26150-8992B			258.00 ?
13	LEFT HEADLAMP	26060-4EAOA	559.00	cut✓	
SUB TOTAL			4038.70	0.00	258.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			807.74	0.00	0.00
GRAND TOTAL			3230.96	0.00	258.00
OVERALL TOTAL			3488.96		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLJ9338Y

TOTAL LABOUR CHARGES	4938.00
TOTAL SPARE PARTS CHARGES	3488.96

GRAND TOTAL	8426.96 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.