

REF:

NS / WNC 17023920 / Strbe2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SJD 2153X

Policy No.

5039196823 - 08 11-11-17 - 10-11-18

Claims No.

MT/0973821 - 002

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 4587L

Yr Regn:

3/10/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius.

C.C

1796

Colour

Maroon

A/C:

Insured / Std / NI / NA

Sp.Reading

39034

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN 36U 205752114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

14/12/2017

D.O.A.

15/12/2017

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

SHC 4587L - X

TAX/12/17/2083

LKK

NTUC

Confirm LIS \$3100, 4 days
Ref: 8737940, 101.

RECEIVED 10/12/2017

Date/Time, File Pass to?



Preli. Report



Final Report

1) typist

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) S + RS. SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format:

TP

Lump Sum / L.B.I. (\$

3100

TOTAL

199

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0975034-002	COMFORT TRANSPORTATION	SHC 8925T	SIL 9498G	23/12/2017	\$ 3,546.44	\$ 1,615.56
2	MT/0977201-001	COMFORT TRANSPORTATION	SHA 7354H	SGS 4292P	22/12/2017	\$ 2,411.58	\$ 850.00
3	MT/0969224-002	SMRT TAXIS P/L	SHB 757U	GBG 6683D	09/11/2017	\$ 8,833.60	\$ 3,300.00
4	MT/0973642-002	SMRT TAXIS P/L	SHB 5004B	SKC 8591L	13/12/2017	\$ 2,398.00	\$ 638.57
5	MT/0972983-002	SMRT TAXIS P/L	SHB 5494U	SJS 2558B	08/12/2017	\$ 8,366.69	\$ 3,000.00
6	MT/0973821-002	SMRT TAXIS P/L	SHC 4587L	SIQ 2153X	14/12/2017	\$ 10,479.40	\$ 3,100.00

Claim received from UKK Auto



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023920/Srb			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 18-12-2017	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJQ 2153X	Veh. Inspected	SHC 4587L
Policy No.	5039196823-08	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/12/2017	Inspection Date	15/12/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

eBaotTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="14/12/2017 13:57"/>						
Vehicle No.(For Motor)	<input type="text" value="SJQ2153X"/>	<input type="button" value="Search"/>							
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5039196823-08	MICHAEL TAN WEE KWONG	S2556335B	GPC	Third Party, Fire & Theft	SJQ2153X	SJQ2153X	11/11/2017	10/11/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/12/2017 09:54
Date Of Accident	14/12/2017 16:40
Exact Location Of Accident	SLIP ROAD FROM AYE TOWARDS JURONG TOWNHALL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4587L
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	YEO KERN HOW
NRIC No	S0102456F
Date Of Birth	12/10/1949
Occupation	OUTDOOR
Date Of Driving Pass	21/12/1972
Driving Experience	44 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY ALONG SLIP ROAD FROM AYE TOWARDS JURONG TOWNHALL AS I WAS LOOKING OUT FOR THE ONCOMING TRAFFIC. SUDDENLY I FELT DOUBLE IMPACT AT THE REAR OF MY TAXI. A VEHICLE SJQ2153X HAD COLLIDED ONTO THE REAR OF THE MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJQ2153X
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver MICHAEL TAN WEE KWONG
 NRIC/Passport Number S2556335B
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Policyholder's Signature _____
Date & Time: _____

Driver's Signature 15/12/17
(If driver is not the policyholder)
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 15/12/2017

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5369K

Vehicle Details

Vehicle No.: SHC4587L

Vehicle to be Exported: No

Intended De-registration Date: 18 Dec 2017

Vehicle Make: TOYOTA

Vehicle Model: PRIUS TAXI (SMRT)

Primary Colour: Maroon

Manufacturing Year: 2014

Engine No.: 2ZR6198817

Chassis No.: JTDKN36U205752114

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$32,920.00

Original Registration Date: 03 Oct 2014

First Registration Date: 03 Oct 2014

Transfer Count: 0

Actual ARF Paid: \$8,088.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 Oct 2022

PARF Rebate Amount: \$6,066.00

Intended COE Rebate Details

COE Expiry Date:	02 Oct 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,938.00
COE Rebate Amount:	\$30,490.00
Total Rebate Amount:	\$36,556.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Dec 2017


OK

SMRT Accident Vehicle Repair Estimates

NTUC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4587L
Ref. No : TAX/12/17/2083
Reg. Date : 03/10/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : YEO KERN HOW
Type of Accident : HEAD TO REAR
Date / Time of Accident : 14/12/2017 04:43:00 PM
Accident Reported Date / Time : 15/12/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 14/12/2017
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093624
Special Instruction to ARC, if any :
TOWED \$40 / SJQ2153X - NTUC IDAC
Prepared Date : 15/12/2017 10:08:34 AM



Sebastian.
15/12/2017.

- Lump Sum Repair.
- Question Mark Item Photo.
- Photo After Paint.
90036121

sebastianyeang@lkkauto.com


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


18/12/17

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205752114

Mileage


: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	600.00
Total Spray Painting Charges	: 1,296.00	600.00
Total Material Charges	: 2,672.27 7209.40	2,536.02
Other Charges	: 960.00	-636.02
TOTAL	: 5,942.27 10479.40	3,100.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	4.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 15/12/2017 01:21:50 AM	15/12/2017 01:57:19 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 15/12/2017 01:21:50 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1712-0565

Invoice No :

Quotation Date : 20/12

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 12/15/2017 1:22:13 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	600.00 /
Total Labour	1,014.00	600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY BUMPER BEAM	180.00	100.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY TAIL GATE	378.00	200.00 /
Total Spray Painting & Panel Beating	1,296.00	600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-766.02
Total Other Costs	960.00	-636.02

10479.40

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached	
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No /	CRK
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No /	NFC
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No /	NFC
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No /	DMG
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No /	Defon
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No /	Defon
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No /	BT
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No /	BT
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No /	BT
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No /	
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No /	Defon
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace	No /	
58307-47060		6505522	END PANEL	1	602.10	100.00	0.00	Replace	Repair	No /	R
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.58	Replace	Replace	No /	
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.83	Replace	Replace	No /	Defon
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.78	Replace	Check	No X	
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No X	
64993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.28	Replace	Check	No X	NH
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Check	No X	
67005-47241			TAILGATE ASY	1	1,007.90	100.00	0.00	Replace	Repair	No /	R
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No /	NFC
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	0	29.40	25.00	0.00	Replace	Not given	No X	
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	0	29.40	25.00	0.00	Replace	Not given	No X	
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	0	29.40	25.00	0.00	Replace	Not given	No X	NH
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No X	
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No /	Im
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No /	Defon
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	100.00	0.00	Replace	Repair	No /	R

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	100.00	0.00	Replace	Repair	No <i>R</i>
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Check	No <i>X</i> <i>NN</i>
TOTAL MATERIALS							4,175.46	2,536.02		
TOTAL MATERIALS(Discounted)							2,672.27	2,536.02		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

2536.02 /
+ 600.00 ✓
+ 730.00 ✓

3866.02 /
- 202
3092.81 /

US \$3100/- /

Sebastian
28/12/2017.

REQUEST FOR SUPPLEMENT PARTS

Contractor:		Date of Collection	1 / 1
Accident Case Number	TAX/12/13/2083	Date of Request	16/12/2017
Vehicle No	SHC 4587 L	Number of Days to Extend (if any)	1 day
Vehicle Model	TOYOTA PRIUS		

S/N	Part Number	Part Description	Quantity	Unit Price
		ARM SUB ASSY, REAR BUMPER	RM 1pc	✓ 15T
		ARM SUB ASSY, REAR BUMPER	LH 1pc	✓ 15T
		END PANEL OVER, DECK TRIM HOLE	1pc	✓ Defm
		END PANEL OVER, DECK TRIM REAR	1pc	✓ Defm

<<Please submit photographs for damaged parts>>

18/12/2017

I, (Name)

(Position)

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

SMRT Accident Vehicle Repair Estimates


19-12-17 / 09:57

19-12-17 / 13:57

18-12-17 / 13:57

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4587L
Ref. No : TAX/12/17/2083
Reg. Date : 03/10/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : YEO KERN HOW
Type of Accident : HEAD TO REAR
Date / Time of Accident : 14/12/2017 04:43:00 PM
Accident Reported Date / Time : 15/12/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 14/12/2017
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093624
Special Instruction to ARC, if any :
TOWED \$40 / SJQ2153X - NTUC IDAC
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang@lkkauto.com HP: 90036121
LUMP SUM REPAIR
Prepared Date : 15/12/2017 10:08:34 AM



QC 19/12/17 14:42 P653 390321 km

Recording Camera ☐ ☒
Radio Antenna ☐ ☒
1st witness _____ Date 19-12-17
2nd witness _____ Date _____

390393 km
1 1/4 1/2 3/4 8格油

Supplementary
& Refer to the Supplementary part 1/18

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 19/12/2017

Vehicle Return Time: 11:33

SMRT staff sign: _____

Completed by Service Advisor, Accident Repair Centre
Chassis No : JTDKN36U205752114 Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,296.00	0.00
Total Material Charges :	4,514.47	4,514.47
Other Charges :	1,040.00	0.00
TOTAL :	7,864.47	0.00
Lum Sum Total :	7,850.00	0.00
No. of Repair Days :	7.00	0.00
Prepared / Adjusted By :		3 days
Arc / Surveyor Sign Off Date :	15/12/2017 01:21:50 PM	01/01/1900 12:00:00 AM

M

Prepared / Adjusted Date :

Remarks :

Prepared Date : 15/12/2017 01:21:50 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 12/15/2017 1:22:13 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY TAIL GATE	378.00	0.00 200
Total Spray Painting & Panel Beating	1,296.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,040.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace ✓ C&K	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓ N&C	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓ N&C	No
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace ✓ N&C	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace ✓ Deform	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace ✓ Deform	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace ✓ BT	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace ✓	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace ✓ Deform	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace ✓ Deform	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace ✓ Deform	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace R	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace ✓	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace ✓	No
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.77	Replace	Replace ✓	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace X	No
34993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.27	Replace	Replace ✓	No
38416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Replace ✓	No
37005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace R	No
5374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓ N&C	No
5574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace X	No
5573-7080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace X	No
5575-7030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace X	No
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace X	No
9350-7030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace ✓ Jm	No
7881-7022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace ✓ Deform	No
2563-7010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Replace R	No

Number	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52562-47010	TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace	No
89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace	No
TOTAL MATERIALS						5,643.16	5,643.09	
TOTAL MATERIALS(Discounted)						4,514.47	4,514.47	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

Thatcham *escribe*

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023920/Srbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 16-01-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJQ 2153X	Veh. Inspected	SHC 4587L	
Policy No.	5039196823-08	Coverage (\$)	0.00	
Claim No.	MT/0973821-002	Excess (\$)	0.00	
Assign From		Assign Date	15/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U205752114	Colour	MAROON	
Odometer	390321	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/12/2017	Inspection Date	15/12/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4587L

Qty	Description of Parts	Condition	Estimate By Workshop.(\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR (DISC 25%)	CRACKED	458.60	343.95
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.07
1	BUMPER LIP COVER RR/LH (DISC 25%)	DEFORMED	72.20	54.15
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.67
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.27
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	DEFORMED	94.80	71.10
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	DEFORMED	94.80	71.10
1	UNDER COVER SUB-ASSY, RR FLOOR (DISC 25%)	DEFORMED	514.50	385.87
1	END PANEL COVER, DECK TRIM HOLE (DISC 25%)	DEFORMED	46.10	34.58
1	END PANEL COVER, DECK TRIM, RR (DISC 25%)	DEFORMED	121.10	90.83
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	TAILGATE DOOR LOCK (DISC 25%)	JAMMED	444.10	333.07
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	DEFORMED	353.40	265.05
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	SPARE TYRE PANEL	NOT NECESSARY	667.70	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	BOX, DECK FLOOR, RR	NOT NECESSARY	649.70	-
1	BOX, RR FLOOR, BOARD	NOT NECESSARY	679.60	-
1	TAIL GATE DOOR, GLASS MOULDING, LH	NOT NECESSARY	29.40	-
1	TAIL GATE DOOR GLASS MOULDING, RH	NOT NECESSARY	29.40	-
1	MOULDING BACK WINDOW, LOWER NO. 1	NOT NECESSARY	29.40	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	ANTENNA, ELECTRICAL LOWER REAR	NOT NECESSARY	157.40	-
1	END PANEL	TO REPAIR	602.10	-
1	TAILGATE ASY	TO REPAIR	1,007.90	-
1	TAIL LAMP BRACKET, LH	TO REPAIR	30.70	-

Report Ref No. NS/INC17023920/Srbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL LAMP BRACKET, RH	TO REPAIR	30.70	-
			7,269.40	2,536.03
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,814.00	710.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,296.00	600.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,270.00	1,330.00
GRAND TOTAL			10,539.40	3,866.03

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,100.00
---	--	--	-----------------

Report Ref No. NS/INC17023920/Srbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.