

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Estimate : 20037

TPAIG

Zaini

Date : 18.12.2017

Vehicle Num : ~~SLN474HH~~ SLM4741H

Make/Model : KIA SORENTO

Chassis/Engine no :

Accident Date : 15.12.2017

Claim No : 1217-20037

Reference :

Policy No :

KNAPH 81BMH 5325217

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Headlamp LH <i>ok</i>	\$ 2,656.90 ✓
1 pc	Front fender LH <i>Broken</i>	\$ 480.70 ✓
1 pc	Front fender inner shield LH <i>ok</i>	\$ 95.40 ✓
1 pc	Front fender arch garnish LH <i>ok</i>	\$ 347.50 ✓
1 pc	Front support panel <i>ok</i>	\$ 922.40 ✓
1 pc	Front grille <i>new</i>	\$ 455.70 ✗
1 pc	Front bumper corner parking sensor <i>ok</i>	\$ 227.50 ✓
1 pc	Front bumper lower garnish <i>new</i>	\$ 372.50 ✗
1 pc	Front bumper <i>ok</i>	\$ 741.70 ✓
1 pc	Front bumper reinforment <i>new</i>	\$ 315.70 ✗
1 pc	Front bumper fog lamp LH <i>ok</i>	\$ 321.30 ✓
1 pc	Front bumper fog lamp cover <i>new</i>	\$ 62.10 ✗
1 pc	Front bumper side retainer <i>ok</i>	\$ 40.20 ✓
1 pc	Front bumper sponge <i>ok</i>	\$ 121.60 ✓
1 pc	Front bumper headlamp nozel motor <i>ok</i>	\$ 401.30 ✓ <i>258.</i>
1 pc	Front bumper headlamp nozel motor cover <i>missing</i>	\$ 48.30 ✓
1 pc	Front sport rim <i>ok</i>	\$ 1,468.50 <i>450(SN)</i>
1 pc	Front shock absorber LH <i>?</i>	\$ 419.00 ✗
1 pc	Front kunckle arm	\$ 357.00 ✗
1 pc	Front lower arm	\$ 474.00 ✗
1 pc	Front wheel bearing	\$ 279.00 ✗
List Item Total :		\$ 10,608.30
Discount 10 % :		\$ 1,060.83
		\$ 9,547.47

6261.50 SN: H50

5635.35

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Estimate : 20037

Date : 18.12.2017

Vehicle Num : SLN4741H

Make/Model : KIA SORENTO

Chassis/Engine no :

Accident Date : 15.12.2017

Claim No : 1217-20037

Qty	Particular	Amount S\$
<u>Nett Item :</u>		
1 pc	Front tyre <i>XL m</i>	\$ 550.00 <i>x</i>
1 set	Front bumper clip <i>m</i>	\$ 50.00 <i>30</i>
1 set	Front fender inner shield clip LH <i>m</i>	\$ 50.00 <i>30</i>
Nett Total :		\$ 650.00
<u>Labour Charge :</u>		
	To check wiring	\$ 80.00 <i>30</i>
	To apply anti rust chemical	\$ 50.00 <i>x</i>
	Remove and replace LH front suspension and under carriage	\$ 380.00 <i>x</i>
	To check wheel alignment	\$ 80.00 <i>✓</i>
	Remove and refix aircon condenser & refill aircon gas	\$ 150.00 <i>60</i>
	Remove and refix radiator	\$ 120.00 <i>60</i>
	To remove and replace spare part and panel beating	\$ 1,200.00 <i>750</i>
	To spray painting and etc	\$ 1,200.00 <i>400</i>
Labour Charge Total :		\$ 3,260.00

E & O . E

Total Amount

\$ 13,457.47

total 7515.35

r/s: BK o.s.m.p.

KIM CHWEE AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

61C