

Sheet1

ZEN WERKZ LLP

BLOCK 3 KAKI BUKIT ROAD 1 #03-04 EUNOS TECHNOLINK
SINGAPORE 415935

Tel : (65) 67428117 HP: 92712214 Fax: (65) 67428117

TP LCR

Vivian

16th December 2017

Blk 3 Kaki Bukit Road 1
#03-04 Eunost Technolink
Singapore 415935

Accident date: 12th December 2017

Estimated repair cost for vehicle no: SLA5990L HONDA STREAM 1.8 A

S/n	Qty	Items	U/price	Amount
				\$1,171.30 902
1	1	Rear Boot Lid <i>Painted</i>		\$50.00 X
2	1	Rear Boot Lid Emblem Logo <i>Not New</i>		\$45.00 ✓
3	1	Rear Boot Lid Stream Logo <i>New</i>		\$162.80 +
4	1	Rear Boot Lid Center Moulding <i>Not New</i>		\$30.00 +
5	6	Rear Boot Lid Center Moulding Clips	\$5.00	\$50.00 +
6	1	Rear Boot Lid Number Plate <i>Not New</i>		\$80.20 +
7	2	Rear Boot Lid Number Plate Lamp	\$40.10	\$85.00 ✓
8	1	Rear Boot Lid Windscreen Seal <i>New</i>		\$159.40 ✓
9	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$161.20 ✓
10	1	Rear Boot Lid Inner Rubber <i>Not</i>		\$341.60 X
11	1	Rear Boot Lid Inner Trim Board <i>Not New</i>		\$764.80 382.40
12	2	Rear tail lamp <i>LH Canted</i>	\$382.40	\$22.00 10
13	4	Rear tail lamp clips <i>New</i>	\$5.50	\$980.00 668
14	1	Rear Bumper <i>Debonded</i>		\$130.00 64
15	2	Rear Bumper Side Bracket <i>New</i>	\$65.00	\$65.00 30
16	10	Rear Bumper Clips <i>New</i>	\$6.50	\$58.00 X
17	1	Rear Bumper Towing Cover <i>Not New</i>		\$350.00 200 (\$20)
18	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$380.00 X
19	1	rear bumper lower cover <i>Not New</i>		\$306.70 +
20	1	Rear End Panel top <i>Not New</i>		\$221.70 +
21	1	Rear End Panel lower		\$166.70 +
22	1	Rear End Panel Top Garnish <i>Not New</i>		

Subtotal :- \$5,781.40

2507 8.20:200

200560

Labour charges

To remove & re-fix rear windscreen

~~\$120.00~~ 100

Gum

~~net \$50.00~~ ✓

To remove & re-fix cushion

~~\$120.00~~ 40

To remove & re-fix reverse sensor

~~\$120.00~~ 50

To Check Wiring System

1470

~~\$80.00~~ 30

Tuff Kote

~~\$120.00~~ x

Panel beating

~~\$1,000.00~~ 600

Spray painting

~~\$1,000.00~~ 600

Subtotal :- \$2,610.00

Total:- \$8,391.40

total: 3675.60

1/s: 2.9K.

05 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: