

ZEN WERKZ LLP

BLOCK 3 KAKI BUKIT ROAD 1 #03-04 EUNOS TECHNOLINK
SINGAPORE 415935

Tel : (65) 67428117 HP: 92712214 Fax: (65) 67428117

16th December 2017

Blk 3 Kaki Bukit Road 1
#03-04 Eunost Technolink
Singapore 415935

Accident date: 12th December 2017

Estimated repair cost for vehicle no: SLA5990L HONDA STREAM 1.8 A

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid		\$1,171.30
2	1	Rear Boot Lid Emblem Logo		\$50.00
3	1	Rear Boot Lid Stream Logo		\$45.00
4	1	Rear Boot Lid Center Moulding		\$162.80
5	6	Rear Boot Lid Center Moulding Clips	\$5.00	\$30.00
6	1	Rear Boot Lid Number Plate		\$50.00
7	2	Rear Boot Lid Number Plate Lamp	\$40.10	\$80.20
8	1	Rear Boot Lid Windscreen Seal		\$85.00
9	1	Rear Boot Lid Inner Lock		\$159.40
10	1	Rear Boot Lid Inner Rubber		\$161.20
11	1	Rear Boot Lid Inner Trim Board		\$341.60
12	2	Rear tail lamp	\$382.40	\$764.80
13	4	Rear tail lamp clips	\$5.50	\$22.00
14	1	Rear Bumper		\$980.00
15	2	Rear Bumper Side Bracket	\$65.00	\$130.00
16	10	Rear Bumper Clips	\$6.50	\$65.00
17	1	Rear Bumper Towing Cover		\$58.00
18	1	Rear Bumper Reverse Sensor		\$350.00
19	1	rear bumper lower cover		\$380.00
20	1	Rear End Panel top		\$306.70
21	1	Rear End Panel lower		\$221.70
22	1	Rear End Panel Top Garnish		\$166.70

Subtotal :- \$5,781.40

Labour charges

To remove & re-fix rear windscreen	\$120.00
Gum	\$50.00
To remove & re-fix cushion	\$120.00
To remove & re-fix reverse sensor	\$120.00
To Check Wiring System	\$80.00
Tuff Kote	\$120.00
Panel beating	\$1,000.00
Spray painting	\$1,000.00
Subtotal :-	<u>\$2,610.00</u>
Total:-	<u>\$8,391.40</u>