

INS. CASE OWNER:

Bernard

CC 4 / AIG170

23977, Kwasu

LAA IDAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT

18/12/17

Date / Time:

18/12/17

Registered in Merimen:

18/12/17

Pre-assign / CCU / FTE



Insured Vehicle No. : 6Y 4917P

Claim No. : 606786567256

Name of Insured : HY-RAY P12

Policy No. : 01005 2551-1000 box

Insured Tel No. : HP: 15/12/17

Make / Model : NISSAN NV350

Excess Sec II : SS D.O.A : 15/12/17

Place of Accident : AMP AVE 8 7 AMP HUB

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : TONY KUN PEI

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : 97808309 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SLD 8777



INSRS: WSP: Tel: Liability: RMKS: cheng Hoe



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date / Time	STAGE	DATE / PIC
20/1/17	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	
20/1/17	Documentation Check List: Handler Typist	
7/5/18	File pass to typist type report	
22/5/18	Email to AIG to seek mandate	
25/5/18	Mandate approve via Merimen.	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
--------------------	------------	----------	-------------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

FINAL SETTLEMENT	Date/Time: 25/5/18	Confirm with: Jue	Email: Call:
------------------	--------------------	-------------------	--------------

Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 27	If NO or B 28, Ass. Lia :
Repair Cost:	SS 9785.26	
Loss of Rental (LOR):	SS (days)	
Loss of Use (LOU):	SS 480.00 (\$60 x 8 days)	
Loss of Income (LOI):	SS (\$ x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search	SS -	
Medical:	SS -	
Disbursement:	SS - (e.g. Tow/ Independent)	1) Claim status: Normal/Reject/Private Settle
Legal Cost	SS -	2) Report Format:
Total:	SS 9265.26	3) Survey fee:

FINAL PAYMENT	Date/Time:	Confirm with:	Email: Call:
---------------	------------	---------------	--------------

Payee 1:	SS 9265.26	Name 1: Chang Hoe Motor Pte Ltd
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

COPY SENT 25/5/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG17023927/Kwa3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 18-12-2017	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GY 4917P	Veh. Inspected	SLD 8171Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/12/2017	Inspection Date	18/12/2017
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Att: Kenneth

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000
ATTN: Motor Claim Department

FAX: 64153727

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 15/12/2017
TP Veh Reg No: GY4917P

Not Authorized
1-B.1
Recovery By pain
8210.52

Estimate No: ES1791410/AMK
Date: 18 Dec 2017
Policy No: 5081506395-01
Veh Reg No: SLD8171Z
Make/Model: HONDA VEZEL 1.5X CVT
Chassis No: RU11113613
Engine No: L15B4033616
Reg. Date: 29/06/2016

Delay

Estimate Repair Cost to Vehicle No :SLD8171Z

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	863.70	1 PC	863.70	✓
2 REAR BUMPER SIDE BUMPER	195.20	2 PC	390.40	✓
3 REAR BUMPER RH REFLECTOR	135.10	1 PC	135.10	✓
4 REAR BUMPER RH SIDE RETAINER	29.30	1 PC	29.30	✓
5 REAR BUMPER CLIP	3.70	4 PC	14.80	✓
6 REAR TAILGATE	1,100.90	1 PC	1,100.90	✓
7 TAILGATE INNER RUBBER	96.80	1 PC	96.80	✓
8 TAILGATE INNER LOCK	180.00	1 PC	180.00	✓
9 TAILGATE EMBLEM 'VEZEL'	56.20	1 PC	56.20	✓
10 TAILGATE NUMBER PLATE LAMP GARNISH	220.90	1 PC	220.90	✓
11 TAILGATE REFLECTOR	240.00	2 PC	480.00	✓
12 TAILGATE WINDSCREEN GLASS MOULDING	158.20	1 PC	158.20	✓
13 TAILGATE INNER TRIM BOARD	225.00	1 PC	225.00	✓
14 TAILLAMP	460.40	2 PC	920.80	✓
15 REAR END PANEL	415.60	1 PC	415.60	✓
16 REAR END PANEL INNER TOP GARNISH	98.20	1 PC	98.20	✓
17 REAR END PANEL UNDER TRAY	190.10	1 PC	190.10	✓
18 REAR END PANEL BUZZER SENSOR (INNER)	89.40	1 PC	89.40	✓
19 REAR END PANEL BUZZER SENSOR (OUTER)	85.00	1 PC	85.00	✓
20 TOOL SPONGE	225.00	1 PC	225.00	✓
21 REAR LUGGAGE COMPARTMENT TOP BOARD	236.30	1 PC	236.30	✓
22 REAR RH FENDER WHEEL ARCH GARNISH	150.20	1 PC	150.20	✓
23 REAR LUGGAGE COMPARTMENT PANEL	1,130.00	1 PC	1,130.00	X
24 REAR FENDER INNER TRIM	295.00	2 PC	590.00	X
			8,081.90	
		Less 20%	1,616.38	6,465.52
Special Net				
25 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
26 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
27 REAR LUGGAGE COMPARTMENT PANEL TOP COAT	80.00	1 PC	80.00	✓
28 REVERSE CAMERA	320.00	1 PC	320.00	X
			475.00	475.00
Labour				
29 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department

Estimate No: ES1791410/AMK
Date: 18 Dec 2017
Policy No: 5081506395-01
Veh Reg No: SLD8171Z
Make/Model: HONDA VEZEL 1.5X
 CVT
Chassis No: RU11113613
Engine No: L15B4033616
Reg. Date: 29/06/2016

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 15/12/2017
TP Veh Reg No: GY4917P

Estimate Repair Cost to Vehicle No :SLD8171Z

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
30 REMOVE & REFIX REAR BUMPER,BOTH SIDE BUMPERS,TAILGATE,SPOILER & ATTACHMENTS,TAILLAMPS;TO CUT,WELD & RENEW REAR END PANEL,REAR LUGGAGE PANEL;KNOCKING & REPAIR REAR FENDERS & REALIGN THE SAME	1,500.00	1 LA	1,500.00	1100
31 PUTTY & RESPRAY REAR BOTH SIDE BUMPERS,TAILGATE,FENDERS, REAR END PANEL,REAR LUGGAGE PANEL & ALL AFFECTED AREAS	1,300.00	1 LA	1,300.00	1200
32 REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION	80.00	1 PC	80.00	✓
33 REMOVE & REFIX REAR MUFFLER,REAR UNDERCARRIAGE & REALIGN THE SAME	350.00	1 LA	350.00	60
34 REMOVE & REFIX REAR SEAT,CARPET TO FACILITATE REPAIR	100.00	1 LA	100.00	✓
35 RUSTPROOFING	90.00	1 LA	90.00	✓
			3,540.00	3,540.00
			Total	SS 10,480.52
			Add GST @ 7%	733.64
			Total Amount Payable	SS 11,214.16

VEHICLE LYING AT :
 NO.10 ANG MO KIO INDUSTRIAL PARK 2A
 #01-04 AMK AUTOPOINT
 SINGAPORE 568047
 TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

UP Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be notified
- All work is subject to final approval from

Acknowledged by Repairer

Signature: _____

Date: _____

Not Authorized
Resony B4 point

HONDA VEZEL

RM1113613

SHD B171Z

PARTS	COST	LIST
1pc Rear bumper	B1-	
2pus - w side bumpers	16/20 4	
1pc - w RH reflector	CR1-	
1pc - w RH side retainer	DR1-	
4pus - w clips	16-	
1pc Tailgate	B1-	
1pc - w inner rubber	DR1/CR1	
1pc - w inner lock	DR1-	
1pc - w emblem (VEZEL)	16-	
1pc - w no. plate lamp garnish	16-	
2pus - w reflectors	CR1-	
1pc - w wls glass moulding	16-	
1pc - w inner trim board	16-	
2pus Taillamps	CR1-	
1pc Rear end panel	B1-	
1pc - w inner top garnish	DR1-	
1pc - w under tray	16-	
1pc - w buzzer sensor (inner)	CR1-	
1pc - w (outer)	CR1-	
1pc Tool sponge	CR1-	
1pc Rear luggage panel top board	16-	
1pc Rear RH fender wheel arch garnish	16-	
1pc Rear luggage panel	B1/16-	

CHENG HOE MOTOR PTE LTD
 10 ANG MO KIO IND PARK 2A
 #01-04 AMK AUTOPOINT
 SINGAPORE 568047
 TEL: 6481 2001 FAX: 6482 1296
 EMAIL: chmank@singnet.com.sg

2pus Rear fenders inner trims ?

SLD8171Z

<u>LABOURS</u>	<u>COST</u>
SV: 1pc Rear no. plate	1pc 35 h ✓
1pc Rear wls glass seatbelt	1pc 40 h ✓
1set Rear luggage panel top coat	1pc 80 h 600
1pc Reverse Camera	320 h ?
R & R Rear wls glass	120 h ✓
R & R Rear bumper, both side bumpers, tailgate, spoiler & attachments, tail lamp, cut, weld & R rear end panel, rear luggage panel, L & R rear fenders & realign the same.	1500 h ¹⁴⁰⁰
Putty & respray rear both side bumpers, tailgate, fenders, rear end panel, rear luggage panel & all affected areas.	1300 h ¹²⁰⁰
R & R Reverse camera, reset & reposition the same	80 h ✓
R & R Rear muffler, rear undercarriage & realign the same	350 h ?
R & R Rear seat, carpet to facilitate repair	100 h ✓
Rustproofing	90 h ✓

View Received Message

This mail is associated with :

***SLD8171Z (1062865672SG)**
[GY4917P]

TP
CHENG WENXUE(ZHENG WENXUE)
Dec 15 2017 1:00PM
[HY-RAY PRIVATE LIMITED]
Cheng Hoe Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 25/05/2018 14:52 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9265.26) - SLD8171Z - Claim Handler: Ler, Bernard-JQ

Approved:9265.26:Hi pls settle as follow: Cost of Repair : \$8,785.26 Loss of Use : \$480.00 8 days @ S\$ 60/day Total : \$9,265.26

DOCUMENTS SUMMARY

There are no documents.

PAYMENT ADVICE



Your Ref : AIG Vehicle no.	:	GY4917P
Claimant Vehicle No.	:	SLD8171Z
Date of Accident	:	15/12/2017
Traffic Accident involving vehicle/s No.	:	ALONG ANG MO KIO AVE 8

BREAKDOWN OF PAYMENT/S

<u>S/No.</u>	<u>Items</u>	<u>Amount</u>	<u>Remark</u>
1	Repair cost	\$ 8,785.26	
2	Loss of Use	\$ 480.00	\$60 X 8 days
3	LTA Search	\$ -	
	TOTAL	\$ 9,265.26	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK
Contact No. : 6256 3561



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG17023927/Kwa3

22 December 2017

HY-RAY PRIVATE LIMITED

40 Jln Pemimpin
#02-10 Tat Ann Bldg
Singapore 577185

Dear Sir/Madam,

ACCIDENT INVOLVING GY 4917P AND SLD 8171Z ON 15/12/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORIZATION TO ACT
(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

I, Cheng Wenxue (Zheng Wenxue) (the third party claimant) of Blk 570 Ang Mo Kio Ave 3 #03-3357 S 560570 (address), owner of SLD8171Z (vehicle no.) hereby authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SLD8171Z that was damaged pursuant to the accident which occurred on 15/12/2017 (date) along Ang Mo Kio Ave 8 (location) involving vehicle no/s GY4917P ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 15 (day) of Dec (month) 2017 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

This Discharge Voucher applies strictly for Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, CHENG HOE MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$8785.26(Repair Cost), S\$480.00 (Loss of Use), S\$0.00 (Disbursement), for vehicle no SLD8171Z that was damaged pursuant to the accident which occurred 15/12/2017 (date) along Ang Mo Kio Ave 8 (location) involving vehicle no/s GY4917P. This is pursuant to the inspection conducted on 18/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Cheng Wenxue (Zheng Wenxue)("the third party claimant") of vehicle no. SLD8171Z make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage SLD8171Z(vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.


This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25 (day) of May (month) 2018 (year)

KSC



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

NO: **CL8180255**
Date: 29 Mar 2018
Policy No: 5081506395-01
Veh Reg No: **SLD8171Z**
Make/Model: HONDA VEZEL 1.5X CVT
Job No: JC1597104

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 15/12/2017
TP Veh Reg No: GY4917P

Description

To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges.
(As recommended by your appointed surveyor)

Quantity	List Price	PAGE:1 Amount
1 PC	<u>SS</u> SS 8,210.52	<u>SS</u> SS 8,210.52

Total	SS 8,210.52
Add GST @ 7%	574.74
Total Amount payable	SS 8,785.26

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2017 Edit Reg		18 Dec 2017 00:00 Edit Adj Rpt	S\$8,210.52 Edit Estimates	S\$8,210.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HY-RAY PRIVATE LIMITED , Co. Reg. No.: 200502767D								
Main Claimant:	CHENG WENXUE(ZHENG WENXUE) , ID: S8201463B								
Vehicle Reg. No.:	SLD8171Z	Date of Loss:	15/12/2017 13:00 - :59 [17 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1062865672SG	Policy/Cover Note No.:	0100521551-12000 (Comprehensive)						
Vehicle Reg. No. (Insured):	GY4917P	Policy No. (Claimant):	5081506395-01						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Bk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/12/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (25/05/2018): Alert - Adj Mandate Approved (S\$9265.26) - SLD8171Z - Claim Handler: Ler, Bernar...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD8171Z (1062865672SG)
 [GY4917P]
 TP
CHENG WENXUE(ZHENG WENXUE)
 Dec 15 2017 1:00PM
[HY-RAY PRIVATE LIMITED]
 Cheng Hoe Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View	View in Browser
Letters/Correspondences															1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit			
Assessment Reports															1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print			
1	19/12/17 12:38	Accident Statement From: SC - Reg. No: GY4917P, Claimant: HY-RAY PRIVATE LIMITED											Load HTM			
Photos/Images															3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
2	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
3	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
4	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
5	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
6	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
7	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
8	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
9	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
10	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
11	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
12	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
13	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
14	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
15	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
16	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
17	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
18	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
19	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
20	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
21	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
22	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
23	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
24	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
25	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
26	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
27	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
28	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
29	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		
30	22/05/18 16:08	General View											Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	22/05/18 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
32	22/05/18 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
33	22/05/18 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
34	22/05/18 16:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	22/05/18 16:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	22/05/18 16:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	22/05/18 16:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	22/05/18 16:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	22/05/18 16:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	22/05/18 16:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	22/05/18 16:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 14:51	ACKNOWLEDGEMENT EMAIL TO AIG DD 18.12.2017	 Load PDF	
2	18/12/17 14:51	EMAIL FROM AIG DD 18.12.2017	 Load PDF	
3	18/12/17 14:51	TP GIA REPORT	 Load PDF	
4	17/05/18 14:28	LETTER TO OI	 Load PDF	
5	22/05/18 16:25	Email to AIG to seek mandate SLD 81712	 Load PDF	
6	28/05/18 14:07	WORKSHOP INVOICE	 Load PDF	
7	28/05/18 14:07	AUTHORISATION TO ACT FORM	 Load PDF	
8	28/05/18 14:07	Release Voucher	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GY4917P (Insd veh)	Model:	HONDA VEZEL 1.5 X CVT (A)
	SLD8171Z (TP veh)		
Date of Accident:	15/12/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	11,214.16	
Final Repair Cost	:	\$	8,785.26	
Loss of Use	:	\$	480.00	8.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	0.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	9,265.26	
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 9,265.26
2)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

28 May
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17023927/KWA3Q2

Date: 28/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100521551-12000
 Claimant Vehicle No: SLD8171Z Insured Vehicle No: GY4917P
 Date of Loss: 15/12/2017 Nature of Claim: TP Claim No: 1062865672SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD8171Z
 Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4033616
 Reg. Date: 29/06/2016 (Man. Year: 2016) Chassis No: RU11113613
 Colour: Metallic Black Odometer: 17059 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
 Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,940.52	5,460.52	1,480.00	21.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	2,750.00	790.00	22.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,480.52	8,210.52	2,270.00	21.66
+ GST 7.00/7.00% (S\$)	733.64	574.74	158.90	21.66
Nett Amount (S\$)	11,214.16	8,785.26	2,428.90	21.66
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
	Nett Liability (S\$)	9,265.26		

INSPECTION

Date of Assignment: 18/12/2017
 Date Inspected: 18/12/2017 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	863.70 FL	*863.70 FL
2	2		*REAR BUMPER SIDE RETAINER	O/S Buckled / N/S Mtg Cracked	390.40 FL	*390.40 FL
3	1		*REAR BUMPER RH REFLECTOR	Cracked	135.10 FL	*135.10 FL
4	1		*REAR BUMPER RH SIDE RETAINER	Distorted	29.30 FL	*29.30 FL
5	4		*REAR BUMPER CLIP	Necessary	14.80 FL	*14.80 FL
6	1		*REAR TAILGATE	Bent	1,100.90 FL	*1,100.90 FL
7	1		*TAILGATE INNER RUBBER	Distorted / Cut	96.80 FL	*96.80 FL
8	1		*TAILGATE INNER LOCK	Dented	180.00 FL	*180.00 FL
9	1		*TAILGATE EMBLEM VEZEL	Necessary	56.20 FL	*56.20 FL
10	1		*TAILGATE NUMBER PLATE GARNISH	Warped	220.90 FL	*220.90 FL
11	2		*TAILGATE REFLECTOR	Cracked	480.00 FL	*480.00 FL
12	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	158.20 FL	*158.20 FL
13	1		*TAILGATE INNER TRIM BOARD	Buckled	225.00 FL	*225.00 FL
14	2		*TAILLAMP	Cracked	920.80 FL	*920.80 FL
15	1		*REAR END PANEL	Bent	415.60 FL	*415.60 FL
16	1		*REAR END PANEL INNER TOP GARNISH	Dented	98.20 FL	*98.20 FL
17	1		*REAR END PANEL UNDER TRAY	Buckled	190.10 FL	*190.10 FL
18	1		*REAR END PANEL BUZZER SENSOR (INNER)	Cracked	89.40 FL	*89.40 FL
19	1		*REAR END PANEL BUZZER SENSOR (OUTER)	Cracked	85.00 FL	*85.00 FL
20	1		*TOOL SPONGE	Cracked	225.00 FL	*225.00 FL
21	1		*REAR LUGGAGE COMPARTMENT TOP BOARD	Buckled	236.30 FL	*236.30 FL
22	1		*REAR RH FENDER WHEEL ARCH GARNISH	Buckled	150.20 FL	*150.20 FL
23	1		*REAR LUGGAGE COMPARTMENT PANEL	Repair	1,130.00 FL	*- FL
24	1		*REAR FENDER INNER TRIM	O/S Necessary	590.00 FL	*295.00 FL
25	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS
26	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
27	1		*REAR LUGGAGE COMPARTMENT PANEL TOP COAT	Necessary	80.00 FS	*60.00 FS
28	1		*REVERSE CAMERA	Serviceable	320.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,556.90	6,791.90
- List Item Discount on L Items 20.00/20.00% (\$)	1,616.38	1,331.38

Total Parts (\$)	6,940.52	5,460.52
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ,BOTH SIDE BUMPER ,TAILGATE SPOILER & ATTACHMENTS ,TAILLAMPS ,TO CUT ,WELD & RENEW REAR END PANEL,REAR LUGGAGE PANEL,KNOCKING & REPAIR REAR FENDERS & REALIGN THE SAME	New	1,500.00	1,100.00
3	PUTTY & RESPRAY REAR BOTH SIDE BUMPERS ,TAILGATE ,FENDERS ,REAR END PANEL,REAR LUGGAGE PANEL & ALL AFFECTED AREAS	New	1,300.00	1,200.00
4	REMOVE & REFIX REVERSE CAMERA ,RESET & PEROSITION	New	80.00	80.00
5	REMOVE & REFIX REAR MUFFLER ,REAR UNDERCARRIAGE & REALIGN THE SAME	New	350.00	60.00
6	REMOVE & REFIX REAR SEAT ,CARPET TO FACILITATE REPAIR	New	100.00	100.00
7	RUSTPROOFING	New	90.00	90.00
Gross Labour Cost (S\$)			3,540.00	2,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >