

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5499B -**AAD1712-138***Not Authored
LSP & FPOOL*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5499B - JHOW

VF1ABL15AUC278813

RENAULT

LATITUDE

13.12.2017

AIG**PART****LIST**

1	1	BUMPER COVER FRT	\$	Bu 1,259.42 ✓
2	1	BUMPER ABSORBER FRT	\$	Sn 394.68 X
3	1	BUMPER BEAM FRT	\$	R 914.08 X
4	1	BUMPER SPOILER FRT	\$	Sn 181.75 X
5	1	BUMPER GRILLE LOWER FRT	\$	Sn 266.80 X
6	1	BUMPER FOG LAMP GRILLE RH	\$	Sn 207.22 X
7	1	BUMPER RETAINER FRT RH	\$	D.V 151.41 ✓
8	1	BUMPER BRACKET FRT RH	\$	R 181.75 X
9	1	HEADLAMP RH	\$	Sn 1,184.43 X
10	1	HEADLAMP PANEL FRT RH	\$	R 152.15 X
11	1	FENDER PANEL FRT RH	\$	Bt 783.83 ✓
12	1	FENDER INSULATOR RH	\$	Sn 130.84 X
13	1	FENDER BRACKET FRT RH	\$	R 34.14 X
14	1	WHEELARCH FRT RH	\$	CR 278.84 ✓
15	1	RADAIOR GRILLE	\$	Sn 1,707.78 X
16	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	Sn 173.36 X
17	1	RADAIOR GRILLE FRAME	\$	Sn 1,353.75 X
18	1	FRAME FULL SUPPORT PANEL	\$	Sn 615.90 X
19	1	FRAME FULL SUPPORT BRACKET	\$	R 89.79 X
20	1	BONNET	\$	R 1,941.63 X
21	1	LOWER ARM RH	\$	Bt 685.76 ✓
22	1	KUNCKLE ARM RH	\$	Bt 846.98 ✓
23	1	KUNCKLE HUB+BEARING RH	\$	M 497.69 ✓
24	1	ABSORBER FRT RH	\$	Bt 360.54 ✓
25	1	DRIVESHAFT RH	\$	R 1,747.45 X
26	1	LOWER ARM RH	\$	Agua 685.76 X
27	1	KUNCKLE ARM RH	\$	Sn 846.98 X
28	1	KUNCKLE HUB+BEARING RH	\$	Sn 497.69 X
29	1	ABSORBER FRT RH	\$	Sn 360.54 X
30	1	STEERING PINION RACK	\$	Bt/In 4,413.11 ✓
31	1	WHEEL HOUSING PANEL FRT RH	\$	R 4,682.09 X
32	1	DOOR PANEL FRT RH	\$	R 2,844.66 X
33	1	DOOR HINGE UPPER RH	\$	R 274.50 X
34	1	DOOR HINGE LOWER RH	\$	R 300.55 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5499B -**AAD1712-138**

35	1	DOOR MOULDING FRT RH	\$	176.82	}	X
36	1	DOOR MIRROR RH	\$	1,483.40		
37	1	DOOR MIRROR GLASS RH	\$	148.20		
38	1	DOOR MIRROR BACK COVER RH	\$	218.46		
39	1	DOOR WHETHERSTRIP FRT RH	\$	474.21		
40	1	DOOR SEAL FRT RH	\$	68.67		
41	1	ROCKER PANEL OUTER RH	\$	987.49		
42	1	DOOR PANEL REAR RH	\$	2,844.66		

TOTAL	\$	37,449.77
10%	\$	3,744.98
	\$	33,704.79

Specical Nett

1	1SET	WHEELARCH CLIP FRT RH	\$	66.00	✓
2	1SET	FRONT BUMPER CLIP	\$	66.00	✓
3	1	RIM RH FRT	\$	385.00	✓
4	1	TYRE RH FRT	\$	330.00	60% ✓
5	1	RIM RH FRT	\$	385.00	Repaired X
6	1	TYRE RH FRT	\$	330.00	X
7	1	DOOR STICKER "Trans-cab"	\$	80.00	X
8	1	DOOR STICKER "Classic"	\$	30.00	X
9	1	DOOR STICKER "6555-3333"	\$	80.00	X

TOTAL	\$	1,752.00
TOTAL PARTS	\$	35,456.79

To Check Electrical Lighting Concerned.	\$	170.00	15/
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	400
Putty and spray painting of the affected portion.	\$	4,500.00	440
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	20/
To check steering geometry and computer wheel alignment	\$	220.00	60/

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST63 SINGAPORE 569111
TEL NO. 6287 6666 FAX NO. 6257 1330
CO/GST REG NO. 201019626G
SHC5499B -

AAD1712-138

To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	X
Towing fees	\$	120.00	50
To rust-proofing of the affected areas.	\$	170.00	30
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	200

TOTAL	\$	10,440.00
Over All Total	\$	45,896.79

(PARTS BY PARTS) Repair Days

15 Days

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: