

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

VEHICLE NO: SJK2959U

QTY

PARTICULAR

LIST ITEMS :

1PCS	FRONT DOOR MIRROR N/S
1PCS	FRONT BUMPER
1PCS	FRONT BUMPER CLIPS
1PCS	FRONT FENDER O/S
1PCS	FRONT FENDER 'VVTI' EMBLEM O/S
1PCS	FRONT SHOCK ABSORBER O/S
1PCS	FRONT LOWER ARM O/S
1PCS	FRONT knuckle ARM O/S
1PCS	FRONT knuckle ARM BEARING O/S
1PCS	FRONT ANTI ROLL BAR
1PCS	FRONT ANTI ROLL BAR LINK
1PCS	STEERING RACK ASSY 1573.60
1PCS	FRONT DRIVE SHAFT O/S
1PCS	ENGINE CROSS MEMBER 2498.20
1SET	ENGINE MOUNTING
1PCS	REAR SHOCK ABSORBER O/S
1PCS	REAR TRAILING ARM O/S
1PCS	REAR LOWER ARM O/S
1PCS	REAR WHEEL HUB BEARING O/S
1PCS	REAR CROSS MEMBER

SPECIAL NETT ITEMS :

1PCS	REAR SPORTS RIM O/S
1PCS	REAR TYRE O/S
1PCS	FRONT SPORTS RIM O/S
1PCS	FRONT TYRE O/S

LABOUR CHARGES :

TO CHECK WIRING
TOWING CHARGE
TO SPRAY RUST PROOFING
TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE
TO DISMENTLE & REPLACING REAR UNDERCARRIAGE
TO CONDUCT FULL WHEEL ALIGNMENT
TO DISMENTLE & LIFT UP ENGINE FOR REPLACING front UNDERCARRIAGE
LABOUR FOR PANEL BEATING
TO PUTTY & SPRAY PAINTING

LKK Auto Consultants hence notify

the Rep of the following:

• Parts price

• Third party Sur.

• No illegal modifications

• Supplementary item(s) must be approved

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AMOUNT \$S

Cur	\$362.30	✓
deep cur	\$481.10	✓
ner	\$43.00	✓
n	\$396.70	✓
ner	\$38.00	✓
but	\$334.50	✓
no/but	\$302.00	✓
but	\$395.20	✓
ner	\$105.00	✓
11	\$285.00	✓
11	\$89.50	✓
but/ner	\$2,665.30	✓
8u	\$1,650.30	✓
no/set	\$3,200.50	✓
11	\$675.00	✓
but	\$281.30	✓
but	\$488.20	✓
1w1	\$366.00	✓
ner	\$350.00	✓
1A	\$1,008.00	✓
	\$13,516.80	

(203)

1618.4
6094.72

no/but	\$600.00	300S.W
ner	\$200.00	500S.W 100
no/but	\$600.00	300S.W
ner/ner	\$200.00	500S.W 100

11	\$50.00	✓
	\$120.00	60
11	\$50.00	✓
	\$500.00	350
	\$300.00	120
	\$150.00	60
	\$480.00	50
	\$500.00	200
	\$500.00	450
TOTAL	\$17,766.80	

not authorized
Helen

2/5 \$6500
Helen

Latitudes After repair

8186.72