ASS. REC. DY: REF: CS3/AIGI702	23939/Sd3 LZ Special Instruction:
From (Person): Winnie Fan of Estimated Cost:	DeterTime: 11:25am
OD TP WS/TP RES/OD RES/EVA/INV/MV7 To Inspect Vehicle No: SIN 3256 at Workshop m/s Hendon Au	T Insured: SLT 3344R
Policy No:	101-19 > 757322 Claim No: 645 709794786
Sum Insured: Make of Veh: (Client's Record)	Excess: D.O.A!\ 2 30 7
CA / REV / REP. / REV 24 HRS Date/Time: 12:16pm 18/12/19 Person Contacted:	H.O.D. Endorsement:
Date/Time Action/Instruction (X) Estimate SLN 3256 T- X	ξ
SIT 3344R-X Dismantle: 19/10/2017	
After repair: 2017 .	

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT3344R AND SLN3256T ON 14/12/2017

From: Fan, Winnie-LW

To: assignments, Admin A

Cc: Fong, Andy-SY, Chin, Lee-Ying

Sent: Monday, 18 December, 2017 11:26:37 AM

Attachments: SLT3344R.TIF

Hi LKK.

Kindly assist to survey.

Winnie Fan

AIG

Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Fax +(65) 6835 7416 winnie-lw.fan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

HENDON AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5 #01-19, Harvest@Woodlands S(757322)
TEL: 94592885 FAX: 63345178

Date:

Pre-repair Inspection

By Fax 6415 3727 Only

M/s AIG Asia Pacific Insurance Ptc. Ltd AIG Building 78 Shenton Way #08-16 Singapore 079120

Dear Sir.

ACCIDENT INVOLVINGSEN 32567 AND SET 3344 R ON 14/12/17 (1) 32:25

We reter to the above matter.

We are the appointed repair workshop of vehicle no. \$4N 3256 T

We understand that you are the insurer of vehicle no. \$1.7 3344 R.

We hereby give you notice of the accident and an apportunity to impose the damaged to the vehicle prior to the commencement of the repairs.

Finally take note that we hereby give you a day: nones to conduct a pre-repair respection of vehicle $m_1SLN/3256/T$ at my premises.



Your faithfully

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	15/12/2017 13:48
Date Of Accident	14/12/2017 22:25
Exact Location Of Accident	TAMPINES ST 31
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
/ehicle Registration Number	SLN3256T
Insured/Policyholder	
Name Of Registered Owner	LOW YONG PEOW @ TAN YONG PEOW
NRIC No	S0030623A
Email Address	ALL.AUTOQUOTES@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96213106
Alternative Phone No	OTHERS-96213106
Vehicle Particulars	OTTLENG-30210100
Manufacturer	KIA
Model	CERATO K3 1.6
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100508288-00000

28/04/2017 TO 27/04/2018 Cover Note Number

Driver

LOW YONG PEOW @ TAN YONG PEOW Name of Driver S0030623A NRIC No 30/06/1953 Date Of Birth INDOOR Occupation Date Of Driving Pass 05/06/1974

43 YEARS AND 6 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-96213106 Mobile Number

Fax Number

OTHERS-96213106 Contact Number

ALL.AUTOQUOTES@GMAIL.COM EMail Address

Address '

APT BLK 106 PASIR RIS ST 12 #03-115 (S) 510106

Postcode

Was driver an employee of the Insured's Company NC

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

...

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLT3344R

Vehicle Make/Model/Colour

Details Of Properties Name of Driver

LEE CHEE HIAN

NRIC/Passport Number

S7381036A

Contact Number

84681386

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of the purpose of the pu
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:

Name: ... NRIC/FIN No.:

Reporting Centre Personnel's Signature

Page 3 of 24

	Accident Sketch Flan Fg. 1	
ETCH PLAN		
EICH PLAN	- A	
	5	A. SLN3256T
	TBDIAN J	R - /1-
\rightarrow . $-$	n: 7	B-SLT 3344P
tompine	1 54 31 . 7	
-		
ESCRIBE CIRCUMSTANCES O	F THE ACCIDENT	
	A STATE OF THE STA	was at the trattic
100 101 12 100 12	- @ 33315brs , -	MAT STATE THE
light junctio	n of tempines	5+ 31.
whom the	green light on,	hobites were
1000	,	
mares 4	1 tollowed o	is well.
move a	TOT STORY	
	I was hit by	a cor 5173344
ころしのり	Las hit by	
	1000	
trong rec		
		we co his Asia Insta
	lesu	SCN 331-67 14 12 21-
		Reporting Only
		Own Damage Claim
		Other Workshop
		CI one noivend
DECLARATION	(i)	ST SHOW
I/We declare the foregoing parti	Culars are true in every respect.	(Salas
经100年	凭人生水流—	150 OND 100
(a) 10 1/1/	Debug Signature	Reporting Centre Personnel's Signature
Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder)	Name:
3041 Firsty	Date & Time:	NRIC/FIN No.:
121.1		1

MOTORCAR (Rear)

ACTION IAC)
(1)Replace (\$\sqrt{2}\$) (2)Repair() (3)Check \$\sqrt{2}\$)
(4)Not Consistent NC)

Aug. 2005

Vehicle No: SLN 3256 T

-3	11		_	71			2.0	
A	6	ča	Γ	1	47	ra	FE	100

NAC	INC 002626	Item	CON	AC	Qty
1137	993626	Rear Number Plate	-	_	-
1138	993627	Rear Number Plate Base	-	_	
1140	993630 993632	Rear Number Plate Garnish	-	-	_
1141	993032	Rear Number Plate Lamp Rear Bumper			-
1142	993085	Rear Bumper Upper	00	×	-
1143	993017	Rear Bumper Lower	-	-	
1144	993054	Rear Bumper Side	-	-	-
1145	993103	Rear Bumper Tow Cover	1		-
1146	992341	Rear Bumper Clips	NEC	7	-
1147	992976	Rear Bumper Bracket	KACE	~	-
1148	993068	Rear Bumper Side Retainer	BR	1	-
1149	993045	Rear Bumper Reinforcement	CRK		-
1150	992970	Rear Bumper Beam	CUN	V	\vdash
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper	1		
1153	993040	Rear Bumper Protector		-	
1154	993036	Rear Bumper Pad	1	-	-
1155	993026	Rear Bumper Moulding			1
1156	993044	Rear Bumper Reflector	NEC	1	
1157	993023	Rear Bumper Lower Spoiler	BT	1	1
1158	994023	Reverse Sensor	SC	1	1
1159	993327	Rear End Panel	100	1	1
1160	993339	Rear End Panel Top Garnish			1
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	1	1
1171		Bootlid Emblem	-		-
1172		Bootlid Handle		-	-
1173		Bootlid Moulding	-		
1174		Bootlid Reflector			
1175		Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH Bootlid Lock	0.0	-	
1178	990377	Bootlid Rubber	DD	1	1
1179	990382		+-	+	-
1180		Bootlid Spoiler	17	-	-
1181	994543		-	-	+
1182		Tailgate Emblem	-	-	+
1183	994643			-	+
1184	994640				+
1185	994545			1	+
1186		and the state of t		-	1
1187	The second second second second			+	+
1188	The second second second			1	+
1189					+
1190	The second second second	and the state of t		1	
1191	994679				1
1192		The state of the s		1	
1193	994602			1	
1194	The State of the S			1	1
1195	The second second second			1	
1196		Tailgate Glass Sealant	***		1
1197					
				1	1
1198	994651	Langare Kuddet			
1198	to a literature and the same		-	+	+

NAC		Item	CON	AC	Cit
10.00				1000	(UVI)
202	993784	Spare Tyre Board			-
203	994328	Spare Tyre Panel			
204	995065	Spare Tyre			
205	994326	Spare Tyre Lock Screw			
206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218		Rear LH Fender			
1219		Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	THE RESIDENCE OF STREET	Rear LH Fender Inner Trim			1913
1222		Rear LH Fender Inner Garnish		-	
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre		T	
1228	993456	Rear RH Fender			
1229		Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415				
1233		Rear RH Fender Inner Shield			
1234		Rear RH Mudflap		-	_
1235		Rear RH Wheel Rim		_	
1236	994025				
1237	995065		-	-	_
1238	995162				_
1239	993401				
1240		Rear Fender Inner Top Garnish		1	
1241	993673	A SOCIAL HAR MANAGED LANGUAGE CONTRACTOR	-	-	-
1242	THE STREET, ST	Rear Fender 1/4 Glass Rubber	-	+	-
1243	and the second s	Rear Fender 1/4 Glass Sealant Rear Windscreen Glass	+	+	-
1245	-	Rear Windscreen Glass Rear Windscreen Rubber	-	+	+
1245	-	A CONTRACTOR OF THE CONTRACTOR	-	+	-
1247		Rear Windscreen Sealant	-	+	+
1248	994729			-	+
1249	-	Rear Fender Air Grille	1	+	+
1250	7.5.0.0.0.0	Fuel Lid	-	-	-
1251	992168		-	-	+
1252			+-	-	+
1253		Fuel Tank Bracket		+	+
1254	THE RESERVE OF THE PARTY OF THE	Fuel Tank Float	-	-	+
1136	att a series in benind the besides	The first terminal and the control of the control o	+-	+	-
1130	77024)	GREET	-	-	+
	1		1	+	+
-	-	-	-	-	+
	-	- to	-	+	+
-	-	1 2	-	-	+
-	1	* 2 days	+	+	+
	-	1 1	-	+	+
	1	J	-	-	-
	-		-	+	-
-	-	1	-	+	+

...CLAIM SUBFOLDER...(Pending for Survey Report) PRI

LAIM SUB	FOLDER TRA	CKING									
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Д	dj Submitted	Ins Auth'ed	State	us		
Main	04 Apr 2018 Edit Reg		18 Dec 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Est	1.17	\$0.00 View Rpt		Rep	Pending for Survey Report Cancel Case		
	Main	R	eference	CI	aim Detail	s T	Documer	nts	1_	Show All	
CLAIM SU	JBFOLDER DI	ETAILS		THE REAL PROPERTY.	MINISTER STATE	[Created	by adjuster]	The Later of the L	and the same of th	THE RESERVE OF THE PERSON NAMED IN	
Insured:	Lee Chee	Hian, Co. Reg.	No.: -			-					
Main Claimant:	LOW YOR	G PEOW @ TAN	YONG PEOW			N'essantia					
Vehicle Re	g. SLN325	6Т			Date of Los		7 00:00 - :59 and 16 Days Fr	om LTA Reg	Date (M	an Yr)]	
Claim Type	TP / 645	7097947SG			Policy/Cove Note No.:	(Comprehe	ensive)				
Vehicle Re No. (Insured):	SLT3344R				Policy No. (Claimant)						
					Excess:						
Repairer:	Hendon A	Automotive (HQ)	280 WOODLANDS I	INDUSTRIAL	PARK E5, #	01-19 HARVES	ST @ WOODLAN	DS, 75732	2 Woodla	nds - Tel:	
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expre	ss) - Tel: 65	-6419-300	[Handled t	y Wui, Shawn	- KJ] Shawr	kaijye.W	ui@aig.con	
Adjuster:	12/04/2		Ltd (HQ) - Tel: 62	256-3561	[Handled b	Sebastian Y	eang Wai Keer) [Fina	I Rpt d	ue	
ASSOCIA	TED MAIL RE	CEIVED					13	View All	Compose	Case Mail	
AIG_SG	(04/04/2018)	: NO TP GIA REF	PORT								
ALL ASS	OCIATED TAS	sks⊟				View All	Search Tasks	Create Nev	v Task	Complete	
Due Dat		Type Tasi	Group Subjec	ct Handl	er Ass	igned By	Completed O	n Cre	ated On	Done?	

Claim Documents

*SLN3256T (6457097947SG)

[SLT3344R]

TP

LOW YONG PEOW @ TAN YONG PEOW

Dec 14 2017 12:00AM

[Lee Chee Hian]

Hendon Automotive

Pho	tos/Images		3 per page	
Vo	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	il Prin
1	03/04/18 16:23	General View	■ Load JPG	-
2	03/04/18 16:23	General View	1 Load JPG	✓
3	03/04/18 16:23	General View	■ Load JPG	V
4	03/04/18 16:23	General View	1 Load JPG	V
5	03/04/18 16:23	General View	€ Load JPG	· 🔽
6	03/04/18 16:23	General View	1 Load JPC	
7	03/04/18 16:23	General View	1 Load JPG	
8	03/04/18 16:23	General View	1 Load JPG	V
9	03/04/18 16:23	General View	1 Load JPC	· 🗸
10	03/04/18 16:23	General View	■ Load JPC	V
11	03/04/18 16:23	General View	1 Load JPC	V
12	03/04/18 16:23	General View	■ Load JPC	
13	03/04/18 16:23	General View	■ Load JPC	V
14	03/04/18 16:23	General View	■ Load JPC	5 V
15	03/04/18 16:23	General View	Load JPC	i 🗵
16	03/04/18 16:23	General View	6 Load JPC	g
17	03/04/18 16:23	General View	€ Load JPC	5 V
18	03/04/18 16:23	General View	1 Load JPC	5 V
19	03/04/18 16:23	General View	Load JPC	5 V
20	03/04/18 16:23	General View	€ Load JPC	3 2
21	03/04/18 16:23	General View	Load JPC	3 2
22	03/04/18 16:23	General View	€ Load JPC	i 🔽
23	03/04/18 16:23	General View	■ Load JPC	3 2
24	03/04/18 16:23	General View	■ Load JPC	3 4
25	03/04/18 16:23	General View	■ Load JPC	3 2
26	03/04/18 16:23	General View	1 Load JPG	G ✓
27	03/04/18 16:23	General View	■ Load JPG	3 2
28	03/04/18 16:23	General View	1 Load JP	G ☑
29	03/04/18 16:23	General View	1 Load JP	G 🔽
30	03/04/18 16:23	General View	€ Load JP	G 🔽
31	03/04/18 16:23	General View	■ Load JPI	G 🔽
32	03/04/18 16:23	General View	■ Load JP	g 🔽
33	03/04/18 16:23	General View	1 Load JP	G 🖳
34	03/04/18 16:23	General View	1 Load JP	G √
35	03/04/18 16:23	General View	1 Load JP	G 🖳
36	03/04/18 16:23	General View	1 Load JP	G 🔽
37	03/04/18 16:23	General View	● Load JP	G ⋤

Pho	tos/Images		3 per page	-
Vo.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna Lord 390	STATE OF THE PARTY.
8	03/04/18 16:23	General View	1 Load JPC	1 12
9	03/04/18 16:23	General View	1 Load JPC	-
0	03/04/18 16:23	General View	1 Load JPC	
1	03/04/18 16:23	General View	1 Load JPC	
2	03/04/18 16:23	General View	1 Load JPC	
3	03/04/18 16:23	General View	⑥ Load JPC	3 🗸
4	03/04/18 16:23	General View	① Load JPC	3 🗸
5	03/04/18 16:23	General View	1 Load JPC	3 2
6	03/04/18 16:23	General View	■ Load JPc	3 😾
7	03/04/18 16:23	General View	1 Load JP	
8	03/04/18 16:23	General View	1 Load JP	G 🗸
9	03/04/18 16:23	General View	1 Load JP	-
0	03/04/18 16:23	General View	1 Load JP	G ₹
1	03/04/18 16:23	General View	1 Load JP	G ✓
2	03/04/18 16:23	General View	1 Load JP	G ✓
3	03/04/18 16:23	General View	1 Load JP	G ✓
54	03/04/18 16:23	General View	Load JP	G ∡
55	03/04/18 16:23	Odometer Reading	1 Load JP	G ✓
6	03/04/18 16:23	General View	Load JP	G 🔽
57	03/04/18 16:23	Chassis Number	1 Load JP	G 🔽
8	03/04/18 16:23	General View	Load JP	G 🔽
59	03/04/18 16:23	General View	1 Load JP	G 🔽
0	03/04/18 16:23	General View	■ Load JP	G 🔽
51	03/04/18 16:23	General View	1 Load JP	G 🔽
52	16/04/18 12:02	Photographs of Damaged Parts	1 Load JP	G 🔽
63	16/04/18 12:02	Photographs of Damaged Parts	■ Load JP	G 🔽
54	16/04/18 12:02	Photographs of Damaged Parts	Load JP	G 🔽
55	16/04/18 12:02	Photographs of Damaged Parts	■ Load JP	G 🔽
56	16/04/18 12:02	Photographs of Damaged Parts	■ Load JP	
67	16/04/18 12:02	Photographs of Damaged Parts	■ Load JP	-
68	16/04/18 12:02	Photographs of Damaged Parts	■ Load JP	-
69	16/04/18 12:02	Photographs of Damaged Parts	€ Load JP	G 🔽
70	16/04/18 12:02	Photographs of Damaged Parts	■ Load JP	G ⋤
71	16/04/18 12:02	Photographs of Damaged Parts	1 Load JP	G ⋤
72	16/04/18 12:02	Photographs of Damaged Parts	1 Load JP	G 🔽
73	16/04/18 12:02	Photographs of Damaged Parts	1 Load JP	-
74	16/04/18 12:02	Photographs of Damaged Parts	① Load JP	-
500	16/04/18 12:02	Photographs of Damaged Parts	Load JF	-
75 76		Photographs of Damaged Parts	② Load 3F	
-	16/04/18 12:02	Photographs of Damaged Parts	Load JF	-
77	16/04/18 12:02	Photographs of Damaged Parts	Load JF	-
78 79	16/04/18 12:02	Photographs of Damaged Parts	O Load JF	-
-	16/04/18 12:02	Photographs of Damaged Parts	1 Load JF	-
80		Photographs of Damaged Parts	O Load JF	-
81	16/04/18 12:02		O Load JF	-
82	16/04/18 12:02	Photographs of Damaged Parts	1 Load 3F	-
83	16/04/18 12:02	Photographs of Damaged Parts	€ Load JF	- F
84	16/04/18 12:02	Photographs of Damaged Parts	1 Load Ji	-
85	16/04/18 12:02	Photographs of Damaged Parts		-
86	16/04/18 12:02	Photo After Spray	1 Load Ji	PG G

Pho	tos/Images		3 per p	age 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
88	16/04/18 12:02	Photo After Spray	0	Load JPG	₹
89	16/04/18 12:03	Photo After Spray	0	Load JPG	✓
90	16/04/18 12:03	Photo After Spray	0	Load JPG	₹
91	16/04/18 12:03	Photo After Spray	0	Load JPG	✓
92	16/04/18 12:03	Photo After Spray	0	Load JPG	V
93	16/04/18 12:03	Photo After Spray	0	Load JPG	✓
94	16/04/18 12:03	Photo After Spray	0	Load JPG	V
95	16/04/18 12:03	Photo After Spray	0	Load JPG	V
96	16/04/18 12:03	Photo After Spray	0	Load JPG	V
97	16/04/18 12:03	Photo After Spray	0	Load JPG	☑
98	16/04/18 12:03	Photo After Spray	0	Load JPG	~
99	16/04/18 12:03	Photo After Spray	0	Load JPG	₹
100	16/04/18 12:03	Photo After Spray	0	Load JPG	V
101	16/04/18 12:03	Photo After Spray	0	Load JPG	✓
102	16/04/18 12:03	Photo After Spray	0	Load JPG	V
103	16/04/18 12:03	Photo After Spray	0	Load JPG	V
104	16/04/18 12:03	Photo After Spray	0	Load JPG	✓
105	16/04/18 12:03	Photo After Spray	0	Load JPG	✓
106	16/04/18 12:03	Photo After Spray	0	Load JPG	V
107	16/04/18 12:03	Photo After Spray	0	Load JPG	☑
108	16/04/18 12:03	Photo After Spray	0	Load JPG	V
Doc	umentation		1 per	page 🔻	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	04/04/18 15:15	OI GIA REPORT	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.		Seattle 1-3.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			-

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG17023939/SD3E2

Date:

17/04/2018

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle

SLN3256T 14/12/2017 Policy No:

Insured Vehicle No:

Nature of Claim:

SLT3344R

TP

Claim No: 6457097947SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No:

SLN3256T

Make & Model:

KIA CERATO K3, 1.6 (A)

Engine No: Chassis No: G4FGGH655419

Reg. Date:

28/04/2017 (Man. Year: 2017)

Odometer:

KNAFX411MH5705458 17455 km

Colour:

Blue 1591 cc

Engine Capacity: Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

205/55 R16 Nexen 6 mm Rear Tyre Size:

205/55 R16

Front Left Side: Front Right Side:

Nexen 6 mm

Rear Left Side: Rear Right Side: Nexen 6 mm Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

18/12/2017

Date Inspected:

18/12/2017 Inspected At:

Hendon Automotive (HQ)

280 WOODLANDS INDUSTRIAL PARK E5, #01-19 HARVEST @ WOODLANDS

Singapore 757322

Estimated Period of Repair:

2.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen ... 17/4/2018

REPAIR DETAILS

Recommended Parts

Qty Part No.	Particulars	Condition	Repairer's	Amount
1	*REAR BUMPER	Dented	0.00 F	*-F
1		Necessary	0.00 F	*-F
1		Broken	0.00 F	*- F
1		Cracked	0.00 F	*- F
1	*REAR BUMPER REFLECTOR	Necessary	0.00 F	*- F
1	*REAR BUMPER LOWER SPOILER	Bent	0.00 F	*-F
1	*REVERSE SENSOR	Shorted	0.00 F	*- F
1	*BOOTLID	Dented	0.00 F	*- F
1	*BOOTLID LOCK	Dented	0.00 F	*-F
anchise part.		Total Parts (S\$)	0.00	0.00
	1 1 1 1 1 1 1 1	1 *REAR BUMPER 1 *REAR BUMPER CLIPS 1 *REAR BUMPER SIDE RETAINER 1 *REAR BUMPER REINFORCEMENT 1 *REAR BUMPER REFLECTOR 1 *REAR BUMPER LOWER SPOILER 1 *REVERSE SENSOR 1 *BOOTLID 1	1 *REAR BUMPER Dented 1 *REAR BUMPER CLIPS Necessary 1 *REAR BUMPER SIDE RETAINER Broken 1 *REAR BUMPER REINFORCEMENT Cracked 1 *REAR BUMPER REFLECTOR Necessary 1 *REAR BUMPER LOWER SPOILER Bent 1 *REVERSE SENSOR Shorted 1 *BOOTLID Dented 1 *BOOTLID LOCK Dented	1 *REAR BUMPER Dented 0.00 F 1 *REAR BUMPER CLIPS Necessary 0.00 F 1 *REAR BUMPER SIDE RETAINER Broken 0.00 F 1 *REAR BUMPER REINFORCEMENT Cracked 0.00 F 1 *REAR BUMPER REFLECTOR Necessary 0.00 F 1 *REAR BUMPER LOWER SPOILER Bent 0.00 F 1 *REVERSE SENSOR Shorted 0.00 F 1 *BOOTLID Dented 0.00 F anchise part Dented 0.00 F

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >